

IMASCO MINERALS INC.
PO BOX 56
SIRDAR, BC V0B 2C0
PH: 250 866 5292
FAX: 250 866 5455

DATE May 29/06
TO Al Hoffman
FROM P. Rodenstein
NUMBER OF PAGES 6

Al, Report as Requested.
So much for modern
technology.
Peter


**MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES**
Mining & Minerals Division
Report of Inspector of Mines

(Issued pursuant to Section 15 of the Mines Act)

 File: 189-10-02-04
 Mine No: 0500284
 Permit No:
 Emp/Cont: 0 / 0
 Orders H&S: RECL:
 Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Picking Belt Shack, Plant

Persons Contacted

MANAGEMENT P. Rodenstein

OHS COMMITTEE J. Wall

WORKERS s.22

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving this report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

An investigation of silica exposure to workers at the Imasco, Sirdar plant was conducted on 7-8 March 06. This was prompted by a silicosis claim (XL 05403467) s.22 in August 05 and accepted by the WCB later last year.

s.22

A walk through survey was conducted on 7 March 06. Roadways were wet from rain, temp approximately 10 C, with a light wind. Due to the wet conditions there was little apparent roadway dust.

There did not appear to be high levels of airborne dust in the picking shack. The muck is washed when it passes over a screen upstream of the jaw crusher.

MANAGERS RESPONSE OF ACTION TAKEN

Al Hoffman

Manager, Occupational Health

7th floor, 1675 Douglas Street Victoria BC V8W 9N3

Address

Date of Inspection: **March 7, 2006**

Signature - Inspector of Mines

Signature - Manager

Dated: May 15, 2006

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

1) Ventilation is provided by drawing air through a fan on tail end side of the conveyor. This is not a good practice as the dust is not filtered before it enters the picking shack. Pursuant to Sections 1.9.1 (2) and 2.3.5 of the Code the ventilation system for the picking shack shall be reviewed and consideration shall be given to positively pressurizing the area so that only filtered air enters the shack.

2) It is my understanding that granite or quartzite rock is crushed dry in winter when water dust suppression can not be used due to freezing of the belt idlers etc. Dry crushing of granite or quartzite shall cease immediately. Management and employees are reminded that it is the inhalation of the respirable silica size fraction (less than 10 micron aero diameter) which can result in silicosis. Dust in this size fraction can not be seen readily with the naked eye.

On March 7th 2006 airborne and settled dust levels were high in the plant, but it is my understanding that significant progress has been made in improving dust collection and housekeeping.

Sampling for airborne dust and collection of bulk samples was conducted on 8 March 06. The results are shown in Figures 1 and 2. A 30 knot northerly wind was blowing on the property; dust levels were considerably lower in the plant on 8 March as compared to the day previous. Roadways were still rain drenched; the ambient temp was approximately 8 deg C. Anecdotal comments by employees indicate that airborne dust levels can vary widely depending on the prevailing wind and whether the roadways are dry or wet.

Figure 1 shows that airborne dust levels were low on the day sampled. Note that this is a snapshot in time and levels on average could be much higher; this is supported by the amount of settled dust in the plant.

Figure 2 shows the percentage of silica (SiO₂) in bulk samples that were located in and around the plant. As expected, samples which were composed of granite (65.49%)

1) A filtered air system will be designed and installed to ensure the shack is under positive pressure. All the openings will be sealed with the exception of the chutes required for waste rock disposal. It is estimated that about 7000 cfm of positive pressure will be required to provide filtered air into the building through a filter system similar to the ones being used in the MCC rooms. This will be completed as soon as practicable. In the short term all pickers have been supplied with and trained in the proper use of dust masks.

2) Based on discussions with the former manager and one of the long time pickers, this was only done once. It has never been standard practice. It has never been done since will not be done in the future.

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>or quartzite(97.32%) were high in silica. It is important to note that dust that had settled around screening operations contained between 10% and 14% silica. If this dust is reentrained into the air during shoveling or sweeping activities it could pose a hazard. It is important to note that airborne respirable silica concentrations can not be extrapolated (predicted) from the bulk sample concentrations. Only further occupational monitoring can determine this.</p> <p>It is also my understanding that granite and quartzite are run through the plant on a batch basis several times per year. It is predicted that silica exposures in the picking shack and the plant could be very high during this time period.</p> <p>Occupational Monitoring Program</p> <p>3) In accordance with Section 2.1.3 of the Code an occupational monitoring program shall be implemented at the mine site to determine exposures to respirable silica, limestone and dolomite. The Ministry can assist you with setting up this program.</p> <p>Ventilation and Clean Up in the Plant</p> <p>4) In accordance with Section 2.3.5 of the Code, efforts shall be made to improved the dust collection system in the plant.</p> <p>Eye Wash Stations</p> <p>5) In accordance with Section 2.4.1 of the Code, a permanent or portable eye wash station shall be located in an area close to the bagging operation. The eyewash station shall be put on a monthly PM schedule to ensure that it is clean and operational.</p> <p>Washroom Facilities</p> <p>6) It is my understanding that the washroom facilities near the picking shack are not operational in the winter. In accordance with Sections 2.11.9 - 2.11.13 of the Code, the requirements for toilet facilities shall be reviewed to ensure that they are</p>	<p>Occupational Monitoring Program</p> <p>3) A copy of the 2002 Workplace Monitoring Procedures Manual published by the Ministry in February, 2002 will be reviewed with the OHSC co-chairs. Included in this manual is a template for a "Mine Workplace Monitoring Program" designed for a small gravel pit. This will be revised as necessary to suit our operation at which time it will be submitted to the Ministry. We will continue to work with Al Hoffman and the Ministry to implement the monitoring program.</p> <p>Ventilation and cleanup in the plant</p> <p>4) This is a multistage process that is currently being implemented.</p> <p>Stage 1: remove cyclones and replace old ducting in inside screening plant. Upgrade collection point covers and collection piping.</p> <p>Stage 2: Install new dryer baghouse. The new dryer baghouse will provide an additional 20 HP (6000 ACFM) of dust collection capacity.</p> <p>Stage 3: Modify ducting from old dryer baghouse to provide sufficient dust collection capacity to outside Stedman crushing pad.</p> <p>Stage 4: Repair and reinstall the round baghouse above the bagging area. better dedust the to Modify ducting in inside the crushing plant to use the old dryer baghouse</p> <p>Stage 5: Optimize double baghouse and old dryer baghouse to dedust the inside and outside crushing circuits.</p> <p>Stage 6: Repair leaks into Cassiar Baghouse. Remove outside bagging area fan that blows into the Cassiar Baghouse from the sling bin loader.</p> <p>5) A portable eyewash station has been purchased and is being installed in the bagging area. In addition there has always been an eyewash station in the washout room located a short distance from the bagging area.</p> <p>6) A waterline will be plumbed into the outside washroom facilities near the picking shack that will make the facilities operational all year.</p>

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

adequate for male and female employees.

Mine Dry

7) There are insufficient shower facilities at the mine site. Workers are changing and storing their dirty coveralls in the lunch room. This is not a good practice. The Manager shall review the requirements of 2.11.5 of the Code and develop a plan to construct appropriate shower facilities for both male and female employees. It is my understanding that there is an abandoned trailer that could be converted to a mine dry as a short term measure.

Medical Surveillance Program

8) In light of the recent silicosis claim at the mine site, it is recommended that all employees be offered the opportunity to have a chest x ray and/or lung function test in consultation with their family physician. Pursuant to section 2.12.7 and 2.12.5 (1) of the Code, the cost of any tests will be borne by the company and the results shall not be revealed to the company without the written informed consent of the employee.

Audiometric Testing

9) The opportunity to undergo an annual hearing test shall be provided to all employees on the site. There are several audiometric testing firms that can provide an onsite opportunity to have this done.

First Aid Supplies and Services

10) In accordance with Section 3.6.1 of the Code the Manager shall review the requirements for first aiders and ensure that there is adequate coverage on all shifts.

Thank you for your co-operation. The Ministry can provide assistance in designing your occupational monitoring program.

Mine Dry

7) This issue was discussed with all female employees on site as well as the OHSC co-chairs. All female employees unanimously agreed that they are not interested in shower facilities at this time. It was agreed among the OHSC co-chairs that converting the trailer to a mine dry is not currently a high priority.

While not the most luxurious of facilities, there are currently shower facilities located in the main office as well as the first aid room. Future plans for an office/warehouse will include shower and dry facilities for both sexes.

Medical Surveillance Program

8) An offer to provide a chest x-ray and/or lung function test has been made to all employees at the Sirdar and Crawford Bay sites.

Annual Audiometric Testing

9) Annual Audiometric Testing is being done on a yearly basis by Okanagan Audio Lab Ltd. Vernon BC. Hearing test results can be made available to the Ministry if requested.

First Aid Supplies and Services

10) Based on the WCB Regulations referred to by Section 3.6.1 of the Mining Code, our site is classified as a "High" hazard Class with a total numbers of "workers" per shift of between 2-15 with less than 20 minutes travel time to hospital.

For this classification we are required to have Level 1 First Aid Kits and level 1 First Aid Training.

In the spring of 2005 a total of 3 new Level 1 First Aid Stations were purchased from Zee Medical out of Cranbrook. Zee Medical continues to professionally service these kits on a monthly basis.

First Aid Training is offered to all employees at the company's expense. Additional Training and educational development assistance is also provided to all employees as per the collective agreement. Employees holding an industrial first aid certificate (to a maximum of one per shift) receive an additional \$0.75 per hour in addition to their regular hourly rate.

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN



Monday, April 03, 2006

File: 18040-02-04
Mine No.: 0500284

March 31, 2006
Mr. Peter Rodenstein
Manager
Imasco Sidar Operation
Box 56
Sirdar, BC V0B 2C0

By Fax: (250) 866-5455

Re: Mine Inspection March 7, 2006
Property: IMASCO - SIRDAR

Enclosed are three copies of my Inspection Report for the above noted property and date.

Please have this report posted in a conspicuous place on the property accessible to the workers in accordance with Section 30(1) of the Mines Act. Please forward a copy to the C0-Chair of your OHSC and to the local union representative.

As noted on page one of the report, please fill in the appropriate areas responding to the Inspector's comments, sign and date the first page, initial the subsequent page(s) and return a copy with your comments to the writer.

A silicosis claim is of concern to the Ministry and I am sure to you and your employees. The Ministry will continue to follow up this investigation and can be of assistance in conducting your occupational monitoring program.

I can be reached at (250) 952-0464 or at e-mail Al.Hoffman@gov.bc.ca if you have further questions.

Yours truly,

Al Hoffman, P.Eng.
Manager, Occupational Health

Enclosures 2
C: Phil Pascuzzi, Regional Office Cranbrook



Province of British Columbia
MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
Mining & Minerals Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 12823
File: 18040-02-04
Mine No: 0500284
Permit No:
Emp/Cont: 0 / 0
Orders H&S: RECL:
Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Picking Belt Shack, Plant

Persons Contacted

MANAGEMENT	P. Rodenstein
OHS COMMITTEE	J. Wall
WORKERS	s.22

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

An investigation of silica exposure to workers at the Imasco, Sirdar plant was conducted on 7-8 March 06. This was prompted by a silicosis claim (XL 05403467) filed s.22 in August 05 and accepted by the WCB later last year.

s.22

A walk through survey was conducted on 7 March 06. Roadways were wet from rain, temp approximately 10 C, with a light wind. Due to the wet conditions there was little apparent roadway dust.

There did not appear to be high levels of airborne dust in the picking shack. The muck is washed when it passes over a screen upstream of the jaw crusher.

MANAGERS RESPONSE OF ACTION TAKEN

Al Hoffman

Manager, Occupational Health

7th floor, 1675 Douglas Street Victoria BC V8W 9N3

Address

Date of Inspection: March 7, 2006

Copies To P. Pascuzzi

Signature - Inspector of Mines

Signature - Manager

Dated: _____, 20

Page 8
EGM-2013-00121

INSPECTION ORDER	MANAGERS RESPONSE OF ACTION TAKEN
<p>Ventilation is provided by drawing air through a fan on tail end side of the conveyor. This is not a good practice as the dust is not filtered before it enters the picking shack. Pursuant to Sections 1.9.1 (2) and 2.3.5 of the Code the ventilation system for the picking shack shall be reviewed and consideration shall be given to positively pressurizing the area so that only filtered air enters the shack.</p> <p>It is my understanding that granite or quartzite rock is crushed dry in winter when water dust suppression can not be used due to freezing of the belt idlers etc. Dry crushing of granite or quartzite shall cease immediately. Management and employees are reminded that it is the inhalation of the respirable silica size fraction (less than 10 micron aero diameter) which can result in silicosis. Dust in this size fraction can not be seen readily with the naked eye.</p> <p>On March 7th 2006 airborne and settled dust levels were high in the plant , but it is my understanding that significant progress has been made in improving dust collection and housekeeping.</p> <p>Sampling for airborne dust and collection of bulk samples was conducted on 8 March 06. The results are shown in Figures 1 and 2. A 30 knot northerly wind was blowing on the property; dust levels were considerably lower in the plant on 8 March as compared to the day previous. Roadways were still rain drenched ; the ambient temp was approximately 8 deg C. Anecdotal comments by employees indicate that airborne dust levels can vary widely depending on the prevailing wind and whether the roadways are dry or wet.</p> <p>Figure 1 shows that airborne dust levels were low on the day sampled. Note that this is a snapshot in time and levels on average could be much higher; this is supported by the amount of settled dust in the plant.</p> <p>Figure 2 shows the percentage of silica (SiO₂) in bulk samples that were located in and around the plant. As expected, samples which were composed of granite (65.49%)</p>	

Date of Inspection: **March 7, 2006**Initials:  (Inspector)Initials: _____ (Manager)
EGM-2013-00121

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

or quartzite(97.32%) were high in silica. It is important to note that dust that had settled around screening operations contained between 10% and 14% silica. If this dust is reentrained into the air during shoveling or sweeping activities it could pose a hazard. It is important to note that airborne respirable silica concentrations can not be extrapolated (predicted) from the bulk sample concentrations. Only further occupational monitoring can determine this.

It is also my understanding that granite and quartzite are run through the plant on a batch basis several times per year. It is predicted that silica exposures in the picking shack and the plant could be very high during this time period.

Occupational Monitoring Program

In accordance with Section 2.1.3 of the Code an occupational monitoring program shall be implemented at the mine site to determine exposures to respirable silica, limestone and dolomite.

The Ministry can assist you with setting up this program.

Ventilation and Clean Up in the Plant

In accordance with Section 2.3.5 of the Code, efforts shall be made to improved the dust collection system in the plant.

Eye Wash Stations

In accordance with Section 2.4.1 of the Code, a permanent or portable eye wash station shall be located in an area close to the bagging operation. The eyewash station shall be put on a monthly PM schedule to ensure that it is clean and operational.


Washroom Facilities

It is my understanding that the washroom facilities near the picking shack are not operational in the winter. In accordance with Sections 2.11.9 - 2.11.13 of the Code, the requirements for toilet facilities shall be reviewed to ensure that they are

Date of Inspection:

March 7, 2006

Initials:



(Inspector)

Initials: _____

(Manager)

EGM-2013-00121

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

adequate for male and female employees.

Mine Dry

There are insufficient shower facilities at the mine site. Workers are changing and storing their dirty coveralls in the lunch room. This is not a good practice. The Manager shall review the requirements of 2.11.5 of the Code and develop a plan to construct appropriate shower facilities for both male and female employees. It is my understanding that there is an abandoned trailer that could be converted to a mine dry as a short term measure.

Medical Surveillance Program

In light of the recent silicosis claim at the mine site, it is recommended that all employees be offered the opportunity to have a chest x ray and/or lung function test in consultation with their family physician. Pursuant to section 2.12.7 and 2.12.5 (1) of the Code, the cost of any tests will be borne by the company and the results shall not be revealed to the company without the written informed consent of the employee.

Audiometric Testing

The opportunity to undergo an annual hearing test shall be provided to all employees on the site. There are several audiometric testing firms that can provide an onsite opportunity to have this done.

First Aid Supplies and Services

In accordance with Section 3.6.1 of the Code the Manager shall review the requirements for first aiders and ensure that there is adequate coverage on all shifts.

Thank you for your co-operation. The Ministry can provide assistance in designing your occupational monitoring program.


INSPECTION ORDER

MANAGERS RESPONSE OF ACTION TAKEN

Date of Inspection:

March 7, 2006

Initials:

 (Inspector)

Initials:

(Manager)

EGM-2013-00121

FIGURE 1

Airborne Dust Results Imasco 8 March 06				
Filter Number	Area/Personal	Total Respirable Dust mg/m3	Total Respirable Silica mg/m3	Comments
15386	Inside screening room	0.08	0	
15393	picking belt shack	0.05	0	
15394	outside screening room	1.06	<0.01	
15403	Personal s.22	sample spoiled pump failure		
15412	s.22	0.46	<0.01	working in plant approximately 1 hr 45 min

TLV (permissible level) = 0.1 mg/m^3
silica respirable

FIGURE 2

VA06020705 - Finalized																
Ministry of Energy, Mines and Petroleum Resources																
# of SAMPLES : 14																
IMASCO MINE SAMPLES																
DATE RECEIVED : 2006-03-14 DATE FINALIZED : 2006-03-22																
PROJECT : "Imasco"																
CERTIFICATE COMMENTS : ""																
PO NUMBER : ""																
SAMPLE		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
Number		SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	LOI	Total
		%	%	%	%	%	%	%	%	%	%	%	%	%	%	%
IM#1	grey granite from mine	66.49	15.28	3.65	3.6	1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	1.88	98.46
IM#2	picking shack stairs	5.89	1.1	0.7	36.95	11.61	0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01	0.12	98.46
IM#3	quartzite sample	97.32	0.6	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01	0.08	99.01
IM#4	mud under picking belt	8.86	1.75	1.04	30.06	15.7	0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01	0.01	98.83
IM#5	oil soil conditioner under picking belt	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	0.01	98.82
IM#6	quartzite cow sand	67.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02	1.94	98.26
IM#7	granite cow sand	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1	0.86	98.16
IM#8	#2 Dillon screen	1.64	0.3	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01	0.01	98.5
IM#9	Stedman Pad entrance door	6.78	0.61	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01	0.01	98.38
IM#10	Niagra screen room	14.55	2.01	0.89	27.17	15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01	0.01	98.67
IM#11	Inside screening room-	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.01	0.02	98.28
IM#13	settled dust moat	10.44	1.83	0.85	30.56	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	0.01	98.5
IM#14	picking belt scrapings	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.06	<0.01	0.01	0.01	98.41
IM#15	outside screen room	1.56	0.22	0.6	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01	0.01	98.47

FIGURE 1

Airborne Dust Results Imasco 8 March 06				
Filter Number	Area/Personal	Total Respirable Dust mg/m3	Total Respirable Silica mg/m3	Comments
15386	Inside screening room	0.08	0	
15393	picking belt shack	0.05	0	
15394	outside screening room	1.06	<0.01	
15403	Personal s.22	sample spoiled pump failure		
15412	s.22	0.46	<0.01	working in plant approximately 1 hr 45 min

TLV (permissible level) = 0.1 mg/m^3
silica respirable

FIGURE 2

VA06020705 - Finalized															
		Ministry of Energy, Mines and Petroleum Resources													
# of SAMPLES : 14		IMASCO MINE SAMPLES													
DATE RECEIVED : 2006-03-14		DATE FINALIZED : 2006-03-22													
PROJECT : "Imasco"															
CERTIFICATE COMMENTS : ""															
PO NUMBER : ""															
SAMPLE Number		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	
		SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	
		%	%	%	%	%	%	%	%	%	%	%	%	%	%
IM#1	grey granite from mine	65.49	15.28	3.65	3.6	1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	
IM#2	picking shack stairs	5.89	1.1	0.7	36.95	11.61	0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01	
IM#3	quartzite sample	97.32	0.6	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01	
IM#4	mud under picking belt	8.86	1.75	1.04	30.06	15.7	0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01	
IM#5	00 soft conditioner under picking belt	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	
IM#6	quartzite cow sand	87.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02	
IM#7	granite cow sand	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1	
IM#8	#2 Dillon screen	1.64	0.3	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01	
IM#9	Stedman Pad entrance door	6.78	0.81	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01	
IM#10	Niagra screen room	14.55	2.01	0.89	27.17	15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01	
IM#11	Inside screening room	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.02	
IM#13	settled dust moat	10.44	1.83	0.85	30.56	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	
IM#14	picking belt scrapings	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01	0.01	
IM#15	outside screen room	1.56	0.22	0.6	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01	

Airborne Dust Results Imasco 8 March 06				
Filter Number	Area/Personal	Total Respirable Dust mg/m3	Total Respirable Silica mg/m3	Comments
15386	Inside screening room	0.08	0	
15393	picking belt shack	0.05	0	
15394	outside screening room	1.06	<0.01	
15403	Personal s.22	sample spoiled pump failure		
15412	s.22	0.46	<0.01	working in plant approximately 1 hr 45 min

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P
1	VA06020705 - Finalized															
2	CLIENT : " Mines And Petroleum Resou"															
3	# of SAMPLES : 14															
4	DATE RECEIVED : 2006-03-14 DATE FINALIZED : 2006-03-22															
5	PROJECT : "Imasco"															
6	CERTIFICATE COMMENTS : ""															
7	PO NUMBER : " "															
8		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
9	SAMPLE	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	LOI	Total
10	DESCRIPT	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%
11	IM#1	65.49	15.28	3.65	3.6	1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	1.88	98.46
12	IM#2	5.89	1.1	0.7	36.95	11.61	0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01	41.6	98.43
13	IM#3	97.32	0.6	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01	0.08	99.01
14	IM#4	8.86	1.75	1.04	30.06	15.7	0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01	40.6	98.83
15	IM#5	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	44	98.92
16	IM#6	87.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02	1.94	98.26
17	IM#7	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1	0.86	98.16
18	IM#8	1.64	0.3	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01	44.8	98.5
19	IM#9	6.78	0.81	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01	42.2	98.38
20	IM#10	14.55	2.01	0.89	27.17	15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01	37.2	98.67
21	IM#11	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.02	37	98.28
22	IM#13	10.44	1.83	0.85	30.56	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	39.2	98.5
23	IM#14	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01	0.01	45.1	98.41
24	IM#15	1.56	0.22	0.6	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01	45.5	98.47

VA06020705 - Finalized		Ministry of Energy, Mines and Petroleum Resources																
# of SAMPLES : 14		IMASCO MINE SAMPLES																
DATE RECEIVED : 2006-03-14		DATE FINALIZED : 2006-03-22																
PROJECT : "Imasco"																		
CERTIFICATE COMMENTS : ""																		
PO NUMBER : " "																		
SAMPLE		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
Number		SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	LOI	Total		
		%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%	%
IM#1	grey granite from mine	65.49	15.28	3.65	3.8	1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	1.88	98.4		
IM#2	picking shack stairs	5.89	1.1	0.7	36.95	11.61	0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01	41.6	98.4		
IM#3	quartzite sample	97.32	0.6	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01	0.08	99.0		
IM#4	mud under picking belt	8.86	1.75	1.04	30.06	15.7	0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01	40.6	98.8		
IM#5	00 soil conditioner under picking belt	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	44	98.9		
IM#6	quartzite cow sand	87.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02	1.94	98.2		
IM#7	granite cow sand	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1	0.88	98.1		
IM#8	#2 Dillon screen	1.64	0.3	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01	44.8	98		
IM#9	Stedman Pad entrance door	6.78	0.81	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01	42.2	98.3		
IM#10	Niagra screen room	14.55	2.01	0.89	27.17	15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01	37.2	98.6		
IM#11	Inside screening room	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.02	37	98.2		
IM#13	settled dust moat	10.44	1.83	0.85	30.56	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	39.2	98		
IM#14	picking belt scrapings	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01	0.01	45.1	98.4		
IM#15	outside screen room	1.56	0.22	0.6	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01	45.5	98.4		

VA06020705 - Finalized																
Ministry of Energy, Mines and Petroleum Resources																
IMASCO MINE SAMPLES																
# of SAMPLES : 14																
DATE RECEIVED : 2006-03-14 DATE FINALIZED : 2006-03-22																
PROJECT : "Imasco"																
CERTIFICATE COMMENTS : ""																
PO NUMBER : " "																
SAMPLE		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
Number		SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	LOI	Total
		%	%	%	%	%	%	%	%	%	%	%	%	%	%	%
IM#1	grey granite from mine	65.49	15.28	3.65	3.6	1.21		2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	1.88
IM#2	picking shack stairs	5.89	1.1	0.7	36.95	11.61		0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01	98.46
IM#3	quartzite sample	97.32	0.6	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01		0.01	<0.01	<0.01	41.6
IM#4	mud under picking belt	8.86	1.75	1.04	30.06	15.7		0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01	98.43
IM#5	00 soil cond/Water under picking belt	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	0.01	99.01
IM#6	quartzite cow sand	87.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01		0.02	40.6
IM#7	granite cow sand	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1	0.86	98.83
IM#8	#2 Dillon screen	1.64	0.3	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01		44.8
IM#9	Stedman Pad entrance door	6.78	0.81	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01	0.01	98.5
IM#10	Niagra screen room	14.55	2.01	0.89	27.17	15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01	0.01	42.2
IM#11	Inside screening room	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.01	0.02	37.2
IM#13	settled dust moat	10.44	1.83	0.85	30.58	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	0.01	37
IM#14	picking belt scrapings	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01		0.01	39.2
IM#15	outside screen room	1.56	0.22	0.6	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01		45.1
																98.47



March 10, 2006

File: *Imasco Sidar Inspection Report 8 March 06*

ALS CHEMEX
212 Brooksbank Avenue,
North Vancouver, B.C., V7J 2C1

Dear Safiann Maiter:

Find enclosed 14 samples that were collected at a limestone/dolomite plant. They also process granite and quartzite through the mill occasionally (samples 1 and 2).

I'm particularly interested in the mass percentage of crystalline silica dioxide in the samples. I have taken respirable airborne samples as well which will be analyzed at another lab using XRD.

We will pay for these samples using VISA. Please note that the BC provincial government is GST exempt. Please contact me or Pat Cheetham at 952-0492 to make payment arrangements.

Sincerely,

Al Hoffman, P.Eng.
Manager, Occupational Health

ALSchemex

MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
MINING & MINERALS DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

Sample Submittal Form

Internal Use Only

Date Received: _____

Client Code: _____

Workorder No: _____

Company Name: _____

Submitted By: AL HOFFMAN Telephone No.: (250) 952-0464

Project: IMASCO Date: 10 MARCH '06

Order No.: _____ Quote No.: _____

Courier: _____ Waybill No.: _____

Sample Type: Rock ☐ Sediment ☐ Soil ☐ Percussion ☐ Ore ☐ Other _____ (Rush 1.5x List Price)

Sample No.	Start No.	Finish No.	Quantity	Elements or Method Codes	Rush (Y)	Range (X)	Trace	Ore
#10				NIAGARA SCREEN ROOM				
11				INSIDE SCREEN LOWER LEVEL				
12				DUST MOAT AREA				
13				BELT SCRAPINGS COARSE ORE				
14				OUTSIDE SCREEN ROOM				
15								
Total:			14					

Special Instructions: _____

Pulp and Reject Instructions

Pulps

- ☐ Return after analysis
- ☐ Return after 90 days
- ☐ Discard after 90 days
- ☐ Paid storage after 90 days

Rejects

- ☐ Return after analysis
- ☐ Return after 45 days
- ☐ Discard after 45 days
- ☐ Paid storage after 45 days

Failure to indicate pulp & reject instructions will result in disposal without notice.

Return Address: _____

Attention: _____

Refer to Pulp and Reject Policy in Service Schedule

Results to: AL HOFFMAN

Address: _____

Email: _____

Fax: _____

MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
MINING & MINERALS DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

☒ Certificate

☐ Webtrieve

☒ Email

☐ Fax

Copy to: _____

Address: _____

Email: _____

Fax: _____

Al.Hoffman@gov.bc.ca
(250) 952-0491

☐ Certificate

☐ Webtrieve

☐ Email

☐ Fax

Invoice to: _____

Address: _____

MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
MINING & MINERALS DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

☐ Certificate required

Authorized by:

Name: _____

(Please Print)

Signature: _____

Al Hoffman, M.Sc., M.Sc.(A) Eng.
MANAGER
OCCUPATIONAL HEALTH

Mailing Address:
PO Box 9320 Stn Prov Govt
Victoria BC V8W 9N3
Telephone: 250 952-0464
Facsimile: 250 952-0491
e-mail: al.hoffman@gems7.gov.bc.ca
Location:
Seventh Floor, 1675 Douglas Street, Victoria

ALCHEMEX

RESOURCES
DIVISION
PROV GOVT
9N3

Phone No.: (250) 952-0464
10 MARCH '06

Sample Submittal Form

Internal Use Only

Date Received: _____

Client Code: _____

Workorder No: _____

Order No: _____ Quote No.: _____
Courier: _____ Waybill No.: _____

Sample Type: Rock ☒ Sediment ☐ Soil ☐ Percussion ☐ Ore ☐ Other Rock & DUST (Rush 1.5x List Price)

Sample No.	Sample Description	Quantity	Elements or Method Codes	Range (x)		
				Trace	Grain	
1	GRANITE					
2	PICKINGSHACK MOD					
3	QUARTZITE					
4	PICKING BELT WASTE					
5	SOIL CONDITIONER					
6	BROWN CON SAND BUNKER					
7	GRANITE CON SAND					
8	#2 DILLON SCREEN BELT					
9	STEDMAN PAD ENTRANCE DOOR					
Total:						

Special Instructions:

Pulp and Reject Instructions

Pulps

- ☐ Return after analysis
☐ Return after 90 days
☐ Discard after 90 days
☐ Paid storage after 90 days

Rejects

- ☐ Return after analysis
☐ Return after 45 days
☐ Discard after 45 days
☐ Paid storage after 45 days

Failure to indicate pulp & reject instructions will result in disposal without notice.

Return Address: _____

Attention: _____

Refer to Pulp and Reject Policy in Service Schedule

Authorized by:

Name: _____

(Please Print)

Signature: _____

AL HOFFMAN
MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
MINING & MINERALS DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

- ☒ Certificate
☐ Webtrieve
☒ Email
☐ Fax

- ☐ Certificate
☐ Webtrieve
☐ Email
☐ Fax

AL Hoffman@gov.bc.ca
(250) 952-0491
MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
MINING & MINERALS DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

- ☐ Certificate required



Natural Resources Canada
Ressources naturelles Canada

CANMET

MINING AND MINERAL SCIENCES LABORATORIES / LABORATOIRES DES MINES ET DES SCIENCES MINÉRALES

X-RAY DIFFRACTION / DIFFRACTION DES RAYONS X

Sudbury Laboratory / Laboratoire de Sudbury

1079 Chemin Kelly Lake Road

Sudbury, Ontario, P3E 5P5

Facsimile Cover Sheet

TO: Al Hoffman
Ministry of Energy
and Mines
Mining Division
P.O. Box 9320 Stn.
Victoria, BC V8W 9N3

Phone: (250) 952-0464
Fax Phone: (250) 952-0491

Date: March 14, 2006

FROM: Kevin Butler
CANMET

Phone: (705) 677-7811
Fax Phone: (705) 670-6556

Number of pages including cover sheet: 2

REMARKS: ☐ Urgent ☒ For your review ☐ Reply ASAP ☐ Please Comment


TRD/XRD 06-021

The attached does not constitute the official report(s), which will be sent by mail, along with the limits of detection and the Terms & Conditions.


Please note that Analytical Limits of Detection and Uncertainties have been calculated for TRD and XRD. This information is available on Page 2 of the original test report which is being sent by mail.

The work has been carried out under the supervision of the project leader, Gary Bonnell (705) 670-6766 (gbonnell@NRCan.gc.ca) to whom inquiries can be made.

 Natural Resources Canada
Ressources Naturelles Canada



X-RAY DIFFRACTION
Sudbury Laboratory
DIFFRACTION DES RAYONS X
Laboratoire de Sudbury



Analysed by:

Checked by:

Date: March 14, 2006

[illegible]

Note: < 0.01 indicates the presence of quartz below the detectable limit of 0.01 mg

Project Leader:

Date: March 14, 2006



NOTIFICATION OF RECEIPT OF SAMPLES VA06020705

Print date : Mar 15, 2006

Client Code : SIS

Page 1 of 1

To:

Al Hoffman
B.C. Ministry of Energy, Mines and Petroleum
Resou
PO Box 9320
Stn Prov Govt
Victoria BC
Canada V8W 9N3

WO Billing address:

Al Hoffman
B.C. Ministry of Energy, Mines and
Petroleum Resou
PO Box 9320
Stn Prov Govt
Victoria BC
Canada V8W 9N3

WORKORDER DISTRIBUTION

<u>REPORT DESCRIPTION</u>	<u>DESTINATION PERSON</u>	<u>DELIVERY</u>
ALS Chemex Standard CSV format	Al Hoffman	Email
Work Order	Al Hoffman	Email
Certificate of analysis	Al Hoffman	Print
Invoice	Al Hoffman	Print

Samples submitted by:

Project: Imasco

P. O. #:

Sample Type: Rock

Date Received: March 13, 2006

Total Samples Received: 14

Pulp Disposition: Paid Storage after 90 Days

Reject Disposition: Monthly Storage

First Sample Description: IM#1

Carrier and Waybill: PUROLATOR 26144841132

ANALYTICAL WORK REQUESTED:

PREP

- | | | |
|----|--------|------------------------------|
| 3 | CRU-31 | Fine crushing - 70% <2mm |
| 14 | LOG-24 | Pulp Login - Rcd w/o Barcode |
| 11 | PUL-41 | Pulverize in Zirconia Ring |
| 14 | WEI-21 | Received Sample Weight |
- Analytes Requested: Recvd Wt.

ANALYTICAL

- | | | |
|----|----------|--------------------------|
| 14 | ME-XRF06 | Whole Rock Package - XRF |
|----|----------|--------------------------|
- Analytes Requested:
Al₂O₃, BaO, CaO, Cr₂O₃, Fe₂O₃, K₂O, LOI, MgO, MnO, Na₂O, P₂O₅, SiO₂, SrO, TiO₂, Total
- | | | |
|----|----------|------------------|
| 14 | OA-GRA06 | LOI for ME-XRF06 |
|----|----------|------------------|

MISCELLANEOUS ITEMS:

- | | | |
|---|--------|--------------------|
| 1 | BAT-01 | Administration Fee |
|---|--------|--------------------|



ALS Chemex

EXCELLENCE IN ANALYTICAL CHEMISTRY

ALS Canada Ltd.

212 Brooksbank Avenue
North Vancouver BC V7J 2C1

Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: B.C. MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOU
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

Page 1 of

INVOICE NUMBER 1372849

BILLING INFORMATION

Certificate: **VA06020705**
Sample Type: **Rock**
Account: **SIS**
Date: **22-MAR-2006**
Project: **Imasco**
P.O. No.:
Quote:
Terms: **Due on Receipt** C1
Comments:

ANALYSED FOR

QUANTITY	CODE	DESCRIPTION	UNIT PRICE	TOTAL
1	BAT-01	Administration Fee	30.00	30.00
14	LOG-24	Pulp Login - Rcd w/o Barcode	0.75	10.50
14	ME-XRF06	Whole Rock Package - XRF	32.00	448.00
11	PUL-31	Pulverize split to 85% <75 um	3.15	34.65
0.26	CRU-31	Weight Charge (kg) - Fine crushing - 70% <2mm	0.25	0.07
3	CRU-31	Fine crushing - 70% <2mm	2.25	6.75

To: B.C. MINISTRY OF ENERGY, MINES AND PETROLEUM
RESOU
ATTN: AL HOFFMAN
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

Please Remit Payments To :

ALS Chemex

212 Brooksbank Avenue
North Vancouver BC V7J 2C1

Payment may be made by: Cheque or Bank Transfer

Beneficiary Name:

ALS Canada Ltd.

Bank:

SWIFT:

Address:

Account:

s.21

SUBTOTAL (CAD) \$ 529.9

TOTAL PAYABLE (CAD) \$ 529.9



ALS Chemex

EXCELLENCE IN ANALYTICAL CHEMISTRY

ALS Canada Ltd.

212 Brooksbank Avenue

North Vancouver BC V7J 2C1

Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: B.C. MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOU
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

Page: 1
Finalized Date: 22-MAR-2006
Account: SIS

CERTIFICATE VA06020705

Project: Imasco

P.O. No.:

This report is for 14 Rock samples submitted to our lab in Vancouver, BC, Canada on
13-MAR-2006.

The following have access to data associated with this certificate:

AL HOFFMAN

SAMPLE PREPARATION

ALS CODE	DESCRIPTION
WEI-21	Received Sample Weight
LOG-24	Pulp Login - Rcd w/o Barcode
CRU-31	Fine crushing - 70% <2mm
PUL-31	Pulverize split to 85% <75 um

ANALYTICAL PROCEDURES

ALS CODE	DESCRIPTION	INSTRUMENT
ME-XRF06	Whole Rock Package - XRF	XRF
OA-GRA06	LOI for ME-XRF06	WST-SIM

To: B.C. MINISTRY OF ENERGY, MINES AND PETROLEUM
RESOU
ATTN: AL HOFFMAN
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

This is the Final Report and supersedes any preliminary report with this certificate number. Results apply to samples as submitted. All
pages of this report have been checked and approved for release.

Signature:



ALS Chemex

EXCELLENCE IN ANALYTICAL CHEMISTRY

ALS Canada Ltd.

212 Brooksbank Avenue

North Vancouver BC V7J 2C1

Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: B.C. MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOU
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

Project: Imasco

Page: 2 - A

Total # Pages: 2 (A - B)

Finalized Date: 22-MAR-2006

Account: SIS

CERTIFICATE OF ANALYSIS VA06020705

Sample Description	Method Analyte Units LOR	WEI-21	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
		Recvd Wt.	SiO2	Al2O3	Fe2O3	CaO	MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO	LOI
		kg	%	%	%	%	%	%	%	%	%	%	%	%	%	%
		0.02	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01	0.01
IM#1		0.04	65.49	15.28	3.65	3.60	1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12	1.88
IM#2		0.12	5.89	1.10	0.70	36.95	11.61	0.11	0.27	<0.01	0.05	0.04	0.10	0.01	0.01	41.60
IM#3		0.10	97.32	0.60	0.66	0.04	0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01	0.08
IM#4		0.12	8.86	1.75	1.04	30.06	15.70	0.20	0.41	<0.01	0.06	0.03	0.10	0.01	0.01	40.60
IM#5		0.06	2.57	0.73	0.68	34.53	16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01	44.00
IM#6		0.10	87.79	3.93	1.61	0.94	0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02	1.94
IM#7		0.04	67.79	14.19	3.52	3.42	1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.10	0.86
IM#8		0.06	1.64	0.30	0.55	34.68	16.32	<0.01	0.08	<0.01	0.02	0.03	0.10	0.01	<0.01	44.80
IM#9		0.04	6.78	0.81	0.62	30.61	16.89	0.07	0.22	<0.01	0.05	0.02	0.10	0.01	0.01	42.20
IM#10		0.06	14.55	2.01	0.89	27.17	15.83	0.30	0.47	0.01	0.06	0.03	0.14	0.01	0.01	37.20
IM#11		0.06	14.34	2.79	1.03	26.93	14.84	0.41	0.69	<0.01	0.09	0.03	0.10	0.01	0.02	37.00
IM#13		0.12	10.44	1.83	0.85	30.56	14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01	39.20
IM#14		0.04	2.14	0.09	0.63	30.08	20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01	0.01	45.10
IM#15		0.02	1.56	0.22	0.60	30.91	19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01	45.50



ALS Chemex

EXCELLENCE IN ANALYTICAL CHEMISTRY

ALS Canada Ltd.

212 Brooksbank Avenue
North Vancouver BC V7J 2C1

Phone: 604 984 0221 Fax: 604 984 0218 www.alschemex.com

To: B.C. MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOU
PO BOX 9320
STN PROV GOVT
VICTORIA BC V8W 9N3

Project: Imasco

Page: 2 - B

Total # Pages: 2 (A - B)

Finalized Date: 22-MAR-2006

Account: SIS

CERTIFICATE OF ANALYSIS VA06020705

Sample Description	Method	Total %
	Analyte Units LOR	
	ME-XRF06	
		0.01
IM#1		98.46
IM#2		98.43
IM#3		99.01
IM#4		98.83
IM#5		98.92
IM#6		98.26
IM#7		98.16
IM#8		98.50
IM#9		98.38
IM#10		98.67
IM#11		98.28
IM#13		98.50
IM#14		98.41
IM#15		98.47



Whole Rock Geochemistry – ME-XRF06

Sample Decomposition: Lithium Tetraborate Fusion* (WEI-GRA06)
Analytical Method: X-Ray Fluorescence Spectroscopy (XRF)

A prepared sample (1.000 g) is added to lithium tetraborate flux (9.000 g), mixed well and fused in a furnace at 1100°C. A flat glass disc is prepared from the resulting melt. This disc is then analyzed by X-ray fluorescence spectrometry. Oxide concentration is calculated from the determined elemental concentration and the result is reported in that format.


To determine loss on ignition (L.O.I.), a porcelain crucible is dried in an oven at 105°C, cooled and the weight recorded. A prepared sample (3.00 g) is added to the crucible and then ashed at 1000°C for one hour. The sample is then cooled in a desiccator, weighed and the percent loss on ignition is calculated.

Element	Symbol	Units	Lower Limit	Upper Limit
Aluminum Oxide	Al ₂ O ₃	%	0.01	100
Barium Oxide	BaO	%	0.01	100
Calcium Oxide	CaO	%	0.01	100
Chromium Oxide	Cr ₂ O ₃	%	0.01	100
Ferric Oxide	Fe ₂ O ₃	%	0.01	100
Potassium Oxide	K ₂ O	%	0.01	100
Magnesium Oxide	MgO	%	0.01	100
Manganese Oxide	MnO	%	0.01	100
Sodium Oxide	Na ₂ O	%	0.01	100
Phosphorus Oxide	P ₂ O ₅	%	0.01	100




Element	Symbol	Units	Lower Limit	Upper Limit
Silicon Oxide	SiO ₂	%	0.01	100
Strontium Oxide	SrO	%	0.01	100
Titanium Oxide	TiO ₂	%	0.01	100
Loss On Ignition	LOI	%	0.01	100
	Total	%	0.01	101

*Note: For samples that are high in sulphides, we may substitute a peroxide fusion in order to obtain better results.



X-RAY DIFFRACTION
Sudbury Laboratory
DIFFRACTION DES RAYONS X
Laboratoire de Sudbury



Date Samples Received: **March 13, 2006**
Date Samples Analysed: **March 13, 2006**
Date of Primary Calib. : **September 25, 2004**
Date of Secondary Calib.: **January 26, 2006**

Analysed by:

Checked by: _____

Date: March 14, 2006

[illegible]

Note: < 0.01 indicates the presence of quartz below the detectable limit of 0.01 mg

Project Leader:

Date:

TERMS AND CONDITIONS FOR SMALL SERVICE JOBS

These terms and conditions hereunder written apply to the work done and the deliverables obtained from the small service job _____, Project 601254.

1. **CANMET** has performed the work in a diligent, thorough and workmanlike manner in accordance with good scientific and technical practices. However, **CANMET** makes no representation or warranty respecting the results arising therefrom, either expressly or implied by law or otherwise, including but not limited to implied warranties or conditions of merchantability or fitness for a particular purpose.
2. **CANMET** shall keep confidential and not disclose to third parties the information contained in or regarding the Deliverables for a period of three (3) years from the coming into force of this Agreement, except with the written consent of the **CLIENT** or where the information: (a) is now or hereafter, through no act or failure to act on the part of **CANMET**, becomes generally known or available to the public without breaching this Agreement; (b) is subsequently disclosed to **CANMET** by a third party, and does not include a confidential obligation; (c) is developed by **CANMET** independently of this Agreement; or (d) is required to be disclosed by law.
3. **CANMET** reserves the right to use the information contained in the Deliverables for policy formulation, in-house research purposes, and to publish summary and non-confidential announcements with respect to the work. Such announcements shall not be published without written consent of the **CLIENT**, which consent shall not be unreasonably withheld.
4. The **CLIENT** shall pay all approved charges for the work completed within thirty (30) days of the date of issue of the invoice. All cheques and money orders shall be made payable to the **Receiver General for Canada** and sent to Natural Resources Canada as per instructions on each invoice. **CANMET** reserves the right to charge interest on overdue accounts at a rate of three percent (3%) above the prime rate set by the Bank of Canada.
5. The **CLIENT** shall indemnify and save harmless Natural Resources Canada and its employees and agents from and against all claims, demands, losses, costs including lawyers fees, damages, actions, suits or proceedings, that are in any manner based upon, arising out of, or attributable to the use of the Deliverables or any part thereof. **CANMET** shall have the right to defend any such action or proceeding with counsel of its own choosing.
6. The **CLIENT** represents that it has not disclosed or provided to **CANMET** any unauthorised proprietary information, samples or documentation pertaining to the work.
7. It shall be the obligation of the **CLIENT**, at its own expense, to transport required samples, to and from **CANMET**.
8. The **CLIENT** shall not use the name of Natural Resources Canada, **CANMET**, or the names of **CANMET** employees, with respect to the work performed or anything arising therefrom, without prior written consent.
9. Neither party to this Agreement shall be liable to the other for any failure or delay in performance caused by circumstances beyond its control, including but not limited to acts of God, fire, labour difficulties, recognized year 2000 problems or governmental action.
10. This Contract shall be governed and construed in accordance with the Laws of the Province of Ontario and the Laws of Canada as applicable and shall be treated in all respects as an Ontario contract.
11. No member of the House of Commons of Canada shall be admitted to any share or part of this Contract or to any benefit to arise from it.
12. The **CLIENT** and **CANMET** shall attempt to resolve any dispute arising out of or pursuant to this Contract by recourse to the process described in Natural Resources Canada's *Preferred Method of Dispute Resolution - Revenue-Generating Agreements* in order to reduce delays and litigation expenses for both Parties.



Province of British Columbia
Ministry of Energy and Mines
Energy and Minerals Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

File: 18070-02-04

OCCUPATIONAL HEALTH INSPECTION

NAME OF MINE: Imasco Plant LOCALITY: Sirdar, BC
OWNER OR OPERATOR: Imasco Minerals Ltd. ADDRESS: Box 55, Sirdar BC V0B 2C0
MANAGER: Mr. Arnold Rennich AREAS INSPECTED: See below

Persons Contacted

MANAGEMENT: Arnold Rennich
OHS COMMITTEE: See below
WORKERS: See below

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union. The mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further, the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION REPORT

MANAGER'S RESPONSE OF ACTION TAKEN

Currently there is no specified limit for respirable insoluble dust (not elsewhere classified). However, this is under review.

Forklift Operator on "Hyster" Forklift, and also working in bagging area. Monitor worn by s.22
Average exposure to respirable particulate.....3.05 mg/m³
Silica content of particulate.....<0.01 mg/m^{3**}

Not required

Forklift Operator on "Hyster" Forklift, in yard and bagging areas. Monitor worn by s.22
Average exposure to respirable particulate.....1.35 mg/m³
Silica content of particulate.....<0.01 mg/m^{3**}

Bagging Machine Operator, bagging dolomite. Monitor worn by s.22
Average exposure to respirable particulate.....2.80 mg/m³
Silica content of particulate.....<0.01 mg/m^{3**}

Copies To: R. Berdusco, A. Hoffman, OHSC Co-Chairs

Art Parker
Inspector of Mines

Signature - Inspector

4th Floor, 1810 Blanshard Street, Victoria, B.C. V8W 9N3
Address

Signature - Manager

Date of Inspection: July 12, 1999

Dated: _____ Page 35, 19
EGM-2013-00121

INSPECTION REPORT	MANAGER'S RESPONSE OF ACTION TAKEN
<p><u>Area Sample</u> taken mid bagging area inside plant. Average respirable particulate measured..... 1.27 mg/m³ Silica content of particulate..... <0.01 mg/m³**</p> <p>**0.01 mg/m³ indicates the presence of quartz below the detection limit of 0.01 mg.</p> <p><u>Plant Operator</u>, working throughout plant, wearing class A hearing protection. Monitor worn by s.22 Average noise exposure:..... monitor failure</p> <p>T *****</p> <p><u>Short-term Respirable Particulate Measurements</u></p> <p>The following readings were taken using a DustTrac real time respirable particulate monitor. This monitor has not been approved as a NIOSH monitoring method, and was used here to indicate possible particulate sources.</p> <p><u>Warehouse Storage Area</u> Average reading: 1.95 mg/m³ Minimum: 1.54 mg/m³ Maximum: 2.38 mg/m³</p> <p><u>Loading Calcium Carbonate Bags on Pallet</u> at open door in plant. Average reading: 3.82 mg/m³ Minimum: 1.42 mg/m³ Maximum: 6.48 mg/m³</p> <p><u>Bagging Machine Operator's Position</u>, bagging calcium carbonate. Average reading: 2.55 mg/m³ Minimum: 0.811 mg/m³ Maximum: 6.58 mg/m³</p> <p><u>Warehouse (storage) Building Across from Plant</u> including carpenter's area. No one in area at time of measurement. Average reading: 0.082 mg/m³ Minimum: 0.036 mg/m³ Maximum: 0.299 mg/m³</p>	

Date of Inspection: July 12, 1999

Initials:


Inspector

Page 36
Manager
EGM-2013-00121



Province of British Columbia
MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES

Mining & Minerals Division

Report of Inspector of Mines

(Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 13422
File: 18040-02-04
Mine No: 0500284
Permit No:
Emp/Cont: 0 / 0
Orders H&S: RECL:
Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	David Sacks	AREAS INSPECTED	Mine Plant, Maintenance Shop, Welding Shop, Lunch Rooms

Persons Contacted

MANAGEMENT	P. Rodenstein
OHS COMMITTEE	Jason Wall
WORKERS	s.22

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

The inspector was accompanied by Caroline Nakatsuka
Inspector of Mines, Occupational Health.

Fire Extinguishers

Fire extinguishers had been checked in August, but the tags were not punched in May, June and July 06. Fire fighting equipment shall be checked on a monthly basis.

Emergency Eye Wash Stations

An eyewash station had been installed on the outside wall of the new change room; however, it was covered with dust and the fluid container was empty. In accordance with Section 2.4.1 (2)(3) eyewash stations shall be installed and maintained. I recommend that they be put on a monthly PM check and that the fluid be topped up after they are used.

Lumber Storage

Lumber and a piece of sheet metal was stored in the rafters

MANAGERS RESPONSE OF ACTION TAKEN

Al Hoffman

Manager, Occupational Health

7th floor, 1675 Douglas Street Victoria BC V8W 9N3

Address

Date of Inspection: August 31, 2006

Copies To Phil Pascuzzi, Garry MacDonald

Signature - Inspector of Mines

Signature - Manager

Dated: _____, 20

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>immediately above the foot of the stairs near the lab. These materials shall be moved as they pose a hazard to workers passing underneath.</p> <p>Lock-Out During Screen Repair</p> <p>A screen repair was underway at the time of inspection. Workers were unable to tell the inspectors where the screens were locked out; it was later determined that the screens were not locked out. There appears to be some confusion if this area can be electrically isolated. A locked out switch could not be found in either MCC room. A lock out procedure shall be developed immediately in accordance with Section 4.11.1 of the Code. The lack of a proper lock out procedure could result in a serious injury or a fatality. A procedure shall be developed immediately.</p> <p>Confined Space Entry</p> <p>At the time of the inspection, two employees were cleaning a bin. They had accessed a storage bin through a hatch in the outside screen room. Both employees were in the bin. One was wearing a safety lanyard, the other was not wearing a fall arrest system. It did not appear that the bin was checked for oxygen deficiency or for the presence of harmful gases. The employees were not aware of a written confined space entry procedure. A spotter was not posted at the bin entranceway. There was no tripod or other rescue equipment nearby to perform an extrication if necessary. The bin was not ventilated. Clearly, the lack of a formal written confined space entry procedure poses a hazardous situation. The procedure to clean bins between products shall be reviewed.</p> <p>In accordance with the Code Section 4.4.1 to 3.4.6 a confined space entry procedure for this and any other confined space work activities shall be developed immediately.</p> <p>Scrubber Discharge Area</p> <p>Dust from the scrubber discharge area was falling from a</p>	

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>distance of 8' to the ground near the outside moat on the north side of the plant building. The sidepack, a direct reading instrument, indicated dust levels exceeding 8 mg/m3 (TLV for respirable particles not otherwise classified is 3 mg/m3).</p> <p>Truck Loading Area</p> <p>A large amount of dust was generated while a truck was being loaded.</p> <p>Palet Storage</p> <p>A stack of #0 and # 30 products palets were stored four-high outside the palet storage room. This stack was clearly leaning and posed a hazard. The procedure to store palets shall be reviewed to ensure that they are stable and don't pose a hazard to workers passing by or to the fork lift operator.</p> <p>Palet Shop</p> <p>A dust collector shall be installed on the table saw in this area. The amount of sawdust in this area is clearly an inhalation and fire hazard. The fan installed through the wall does not have sufficient capture velocity to capture saw dust and will not collect any dust that is blown outside. This was mentioned on a previous inspection report and shall be completed by Dec. 1, 2006.</p> <p>Motor Storage Shack</p> <p>This area needs to be cleaned up.</p> <p>Maintenance Shop</p> <p>Housekeeping in this area is very poor. A propane tank on the east wall was not supported or chained in place. Oily rags were stored in a card board box. The parts washing tank had been jacked up on one side. The tank lid requires a fusible link to close the lid in the event of a fire. Waste oil was improperly stored in open containers on the east wall fo the shop.</p>	

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN																
<p>Unused parts and materials should be stored properly as they pose a tripping hazard.</p> <p>The pedestal grinding wheel did not have a proper exhaust system.</p> <p>Welding Shop</p> <p>Housekeeping needs to be improved. Flammable spray cans containing belt dressing, paints and solvents were improperly stored on a wooden shelf. Flammable materials shall be stored in an approved storage cabinet.</p> <p>Occupational Monitoring Program</p> <p>As indicated in our previous report, a monitoring program specifically for airborne dust and silica shall be implemented by December 1, 2006. Ministry staff can provide assistance with this program.</p> <p>Sidepak Dust Results</p> <p>The sidepak is an electronic direct reading instrument that measures respirable dust concentrations in real time. It is not an approved method because it has to be calibrated with gravimetric sampling results. It does however give a reasonably accurate reading of dust concentrations.</p> <table> <tr> <th>Location</th><th>Respirable Dust Concentration mg/m3</th></tr> <tr> <td>Outside office</td><td>0.013</td></tr> <tr> <td>picking belt</td><td>0.06</td></tr> <tr> <td>wash out room</td><td>0.035</td></tr> <tr> <td>top of mill</td><td>4.67</td></tr> <tr> <td>outside screening room</td><td>0.365</td></tr> <tr> <td>screening room</td><td>4.8 - 6.8 (bin hatch open)</td></tr> <tr> <td>fan scrubber discharge</td><td>>8</td></tr> </table> <p>The current TLV for respirable particles not otherwise classified is 3 mg/m3. Clearly, dust levels are very high in the plant under some circumstances.</p>	Location	Respirable Dust Concentration mg/m3	Outside office	0.013	picking belt	0.06	wash out room	0.035	top of mill	4.67	outside screening room	0.365	screening room	4.8 - 6.8 (bin hatch open)	fan scrubber discharge	>8	
Location	Respirable Dust Concentration mg/m3																
Outside office	0.013																
picking belt	0.06																
wash out room	0.035																
top of mill	4.67																
outside screening room	0.365																
screening room	4.8 - 6.8 (bin hatch open)																
fan scrubber discharge	>8																

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>Wooden Pedestrian Ramp</p> <p>A loose board was found at the top of the ramp. It is my understanding that plans are in place to replace this ramp with stairs.</p> <p>Open Hole Conditions</p> <p>Two covers that were covering sweeping holes were left off in the floor adjacent to the top of the wooden ramp. Workers should be reminded to replace these covers or install barriers while cleaning operations are underway.</p> <p>Conveyor Pull Cords</p> <p>The emergency stop cord was disconnected on the conveyor on the 2nd floor of the mill building.</p> <p>Toilet Facilities</p> <p>The outdoor male and female facilities were in very poor condition. The male toilet bowl was in pieces on the floor. A broken mirror was hanging from the wall. The female washroom was dirty and was not supplied with paper or soap. Clearly this is unacceptable. I understand that there is one toilet in the plant. The Manager shall review the requirements for male and female washrooms and dry facilities in Sections 2.11.5 to 2.11.11 of the Code and submit a plan to comply with the Code by Dec. 1, 2006.</p> <p>Workplace Monitoring</p> <p>Workplace monitoring was conducted by the Ministry during the inspection. Monitoring was conducted from about 9:40am to 3:00pm. The crusher, drill and plant were not running for the duration of sampling. The crusher shut down at approximately 11:30. The monitoring equipment was only worn by the picking belt worker for about 1 hour and 45 minutes which is not representative of their normal dust exposure. The plant was not running during monitoring. The dust results for plant workers are likely lower as a result.</p>	

INSPECTION ORDERS				MANAGERS RESPONSE OF ACTION TAKEN
Sampled August 31, 2006				
Location/Job	Respirable Dust mg/m3	Quartz mg/m3	%	
Plant Operator Personal sample s.22 (monitor worn until ~1:30) Activities included QC with the water table, loading a product truck with a drop chute.	3.89	0.02	0	
Plant Operator Personal sample s.22 Activities included changing screens on the hummer (unusual work), running forklift, sweeping for ~30 min and doing checks. Not as dusty as usual due to plant not running.	3.72	0.03	1	
Plant Labourer Personal sample s.22 Spent 3 hours cleaning 2 bins out, rest of time spent bagging product	53.32	0.03	0	
Picking belt Personal sample s.22 only worn for ~1 hour and 45 min	0.34	0.0	0	
8- hour Limit	3	0.1		
12-hour Limit	2	0.067		
The dust results for the plant workers are above the limit for respirable dust. Control measures shall be investigated to lower plant workers' dust exposure. In the interim workers shall wear appropriate, NIOSH approved respiratory protection to lower their exposure.				
For the plant operators, half mask air purifying respirators may be adequate. These respirators have an assigned				

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>protection factor (APF) of 10. This means that workers exposure when wearing the respirator properly can be thought of as reduced by a factor of 10. For instance the plant operator's dust result is 3.89 mg/m³ indicating that without a respirator his exposure would be about 3.89 mg/m³ of respirable dust. Properly wearing a fitted half mask air purifying respirator with an APF of 10 his exposure would be closer to 0.389 mg/m³.</p> <p>For the plant labourer the dust result is well above the limit at 53.32 mg/m³. Using a respirator with an APF of 10 would not bring the worker's dust exposure within the limit of 3 mg/m³. In order to do so with a respirator would require the use of a respirator with a higher APF. There are several options to do this. They include powered air purifying systems, supplied air systems or using a full face respirator. More detailed information can be obtained from respiratory protection suppliers. The high dust result is likely from the cleaning of bins. This work process shall be reviewed to reduce worker's dust exposure and/or engineering controls investigated. A vacuum system below the bin may be of use to pull the dust down and out of the bin. In the interim workers shall wear appropriate NIOSH approved respiratory protection with an APF of at least 25 when cleaning out bins.</p>	

IMASCO MINERALS INC.
PO BOX 56, 8660 HWY 3A
SIRDAR, BC V0B 2C0

DATE: Nov 9 / 06

TO: Al Hoffman

FROM: Rodenstein

NUMBER OF PAGES (INCL COVER SHEET) 4

Al

As requested

Pete


**MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES**
Mining & Minerals Division
Report of Inspector of Mines

(Issued pursuant to Section 15 of the Mines Act)

 File: 18040-02-04
 Mine No: 0500284
 Permit No:
 Emp/Cont: 0 / 0
 Orders H&S: RECL:
 Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Mine Plant, Maintenance Shop, Welding Shop, Lunch Rooms

Persons Contacted

MANAGEMENT	P. Rodenstein
OHS COMMITTEE	Jason Wall
WORKERS	s.22

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

The inspector was accompanied by Caroline Nakatsuka
Inspector of Mines, Occupational Health.

Fire Extinguishers

Fire extinguishers had been checked in August, but the tags were not punched in May, June and July 06. Fire fighting equipment shall be checked on a monthly basis.

Emergency Eye Wash Stations

An eyewash station had been installed on the outside wall of the new change room; however, it was covered with dust and the fluid container was empty. In accordance with Section 2.4.1 (2)(3) eyewash stations shall be installed and maintained. I recommend that they be put on a monthly PM check and that the fluid be topped up after they are used.

Lumber Storage

Lumber and a piece of sheet metal was stored in the rafters

MANAGERS RESPONSE OF ACTION TAKEN

Done .

Done . - protected from
dust by plastic
cover!

Al Hoffman

Manager, Occupational Health

7th floor, 1675 Douglas Street Victoria BC V8W 9N3

Address

 Date of Inspection: August 31, 2006

 Copies To Phil Pascuzzi, Garry MacDonald

 Signature:  Inspector of Mines

Signature - Manager

 Dated: Nov 1/06 .20 06

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

immediately above the foot of the stairs near the lab. These materials shall be moved as they pose a hazard to workers passing underneath.

Lock-Out During Screen Repair

A screen repair was underway at the time of inspection. Workers were unable to tell the inspectors where the screens were locked out; it was later determined that the screens were not locked out. There appears to be some confusion if this area can be electrically isolated. A locked out switch could not be found in either MCC room. A lock out procedure shall be developed immediately in accordance with Section 4.11.1 of the Code. The lack of a proper lock out procedure could result in a serious injury or a fatality. A procedure shall be developed immediately.

Confined Space Entry

At the time of the inspection, two employees were cleaning a bin. They had accessed a storage bin through a hatch in the outside screen room. Both employees were in the bin. One was wearing a safety lanyard, the other was not wearing a fall arrest system. It did not appear that the bin was checked for oxygen deficiency or for the presence of harmful gases. The employees were not aware of a written confined space entry procedure. A spotter was not posted at the bin entranceway. There was no tripod or other rescue equipment nearby to perform an extrication if necessary. The bin was not ventilated. Clearly, the lack of a formal written confined space entry procedure poses a hazardous situation. The procedure to clean bins between products shall be reviewed.

In accordance with the Code Section 4.4.1 to 3.4.6 a confined space entry procedure for this and any other confined space work activities shall be developed immediately.

Scrubber Discharge Area

Dust from the scrubber discharge area was falling from a

Done.

Lockout procedure in place. Screen in Question will be fixed to allow it to be locked out. This is the only piece of equipment that could not be locked out.

Storage bin had open bottom. All employees have been spoken to that only one employee can enter a bin at a time. Longer term plan is to fix bins so entry into bins is not required for cleanup.

needs Clarification

Agreed.

Date of Inspection: **August 31, 2006**

Initials:  (Inspector)

Initials:  (Manager)

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

distance of 8' to the ground near the outside moat on the north side of the plant building. The sidepack, a direct reading instrument, indicated dust levels exceeding 8 mg/m³ (TLV for respirable particles not otherwise classified is 3 mg/m³).

Truck Loading Area

A large amount of dust was generated while a truck was being loaded.

Palet Storage

A stack of #0 and # 30 products palets were stored four-high outside the palet storage room. This stack was clearly leaning and posed a hazard. The procedure to store palets shall be reviewed to ensure that they are stable and don't pose a hazard to workers passing by or to the fork lift operator.

Palet Shop

A dust collector shall be installed on the table saw in this area. The amount of sawdust in this area is clearly an inhalation and fire hazard. The fan installed through the wall does not have sufficient capture velocity to capture saw dust and will not collect any dust that is blown outside. This was mentioned on a previous inspection report and shall be completed by Dec. 1, 2006.

Motor Storage Shack

This area needs to be cleaned up.

Maintenance Shop

Housekeeping in this area is very poor. A propane tank on the east wall was not supported or chained in place. Oily rags were stored in a card board box. The parts washing tank had been jacked up on one side. The tank lid requires a fusible link to close the lid in the event of a fire. Waste oil was improperly stored in open containers on the east wall fo the shop.

The forklift operator immediately restacked the pallets. It is procedure to immediately restack pallets that are leaning too far. This is based on over 30 years of experience. A dust collector will be installed.

Done.

Cleanup done.

Date of inspection: August 31, 2006

Initials: CA (Inspector)

Initials: PR (Manager)

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

Unused parts and materials should be stored properly as they pose a tripping hazard.

The pedestal grinding wheel did not have a proper exhaust system.

Welding Shop

Housekeeping needs to be improved. Flammable spray cans containing belt dressing, paints and solvents were improperly stored on a wooden shelf. Flammable materials shall be stored in an approved storage cabinet.

Occupational Monitoring Program

As indicated in our previous report, a monitoring program specifically for airborne dust and silica shall be implemented by December 1, 2006. Ministry staff can provide assistance with this program.

Sidepak Dust Results

The sidepak is an electronic direct reading instrument that measures respirable dust concentrations in real time. It is not an approved method because it has to be calibrated with gravimetric sampling results. It does however give a reasonably accurate reading of dust concentrations.

Location	Respirable Dust Concentration mg/m3
Outside office	0.013
picking belt	0.06
wash out room	0.035
top of mill	4.67
outside screening room	0.365
screening room	4.8 - 6.8 (bin hatch open)
fan scrubber discharge	>8

The current TLV for respirable particles not otherwise classified is 3 mg/m3. Clearly, dust levels are very high in the plant under some circumstances.

Storage Cabinets have been installed.

Agreed.

Date of Inspection: August 31, 2006

Initials: [Signature] (Inspector)

Initials: MR (Manager)

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

Wooden Pedestrian Ramp

A loose board was found at the top of the ramp. It is my understanding that plans are in place to replace this ramp with stairs.

Repaired

Open Hole Conditions

Two covers that were covering sweeping holes were left off in the floor adjacent to the top of the wooden ramp. Workers should be reminded to replace these covers or install barriers while cleaning operations are underway.

Discussed with all employees.

Conveyor Pull Cords

The emergency stop cord was disconnected on the conveyor on the 2nd floor of the mill building.

Repaired.

Toilet Facilities

The outdoor male and female facilities were in very poor condition. The male toilet bowl was in pieces on the floor. A broken mirror was hanging from the wall. The female washroom was dirty and was not supplied with paper or soap. Clearly this is unacceptable. I understand that there is one toilet in the plant. The Manager shall review the requirements for male and female washrooms and dry facilities in Sections 2.11.5 to 2.11.11 of the Code and submit a plan to comply with the Code by Dec. 1, 2006.

*Water supply installed
Male toilet facilities
being repaired.*

Workplace Monitoring

Workplace monitoring was conducted by the Ministry during the inspection. Monitoring was conducted from about 9:40am to 3:00pm. The crusher, drill and plant were not running for the duration of sampling. The crusher shut down at approximately 11:30. The monitoring equipment was only worn by the picking belt worker for about 1 hour and 45 minutes which is not representative of their normal dust exposure. The plant was not running during monitoring. The dust results for plant workers are likely lower as a result.

Date of Inspection: August 31, 2006

Initials: [Signature] (Inspector)

Initials: PR (Manager)

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

Sampled August 31, 2006

Location/Job	Respirable Dust mg/m3	Quartz mg/m3	%
--------------	--------------------------	-----------------	---

Plant Operator Personal sample s.22	3.89	0.02	0
---	------	------	---

(monitor worn until ~1:30)

Activities included QC with the water table, loading a product truck with a drop chute.

Plant Operator Personal sample s.22	3.72	0.03	1
---	------	------	---

Activities included changing screens on the hummer (unusual work), running forklift, sweeping for ~30 min and doing checks. Not as dusty as usual due to plant not running.

Plant Labourer Personal sample s.22	53.32	0.03	0
---	-------	------	---

Spent 3 hours cleaning 2 bins out, rest of time spent bagging product

Picking belt Personal sample s.22	0.34	0.0	0
---	------	-----	---

only worn for ~1 hour and 45 min

8-hour Limit	3	0.1
12-hour Limit	2	0.067

The dust results for the plant workers are above the limit for respirable dust. Control measures shall be investigated to lower plant workers' dust exposure. In the interim workers shall wear appropriate, NIOSH approved respiratory protection to lower their exposure.

For the plant operators, half mask air purifying respirators may be adequate. These respirators have an assigned

Date of inspection: August 31, 2006

Initials:  (Inspector)

Initials: PR (Manager)

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

protection factor (APF) of 10. This means that workers exposure when wearing the respirator properly can be thought of as reduced by a factor of 10. For instance the plant operator's dust result is 3.89 mg/m³ indicating that without a respirator his exposure would be about 3.89 mg/m³ of respirable dust. Properly wearing a fitted half mask air purifying respirator with an APF of 10 his exposure would be closer to 0.389 mg/m³.

For the plant labourer the dust result is well above the limit at 53.32 mg/m³. Using a respirator with an APF of 10 would not bring the worker's dust exposure within the limit of 3 mg/m³. In order to do so with a respirator would require the use of a respirator with a higher APF. There are several options to do this. They include powered air purifying systems, supplied air systems or using a full face respirator. More detailed information can be obtained from respiratory protection suppliers. The high dust result is likely from the cleaning of bins. This work process shall be reviewed to reduce worker's dust exposure and/or engineering controls investigated. A vacuum system below the bin may be of use to pull the dust down and out of the bin. In the interim workers shall wear appropriate NIOSH approved respiratory protection with an APF of at least 25 when cleaning out bins.

Date of Inspection: August 31, 2006

Initials:  (Inspector)

Initials: PR (Manager)



The Best Place on Earth

Province of British Columbia
MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOURCES
Mining & Mineral Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 12783.0
File: 18040-02-XX
Mine No.: 0500284
Permit No.:
Emp/Cont: 0.0 / 0.0
Orders H&S: 8.0 RECL: 0.0
Stop Work: 0.0

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Rick Czar	AREAS INSPECTED	Plant site.

Persons Contacted

MANAGEMENT	P. Rodenstein
OHS COMMITTEE	J. Wall
WORKERS	s.22

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION ORDERS

The purpose of this Inspection was two fold, one was to review the plant conditions from a dusty workplace exposure and two was looking at nip points and pull cords on conveyors.

The handrail from crusher loader pocket to the crusher control room requires re-bolting to secure the one end of the removable handrail. HSRC 4.1.7

Plant feeder conveyor requires improved guarding at the tail pulley nip point. HSRC 4.4.16 (6)

The new compressor room requires the installation of fire extinguishers. HSRC 4.4.10

G25P fork lift has a lot of dust in the cab from muddy boots which becomes airborne. This cab shall be cleaned out on a

MANAGERS RESPONSE OF ACTION TAKEN

Philip Pascuzzi

Inspector of Mines

2nd floor, 42 - 8th Ave. S. Cranbrook BC V1C 2K3

Address

Date of Inspection: 3/7/2006

Copies To

Signature - Inspector of Mines

Signature - Manager

Dated: _____, 20

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>more frequent basis.HSRC 2.2.1</p> <p>The inside return belt tail pulley has a large hole in the guard that shall be repaired.HSRC 4.4.16(6)</p> <p>The stairway from the Stedmond to the dryer shall be cleared of all debris that has slid down the bank onto the staircase.HSRC 4.1.4</p> <p>There shall be a lock-out tag incorporated into the IMASCO lock-out procedure.HSRC 4.11.3 (3)</p> <p>All the conveyors not reviewed during this inspection shall be inspected by the OHSC to ensure all accessible nip points and pull cords are in place and functioning.</p> <p>It was noted that all equipment operators observed were wearing their belts and the rotary lights are in use.</p> <p>The Occupational Health and Safety Committee shall review the requirements under HSRC 1.6.8 and 1.6.9 for the IMASCO OHSC.</p> <p>The results of the workplace dust exposure inspection will be submitted by Al Hoffman Manager of Occupational Health.</p>	

Date of Inspection

3/7/2006

Initials



(Inspector)

Initials

(Manager)



Monday, April 03, 2006

File: 18040-02-04
Mine No.: 0500284

March 31, 2006
Mr. Peter Rodenstein
Manager
Imasco Sidar Operation
Box 56
Sirdar, BC V0B 2C0

By Fax: (250) 866-5455

Re: Mine Inspection March 7, 2006
Property: IMASCO - SIRDAR

Enclosed are three copies of my Inspection Report for the above noted property and date.

Please have this report posted in a conspicuous place on the property accessible to the workers in accordance with Section 30(1) of the Mines Act. Please forward a copy to the C0-Chair of your OHSC and to the local union representative.

As noted on page one of the report, please fill in the appropriate areas responding to the Inspector's comments, sign and date the first page, initial the subsequent page(s) and return a copy with your comments to the writer.

A silicosis claim is of concern to the Ministry and I am sure to you and your employees. The Ministry will continue to follow up this investigation and can be of assistance in conducting your occupational monitoring program.

I can be reached at (250) 952-0464 or at e-mail Al.Hoffman@gov.bc.ca if you have further questions.

Yours truly,

Al Hoffman, P.Eng.
Manager, Occupational Health

Enclosures 2
C: Phil Pascuzzi, Regional Office Cranbrook

VA06020705 - Finalized

Figure 2

Ministry of Energy, Mines and Petroleum Resc
IMASCO MINE SAMPLES

of SAMPLES : 14

DATE RECEIVED : 2006-03-14 DATE FINALIZED : 2006-03-22

PROJECT : "Imasco"

CERTIFICATE COMMENTS : ""

PO NUMBER : " "

SAMPLE Number		ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
		SiO2	Al2O3	Fe2O3	CaO
		%	%	%	%
IM#1	grey granite from mine	65.49	15.28	3.65	3.6
IM#2	picking shack stairs	5.89	1.1	0.7	36.95
IM#3	quartzite sample	97.32	0.6	0.66	0.04
IM#4	mud under picking belt	8.86	1.75	1.04	30.06
IM#5	00 soil conditioner under picking belt	2.57	0.73	0.68	34.53
IM#6	quartzite cow sand	87.79	3.93	1.61	0.94
IM#7	granite cow sand	67.79	14.19	3.52	3.42
IM#8	#2 Dillon screen	1.64	0.3	0.55	34.68
IM#9	Stedman Pad entrance door	6.78	0.81	0.62	30.61
IM#10	Niagra screen room	14.55	2.01	0.89	27.17
IM#11	Inside screening room	14.34	2.79	1.03	26.93
IM#13	settled dust moat	10.44	1.83	0.85	30.56
IM#14	picking belt scrapings	2.14	0.09	0.63	30.08
IM#15	outside screen room	1.56	0.22	0.6	30.91

ources

ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06	ME-XRF06
MgO	Na2O	K2O	Cr2O3	TiO2	MnO	P2O5	SrO	BaO
%	%	%	%	%	%	%	%	%
1.21	2.87	3.59	<0.01	0.42	0.09	0.18	0.09	0.12
11.61	0.11	0.27	<0.01	0.05	0.04	0.1	0.01	0.01
0.09	0.04	0.18	<0.01	0.01	<0.01	0.01	<0.01	<0.01
15.7	0.2	0.41	<0.01	0.06	0.03	0.1	0.01	0.01
16.01	0.01	0.19	<0.01	0.08	0.02	0.08	0.01	0.01
0.64	0.18	0.89	0.01	0.24	0.03	0.04	<0.01	0.02
1.28	3.03	3.17	0.01	0.44	0.09	0.19	0.08	0.1
16.32	<0.01	0.08	<0.01	0.02	0.03	0.1	0.01	<0.01
16.89	0.07	0.22	<0.01	0.05	0.02	0.1	0.01	0.01
15.83	0.3	0.47	0.01	0.06	0.03	0.14	0.01	0.01
14.84	0.41	0.69	<0.01	0.09	0.03	0.1	0.01	0.02
14.61	0.28	0.46	<0.01	0.07	0.03	0.14	0.01	0.01
20.27	<0.01	0.03	<0.01	<0.01	0.02	0.05	<0.01	0.01
19.53	<0.01	0.06	<0.01	<0.01	0.02	0.07	<0.01	<0.01

ME-XRF06 LOI %	ME-XRF06 Total %
1.88	98.46
41.6	98.43
0.08	99.01
40.6	98.83
44	98.92
1.94	98.26
0.86	98.16
44.8	98.5
42.2	98.38
37.2	98.67
37	98.28
39.2	98.5
45.1	98.41
45.5	98.47



Province of British Columbia
MINISTRY OF ENERGY, MINES AND
PETROLEUM RESOURCES
Mining & Mineral Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 13311.0
File: 18040-02-XX
Mine No.: 0500284
Permit No.:
Emp/Cont: 0.0 / 0.0
Orders H&S: 9.0 RECL: 0.0
Stop Work: 0.0

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Plant / Crusher / Mine

Persons Contacted

MANAGEMENT	D. Anderson
OHS COMMITTEE	
WORKERS	Operations and maintenance

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION ORDERS

This inspection was in the accompany of Don Anderson and Garry MacDonald (Inspector of Mines Mechanical)

-The new compressor building has a MCC located in it. The ambient air temperature inside this room on the date of this inspection was very high due to equipment heating combined with +30 degree Celsius outside temperature. As per 4.2.1 of M421-00 electrical equipment rooms shall be sufficiently ventilated to maintain equipment at safe temperatures. This shall be remedied within 1 month.

-The maintenance shop housekeeping both inside (electrical equipment, tires etc) and outside (waste oil storage) was poor. The used oil containers, batteries, scrap etc shall be removed. The area in front of the shop electrical panel is being utilized for tire storage. This area must

MANAGERS RESPONSE OF ACTION TAKEN

Terry Paterson

Inspector of Mines Electrical

2nd floor, 42 - 8th Ave. S. Cranbrook BC V1C 2K3

Address

Signature -- Inspector of Mines

Signature -- Manager

Date of Inspection: 15/08/2006

Copies To P. Pascuzzi

Dated: _____, 20____

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>be kept clear as per 2-312 of the CEC. The lighting panel in this area is missing it's cover and there were bare conductors. These deficiencies shall be remedied within 7 days.</p> <p>-Both the small forklifts on site are being utilized outside the confines of the shop and plant (being driven outside on rough terrain). These machines do not have roll over protective structures as required by 4.9.11 of the HSR Code.</p> <p>-The emergency trip wire at the tail end of the landscape dryer needs to be re-established as per 4.4.16 (4). There were guards on equipment and tail pulleys in this area that were missing contrary to 4.4.16 (6) These shall be remedied immediately.</p> <p>-There are 2 manbaskets on site that are utilized with the boom truck. One of the manbaskets has been altered by the addition of angle iron brackets and a lifting device(used as a safety harness). This modification shall conform to 4.5.1 of the HSR code. These manbaskets shall also be non destructively tested as per 4.5.4 of the HSR code.</p> <p>-The emergency trip wire for the rock picking conveyor has a section around the tail end(section coming from the wash screens) on both sides that are missing. The conveyor to the sand screw also is missing emergency trip cords as well as the guarding around the drive and tail pulleys. These shall be replaced as per 4.4.16 (4) and (6) of the HSR code.</p> <p>-The gaurdrails and handrails around the crusher area and rock sorting area need to be designed and modified to meet the requirements of 4.1.7. The walkways are also in need of modification in this area to provide a consistent walking surface devoid of openings and elevation changes.</p> <p>-Some of the columns that are supporting the roof of the rock storage building have been damaged. These shall be inspected and necessary repairs shall be performed within 60 days.</p> <p>-The sand bagging conveyor in the plant requires emergency trip cords installed as per 4.4.16 (4) of the HSR code.</p> <p>-There were no items of deficiency noted at the underground mine during this inspection.</p>	

Date of Inspection 15/08/2006 Initials _____ (Inspector) Initials _____ (Manager)



Province of British Columbia
MINISTRY OF ENERGY AND MINES
Mining & Minerals Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 12359
File:
Mine No: 0500284
Permit No:
Emp/Cont: 20 / 0
Orders II&S: 3 RECL:
Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Site tour

Persons Contacted

MANAGEMENT	Peter Rodenstein, Don Anderson
OHS COMMITTEE	
WORKERS	various

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

This inspector was accompanied by Micah Carmody,
Inspector of Mines, Ergonomics.

PALLET CONSTRUCTION

In the pallet making area the sawdust shall be cleaned up and a dust collection system shall be installed on the saw to reduce the workers' wood dust exposure.

PULL CORDS

In accordance with the HSR Code 4.4.16(4) the outfeed conveyor section outside the rock sorting shed shall have a pull cord to stop the conveyor in an emergency.

TOE BOARDS

There were a few areas where toeboards shall be installed. They include:
the catwalk by the 00 dolomite tank
around the big Steadman screen

MANAGERS RESPONSE OF ACTION TAKEN

shed cleaned up and collection
fan will be lowered.

Will be done

Items have been added
to the maintenance

Caroline Nakatsuka, MSc, BMLSc
Inspector of Mines Occupational Health
PO Box 9320 Strn Prov Govt Victoria BC V8W 9N3
Address

Signature - Inspector of Mines

Signature - Manager

Date of Inspection: **September 15, 2005**

Dated: **Sept 30**, 2005

Copies To **Phil Pascuzzi, Al Hoffman, Construction & Specialized Workers Union Local 1611**

Page 60
EGM-2013-00121

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>the catwalk around the dryer the catwalk around the primary jaw crusher</p>	<p><i>backlog.</i></p>
<p>Toe boards should be approximately 100 mm in height.</p>	
<p>HANDRAIL</p>	
<p>Hand rails were discussed during the inspection. The HSR Code 4.1.7 states that handrails shall be installed for flights of stairs that have more than 4 risers. Thus the 3 metal steps at the north end of the moat do not need a handrail. The stairs outside the screening room may need a handrail.</p>	<p><i>OK.</i></p>
<p>WORKPLACE MONITORING PROGRAM</p>	
<p>The possibility of the mine arranging workplace monitoring for dust was discussed.</p>	



Province of British Columbia
MINISTRY OF ENERGY AND MINES
Mining & Minerals Division
Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 12367
File:
Mine No: 0500284
Permit No:
Emp/Cont: 20 / 0
Orders H&S: 1 RECL:
Stop Work:

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	IMASCO Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	Peter Rodenstein	AREAS INSPECTED	Site tour

Persons Contacted

MANAGEMENT Don Anderson, Peter Rodenstein

OHS COMMITTEE

WORKERS

s.22

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS

This inspector was accompanied by Caroline Nakatsuka, Inspector of Mines, Occupational Hygiene.

Bagging
PALLET ROOM

Operators seats for the 'sand bagger' and 'chip bagger' do not provide adequate support for the workers and shall be replaced. This was discussed. Note that this order refers only to the seat (cushion and cover) and not the entire chair.

Modifications to the above machines that reduce reaching and awkward postures were noted. May the inspector return to take pictures?

MSD-PREVENTION TRAINING

The code requirement (1.6.9 (1) (h)) for OHSC members, as a minimum, to be trained in the recognition, evaluation and prevention of adverse health effects resulting in musculo-skeletal disorders was discussed following the inspection. I will be contacting you in the future to arrange a training date and location.

MANAGERS RESPONSE OF ACTION TAKEN

Parts on order.

OK

OK

Micah Carmody

Inspector of Mines - Ergonomics

7th Floor - 1675 Douglas Street Victoria BC V8W 9N3

Address

Date of Inspection: **September 15, 2005**

Copies To **Phil Pascuzzi, Al Hoffman**

Micah Carmody
Signature - Inspector of Mines

P. Rodenstein
Signature - Manager

Dated: *Sept 30*, 20 *05*



AH
PAT:
Please make up
file for
SIRDAR

October 9, 1996

AZ

Mr. A. Rennich, Manager
IMASCO Ltd.
P.O. Box 56
Sirdar, BC
V0B 2C0

Dear Mr. Rennich:

Enclosed is the report for my inspection at your plant on October 5, 1996. Please post a copy per section 30 of the *Health, Safety and Reclamation Code for Mines in B.C.*

Should you or Mr. Anderson have any questions about this report, please don't hesitate to contact me at (250) 952 0500.

Yours very truly,

Art Parker
Inspector of Mines,
Occupational Health

Encls.

Province of British Columbia
Ministry of Employment and Investment
MINES BRANCH

Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

File: 18020-02-07

OCCUPATIONAL HEALTH

Name of Mine: Sirdar Plant

Locality: Sirdar, BC

Owner or Operator: Imasco Ltd.

Address: P.O. Box 56
Sirdar BC V0B 2C0

Manager: Mr. A. Rennich

Areas Inspected: See below

Persons Contacted

Management: Mr. Don Anderson

OHS Committee:

Workers:

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union. The mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further, the manager shall post a copy to the bulletin board, to be replaced by a copy of the manager's response.

In this document, "Code" means *Health, Safety and Reclamation Code for Mines in British Columbia*.

Inspection Report	Manager's Response of Action Taken
<p>NOISE MONITORING <u>Note:</u> Noise levels over 85 dBA (average, 8 hours) have been demonstrated to cause permanent hearing loss unless hearing protection is worn, as required by the Code.</p> <p><u>Bagging Plant:</u></p> <p>Rock product bagging machine, operator's ear position while operating equipment. Average noise level.....89.5 dBA</p> <p>Bagging machine operator and persons working in the immediate vicinity were not wearing hearing protection.</p> <p>Hearing protection shall be worn in compliance with Tables 2-2 and 2-3 of the Code.</p>	

Copies To: R. Berdusco, P.Eng.; A. Hoffman, P.Eng.; G. MacDonald; E. Taje;
OHSC Co-Chairs


Art Parker

Inspector of Mines

4th Floor, 1810 Blanshard St.,
Victoria, BC V8V 1X4

Address

Date of Inspection: October 4, 1996


Signature - Inspector

Signature - Manager

Dated: _____, 19____

Inspection Report	Manager's Response of Action Taken
<p><u>Bagging Plant - cont'd.</u></p> <p>Persons in this area were wearing bump caps, not hardhats as required by the Code (1.8.3). Hardhats shall be worn in this area unless a variance is requested from the District Inspector within 30 days of receipt of this report.</p> <p><u>Rock Sorting Conveyor:</u></p> <p>Not operating at time of inspection.</p>	

Date of Inspection: October 4, 1996

Initials: _____

Inspector

Manager



Natural Resources Canada
Ressources naturelles Canada

CANMET

Mining and Mineral Sciences Laboratories

Sudbury Laboratory
1079 Kelly Lake Road
Sudbury, Ontario, P3E 5P5

Telephone: (705) 670-6766

Fax: (705) 670-6556

Please include the following information when returning filter cassettes:

Results sent to: Caroline Nakatsuka
MINISTRY OF ENERGY AND MINES
MINING DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3


Bill to: MINISTRY OF ENERGY AND MINES
MINING DIVISION
PO BOX 9320 STN PROV GOVT
VICTORIA BC V8W 9N3

P.O. Number: Imasco


Total Number of samples : 5

Required				Optional			
Filter #	Analysis Required TRD	Analysis Required RCD	Analysis Required Quartz	Sample Volume (m ³)	Initial Flow L/min	Final Flow L/min	Elapsed Time (min)
15396	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	0.584	2.727	2.754	213
15388	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	0.895	2.787	2.790	321
15405	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	0.606	2.737	2.720	222
15369	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	0.274	2.728	2.754	100
11815	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	N/A			
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				

 Natural Resources Canada
Ressources Naturelles Canada



X-RAY DIFFRACTION
Sudbury Laboratory
DIFFRACTION DES RAYONS X
Laboratoire de Sudbury



Date Samples Received: **September 11, 2006**
Date Samples Analysed: **September 11, 2006**
Date of Primary Calib. : **June 23, 2006**
Date of Secondary Calib. : **August 16, 2006**

Analysed by:

Checked by:

Date: September 11, 2006

Note: < 0.01 indicates the presence of quartz below the detectable limit of 0.01 mg

Project Leader:

Date:

PROTECTED BUSINESS INFORMATION

TERMS AND CONDITIONS FOR SMALL SERVICE JOBS

These terms and conditions hereunder written apply to the work done and the deliverables obtained from the small service job _____, Project 601254.

1. **CANMET** has performed the work in a diligent, thorough and workmanlike manner in accordance with good scientific and technical practices. However, **CANMET** makes no representation or warranty respecting the results arising therefrom, either expressly or implied by law or otherwise, including but not limited to implied warranties or conditions of merchantability or fitness for a particular purpose.
2. **CANMET** shall keep confidential and not disclose to third parties the information contained in or regarding the Deliverables for a period of three (3) years from the coming into force of this Agreement, except with the written consent of the **CLIENT** or where the information: (a) is now or hereafter, through no act or failure to act on the part of **CANMET**, becomes generally known or available to the public without breaching this Agreement; (b) is subsequently disclosed to **CANMET** by a third party, and does not include a confidential obligation; (c) is developed by **CANMET** independently of this Agreement; or (d) is required to be disclosed by law.
3. **CANMET** reserves the right to use the information contained in the Deliverables for policy formulation, in-house research purposes, and to publish summary and non-confidential announcements with respect to the work. Such announcements shall not be published without written consent of the **CLIENT**, which consent shall not be unreasonably withheld.
4. The **CLIENT** shall pay all approved charges for the work completed within thirty (30) days of the date of issue of the invoice. All cheques and money orders shall be made payable to the **Receiver General for Canada** and sent to Natural Resources Canada as per instructions on each invoice. **CANMET** reserves the right to charge interest on overdue accounts at a rate of three percent (3%) above the prime rate set by the Bank of Canada.
5. The **CLIENT** shall indemnify and save harmless Natural Resources Canada and its employees and agents from and against all claims, demands, losses, costs including lawyers fees, damages, actions, suits or proceedings, that are in any manner based upon, arising out of, or attributable to the use of the Deliverables or any part thereto. **CANMET** shall have the right to defend any such action or proceeding with counsel of its own choosing.
6. The **CLIENT** represents that it has not disclosed or provided to **CANMET** any unauthorised proprietary information, samples or documentation pertaining to the work.
7. It shall be the obligation of the **CLIENT**, at its own expense, to transport required samples, to and from **CANMET**.
8. The **CLIENT** shall not use the name of Natural Resources Canada, **CANMET**, or the names of **CANMET** employees, with respect to the work performed or anything arising therefrom, without prior written consent.
9. Neither party to this Agreement shall be liable to the other for any failure or delay in performance caused by circumstances beyond its control, including but not limited to acts of God, fire, labour difficulties, recognized year 2000 problems or governmental action.
10. This Contract shall be governed and construed in accordance with the Laws of the Province of Ontario and the Laws of Canada as applicable and shall be treated in all respects as an Ontario contract.
11. No member of the House of Commons of Canada shall be admitted to any share or part of this Contract or to any benefit to arise from it.
12. The **CLIENT** and **CANMET** shall attempt to resolve any dispute arising out of or pursuant to this Contract by recourse to the process described in Natural Resources Canada's *Preferred Method of Dispute Resolution - Revenue-Generating Agreements* in order to reduce delays and litigation expenses for both Parties.

Inspection Report

NAME OF MINE	IMASCO - SIRDAR	LOCALITY	Sirdar
OWNER/OPERATOR	Plateau Constuction Ltd Imasco Minerals Inc.	ADDRESS	PO Box 56 Sirdar BC V0B 2C0
MANAGER	David Sacks	AREAS INSPECTED	Plant and Shops

Persons Contacted

MANAGEMENT	R. Czar. D. Anderson
OHS COMMITTEE	J. Wall
WORKERS	

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION ORDERS

SECTION :6.8.3 Traffic Control

The manager shall submit a traffic control plan for the Plant and Primary Crushing area which will include a procedure for notifying the Loader Operator of any person or vehicle that are wanting to enter the work area of the Loader. This control plan shall be submitted to this Inspector within Two weeks of receipt of this report.

SECTION :4.3.8 Fire Protection and Control

It was noted for the second time that the fuel storage containment dike at the primary crusher is no longer impervious. This condtion shall be recified with in the next 30 days from the receipt of this report.

SECTION :6.19.2 Logbook to be Maintained

The manager shall develop an effective log book system to meet the requirements of this section of the HSRC with in 2 weeks of reciept of this report.

SECTION :4.1.7(4)

At the primary crusher a hand rail was removed to allow access for the back hoe but no detour guards or barricades were in place to prevent works from exposure to falling in the crusher. This hazard is to be corrected immediatly and a prodecure develop as to what precautions workers are put into place when hand rails have to be removed.

SECTION :4.4.16(4)

A pull cord on the sand belt conveyor was broken and unattached while the belt was running. This is not the first time Inspectors have noted broken or disconnected pull cords. This practice has to discontinue immediately. Cords have to be immediately repaired or the area barricaded off the prevent

MANAGERS RESPONSE OF ACTION TAKEN

TYPE MANAGERS RESPONSE HERE

Done

A comprehensive Traffic Control Plan has been established.

Maps & policy implementation week of March 3.

Signage is on order

(See attached).

Double walled fuel storage tanks ordered.. 3 in tanks

Delivery = 2 to 3 weeks

*with 100% inspection
To be completed*

Logbooks acquired and in use.

London OK inspection

Done

Hand rail welded. Chains added to block access when machine is in use.

Sign erected "Do Not Enter"

Done

Inspection of all pull cords and associated switches complete.

Re-inspection every 6 months.

Pull cords added to walk about checklist.

entry to the hazardous area.

SECTION :4.1.1 Design and Construction

At the Landscape picking shack to was noted that the down stream carrier roll shall be relocated further away from the work area of the picker.

There shall be a full risk evalutaion of the Picker shack and an action plan developed to replace or repair this shack with in 60 days of receipt of this inspection report.

SECTION :6.10.1(4)

A dump block shall be installed at the feed hopper that will meet the requirements of this section of the HSRC. This block shall be installed within two weeks of reciept of this inspection report.

SECTION :4.11.3 Locks and Tags

During this inspection a worker was observed breaking rocks in the primary crusher without locking-out the crusher. This is the second time this Inspector has observed persons in shutes or on screens with out the use of lock-out. All employees are to be trained and monitored in the use of the lock-out procdure. This requirement shall be conducted within 7 days of reciept of this report. Violation of this procedure shall not be tolerated.

SECTION :4.9.14 Tires and Rims

It was noted that vehicles tires are being repaired and mounted and dismounted in the Maintenance shop by a contractor. When asked for the procedure that meets the requirement of this section of the HSRC there is none available. It was also noted that a tire in this shop was mounted on a very baddly damaged rim. This is a violation of the HSRC. So immediately no tire repair shall be conducted on this mine site until the requirements of this section are complied with.

SECTION :3.6.2 First Aid Supplies } 305A

By reveiwing the present level of first aid and the travel time to the nearest hospital, This Inspector orders the First aid requirement be raised to a OFA level 3 with the appropiate level of supplies and ETV as perscribed by Worksafe BC.

SECTION :6.8.1 Duty to Keep Plans, Surface

Updated mine plans for the Open pits at Crawfordbay, Sirdar

Done

Roller removed (not needed)

General arrangement for replacement has been formed. This includes improvements to the belt configuration as well as new work areas for personnel.

Done

Lock out procedure training has been reviewed with all employees and they have been informed that non-compliance is subject to discipline.

pen marking in lock is good.
→ remove lock out tag

Tire change policy does exist. It is mounted in proximity to the tire change area. It has been reviewed with the contractor who is required to sign off on this policy. nothing

The tire noted in this report was received with a recently acquired drill. It was not intended for use, rather the unusual size of rubber tire has been salvaged and the rim scrapped.

For most of the year the Sirdar plant has staffing levels that would necessitate an upgrade to Level 2. The drive time to local hospital is just under 20 minutes. Arrangements are being made to train 2 employees as OFA Level 2 and upgrade the first aid supplies. ETV re-supply April 14/08.

To be discussed

and Lost Creek shall be submitted to the regional Inspector office within 30 days of receipt of this report.

SECTION :6.3.2 Copy for Inspections

Update mine plans meeting, the requirements of this section of the HSRC, for the Underground mines at Crawfordbay and Sirdar shall be submitted to the regional Inspectors office within 30 days of receipt of this report.

SECTION :4.1.11 Walkways and Vehicle Curbs

There were a number of walkways around the Plant that did not meet this requirement. There were narrow uneven walkways and tripping hazards present in most walkways around the outside conveyor system. This requirement will be complied with within 30 days of receipt of this report. ➤

SECTION :4.1.6 Storage of Materials

In two cases during this inspection it was noted where material was being stored on stairways. These materials shall be removed immediately and a review done with workers outlining the need to keep stairways free of tripping hazards. This requirement shall be reviewed at the next Crew safety meeting.

SECTION :1.11.1 Training

During this Inspection a number of workers were asked how they were trained to carry-out the tasks they were being asked to carryout. In all cases the answer was, the training was done with the buddy system, by just working it out on our own or there has been no training at all. Eg: Loader, Boom Truck operator, Forklift operator, Propane filling etc. The manager shall ensure that workers are adequately trained to do their job.

This process shall start immediately and a plan with objectives and dates for completion, shall be submitted to this Inspector within three weeks of receipt of this inspection report.

SECTION :1.11.2 Training

There appears to be very few records of employee training at this mine site.

The manager shall develop a training record system to meet the requirement of this section of the HSRC for both Workers and Supervisors. This record system shall be implemented along with the employee job training program.

SECTION: 1.9.1 (1)&(2) Workplace Conditions

It has been identified for a number of years now that this Plant site has an ongoing problem with dust control and worker exposure to dust. The HSRC requires the Manager take all

Complete except for pillar stability report from Golders Associates. The engineering work including site visit has been done and we should have the written report very soon.

As above

Done

All walkways have been cleared of tripping hazards.

All kick boards at Primary Crusher installed.

Routine has been established to inspect and maintain walkways around the plant.

Done.

Reviewed with crew March 29, 2008

A comprehensive Program of manuals has been established and implementation is underway.

Please see attachments.

3 employees underwent training on forklift.

Scheduled training March 18 & 19 includes forklift (for others), boom truck, hoisting / rigging.

Setting up programs for loader, backhoe and dump truck.

Please see attachments

All training will be documented OHS Manual and in employee files.

Copies can be provided on request.

Review next Inspection.

Development of Workplace Monitoring Program is underway. Caroline Nakatsuka visited the site the week of Mar 3rd, reviewed the process and sampling procedures. A monitoring

reasonable and practicable measures to ensure that the workplace is free of potentially hazardous agents. Where practicable institute controls at the source to ensure workers are not exposed to hazards in excess of the prescribed limits in the code.

It is recognized that some improvements have been made but fall short of protecting the workers from this hazard exposure. There was an order from August 31, 2006, to develop a workplace monitoring specifically for airborne dust and silica by December 01, 2006. To date this order has not been implemented. This continued non-compliance behaviour shall not continue.

The Manager shall within 30 days of receipt of this report develop a workplace monitoring program as required by the HSRC.

Also the Manager shall within 60 days of receipt of this report develop an acceptable action plan to address control measures, at the source, of workplace hazards to reduce them to the lowest level practicable and submit this plan to the regional Inspector of Mines.

program is being built (in the OHS manual) that will address the needs of our site and will start sampling once a week till we find out our base levels. Additional equipment will be rented when we are on quartzite or granite we will be able to get samples from all areas workers are working. We will review these findings and plan from the worst case scenario.

We will still be going forward with our plans to improve the overall dust handling equipment. This will be dependant on the feedback we get from the engineers and Allied Blower. We will keep you updated on the progress with the monitoring program and engineering results.

