

# **Rails to Trails** **Routine Condition Bridge Inspection Form**

Crossing <b>OTTER CREEK</b>	Structure # <b>KV-060</b>	Site # <b>KV-060</b>	Length <b>103</b>	UTM Zone and E <b>10 662211</b>	UTM N <b>5491037</b>
Trail Name <b>KVRT</b>	Km <b>139.3</b>		Deck Type <b>TIMB</b>	Girder Type <b>TIMBER</b>	Abutment Type <b>TIMBER</b>
Inspection Co. Name <b>SNT Engineering Ltd.</b>	Inspector's Name /Signature <b>J Cox, E Miller</b>			Inspection Date: <b>3-Oct-12</b>	Next Inspection: <b>1-Jul-13</b>

**GENERAL INFORMATION:**  
**LEFT/RIGHT APPROACHES (as seen facing downstream)**  
 E = excellent; G = good; F = fair; P = poor; N/A = not appl.

Item	Present Condition (circle or fill-in)	Comments (a comment is mandatory if condition "Poor" is selected)
Alignment	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/>	
Bridge Ahead Signs Missing	0 <input type="radio"/> 1 <input type="radio"/> 2 <input type="radio"/>	
Brushing Required	Yes <input type="radio"/> No <input type="radio"/>	
Delineator Missing Left	0 <input type="radio"/> 1 <input type="radio"/> 2 <input type="radio"/>	
Delineator Missing Right	0 <input type="radio"/> 1 <input type="radio"/> 2 <input type="radio"/>	
Approach Handrail/Guardrail	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Posted Load Rating (tonnes)		N/A
Road Surface	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/>	

**LEFT/RIGHT ABUTMENTS (as seen facing downstream)**

Log/Timber Crib	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Tie-backs	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Bin Wall	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Concrete	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Stone Blocks	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Caps or sills	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	HEAVY DECAY
Piles or Posts	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Ballast Wall	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	HEAVY DECAY
Wing Wall	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Fill	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Bearings	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Riprap	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	

**DECK**

Running Planks	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Sub-deck	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	SPLIT PLANKS/ WEATHERED
Ties	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	SPLIT PLANKS/ WEATHERED
Nails	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	NAIL HEADS PULLING
Deck to Girder Bolts	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Hardware	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Curb Rail/Blocks/Posts	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Handrail/Walkouts	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/> N/A <input type="radio"/>	
Overall Deck Condition	E <input checked="" type="radio"/> G <input type="radio"/> F <input type="radio"/> P <input type="radio"/>	HEAVY QUAD USE

# Rails to Trails

## Routine Condition Bridge Inspection Form

Crossing <b>OTTER CREEK</b>	Structure # <b>KV-060</b>	Site # <b>KV-060</b>	Length <b>103</b>	UTM Zone and E <b>10 662211</b>	UTM N <b>5491037</b>
Trail Name <b>KVRT</b>	Km <b>139.3</b>		Deck Type <b>TIMB</b>	Girder Type <b>TIMBER</b>	Abutment Type <b>TIMBER</b>

<b>PIERS</b> (numbered from left bank)	<b>Pier # 1 of 21</b>	<b>Comments</b>	<b>TYP</b>	
Caps or sills	G	F	P	N/A
Material	G	F	P	N/A
Bearings	G	F	P	N/A
<b>Pier # 2 of</b>				
Caps or sills	G	F	P	N/A
Material	G	F	P	N/A
Bearings	G	F	P	N/A

<b>SUPERSTRUCTURE</b>					
Steel	E	G	F	P	N/A
Bracing	E	G	F	P	N/A
Bearing	E	G	F	P	
Hardware	E	G	F	P	
Overall Superstructure Condition	E	G	F	P	MATERIAL WEATHERED AND SOME ROTTING

<b>CHANNEL</b>		
Est. Present Water Level Depth (m) <b>0.8</b>	Est. Present Water Level Width (m) <b>70</b>	Est. High Water Level Clearance (m) <b>2.5</b>

<b>HAZARDS</b> (indicate Y or N)				
High Water?	Scour?	Ice?	Debris?	Aggradation?
N	N	N	N	N
Hazard Comments				

<b>REPAIRS</b> (H = High, M= Medium, L = Low)			
#	Priority	Description	Estimate (\$)
1	M	REPLACE MISSING HANDRAIL AT RIGHT SIDE	
2			
3			

<b>ITEMS TO MONITOR</b>	
#	Description
1	RECOMMEND CLOSE PROXIMITY INSPECTION OF PIERS AND ABUTMENTS
2	
3	

General Comments	HEAVY QUAD USE, LOCAL RESIDENT HAS RE-NAILED RUNNING SURFACE
------------------	--

P.Eng inspection required?	<b>Y</b> <b>N</b>	Estimated date of replacement:	<b>2020</b>
----------------------------	-------------------	--------------------------------	-------------

<b>PROFESSIONAL ENGINEER (PEng) CERTIFICATION</b>			
Current Load Rating GVW (tonnes):	<b>5</b>	New Load Rating GVW (tonnes)	Replacement Date <b>2020</b>
Reviewed by - P.Eng.	Les Thiessen		Date: January 17, 2013



## Bridge Inspection Photos

**Structure # :** KV-060  
**Name of Crossing:** OTTER CREEK  
**Name of Trail:** KVRT  
**km:** 139.3  
**Inspection Date:** 10/3/2012  
(Left and Right as seen facing downstream)



**LEFT APPROACH**



**RIGHT APPROACH**



**RIGHT ABUTMENT**



**LEFT ABUTMENT**



**TYPICAL PILE & BEAM**



**TYPICAL CAP BEAM**



**VIEW FROM UPSTREAM**



**VIEW FROM DOWNSTREAM**

**Rails to Trails**  
**Routine Condition Bridge Inspection Form**



Crossing Otter Lake	Structure # KV-060	Site # KV-060	Km 139.3	UTM Zone 11 N	UTM E 228253	UTM N 5495442	Width (m) 2.1	Length (m) 105.2
Trail Name Kettle Valley		Super-Structure Timber						
		Sub-Structure Timber						
Inspection Co. Name Brook Robazza	Inspector's Signature			Inspection Date June 27, 2019		Next Inspection		
GENERAL INFORMATION:								
LEFT/RIGHT APPROACHES (as seen facing downstream)								
Item	Present Condition	Comments						
Alignment	Good	Gentle curve on camp approach.						
Bridge Ahead Signs Missing	2							
Brushing Required	No	No significant vegetation growth impacting approaches.						
Delineator Missing Left	2							
Delineator Missing Right	2							
Approach Handrail/Guardrail	Poor	None present at woods approach. End section of hand rails removed at the woods-downstream approach.						
Posted Load Rating (tonnes)	0	No sign.						
Road Surface	Fair	Some pot holes and rutting.						
LEFT/RIGHT ABUTMENTS (as seen facing downstream)								
Log/Timber Cribs	NA	None present.						
Tie-backs	NA	None present.						
Bin Wall	NA							
Caps or sills	Poor	Abutment caps starting to fail.						
Piles or Posts								
Ballast Wall	Poor	Either failed or never present.						
Wing Wall								
Fill	Poor	No fill retention.						
Bearings	Poor	Completely filled with soil.						
Riprap								


**Rails to Trails**  
**Routine Condition Bridge Inspection Form**



Crossing Otter Lake	Structure # KV-060	Site # KV-060	Km 139.3	UTM Zone 11 N	UTM E 228253	UTM N 5495442	Width (m) 2.1	Length (m) 105.2
Trail Name Kettle Valley		Super-Structure Timber						
		Sub-Structure Timber						
DECK		Condition		Comments				
Running Planks	Good		Some ATV wear and some slightly loose boards.					
Sub-deck	NA		Only 3 lengths of subdeck only above stringers.					
Ties	Poor		Some moss growth and signs of rot on most ties and top surfaces are in generally very poor condition due to rot.					
Nails	Fair		Small nails of which many are beginning to protrude.					
Deck to Girder Bolts	Good		Bolts in good condition but ties are rotten, limiting the effectiveness of the connection.					
Hardware	Good		Mostly timber "hardware" in good condition.					
Curb Rail/Blocks/Posts	Poor		No curb rail present.					
Handrail/Walkouts	Fair		Some sections of railing damaged or removed.					
Overall Deck Condition	Fair		Overall good condition except for railing and ties.					
PIERS		Condition		Comments				
Caps or Sills	Fair		Signs of rot and deterioration on most caps.					
Bearings	Good		Timber bearing pads in overall good condition.					
PILES		Condition		Comments				
Caps or Sills	Fair		Some piles show large cracks and deterioration.					
Bearings	Good		Timber bearing in overall good condition.					
SUPERSTRUCTURE		Condition		Comments				
Steel	Good		Exterior stringers show some weather damage but overall good.					
Bracing	Fair		Some cross bracing on piers are damaged or have become loose.					
Bearings								
Hardware	Fair		Some signs of moderate corrosion.					
Overall Superstructure Condition	Fair		Overall good condition except for railing and ties.					
CHANNEL								
Est. Present Water Level Depth (m)			Est. Present Water Level Width (m)			Est. High Water Level Clearance (m)		
0			0			0		

Rails to Trails  
Routine Condition Bridge Inspection Form



Crossing Otter Lake	Structure # KV-060	Site # KV-060	Km 139.3	UTM Zone 11 N	UTM E 228253	UTM N 5495442	Width (m) 2.1	Length (m) 105.2
Trail Name Kettle Valley		Super-Structure Timber						
		Sub-Structure Timber						
HAZARDS								
High Water? No		Scour? No		Ice? No		Debris? No		Aggradation? No
	Hazard Comments	Just off Otter Lake. Low risk of major hydrological damage.						
REPAIRS								
#	Priority	Description						Estimate (\$)
1	High	Replace all removed or damaged railing. Tighten all posts						
2								
3								
ITEMS TO MONITOR								
#	Description							
1	Conditions of ties, caps, and piles.							
2								
3								
General Comments								
P. Eng inspection required?		Yes		Estimated date of replacement:			0	
PROFESSIONAL ENGINEER (P.Eng)						Reviewed By: Daniel Estey		
Current Load Rating GVW (tonnes): 5		New Load Rating GVW (tonnes): 5		Reviewed by: 				
Replacement Date:				0		2019/10/30		

Rails to Trails  
Routine Condition Bridge Inspection Form



Location



Rails to Trails  
Routine Condition Bridge Inspection Form



Piers

	Cap or Sills	Bearings
Condition	Fair	Good
Comment	Signs of rot and deterioration on most caps.	Timber bearing pads in overall good condition.



Rails to Trails  
Routine Condition Bridge Inspection Form



Piers

	Cap or Sills	Bearings
Condition	Fair	Good
Comment	Signs of rot and deterioration on most caps.	Timber bearing pads in overall good condition.





Rails to Trails  
Routine Condition Bridge Inspection Form



Piles

	Cap or Sills	Bearings
Condition	Fair	Good
Comment	Some piles show large cracks and deterioration.	Timber bearing in overall good condition.



Rails to Trails  
Routine Condition Bridge Inspection Form



Piles

	Cap or Sills	Bearings
Condition	Fair	Good
Comment	Some piles show large cracks and deterioration.	Timber bearing in overall good condition.



Rails to Trails  
Routine Condition Bridge Inspection Form



**Item to Monitor**

Conditions of ties, caps, and piles.

None

Rails to Trails  
Routine Condition Bridge Inspection Form



**Repair**

Priority	Description	Estimate
High	Replace all removed or damaged railing. Tighten all posts	

None

**Additional Photos**



**Additional Photos**



Rails to Trails  
Routine Condition Bridge Inspection Form



**Additional Photos**



Rails to Trails  
Routine Condition Bridge Inspection Form



**Additional Photos**





**Additional Photos**



**Additional Photos**



**Additional Photos**



**Additional Photos**



**Additional Photos**





**Additional Photos**



**Additional Photos**



Rails to Trails  
Routine Condition Bridge Inspection Form



**Additional Photos**





Rails to Trails  
Routine Condition Bridge Inspection Form



**Additional Photos**



**Additional Photos**



**Additional Photos**



**Additional Photos**



**Additional Photos**



**Additional Photos**





Rails to Trails  
Routine Condition Bridge Inspection Form



**Additional Photos**



**Additional Photos**





**Additional Photos**



**Additional Photos**



Rails to Trails  
Routine Condition Bridge Inspection Form




**Additional Photos**




## BRIDGE INFORMATION:

<b>Bridge No./Name</b>	KV-060: Kettle Valley Railway		
<b>Inspection Date</b>	October 9, 2020		
<b>Inspected By</b>	Mike Hanson, P.Eng. Josh Stadnyk, EIT.		
<b>Temperature (°C)</b>	15		
<b>Access Method</b>	Ground level assessment		
<b>Year Built</b>	Unknown		
<b>Camp/Town</b>	River Right		
<b>Number of Spans</b>	23	<b>Span Lengths (m)</b>	4.3 to 4.8 m
<b>Superstructure</b>	Six creosote treated sawn stringers, spaced 150 mm in pairs and 650 mm clear distance between pairs. Stringers are 245 x 500 mm and generally continuous over two spans, aside from the stringers in the first and last spans, which are simply supported.		
<b>Deck</b>	Untreated ties, 185 x 185 mm spaced at 300 mm c/c. Longitudinal nailing plank across ties supporting deck planks; all planks 140 x 35 mm. Running surface width 1.83 m, total deck width 3.58 m.		
<b>Curb</b>	Untreated timber handrails.		
<b>Substructure</b>	Creosote treated timber piles, cap beams and ballast walls. Piles are typically 300 mm diameter, cap beams are 400 mm deep x 300 mm wide timbers.		



STANDARD NAMING CONVENTION:



NOTE:

- ABUTMENTS, SPANS, AND PIERS NUMBERED FROM LEFT TO RIGHT WHEN LOOKING DOWNSTREAM
- PILES AND GIRDERS NUMBERED UPSTREAM TO DOWNSTREAM

GENERAL BRIDGE CONDITION:

Bridge Element	<u>Previous</u>	<u>Current</u>
Superstructure	--	Poor
Substructure	--	Poor
Deck	--	Poor
Load Posting	--	--
Date for Next Close Proximity Inspection	--	2021

BRIDGE INSPECTION SUMMARY:

The bridge is generally in poor condition with severe widespread decay in the piles and deck ties. Severe decay was also noted in the exterior stringers where accessible from ground level which suggests numerous other stringers where not accessible are also in poor condition.

At least 75% of the deck ties are in poor condition with extensive decay in the upper half of the ties. The deck planks are generally in fair condition and help to distribute the load evenly across the decaying ties. Given the extent and severity of decay throughout the bridge, it is likely that a full bridge replacement is the most cost effective solution, rather than undertaking extensive repairs. Furthermore, much of the decay in the piles were noted at or near ground and present water level, which suggests that posting the piles, may not be feasible.

We recommend the bridge be restricted to pedestrians and recreational off road vehicles (UTV, ATV and dirt bikes/e-bikes) only, with a maximum speed of 5 km/hr over the bridge, until significant repairs or a full replacement is completed. Equestrian use should be prohibited as the thin (38 mm) deck planks and decayed ties are not likely to provide adequate capacity for the concentrated point loads of a horse hoof. If the bridge is to remain open under these restrictions, we recommend the bridge be monitored

on a monthly basis for signs of distress or failure. We also recommend a detailed inspection of the upper section of piles, caps and stringers be completed using a boat and/or ladder to determine the extent of decay and confirm if the load restrictions are suitable. Please note that a full closure may be required based on the results of this inspections.

The age of the structure is not known, however based on the existing condition the structure has certainly exceeded its useful life.

#### INSPECTION NOTES:

---

##### **Approaches:**

- The approaches are generally in fair condition.
- Minor pothole/loss of fill at the ends of the bridge deck.
- Vegetation overgrown at the right approach, reducing visibility.
- No bridge ahead signs.
- No approach barriers or guard rails.
- Large boulders in center of pathway to restrict larger vehicle access.
- No visible ballast walls, which is causing fill to spill around ends of the stringers.

##### **Deck:**

- The deck is generally in poor condition.
- The ties have widespread decay with at least 75 mm of severe decay noted on the top face of most of the ties. At least 75% of ties are in poor condition.
- The nailing planks and deck planks are in fair condition with minor decay in isolated areas.
- Limited access to inspect deck from under bridge.
- The handrails are generally in fair condition with several isolated sections with damaged handrail posts and planks.
- The handrails at both ends of the bridge are damaged and appear to have either been purposely removed or damaged for additional vehicle clearance.

##### **Substructure:**

###### **Abutments:**

- Both abutments are buried in fill with no access for inspecting the caps/ sills and piles.

###### **Piers:**

- The piers are typically in fair to poor condition.
- There are a number of heavily decayed piles with at most 50 mm shell remaining, as noted in the table below.
- All piles were inspected from ground level and at the present water level.
- Access to the cap beams were limited to piers 1, 2, and 22 where the caps are reachable from ground level.
- Pier 2 cap cored below stringer 6, 25 mm shell remaining in the upper 150 mm of the cap. Sounding indicates decay is present throughout the cap.
- The cross bracing has widespread decay, as noted in the table below.

Substructure Decay:

The table below provides a summary of the condition noted. All piles and bracing was hammer sounded, and selective coring was completed where deemed necessary to confirm the extent of decay. Photos of each pier are provided in the photo log, with coring locations denoted in pink. Piles and bracing with severe decay are considered poor condition and are denoted with a red shaded cell in the table below. Grey cells indicate where components are not applicable to that pier, and "P" indicates where the pile has been posted.

Pier	Pile									Bracing		Comments
	1	2	3	4	5	6	7	8	9	Left	Right	
1												Pile 4 cored, sound
2												
3												Pile 3 sound at ground level
4					P							Pile 1 cored, soft but no rot
5												
6												Pile 8 cored, sound
7												Pile 7 rot at 1.0m above PWL
8												
9	P											Pile 7 cored, sound
10	P											
11	P											Pile 6 cored, sound
12	P											
13	P					P						
14												Pile 3 cored, sound
15												
16						P						

Pier	Pile									Bracing		Comments
	1	2	3	4	5	6	7	8	9	Left	Right	
17								P				
18												
19						P						Pile 3 cored, sound
20												Pair of piles at 7, right is rotten
21	P		P									Pile 6 has wide split, no rot
22				P								Rot in pile 4 is in the sill/ blocking, no crushing noted

**Stringers:**

- Limited access from ground level to inspect stringers.
- Stringer 6 on spans 1 and 2 cored, 25 mm shell remaining on upper 150 mm of both stringers.
- Interior stringers at spans 1 and 2 sounded, no rot noted.
- Ends of stringers at spans 1 and 23 are buried; end of span 23 stringers are heavily decayed.
- Based on visual observations all of the exterior stringers appear to be in similar condition and therefore are likely to all have high levels of decay.

**Channel:**

- Limited flow during the inspection.
- Bridge is located at the head of the channel at Otter Lake.
- 0.7 m estimated present water level depth
- 56.0 m estimated present water level width
- 2.0 m estimated high water level clearance

LIST OF MAINTENANCE/ REPAIR ITEMS:

Item No.	Description	Priority
1	Replace broken handrails	High
2	Install additional vehicle barriers	High
3	Plan for full bridge replacement	High

LIST OF MONITORING ITEMS:

1. Monitor bridge components for signs of failure, particularly the deck ties.



Prepared by:



Mike Hanson, P.Eng.  
Lead Bridge Inspector

Reviewed by:

A handwritten signature in black ink, appearing to read "Michael Foster".

Michael Foster, P.Eng.  
Supervising Engineer



**Photo 1**  
Bridge elevation from upstream (Lake)



**Photo 2**  
Looking downstream



**Photo 3**  
Left approach, looking away from bridge



**Photo 4**  
Right approach, looking towards bridge



**Photo 5**  
Right approach, looking away from bridge



**Photo 6**  
Railing at left abutment



**Photo 7**  
Railing at left abutment



**Photo 8**  
Railing near middle of bridge



**Photo 9**  
Railing at right abutment



**Photo 10**  
General deck condition



**Photo 11**  
Typical deck tie condition



**Photo 12**  
Typical deck tie condition





**Photo 13**  
Typical deck tie condition



**Photo 14**  
Span 2 stringer 6 condition



**Photo 15**  
Span 2 stringer 1 condition



**Photo 16**  
Span 23 stringer 1 condition



**Photo 17**  
Left abutment



**Photo 18**  
Pier 1



**Photo 19**  
Pier 2



**Photo 20**  
Pier 3



**Photo 21**  
Pier 4



**Photo 22**  
Pier 4 blocking



**Photo 23**  
Pier 5



**Photo 24**  
Pier 6





**Photo 25**  
Pier 7



**Photo 26**  
Pier 8





**Photo 27**  
Pier 9



**Photo 28**  
Pier 9, Pile 1



**Photo 29**  
Pier 10



**Photo 30**  
Pier 11



**Photo 31**  
Pier 12



**Photo 32**  
Pier 13



**Photo 33**  
Pier 14



**Photo 34**  
Pier 15



**Photo 35**  
Pier 16



**Photo 36**  
Pier 17



**Photo 37**  
Pier 18



**Photo 38**  
Pier 19





**Photo 39**  
Pier 20




**Photo 40**  
Pier 21





**Photo 41**  
Pier 22







Structure	Span (m)	Total Replacement Cost
KV-060	103	\$2,575,000.00
KV-062	8.9	\$133,500.00
KV-063	31.46	\$786,500.00
KV-064	8.8	\$132,000.00
KV-066	25.9	\$388,500.00
KV-067	27	\$405,000.00
KV-068	45	\$675,000.00
KV-069	30	\$750,000.00
KV-071	26.2	\$393,000.00
KV-072	33	\$825,000.00
KV-074	7.4	\$111,000.00
construction premium*	15%	\$1,076,175.00
<b>TOTAL</b>		<b>\$8,250,675.00</b>
General replacement cost per meter provided by Drew Alway. Bridges less than 30 = replacement cost of \$15K/M, bridges 30m or over = replacement cost of \$25K/M		
* costs for new bridges increased due to increased labour and materials costs and due to the fact that new bridges are often longer than original to accomodate stream values		