

Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: 2020W-01____

Service Area: SA13 - Okanagan-Shuswap

Name of Contractor: AIM Roads

Date: October 20, 2020

Prepared by: Peter Cocker

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Maintenance Specification 1.01 "to provide a smooth, stable, sealed surface of highway and bicycle/pedestrian paths".

Maintenance Specification 1.03 "to provide a safe, smooth, stable, compacted and free draining dirt and gravel highways and shoulders.

Performance Criteria – construct temporary patches consistent with the profile and crossfall of the adjacent surfaces as per table PM1.01.2-1

Performance Criteria – Grading or Re-shaping of dirt and gravel highways as per table PM1.03.3-2.

Non-conformance with timeframes set out in table PM1.01.2(a) on Class 5 road. Non-conformance with time frame set out in table PM1.03.3-2 (b) on class 5 road

SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES	Х	Deadline for correction: October 23, 2020	
NO	*************	MOT accepts the non-conforming product/s	service
		Reason:	
N/A		Reason:	
Гетроі	rary F	pon completion of required correction: Patching must be completed by October	
-		vement edge drop must be repaired by 2020. (no later than Oct 26- as stated in	Nici
email).	\subset	anglated Novarin	Contractor Signature:
Contrac	tor re	presentative confirms correction complete.	Contractor dignature.
Date ac	cepte	d by MOT: Click here to enter a date.	MOT Representative: _PC
		Nov 27th/2020	

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: October 30, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)

The root-cause resulting in the non-conformity with the contractual requirements is due to a lack of material and planning for repair and maintenance of the identified areas by the operations team. AlM's internal training processes and associated plans for temporary patching were not executed within a timely matter according to the specifications due to underestimated timeframes for other summer works and prioritizing the planning for the repairs of these specific areas.

Note: The extreme weather and high volumes of water has resulted in erosion and unusual wear on the road surface throughout SA 13, increasing the rate of delamination and potholes in many areas. AIM has underestimated the frequency and number of repairs required to maintain the above mentioned specification.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AlM intends to implement hot mix to patch the required locations and shoulder drops along the Class 5 road that remain unrepaired in order to meet specification timeframes. Pothole patching is ongoing as of Oct 20 and will be completed no later than Oct 26 (as noted via email). AIM plans to prevent the reoccurrence of the above NCR by prioritizing all repairs with major safety concerns and noncompliances notified to AIM by the ministry. AIM plans to prevent the re-occurrence of the nonconformance moving forward next season by considering extreme weather conditions and the possibility of excessive rain contributing to an increase in road surface maintenance.

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report...

Name:Celina Guerreiro	O Man
Co	ntractor Signature:
MOT representative accepts the corrective action plan. responsibility to perform the services in accordance with Name:	
Date: October 20, 2020	me i oignataie.

INSTRUCTIONS:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



NCR #: AB20S-01

Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

<u>Service Area</u>: SA13 - Okanagan-Shuswap <u>Name of Contractor</u>: AIM Roads Inc.

Date: June 22, 2020 Prepared by: Aimee Barre

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Maintenance Specification - Surface Cleaning PM 1.07.2-1

Performance Criteria h) All other Highways, Travelled Lanes, Shoulders, Raised Hard Surfaced Infrastructure, intersections, adjacent to barrier, and pedestrian walkways by June 15

Accumulations were observed along Eagle Bay Rd, Torry Rd, Keane Rd, Ivy Rd, and Reid Rd through field observations and End Product Audit (refer to **Audit #20-21S** for additional information and photos).

SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES	Х	Deadline for correction: NA	
NO	_	MOT accepts the non-conforming product/s Reason:	ervice
N/A		Reason:	
Signatur	es up	on completion of required correction:	
Contrac	ctor re	presentative confirms correction complete.	Contractor Signature:
Date ac	cepte	ed by MOT: Click here to enter a date.	MOT Representative:

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: NA

4B) Root Cause Analysis: (Why did the non-conformance occur?)

The root-cause resulting in the non-conformity with the contractual requirements is due to a lack of understanding of new equipment operation processes by the field operator that resulted due to a lack of



Ministry of Transportation and Infrastructure

training from the foreman. AIM's internal training processes and associated plans for surface cleaning were not executed properly by the operations team.

Outside influences such as extreme rain events with excessive water volumes have resulted in surface runoff from adjacent gravel surfaces. This has resulted in a larger volume of gravel accumulation on the road surface than usual at this time of the year. AIM has underestimated the frequency required to maintain a clean road surface when undergoing extreme rain events in accordance with the June 15 due date.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AIM intends to implement proper training for all new equipment prior to commencing works moving forward through the generation of appropriate standard operating procedures and communication between foreman and operators. AIM plans to prevent the re-occurrence of the non-conformance moving forward by considering extreme weather conditions and the possibility of excessive rain regarding scheduling for road surface cleaning. AIM has planned to redo the surfacing cleaning as soon as possible to ensure safer road surface for all road users.

AIM is currently undergoing a large scale internal audit that will result in major process and performance to ensure compliance with the contractual requirements.

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report.

Contractor Signature:

Name: Celina Guerreiro

MOT representative accepts the corrective action plan. Acceptance does not negate the contractor's responsibility to perform the services in accordance with the contract requirements.

Aimee Barre

Date: June 26, 2020

MOTI Signature:

INSTRUCTIONS:

Name:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



DATE: (dd:mm:yyyy)	24-09-20	20		NCR #:	AB20S-02
ERVICE AREA:	SA13 Oka Shuswap	_		CONTRACTOR:	AIM Roads
REFERENCE AUDIT #:			20-25\$		
REFERENCE AUDIT TOPI	IC:	5.01 Sign	System Mai	ntenance	
ATE DISCUSSED WITH	мс:	24-09-20	20		
ECTION 2 : ATTENDA	ANCE REGIS	STER			
	NAME				TITLE
A	NAME imee Barre		-		nager, Roads
SECTION 3 : DESCRIP	TION OF NO	ON-CONFORI	MANCE		
Contractor failed to mee Highway Maintenance A ocations for each record oordinates, with no oth	et basic cont Agreements (d. Multiple ro ner identifyir	ract requirem May 26, 2020 ecords from J ng factors suc	nents as set o 0). Activity N uly 2020 and h as Landma	umber 501302 and 501 I August 2020 D3 repor rks.	Services Reporting Manual 1308 require site specific GP rts have identical GPS n site during Audit #20-25S.
contractor failed to mee lighway Maintenance A ocations for each record oordinates, with no oth ack of location specific	et basic cont Agreements (d. Multiple ro ner identifyir ity resulted i	ract requirem (May 26, 2020 ecords from J ng factors suc n inability to a	nents as set o 0). Activity N uly 2020 and h as Landma	umber 501302 and 501 I August 2020 D3 repor rks.	1308 require site specific GP rts have identical GPS
Contractor failed to mee lighway Maintenance A ocations for each record oordinates, with no oth	et basic control Agreements (d. Multiple rener identifying ity resulted in D CORRECT Ve to redo/co	ract requirem (May 26, 2020 ecords from J ng factors such n inability to a	nents as set of 0). Activity N uly 2020 and h as Landma accurately id	umber 501302 and 501 I August 2020 D3 repor rks. entify signs installed or	1308 require site specific GP rts have identical GPS n site during Audit #20-25S.

No	x	MoTI accepts the reasoning:	e non-conforming product,	service for the following	
N/A		Time and effort will be better utilized moving forward with improvements with reporting to meet compliance.			
	pon completion o	of required correction:			
Contractor reaccepted.	epresentative cor	firms correction complete	and the Ministry Represent	cative confirms correction is	
	Ministry Represe	ntative:	Contract	tor Representative:	
Name:		n/a	Name:	n/a	
Signature:			Signature :		
Date:			Date:		

SECTION 5: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

Deadline for submission of corrective action plan to MoTI:

November 6, 2020

Root Cause Analysis: (Why did the non-conformance occur?)

The root-cause resulting in the non-conformity with the contractual requirements regarding the Maintenance Services Reporting Manual - Highway Maintenance Agreements for GPS accuracy for signage is due to a technical error with the data entry in the field and the SmartRoads Program. Due to a new sign maintenance program and crew and the entry prompts in the software program used to document sign works, data was being missed when the forms were being created in the field. Errors with GPS locations was noted due to signs located in one area having multiple pieces of the sign being repaired resulting in multiple entries in one location without comment to determine which pieces of the sign were being replaced.

Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AIM's QHSE staff and Operations Team intends to work with the sign foreman and SmartRoads to ensure that the field form prompts for comment entry and the foreman knows the importance of entering comments when installing signs. The sign foreman's monthly submittal for Quantified work will also be utilized and compared with our SRs generated report to ensure that all duplicated locations have comments explaining the duplication.

Signatures upon completion of root cause analysis & corrective action plan:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the non-conformance identified within this report.

Contractor Representative:	
Name:	Signature :
Date:	
Ministry representative accepts the corrective action plan. A responsibility to perform the services in accordance with the	
Ministry Representative:	
Name: Aimee Barre	Signature :
Date: 2020/10/20	



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: KOD_W202021_NCR03

Service Area: SA08 - South Okanagan Name of Contractor: Click to choose MC

Date: November 19, 2020 Prepared by: Kylee O'Dell

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

During a major snow event on November 16, 2020, multiple classification of sides roads were documented by the area managers as exceeding the accumulations specification (PM3.01.2-1) in the Princeton Area. Roads reviewed included Highway 3 E and W, Highway 5A and Coalmont Road. Highway 3 ended up being closed for several hours.

ADDITIONAL INFORMATION REQUIRED IN RESPONSE:

- 1. Was all available equipment at Princeton yard in use during the storm? Was any equipment in the shop? Yes, 5 trucks were plowing all day. 3 trucks were in the shop getting repaired at the time. Two of the three had major re-build done this summer and were not 100% ready as per the mechanical dept so they were locked out. One is scheduled to be out Nov 30 and the other Dec 4th. The third was down for day to day mechanical repairs. The additional mechanics are definitely helping but are not trained in dealing with spreader controls, valve blocking for sander chains, underbodies, and wings and such. This takes time for any mechanic to learn the specialties of winter equipment.
- 2. Have cycle times for the Princeton area been completed and confirmation that sufficient equipment has been assigned to the yard? Yes, the cycle times for Princeton area have not changed.
- 3. When were subcontractors contacted? What contractors were used for during and post-event cleanup? Was assistance from the Keremeos yard considered/used for the E end of the foreman area? Arnica was called in at 2pm. They arrived late afternoon and worked the next day for the clean up. Keremeos had all their equipment in use so nothing was available to share during the day when snow was the heaviest. The Keremeos night shift plowed and sanded Hwy 3 east in the evening.
- 4. What coordination efforts were made with SA7 Maintenance Contractor/Ministry personnel when Highway 3 was closed? No SA7 contact. The road closure was posted on Drive BC and 13 point MVI was sent out by the CC.

SA07 and all other neighbouring contractors contact list have been supplied to the call center. The call center can now reach out on the foreman behalf and provide information directly to whoever is on the contact list.

All yards now have an additional foreman cell phone that all on shift foreman are to have with them so they can make and receive calls when they need to.

5. Was their enough material (salt/sand) available for response to this event? **Yes, 418 cubic** metres of salt and 6000 cubic metres of sand. SDAS material usage sheets attached.

SECTION 3: REQUIRED CORRECTION



Ministry of Transportation and Infrastructure

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed. YES Deadline for correction: November 27, 2020 NO MOT accepts the non-conforming product/service Reason: Reason: N/A Signatures upon completion of required correction: Contractor representative confirms correction complete. Contractor Signature: MOT Representative: ____Kylee O'Dell Date accepted by MOT: December 3, 2020 SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN 4A) Deadline for submission of corrective action plan to MOT: December 1, 2020 4B) Root Cause Analysis: (Why did the non-conformance occur?) Non-forecasted snowfall event took place on November 16th and AIM Roads had not called in auxiliary workers or subcontractors ahead of time. The forecasts were calling for rain and 2-3cm of snow. The snow was very heavy throughout the afternoon, which brought us out of the specification maximum accumulations in the Princeton area. Last minute calls for staff took time to arrive. A tractor-trailer spun out causing a road closure, which prevented our equipment from plowing the west end of Hwy 3 for a few hours. **4C)** Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?) Having the 3 trucks available from the shop will improve fleet resources in the future. Contacting adjacent service areas when road closures happen will take place from now on. Signatures: Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report. Name: Sharon Boyles Contractor Signature: ___ MOT representative accepts the corrective action plan. Acceptance does not negate the contractor's

responsibility to perform the services in accordance with the contract requirements.

Distribution: Original to District; Copy to Contractor

Name: Kylee O'Dell

MOTI Signature: KOD



Ministry of Transportation and Infrastructure

Date: December 3, 2020

INSTRUCTIONS: SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: DB_W202021_NCR01

Service Area: SA08 - South Okanagan Name of Contractor: Click to choose MC

Date: November 21, 2020 Prepared by: Denise Bollinger

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

<u>During a monitoring on November 21, 2020, Coalmont Road was found in non-conformance</u> of Winter Maintenance Specification:

PM3.01.2-4 Respond to allowable Compact conditions on Travelled Lanes at all times as follows: for Highway Classification C

b) remove pot-hole in compact exceeding 25mm depth and averaging more than 1 per 25 metres of highway within 48 hours.

A previous monitoring record, on November 19, 2020 showed the same pot-holes and a call was made that afternoon to inform the Superintendent of the Princeton Foreman Area, Rob Sanders. Rob responded by saying he would rectify the situation as soon as possible by sending out another truck.

On November 21, 2020, the same pot-holes had degraded. The depth of one was over 15cm and had eroded to over one lane width and was considered a dangerous situation for the travelling public, as well as further degradation of the gravel road base. A further call was made to Rob and he said it would be rectified in the next couple of days.

On both occasions of monitoring, November 19, 3:12 pm and November 21, 3:53 pm, texts, with photos of this situation attached, were sent to Rob, after the phone conversation.

Monitoring records, with photos available, upon request if required by MC.

SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES	Deadline for correction: November 30, 2020
NO	MOT accepts the non-conforming product/service
	Reason:
N/A	Reason:

Signatures upon completion of required correction:



Ministry of Transportation and Infrastructure

Contractor representative confirms correction complete.	Contractor Signature:
Date accepted by MOT:	MOT Representative:
SECTION 4: ROOT CAUSE ANALYSIS & CORRE	ECTIVE ACTION PLAN
4A) Deadline for submission of corrective action plan to M	IOT: November 30, 2020
4B) Root Cause Analysis: (Why did the non-conformance of The road surface was eroded by many freeze thaw cycle awarded to AIM Roads had not been previously grave are little to no gravel materials on the surface to reshad at night and melts during the day the existing material frozen sections would pop out creating further degraded delayed re-shaping. On November 16th there was a single equipment was busy clearing snow up until the 19th of AIM Roads hauled in 35 m3 of gravel to make repairs a conditions were more favourable. This repair is temporable. To prevent this from happening in the future minus crush in the summer of 2021.	cles this fall. The existing road when alled and maintained for many years. There ape when grading. When the road freezes I becomes too saturated to reshape and dation. Knowing this, the senior foreman nowfall that saturated the road. Our f November as well. The vent re-occurrence of the non-conformance?) to Coalmont Road on November 23rd when orary as frozen grade does not compact
Signatures: Contractor representative commits to implementing the cintended to prevent the re-occurrence of the Non-conform	
Name:Sharon Boyles Cont	tractor Signature:
MOT representative accepts the corrective action plan. A responsibility to perform the services in accordance with	
Name:	MOTI Signature:
Date:	
INSTRUCTIONS: SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT	

Distribution: Original to District; Copy to Contractor

SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: KOD_W202021_NCR01

Service Area: SA08 - South Okanagan Name of Contractor: Click to choose MC

Date: October 26, 2020 Prepared by: Kylee O'Dell (on behalf of Denise Bollinger)

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

During a snow event on October 23, 2020, multiple classification of sides roads were documented by the auxiliary area manager, Denise Bollinger, as exceeding the accumulations specification (PM3.01.2-1) in the Penticton Area. Roads reviewed included Apex Mountain Road and other Apex resort area roads.

Monitoring records with photos available upon request if required by MC.

SECTION 3: REQUIRED CORRECTION

S

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.					
YES		Deadline for correction:			
NO		MOT accepts the non-conforming product/s	service		
		Reason:			
N/A	Х	Reason: Correction completed based on fie	eld observation.		
ignatur	gnatures upon completion of required correction:				
Contrac	tor re	presentative confirms correction complete.	Contractor Signature:		
Date ac	Date accepted by MOT: November 10, 2020 MOT Representative: Kylee O'Dell				

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: October 30, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)



Ministry of Transportation and Infrastructure

Oct 23, 2020 was forecast for 5-10cm of snow in the Penticton area. We had 20cm by noon. Our plow truck broke down on Apex Mtn early in the morning. All trucks were deployed on the other Class A roads and Sr. Foreman knew that a grader was needed for the steep incline of Apex Mtn. Rd. A grader operator was not available until 2pm. Winter shifts had not started for this unprecedented early storm. AIM QA Supervisor wrote an internal non-conformance for the snow accumulations on Apex Mtn Rd.

Taken from Global news:

A 120-year-old record for most snowfall on an October day has been broken in Kelowna.

The previous record was 12.7 cm in 1899, according to Environment Canada.

Kelowna is currently sitting at around 13 cm of snowfall for the day.

And in Penticton, the South Okanagan city matched a 95 year-old record at 11 cm of snowfall.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

Operations held a storm debrief on Monday Oct.26 with all Sr. Foremen and QA staff to discuss how to deal with early snow season starts. Considerations for winter preparation of equipment earlier and have more resources available next Fall. Historically, winter shifts start at the end of October. Although this storm was not expected to be so intense and could not have been predicted by AIM management, more planning of auxiliaries on standby for storms when winter shifts are not in place will be carried out in the future.

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report					
Name:Sharon Boyles	Contractor Signature:				
MOT representative accepts the corrective action pl responsibility to perform the services in accordance	1 0				
Name:Kylee O'Dell	MOTI Signature:KOD				
Date: October 30, 2020					

INSTRUCTIONS:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: KOD_W202021_NCR02

Service Area: SA08 - South Okanagan Name of Contractor: Click to choose MC

Date: October 26, 2020 Prepared by: Kylee O'Dell (on behalf of Denise Bollinger)

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

During a snow event on October 23, 2020, Green Mountain Road was documented by the auxiliary area manager, Denise Bollinger, as exceeding the snow and ice bonding control specification (PM3.02.2-3) in the Keremeos and Penticton Foreman Areas.

Monitoring records with photos available upon request if required by MC.

SECTION 3: REQUIRED CORRECTION

Does C	ontract	tor have to re-do/do the work? Select N/A if non-co	onformance is not curable or opportunity to rectify has passed.
YES		Deadline for correction:	
NO		MOT accepts the non-conforming product/s	service
		Reason:	
N/A	X	Reason: Correction completed based on fie	eld observation.
Signatu	res up	on completion of required correction:	
Contra	ctor re	epresentative confirms correction complete.	Contractor Signature:
Date a	ccepte	ed by MOT: November 10, 2020	MOT Representative:Kylee O'Dell

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: October 30, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)



Ministry of Transportation and Infrastructure

Oct 23, 2020 was forecast for 5-10cm of snow in the Penticton area. We had 20cm by noon and it continued to snow until Oct.24th. AIM had equipment breakdown in the morning that was assigned to Green Mountain and Apex Mountain Roads. In the afternoon a plow and grader cleaned off and salted/sanded Green Mountain Road. A quality inspection was carried out at 2:15pm which shows the road within the specifications. The spec referenced is below.

PM3.02.2-3

Restore traction on Travelled Lanes immediately, when Slippery conditions occur outside of a Weather Event.

Would you please provide clarification on how AIM was not meeting this specification on October 23rd during a major storm event that continued until October 24th. Once the equipment was repaired it was deployed and snow clearing continued all weekend. Many tonnes of salt and sand were placed on Green Mountain Road as well.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?) AIM Roads will continue to prepare equipment for the winter season and has purchased additional plow trucks that are arriving in November and December. This will allow us to have backup equipment more readily available for this winter season. Winter shifts have started so our staff resources has improved since this early winter event.

Signatures: Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report					
Name:	Contractor Signature:				
MOT representative accepts the corrective action plan. Acceptance does not negate the contractor's responsibility to perform the services in accordance with the contract requirements.					
Name:Kylee O'Dell	MOTI Signature:	KOD			
Date:					
INSTRUCTIONS:					

Distribution: Original to District; Copy to Contractor

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: SL W202021 NCR01

Service Area: SA08 - South Okanagan Name of Contractor: AIM Roads

Date: October 26, 2020 Prepared by: Scott Lain

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

During snow event on October 23, 2020 the contractor exceeded maximum allowable accumulations as per maintenance specification PM3.01.2-1/b & c. and SA 08 Local Area Specification 1.14.2-1 for Highway 97C and 97D. Monitoring records and photos available upon request if required by the MC.

SECTION 3: REQUIRED CORRECTION

YES	Χ	Deadline for correction: Immediate		
NO		MOT accepts the non-conforming product/s Reason:	service	
N/A		Reason:		
Signatur	res up	on completion of required correction:		
Contra	ctor re	epresentative confirms correction complete.	Contractor Signature:	
Date a	ccepte	ed by MOT: November 9, 2020	MOT Representative:	Scott Lain

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: October 30, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)

On October 23, 2020 Highway 97C and 97D experienced record breaking amounts of snowfall with over 50cm recorded at the Pennask Summit. As there was 15-20cm of snow forecasted, AIM Roads was not anticipating the intensity of this storm and had less equipment available at this time. We had



Ministry of Transportation and Infrastructure

not moved into winter shifts as this was planned for the end of October. During the morning our resources were maintaining the highway within specifications. QA inspections show lanes within the 4cm tolerance. In the early afternoon there were several vehicles spinning on the hills in the winter conditions as trucks did not chain up at the pullouts and smaller vehicles did not have sufficient tires. This caused our plow trucks delays in the worse part of the storm accumulations and put the highway out of spec.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?) AIM Roads will have more spare equipment available and auxiliary staff on call for storms in the future. We have purchased more plow trucks to join the fleet in November and December. Management has to ensure extra resources of operators and mechanics are available during storm events in case of higher than expected snow accumulations and equipment breakdowns.

AIM would also suggest making the chain up rules mandatory on Highway 97C and 97D to reduce the truck stoppages in hazardous winter conditions.

Signatures: Contractor representative commits to implementing intended to prevent the re-occurrence of the Non-occurrence of the No	g the corrective action plan and confirms that the plan is conformance identified in section 2 of this report.
Name:	Contractor Signature:
MOT representative accepts the corrective action presponsibility to perform the services in accordance	plan. Acceptance does not negate the contractor's e with the contract requirements.
Name:Scott Lain	MOTI Signature:
Date: November 9, 2020	

INSTRUCTIONS:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure




AUDIT REPORT

ECHON 1: AUDII	ar war and a second				-		SHORT RESPONSE T
ECTION I : AUDIT	DETAILS		100				
DATE: (yyyy-mm-del)		2020-09-1	5	AUDIT REPORT #:	20-1	1S	
AUDIT TYPE:	Field Sho	ort Response Time		AUDITOR:	Chad N	farsh	
SERVICE AREA:	SA 13]	CONTRACTOR NAME.	AIMR	oads	
INITIAL INSPECTION:	13:08	(hh:mm)		ROAD TYPE:	20km H	ghway	1
FOLLOW UP INSPECTION:	24-Sep-20						
	(mmm:dd)	(hh mm)		HIGHWAY#	East Vernon and Hwy	5	1
HIGHWAY NAME: East Vernon and Hwy 6		6		SEGMENT #	East Vernon Rd and H	wy 6 15st to Noble C	4
HIGHWAY CLASS: East Vernon class 4 and Hwy 6 class 1		d Hwy 6 class 1		if collecting mul	tiple roads place names nu	nhers in hox to right	
ROAD & WEATHER CONDI	TIONS:	Bare and Dry					
ECTION 2 : ROAD	OBSERVATIO:	VS.		No contracts			
	Maintenance Observed		KM	1st Phase	Obervations	Response Time	Comments/Phase 2 Observations
PM5.01.2-1	The state of the s		0.1		ernon Int. 30km/hr brushin		no change
PM5.01.2-1			0.2	W54 at BX Creek Jeanin		Id	no change
PM5.01.2-1			0.4	50km/hr sign brushing		1d	no change
PM1.03.3-2			0.5	Shoulder Drop		6d	no change
PM1.01.2-1			1	Potholes at Haynes Rd In		3d	no change
PM1.03.3-2			1.3	Shoulder Drop		6d	no change
PM5.01.2-1			1.3	Missing Chevron		1d	no change
PM5.01.2-1			1.4	Slow Sign brushing		ld	no change
PM1.03.3-2			1.9	Shoulder Drop		6d	no change
PM1.03.3-2	111-111-111		2.8	Shoulder Drop		6d	no change
PM1.03.3-2			3.6	Shoulder Drop		3d	no change
PM5.01.2-1			5	Neighbor Hood Watch Si	gn Brushing on Mountview	at 7d	no change
From Moutview Rd to Silver	star Rd						
PM5.01.2-1			0.3	Stop sign with sticker		1d	no change
PM5.01.2-1			1.5	Short Stop Sign in Ditch	line	ld	no change
PM5.01.2-1			1.8	East Vernon and Welker	Rd sign beni	1d	no change
PM1.03.3-2			2.1	Shoulder Drop	41.5	6d	no change
PM5.01.2-1 PM1.03.3-2			2.5	Fadded Curve Sign and b Shoulder Drop	rustility	1d	no change
PM5.01.2-1			3.7	30km/hr sign brushing		6d 1d	no change
PM5.01.2-1			5.2	Chevron Missing		1d	no change
Hwy 6 starting at 15th Street	poing East		2.6	Chryson bussing		10	no change
Not an SRT stem but noted as a			0.2	Mowing/brushing should sign visibility	er, may soon cause issues w	ith n/a	no change
PM1,10.2-2			111	Disconnected Bull nose		3d	no change
PM1.07			113.1	Hwy 6 and Hill Dr. Island	not swept	Immediately	no change
Noble Canyon Rd to 15th Str	eet Vernon going West						
M5.01.2-1			12.8	Brushing Do Not Pass Pla	ow sign	14	no change
Not an SRT item but noted as a	potential issue		13.4-14.0	Brushing (may soon cause with ice forming in winter	e site line and shading issue r)	s n/a	no change



Ministry of Transportation and Infrastructure



SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: November 9, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)

The above NCR resulted from multiple Short Response Time Audits conducted throughout Sept 2020 (20-09s,20-12s,20-11s) demonstrated a non-compliance with the specifications PM5.01.2-1 regarding signs. The root-cause resulting in the non-conformity with the contractual requirements is due to a failure of following and executing AIM internal processes outlined in the LAOP and QMS manual for performing short time response (more specifically Work IDs) in regards to identification and replace/repair of signs and other short response time items. The work performed did not meet the specifications for SRT and safety concerns due to, but not limited to, a misunderstanding for properly recording Work IDs for short response time items that require repair or replacement, properly



Ministry of Transportation and Infrastructure

documenting the priority of the SRT within our tracking system and improper planning or improper prioritizing of the safety concerns related to signs and other short time response items.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

The QHSE Team will work closely with the Operations Team within AIM to aid the operations staff to Work ID SRT items (signs) identified that require replacement and/or repair. Over the winter months, during times of moderate weather, training will be ongoing regarding SRs and proper identifications. The foreman of the above listed items will be scheduling the repairs of the identified list as soon as possible by high to low safety risk. Extreme weather may impede on the scheduling of the above repairs due to winter works taking priority in weather events.

AIM plans to prevent the re-occurrence of the non-conformance moving forward by increasing SRT training and education to all foreman and field staff. Organizing and readjusting the current Work ID process is required to ensure it is user friendly and easily done in the field.

AIM is currently undergoing a large scale internal audit that will result in major process and performance to ensure compliance with the contractual requirements. Further changes to the system will occur as errors in the process are identified and adjusted."

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report...

Name:Celina Guerreiro	1 thin
	Contractor Signature:
MOT representative accepts the corrective a responsibility to perform the services in acceptance.	action plan. Acceptance does not negate the contractor's ordance with the contract requirements.
Name:	MOTI Signature:
Date: October 23, 2020	
NSTRUCTIONS:	

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: 2020S-04____

Service Area: SA13 - Okanagan-Shuswap

Name of Contractor: AIM Roads

Date: July 9, 2020

N/A

Prepared by: Peter Cocker

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Maintenance Specification 1.01 "to provide a smooth, stable, sealed surface of highway and bicycle/pedestrian paths".

Performance Criteria – construct temporary patches consistent with the profile and crossfall of the adjacent surfaces as per table PM1.01.2-1

Non-conformance with timeframes set out in table PM1.01.2-1 on Class 2,4,5,6 roads identified in Audit 20-08S

SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES x Deadline for correction: July 13, 2020

NO MOT accepts the non-conforming product/service

Reason:

Signatures upon completion of required correction: Temporary Patching must be completed by July 13th 2020.

Contractor Signature:

Contractor representative confirms correction complete.

Date accepted by MOT: Click here to enter a date.

MOT Representative: _PC_____

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: July 17, 2020



Ministry of Transportation and Infrastructure

4B) Root Cause Analysis: (Why did the non-conformance occur?)

The root-cause resulting in the non-conformity with the contractual requirements is due to a lack of material and planning for repair and maintenance of the identified areas by the operations team. AIM's internal training processes and associated plans for temporary patching were not executed within a timely matter according to the specifications due to a shortage of auxiliary personnel to conduct road repairs and a shortage of material (cold mix) supplied by the supplier.

The delamination of the road surface (specifically 97B) has resulted in a higher volume and higher frequency of road maintenance repairs. The extreme weather and high volumes of water has resulted in erosion and unusual wear on the road surface, increasing the rate of delamination and potholes. AIM has underestimated the frequency required to maintain the above mentioned specification.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AIM intends to implement hot mix (that has been recently approved by MOTI) to aid in increasing the frequency and time that potholes remain unrepaired in order to meet specification timeframes. Pothole patching is scheduled for the last week of July. An increase in auxiliary personnel is being considered in order to manage the large volume of road surface maintenance issues. AIM plans to prevent the reoccurrence of the non-conformance moving forward by considering extreme weather conditions and the possibility of excessive rain contributing to a increase in road surface maintenance.

AIM is currently undergoing a large scale internal audit that will result in major process and performance to ensure compliance with the contractual requirements.

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report...

Name: Celina Guerreiro

Name: Veter Cocked

Contractor Signature:

MOTI Signature:

MOT representative accepts the corrective action plan. Acceptance does not negate the contractor's responsibility to perform the services in accordance with the contract requirements,

Date: July 17, 2020

INSTRUCTIONS:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT



AUDIT REPORT

TASK

		20-055
10:30am		
15A 13	CONTRACTO	R: AIM Roads
Bridge Insp	ections	
Road Patrol	5	
		SA 13 CONTRACTOR Bridge Inspections Road Patrols

SECTION 2 : ATTENDANCE REGISTER

TITLE:		
BRIDGE AREA MANAGER		
Bridge Operations Super.		
axality Environmental Supervisor		

SECTION 3: RECORDS REVIEW / FINDINGS

QUESTION #1:

- 1)Does the contractor do all required structure inspections as per PM7.03.2-3? (a-k)
- ·I would like to see bridge inspections
- ·Quality Control records for inspections
- •Examples of inspections (I will randomly choose when we meet)
- ·Any evidence to support your answer to the question
- 2) Has the contractor completed all structure inspections as per PM7.03.3? (a-d)
- ·I would like to see the tracking for this
- ·Any Quality Control records for this activity
- Examples (I will randomly choose when we meet)
- Any evidence to support your answer to the question
- 3)Does the contractor complete safety patrols at the continuous frequencies listed in PM7.04.2-2.
- ·I will randomly pick two roads from each summer class and a timeframe that would encompass that patrol period
- ·Quality Control records
- ·Any evidence to support your answer to the question

EVIDENCE:

QUESTION #1:

The contractor is compliant

Random Bridge Inspections pulled for Structure numbers: 06049, 04517R, 08169 and 00824

- inspections for these structures were all completed within appropriate time frames

Quality Control for completed tasks showed inspections completed within time frames:

- QM11-SA13-2020-000272, 000783, 005545, 004434, 003501

QUESTION #2:

The contractor is compliant

a) Inspections are still on paper. Random Examples of First Year Inspections provided for Structure Numbers 06802, 06057, 6502. All completed

Internal Audit PM7.03 Feb 13, 2020 Highway Patrol

b) Sturctures completed by Certified Bridgeman or Bridge Engineer

Rick, Steve or Rod

- -QM07-SA13-2020-019 OFI to transition Bridge Crew to SmartRoads
- c)Minimally using as the inspections are on paper and time consuming to use to go back and plan from however the bridge crew is transitioning to the SmartRoad system
- d) Internal OFI issued for Invasive Species QM-SA13-2020-000020 will be adding invasive species to SmartRoads Bridge inspection form

OUESTION #3:

The contractor is NOT compliant

The contractor was able to provide SmartRoads GPS reports for Class 1-5 roads showing that these roads had been patrolled in the appropriate time frames. The Contractor was not able to provide evidence that Class 6 or 7 roads had been patrolled.

AUDIT FINDINGS:

The Contractor was not compliant. No evidence provided that Class 6 or 7 roads have been patrolled within the appropriate time frames.

Note that during the next Joint Operations Meetings there should be a discussion on the definition of a Patrol Vehicle and what that vehicle needs to meet the requirements of a patrol vehicle

SECTION 4: AUDIT SUMMARY/FOLLOW UP

WAS THE CONTRACTOR IN CONF	FORMANCE?	NO	WAS A NCR/OFI ISSUED?	YES
IS A FOLLOW-UP NEEDED?	YES		if "yes" fill out Section	5 below

IF YES, WHAT FOR?

The Contractor was not able to provide evidence that Summer Class 6 or 7 roads have been patrolled or met patrol frequencies as noted in PM7.04.2-2 a)

SECTION 5: NCR/OFI SUMMARY

MAINTENANCE SPEC FOR NCR/OFI	NCR /	NCR/OFI#	DATE ISSUED	COMMENTS
PM7.04.2-22	Yes	CM 20205-01	Oct 5,2020	
,				



SECTION 1 : T	TRACKING DETAILS	3	
Date Issued:	2020-10-05	NCR Number:	CM2020S-06
		Issued By:	Chad Marsh
Service Area:	SA 13	Contractor Name:	AJM Roads
SECTION 2 : D	DESCRIPTION OF NO	ON-CONFORMANC	E
What is being assesse	ed?:		
Road Patrols as per sp	pecification PM7.04.2-2 a)		
Findings:			
The Contractor was n	ot compliant, unable to show evid	dence that patrol times have been	en met on Class 6 and 7 roads.
Evidence/Records Re SmartRoads gps track			
SECTION 3 : F	REQUIRED CORREC	TION	
Does Contractor hav	e to re-do/do the work? Select N	/A if non-conformance is not o	curable or opportunity to rectify has passed
		r correction: ots the non-conforming product	/service
1	N/A X Reason:	This activity	cannot be retroactivly redone.
Signatures upon con	apletion of required correction:		
Contractor respresent	ative confirms correction comple	te Contractor Representat	tive:
Date accepted by Mo	ті:	MoTI Representative	e:
SECTION 4 : F	ROOT CAUSE ANAL	YSIS & CORRECTI	VE ACTION PLAN
	mission of corrective plan to Mol		-Oct-20
	lysis (Why did the non-conformar n Plan: (How will the contractor p		n-conformance?)
SECTION 5 : S		WEST MADE	
	ntive commits to implementing the n-conformance identified in section		nfirms that the plan is intended to prevent the re-
1	Name:	Contractor Signature	e:
services in accordance	e with the contract requirements.		he contractor's responsibility to perform the
1	Name:	MoTI Signature:	1-



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: 2020S-01____

Service Area: SA13 - Okanagan-Shuswap

Name of Contractor: AIM Roads

Date: June 17, 2020

Prepared by: Peter Cocker

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Maintenance Specification 5.01.2 "Maintain Sign System so they are clean, repaired, legible, visible, erect and properly placed.

Performance Criteria a) Regulatory and Warning Signs (Class 1&2 highway) = 1D

Non-conformance with sight lines to Regulatory 50km/h sign at the north end of Grindrod (97a),70km/h Warning sign 4.2 km north of Grindrod (97a), and Warning sign 200m north of 34th Ave (97b)

SECTION 3: REQUIRED CORRECTION

Does Co	ontract	or have to re-do/do the work? Select N/A if non-co	nformance is not curable or opportunity to rectify has passed.
YES	x	Deadline for correction: June 20, 2020	
NO	(MOT accepts the non-conforming product/s Reason:	ervice
N/A		Reason:	
Signatur	es up	on completion of required correction: Correct	ion completed June 25, 2020
Contrac	ctor re	presentative confirms correction complete.	Contractor Signature:
Date ac	ccepte	ed by MOT: June 25, 2020	MOT Representative: _PC

SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: July 10, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)



Ministry of Transportation and Infrastructure

The root-cause resulting in the non-conformances with the contractual requirements listed above (Section 2) are due to a failure of following and executing AIM internal processes outlined in the Quality Maintenance Manual (QMS) and the Operations Maintenance Manual (OMM). These include but are not limited to communication and tracking failures within AIM's operations team for identified works on signs requiring repair or maintenance, an absence of document referral for steps in completing duties and conducting required repairs to signs, a shortage of personal specifically delegated to sign maintenance and repair, a lack of training within all departments of AIM standard operating procedures, specifically routine maintenance services and delay in repairing and maintaining signs according to the specification timeframes.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AIM plans to prevent the re-occurrence of the above non-conformances moving forward from implementing a series of changes to aid in improving the effectiveness and support in conducting existing and new internal processes. All AIM employees who will be conducting sign inspections will be provided the proper training through orientation of sign specifications and tracking requirements in order to identify and repairs signs within the specification timeframes (including brushing, cleaning, straightening and replacement). Hiring of specific personnel (including a senior foreman and 2 field personnel for sign identification) and tracking has been conducted for SA 13 (specifically SA 13 south) and will aid in improving all over tracking and repair of sign maintenance and aid in providing appropriate support for executing all proposed plans and the QMS. The operations team has implemented a specific schedule for the sign team that allows for proper sign identification coverage and prioritization by HWY classification. The QMS, alongside other AIM documentation and processes will be updated and adjusted to be reflect internal team additions and changes for more efficient and standardized processes. Due to the large volume of signs that require repairs, AIM is working closely with MOTI to produce a long-term plan in repairing all the signs that our out of specification for the duration of the contract based on HWY classification and priority.

AIM has conducted the required repairs and responded to MOTI after completion on June 25, 2020.

AIM is currently undergoing a large scale internal audit that will result in major process and performance to ensure compliance with the contractual requirements.

Date: July 6, 2020

Signatures:



Ministry of Transportation and Infrastructure

INSTRUCTIONS: SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

NCR #: AO20S-04

Service Area: SA13 - Okanagan-Shuswap

Name of Contractor: AIM Roads Inc

Date: June 24, 2020

Prepared by: Alex O'Brien

SECTION 2: DESCRIPTION OF NON-CONFORMANCE


Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

Surface Cleaning timeline has not been met under PM1.07.2-1g). Some sections of Class 1 and 2 Highways have still not been swept to provide safe, clean surface conditions, and facilitate free drainage. This timeline of May 15 was not met across the Service Area. The contractor has written an internal Non-Conformance report, though this is a repeat NCR from Year 1 of the Contract. All outstanding sweeping on Class 1 and 2 Highways is to be corrected per Section 3 of this NCR.

Pavement markings have been obscured for far more than 7 days coming just West of Lumby due to Accumulations on Hwy 6 in the Armstrong Foreman area. The contractor is also found to be non-conforming under PM1.07.2-1c). Under 1.07.4a) the coordination of surface sweeping was not done with the pavement marking contractor, and some sections were not properly painted as a result. One section is depicted below.



Hwy 6 Lumby West- pavement marking obsured and not coordinated with pavement marking contractor



The contractor is also found to be non-conforming under PM1.07.-2 b) as the roadside barrier run just East of Dure Meadows Rd on Hwy 6 within the Armstrong foreman area. This has caused ponding after rainfall. When the white pavement marking was done in this area, a pond was forms at the bottom of the photo and it can be seen that this section was not painted. PM1.07.2-3 stipulating all drainage holes, scuppers, and barrier openings are to be cleaned annual has not been met in this area. The barrier run pictured below for instance has been blocked for over a year and free drainage has been impeded.



Hwy 6 East of Dure Meadows Rd- Drainage barrier blocked

SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES	X	Deadline for correction: July 1, 2020 MOT accepts the non-conforming product/s Reason:	ervice
N/A		Reason:	
_		oon completion of required correction: epresentative confirms correction complete.	Contractor Signature:
Date a	ccent	ed by MOT: Click here to enter a date	MOT Representative:



SECTION 4: ROOT CAUSE ANALYSIS & CORRECTIVE ACTION PLAN

4A) Deadline for submission of corrective action plan to MOT: July 1, 2020

4B) Root Cause Analysis: (Why did the non-conformance occur?)

The root-cause resulting in the non-conformances with the contractual requirements listed above (Section 3) are due to a failure of following and executing AIM internal processes outlined in the Quality Maintenance Manual (QMS) and unpredicted increased frequency of road maintenance due to extreme weather events. These include but are not limited to a lack of communication and guidance from the AIM internal mechanical division, an absence of document referral for steps in completing duties, a lack of training within all departments of AIM standard operating procedures, specifically routine maintenance services and delay in executing the proposed spring road maintenance services plan. The regional area has also undergone extreme weather condition with above average water volumes resulting in increased accumulation of sediment and runoff drainage holes, scuppers, and barrier openings. The extreme rainfall has also contributed in delayed sweeping efforts due to unable to sweep in high water volume road conditions. This has resulted in a frequency demand for sweeping and cleaning that was not included or predicted in the spring road maintenance services plan. The frequency of demand for sweeping and cleaning has resulted unpredicted in increased personnel and rescheduling of priority work which has contributed in the non-conformances listed above (Section 3). AIM will continue to coordinate and communicate with the contractor to ensure all line painting requirements are met within the specifications.

4C) Corrective Action Plan: (How will the contractor prevent re-occurrence of the non-conformance?)

AIM plans to prevent the re-occurrence of the above non-conformances moving forward from implementing a series of changes to aid in improving the effectiveness and support in conducting existing and new internal processes. All AIM employees will be provided the proper training through orientation and process specific standard operating procedures. Changes within the mechanical operations team have been made, which will aid in providing appropriate support for executing all proposed plans and the QMS. The QMS, alongside other AIM documentation and processes will be updated and adjusted to be reflect internal team additions and changes for more efficient and standardized processes. AIM will consider extreme rainfall events as part of their scheduling for road maintenance moving forward and adjusting their frequency and capacity to adjust to any weather events. AIM will ensure that the winter shift will remain on next year until the sweeping program and will allow for the operator to sweep for a full 24 hour period. AIM's operations team has scheduled the above surface cleaning to be completed as soon as possible.

AIM is currently undergoing a large scale internal audit that will result in major process and performance to ensure compliance with the contractual requirements.

Signatures:

Contractor representative commits to implementing the corrective action plan and confirms that the plan is intended to prevent the re-occurrence of the Non-conformance identified in section 2 of this report.



Ministry of Transportation and Infrastructure

Name: Celina Guerreiro

Contractor Signature: ____

MOT representative accepts the corrective action plan. Acceptance does not negate the contractor's responsibility to perform the services in accordance with the contract requirements.

MOTI Signature: Z

Date: July 1, 2020

INSTRUCTIONS:

SECTION 1, 2 AND 3 TO BE COMPLETED BY MOT SECTION 4 TO BE COMPLETED BY THE CONTRACTOR



	DETAILS			
TE: (dd:mm:yyyy)	13/11/2020		NCR #:	MS-20W-01
FRVICE AREA:	S.A.13		CONTRACTOR:	AIM Roads
FFERENCE AUDIT #:				
FERENCE AUDIT TOPIC:				
ATE DISCUSSED WITH MC	: 17/1	1/2020		
ECTION 2 : ATTENDANG	CE REGISTER			
	NAME			TITLE
	Mike Scott		Distr	rict Ops. Tech.
	ON OF NON-CONFORMAN			
··· NI	TI monitoring reports show	w the followin	g class C and D roads to be	e out of spec. for maximum winte
ccumulations. • # 842 Grandview Pl				
# 842 Grandview Pl# 904 Duncan Road	d class D – 20 cm			
ccumulations. # 842 Grandview Pl # 904 Duncan Road # 896 Parkview Place	d class D – 20 cm			
 # 842 Grandview Plant # 904 Duncan Road # 896 Parkview Plant # 124 Six Mile Cree # 415 Westshores F 	d class D – 20 cm ce class D – 24 cm ek Road class C – 24 cm Road class C – 15 cm			
 # 842 Grandview Pl # 904 Duncan Road # 896 Parkview Place # 124 Six Mile Cree # 415 Westshores F # 64 Irish Creek Road 	d class D – 20 cm ce class D – 24 cm ek Road class C – 24 cm Road class C – 15 cm ad class D – 18 cm			
 # 842 Grandview Pl # 904 Duncan Road # 896 Parkview Place # 124 Six Mile Cree # 415 Westshores F # 64 Irish Creek Road 	d class D – 20 cm ce class D – 24 cm ek Road class C – 24 cm Road class C – 15 cm			
 # 842 Grandview Pl # 904 Duncan Road # 896 Parkview Place # 124 Six Mile Cree # 415 Westshores F # 64 Irish Creek Road 	d class D – 20 cm ce class D – 24 cm ek Road class C – 24 cm Road class C – 15 cm ad class D – 18 cm			
 # 842 Grandview Pl # 904 Duncan Road # 896 Parkview Place # 124 Six Mile Cree # 415 Westshores F # 64 Irish Creek Road 	d class D – 20 cm ce class D – 24 cm ek Road class C – 24 cm Road class C – 15 cm ad class D – 18 cm			

3.01.2 Routine Maintenance Services

PM3.01.2-1 Remove Winter Accumulations from Travelled Lanes as follows:

Performance Criteria		Maximum Winter Accumulations Response by Highway Classification					
		A	В	C	D	E	
a)	One lane each direction	4 cm	6 cm	10 cm	15 cm	25 cm	
6)	Second lane	8 cm	10 cm	n/a	n/a	n/a	
c)	All other lanes including brake checks, chain up/off areas and any other vehicle accessible portions within the Right-of- Way	12 cm	16 cm	20 cm	20 cm	n/a	
d)	Rest Areas, pull-outs and parking areas at a minimum 2.5 metre pass width	12 cm	16 cm	20 cm	20 cm	n/a	

SECTION 4	: REOUIRED	CORRECTION
	. ILLQ CIILLD	

N/A

has passed.			
Yes		Dead line for correction):
No		MoTI accepts the non-	onforming product/service for the following reasoning:
N/A	X	Reasoning:	Roads have been plowed

Does the Contractor have to redo/complete the work? Select N/A if non-conformance is not curable or opportunity to rectify

Signatures upon completion of required correction:

Contractor representative confirms correction complete and the Ministry Representative confirms correction is accepted.

Reasoning:

iviinistry kepresentative:			Contractor Representative:			
Name:			Name:			

Signature:	Signature:
Date:	Date:
SECTION 5 : ROOT CAUSE ANALYSIS & CORRECTIVE ACTION	N PLAN
Deadline for submission of corrective action plan to MoTI:	27/11/2020
Root Cause Analysis: (Why did the non-conformance occur?)	
Corrective Action Plan: (How will the contractor prevent re-occurr	ence of the non-conformance?)
Signatures upon completion of root cause analysis & corrective a	ction plan:
Contractor representative commits to implementing the corrective the re-occurrence of the non-conformance identified within this re-	
Contractor Representative:	
Name:	Signature:
Date:	
Ministry representative accepts the corrective action plan. Accepts perform the services in accordance with the contract requirement.	
Ministry Representative:	
Name:	Cinnaturo
	Signature:



NCR #: AO20S-03

Ministry of Transportation and Infrastructure

SECTION 1: TRACKING DETAILS

<u>Service Area</u>: SA13 - Okanagan-Shuswap <u>Name of Contractor</u>: AIM Roads Inc

Date: June 19, 2020 Prepared by: Alex O'Brien

SECTION 2: DESCRIPTION OF NON-CONFORMANCE

Quote the contractual requirement which is not being met and/or the relevant section of the QMS. Also quote location of non-conformance, e.g., highway number, foreman area, when applicable

Trinity Valley Rd #130 is a Class 4 road that spans both the Cherryville and Armstrong foreman areas. The road was found to be in an acceptable condition on the Lumby (Cherryville yard) end, with minor infrequent potholes on the gravel portion. The Enderby (Armstrong yard) end was in a deplorable state, with frequent, high severity potholes that presented serious safety issues for road users.

The potholes averaged far more than 1 per 25 metres, and they spanned across the road width on many sections for well over 2 days. The response time for a Class 4 gravel road in this condition is 2 days to provide a safe, smooth, stable, compacted and free draining surface. MoTI was given a low level of confidence the road would be graded anytime in the near future due to the grader needing to be on other roads in the large Armstrong foreman area.







SECTION 3: REQUIRED CORRECTION

Does Contractor have to re-do/do the work? Select N/A if non-conformance is not curable or opportunity to rectify has passed.

YES X Deadline for correction: June 20, 2020

NO MOT accepts the non-conforming product/service Reason:

N/A Reason:



Ministry of Transportation and Infrastructure

Signatures upon completion of required correction:	
Contractor representative confirms correction complete.	Contractor Signature:
Date accepted by MOT:	MOT Representative:
SECTION 4: ROOT CAUSE ANALYSIS & CORRE	CTIVE ACTION PLAN
4A) Deadline for submission of corrective action plan to M	OT: June 26, 2020
4B) Root Cause Analysis: (Why did the non-conformance of	ccur?)
4C) Corrective Action Plan: (How will the contractor prev	ent re-occurrence of the non-conformance?)
Signatures:	
Contractor representative commits to implementing the contractor representative contractor represent	
Name: Cont	ractor Signature:
MOT representative accepts the corrective action plan. A responsibility to perform the services in accordance with	
Name:	MOTI Signature:
Date:	
INSTRUCTIONS:	

Distribution: Original to District; Copy to Contractor

SECTION 4 TO BE COMPLETED BY THE CONTRACTOR