PROVINCE OF BRITISH COLUMBIA Ministry of Community, Aboriginal and Women's Services Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DKI 2009 06 17 05 01

Location of Incident:

245 3RD STREET KITHMAT BC V8C 2N8

s.21

of Occupants (At time of fire): 0

of Injured: 0

of Deaths: 0

Total Dollar Loss Estimate:

s.21

Related to Wildland Interface Fire: NO

Property Value:

Content Value:

s.21

Total Value at Risk:

s.21

Code Name:

Code Description

PROPERTY COMPLEX: 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION: 6330 BASIC METAL PRODUCTS MANUFACTURE - INCLUDES TRANSFORMATION

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 3000 501 TO 1000M2 (5383 - 10764FT2)

YEAR OF CONSTRUCTION: 1980 1980

MANUAL FIRE PROTECTION: 2000 EXTINGUISHERS & STANDPIPE SYSTEM

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S

AUTOMATIC FIRE ALARM SYSTE: 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY

SMOKE ALARM OPERATION: 9500 ALARM NOT ACTIVATED - UNKNOWN

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 7600 EXTERIOR WALL

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 2900 HEATING EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 4000 EXTERIOR TRIM & APPURTENANCE - INCLUDES DOOR, PORCH, PLATFOR

ACT OR OMISSION: 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer

LAFC Badge #

Telephone

ReportDate

KLIE, JOHN

1238

250-632-8940

2009-06-19

PROVINCE OF BRITISH COLUMBIA Ministry of Community, Aboriginal and Women's Services Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DKI 2009 06 17 05 01

Remarks:						
TO START DOWNS	IN ROOF DRAIN DO POUT (ABS PIPE) ON BROKE THROUGH I	FIRE. FIRE SPR	EAD FROM GRO	OUND LEVEL ON	ED CAUSING EX EXTERIOR WAI	CESSIVE HEA' LL TO ROOF

PROVINCE OF BRITISH COLUMBIA

Ministry of Community, Aboriginal and Women's Services

Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DKI 2009 06 17 05 01

Name no.

Name Status Phone

: OWNER S22

Name Address

S22

: MEIER, WILLIE

S22

Claims Adjuster Name Claims Adjuster Firm Claim Number

: 1. DAVE, WATSON : 1. HORIZON CLAIMS

KITIMAT BRITISH COLUMBIA

Insurance Company Policy Number

: 1. RSA INSURANCE : 1. COM 029133351

LOSS ESTIMATES:

Property Loss: s.21 Content Loss: s.21 Total Loss:

s.21

REMARKS:

Investigating Officer

LAFC Badge #

KLIE, JOHN

1238

Telephone

ReportDate 2009-06-19

250-632-8940

PSS 2011-01355 Page 3