PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: 688 2011 08 22 13 01

Location of Incident:			A WAY S INDIAN BAND BC		
# of Occupants (At time of fire): 100	# of Injured:	0	# of Deaths: 0	Total	Dollar Loss Estimate: \$0
Related to Wildland Interface Fire: NO	Property Val	lue: \$0	Content Val	ue: \$0	Total Value at Risk: \$0
Code Name	e: Code	e Descrij	otion		
PROPERTY COMPLEX	: 3200 RES	IDENTIA	AL - APARTMENT		
PROPERTY CLASSIFICATION	: 3990 RES	IDENTIA	AL MISCELLANEOU	JS - UNCLA	SSIFIED (DESCRIBE)
GENERAL CONSTRUCTION	: 2000 PRO	TECTEI	COMBUSTIBLE CO	ONSTRUCT	ION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT	: 0050 5 ST	ORIES A	ABOVE GRADE		
GROUND FLOOR AREA	: 4000 1001	TO 250	0M2 (10765 - 26910F	T2)	
YEAR OF CONSTRUCTION	: 2010 2010	1			
MANUAL FIRE PROTECTION	: 2000 EXT	INGUIS	HERS & STANDPIPI	E SYSTEM	
OUTSIDE FIRE PROTECTION	: 7000 FIRE	E DEPAR	RTMENT ONLY		
SPRINKLER PROTECTION	: 1000 COM	1PLETE	SPRINKLER PROTE	CTION - SU	PERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE	: 3000 FIRE	EALARN	M SYSTEM - OFF-SI	TE MONITO	RING AGENCY
SMOKE ALARM OPERATION	: 5000 ALA	RM AC	TIVATED - OCCUPA	NT ACTION	I UNKNOWN
INITIAL DETECTION	: 4000 HEA	T DETE	CTOR DEVICE		
TRANSMISSION OF ALARM	: 3000 PRIV	/ATE FI	RE ALARM SYSTEM	A - INCLUD	ES SIGNAL/ALARM RECEIVED I
FIRE SERVICE	: 1000 CAR	EER FIF	RE DEPARTMENT O	NLY	
INCIDENT	: 1000 FIRE	E - FIRE	DEPARTMENT ATT	ENDED	
ACTION TAKEN	: 4000 EXT	INGUIS	HED BY AUTOMAT	IC SYSTEM	
METHOD OF FIRE CONTROL	: 6900 SPR	INKLER	PROTECTION - UN	CLASSIFIEI	D (DESCRIBE)
FIRE ORIGIN, LEVEL	: 8000 ROC	F LEVE	L - INCLUDES CON	CEALED RO	OOF SPACE, ATTIC
FIRE ORIGIN, AREA	: 6200 HEA	TING E	QUIPMENT ROOM -	INCLUDES	FURNACE ROOM, WATER HEATER
EXTENT OF FIRE	: 3000 CON	FINED	TO ROOM OF ORIG	IN	
EXTENT OF DAMAGE	: 5000 CON	FINED	TO BUILDING OF O	RIGIN	
IGNITING OBJECT	: 2200 WAT	ΓER HEA	ATER		
FUEL OR ENERGY	: 4100 FUE	L GAS -	NATURAL GAS		
FORM OF HEAT	: 4000 DIRI	ECT FLA	ME		
MATERIAL FIRST IGNITED	: 6100 NAT	URAL C	GAS		
ACT OR OMISSION	: 4200 AUT	OMATI	C CONTROL FAILU	RE	

Investigating Officer LAFC Badge # BUTLER/FUNK, COREY/DANIEL 2271 Telephone ReportDate

250-372-5131 2011-08-23

PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: 688 2011 08 22 13 01

Remarks:

FIRE ALARM COMPANY NOTIFIED FIRE DEPARTMENT THAT THE BUILDING HAD AUDIBLE ALARM. ANOTHER CALLER NOTIFIED F.D. THAT WATER WAS COMING FROM THE FOURTH FLOOR. WHEN FIRE DEPARTMENT ARRIVED, WATER WAS FOUND COMING FROM THE CEILING OF THE 1ST 2ND AND THIRD FLOOR. UPON FURTHER INVESTIGATION, ALARM PANEL INDICATED THAT THE ALARM WAS TRIPPED FROM THE 'PENTHOUSE' FLOOR. WHEN CREW ARRIVED ON THE ROOF OF THE BUILDING, THEY FOUND A MECHANICAL ROOM WITH WATER FLOWING FROM IT. WHEN THE DOOR WAS OPENED THEY SAW INDICATIONS OF A FIRE IN THE LEFT HAND SIDE NEAR A HOT WATER TANK. THE SMELL OF NATURAL GAS WAS STRONG AND THEY COULD HEAR GAS ESCAPING FROM A REGULATOR NEAR THE WATER TANK. WATER FROM TRIPPED SPRINKLER AND GAS WERE THEN SHUT OFF TO THE FLOOR. WHEN FIRE INSPECTOR ARRIVED, IT WAS DETERMINED THAT A POSSIBLE NATURAL GAS REGULATOR MALFUNCTION OCCURED AND THE GAS WAS IGNITED BY THE NEARBY HOT WATER TANK PILOT LIGHT. THE SPACE BETWEEN THE GAS LEAK AND PILOT LIGHT WAS APPROXIMATELY 10 INCHES. THE FIRE WAS CONFINED TO THE LEFT HAND SIDE OF THE MECHANICAL ROOM AND WAS EXTINGUISHED QUICKLY BY THE SPRINKLER HEAD APPROXIMATELY 10 FT AWAY. A GAS INSPECTOR FROM BC SAFETY AUTHORITY WAS CALLED TO INVESTIGATE THE POSSIBLE MALFUNCTIONING REGULATOR. GAS INSPECTOR CANNOT BE CONTACTED, MULTIPLE TRIES HAVE BEEN MADE. GAS REGULATOR SPECIFICATIONS: NAME: MAXITROL 0849 24 NAT 8.0.

Investigating Officer BUTLER/FUNK, COREY/DANIEL LAFC Badge #

 Telephone
 ReportDate

 250-372-5131
 2011-08-23

PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissione

FIRE REPORT - STRUCTURE (NAMES)

Emergency Managemen	INCIDENT NUME	INCIDENT NUMBER: 688 2011 08 22 13 01				
Name no. Name Address	: : : KAMI	s.22 .00PS BRITISH COLUMBIA	Name Status Phone	:	s.22	
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number		SER ANDERSON/HOUSTON C	GRANT/HUB			
LOSS ESTIMATES: Property Loss : \$0		Content Loss: \$0	Total Loss: \$0			
REMARKS:						
s.22	s.22	HIS CONT	FACT INFORMATION IS: WORK	-	s.22	CELL
Name no. Name Address	:	s.22	Name Status Phone	:	s.22	
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: : : :					
LOSS ESTIMATES: Property Loss : \$0		Content Loss: \$0	Total Loss : \$0			
REMARKS:						

Investigating Officer BUTLER/FUNK, COREY/DANIEL	LAFC Badge #	Telephone	ReportDate
	2271	250-372-5131	2011-08-23

PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES) INCIDENT NUMBER: 688 2011 08 22 13 01

Name no. Name Address	:	s.22		Name Status Phone	: : s.22
Address	·		LUMBIA V2C5R9		
Claims Adjuster Name	:				
Claims Adjuster Firm	:				
Claim Number	:				
Insurance Company	:				
Policy Number	:				
LOSS ESTIMATES:					
Property Loss: \$0			Content Loss: \$0	Total Loss: \$0	
REMARKS:					

Investigating Officer	
BUTLER/FUNK,	
COREY/DANIEL	

LAFC Badge # 2271
 Telephone
 ReportDate

 250-372-5131
 2011-08-23