



Southern section of quarry ready  
for seeding



Province of British Columbia  
MINISTRY OF ENERGY, MINES  
AND PETROLEUM RESOURCES  
Mining & Minerals Division  
Report of Inspector of Mines  
(Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 12418  
File: 18070-02  
Mine No: 1500021  
Permit No: Q-11-001  
Emp/Cont: 0 / 0  
Orders H&S: 1 RECL:  
Stop Work:

Inspection Report

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, -120.817, 092I/15W Tranquille
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	714 Sarcee ST. Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	General site

Persons Contacted

MANAGEMENT Dave Bowers

OHS COMMITTEE

WORKERS

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

INSPECTION ORDERS


At the time of inspection, work was being carried out on the southern area of the quarry. The floor had been smoothed and prepared for seeding. Pit faces were found to be an acceptable height.

Tandem & pups were being used to transport material from the quarry to the process plant in Kamloops.

Drip trays have been added to the oil storage site.

Shoulder barriers shall be provided on all travelways where the drop off is greater than 3 metres. The barriers shall be of appropriate thickness and height pursuant to 6.9.1 of the Code. To be remedied immediately.

MANAGERS RESPONSE OF ACTION TAKEN



A shoulder Barrier has been provided where the drop is greater than three meters. This barrier is made up of overburden and earth.

Joe Seguin

Inspector of Mines

162 Oriole Road Kamloops BC V2C 4N7

Address

Date of Inspection:

October 4, 2005

Copies To

Dave Bowers

Signature - Inspector of Mines

Signature - Manager

Dated:

Dec 6-

EGM-201200259

Page 2





Southern section of quarry ready  
for seeding



**Province of British Columbia**  
**MINISTRY OF ENERGY, MINES AND**  
**PETROLEUM RESOURCES**  
**Mining & Mineral Division**  
**Report of Inspector of Mines**  
**(Issued pursuant to Section 15 of the *Mines Act*)**

**Inspection No.:** 12418.0  
**File:** 18070-02  
**Mine No.:** 1500021  
**Permit No.:** Q-11-001  
**Emp/Cont:** 0.0 / 0.0  
**Orders H&S:** 1.0 RECL: 0.0  
**Stop Work:** 0.0

**Inspection Report**

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, 120.817 Kamloops
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	724 East Sarcee Street. Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	General site

**Persons Contacted**

MANAGEMENT Dave Bowers  
 OHS COMMITTEE  
 WORKERS

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**INSPECTION ORDERS**

**MANAGERS RESPONSE OF ACTION TAKEN**

*TYPE MANAGERS RESPONSE HERE*

Joe Seguin

Inspector of Mines

162 Oriole Road Kamloops BC V2C 4N7

Address

Signature Inspector of Mines

Signature Manager

Date of Inspection: 04/10/2005

Copies To Dave Bowers

Dated: \_\_\_\_\_, 20\_\_\_\_





Province of British Columbia  
**MINISTRY OF ENERGY, MINES  
 AND PETROLEUM RESOURCES**  
 Mining & Minerals Division  
**Report of Inspector of Mines**  
 (Issued pursuant to Section 15 of the Mines Act)

Inspection No.: 12891  
 File: 18070-02-09  
 Mine No: 1500021  
 Permit No: Q-11-001  
 Emp/Contr: 0 / 0  
 Orders H&S: RECL: 1  
 Stop Work:

### Inspection Report

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, -120.817, 0921/15W Tranquille
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	714 Sarcee ST. Kamloops BC V2Y 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	Access, general area.

### Persons Contacted

MANAGEMENT	No.
OHS COMMITTEE	
WORKERS	Dave Bowers

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia

### INSPECTION ORDERS

Dave Bowers was on site at the time of the inspection.

Approximately 1 to 2 ha in the Red Lake pit area have been recontoured and are ready for seeding. This area shall be seeded within 60 days.

Progressive reclamation shall continue to occur.

The Depples pit has been cleared and stumped and is ready for excavation.

### MANAGER'S RESPONSE OF ACTION TAKEN

Reclamation will continue to occur on an ongoing basis.  
 Seeding of reclaimed areas will be done within the 60 day period.

Ministry of Energy and Mines  
 Kamloops, B.C.

Rec'd MAY 11 2006

Darren Bruhjell, P. Eng.

Inspector of Mines

162 Oriole Road Kamloops BC V2C 4N7

Address

Date of Inspection: April 21, 2006

Copies To

*D. Bruhjell*  
 Signature - Inspector of Mines

*Steve Runn*  
 Signature - Manager

Dated: May 8-

EGM-2013-00259  
 Page 5



Province of British Columbia  
MINISTRY OF ENERGY, MINES AND  
PETROLEUM RESOURCES  
Mining & Mineral Division  
Report of Inspector of Mines  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 12891.0  
File: 18070-02-09  
Mine No.: 1500021  
Permit No.: Q-11-001  
Emp/Cont: 0.0 / 0.0  
Orders H&S: 0.0 RECL: 1.0  
Stop Work: 0.0

Inspection Report

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, 120.817 Kamloops
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	724 East Sarcee Street. Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	Access, general area.

Persons Contacted

MANAGEMENT No.  
OHS COMMITTEE  
WORKERS Dave Bowers

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION ORDERS

MANAGERS RESPONSE OF ACTION TAKEN

TYPE MANAGERS RESPONSE HERE

Darren Bruhjell, P. Ag.

Inspector of Mines

162 Oriole Road Kamloops BC V2C 4N7

Address

Signature Inspector of Mines

Signature Manager

Date of Inspection: 21/04/2006

Dated: , 20

Copies To



Ministry of  
Energy and Mines

Province of British Columbia  
**Ministry of Energy and  
Mines**

**Report of Inspector of Mines**  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 27499  
File: 19070-02-08  
Mine No.: 1500021  
Permit No.: Q-11-001  
Emp/Cont: 2 / 0  
Orders H&S: 12 RECL: 0  
Stop Work: 0

**Inspection Report**

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, -120.817 Kamloops
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	724 East Sarscoe Street Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	Shop; Combo Trailer, Pit and Yard

**Persons Contacted**

MANAGEMENT

OHS COMMITTEE

WORKERS Dave Bowers

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**INSPECTION ORDERS**

This inspection was conducted on October 10/13 by Sandy Gillies Inspector of Mines Mechanical and Rick Adams Inspector of Mines. The following orders were issued as a result of the inspection.

**1.8.1 The manager shall**

(1) except for protective footwear and prescription eyeglasses, supply properly fitted personal protective equipment as required by the code,

(2) ensure that workers are instructed in the use and maintenance of the equipment, the reasons for it, and also on its location and limitations, and


(3) ensure that the equipment is adequate for its purpose.  
**Workers' Responsibility**

**1.8.2 All persons shall wear the personal protective equipment as required by the code.**

**Protective Hat 1.8.3**

**MANAGERS RESPONSE OF ACTION TAKEN**

**DO NOT MODIFY THIS TEXT**



Sandy Gillies

Inspector of Mines, Mechanical

2nd Floor, 441 Columbia Street Kamloops BC V2C 2T3

Address

Date of Inspection: 10/10/2013

Copies To Steve Rothman.

Signature - Inspector of Mines

Signature - Manager

Dated: Oct/30/2013

20

## Report of Inspector of Mines Page 2 of 4

## INSPECTION ORDERS

## MANAGERS RESPONSE OF ACTION TAKEN

A protective hat complying with the relevant requirements of CSA Standard Z94.1-M1977 "Industrial Protective Headgear," and suitable for the type of work or activity being performed, shall be worn by persons where there is a risk of head injury or where required by the manager or an inspector. Where conditions may cause the hat to be accidentally dislodged

(1) a device shall be incorporated into the hat and worn in order to prevent the hat being dislodged during a fall, and  
(2) in the case of underground work, a chin strap and hearing protection muffs attached to the hat shall be worn.

**Protective Footwear**

1.8.4 Protective footwear complying with the relevant requirements of CSA Standard Z195-M1984 "Protective Footwear", and suitable for the type of work or activity being performed, shall be worn by persons where there is a risk of foot injury or where required by the manager or an inspector.

**Eye Protection 1.8.5**

Properly fitting goggles, face shields, or other eye protective equipment complying with the relevant requirements of CAN/CSA Standard Z94.3-M88 "Industrial Eye and Face Protectors," and suitable for the type of work or activity being performed, shall be worn by a person who

- (1) is handling or is exposed to any material which is likely to injure or irritate the eyes,
- (2) is engaged in any work in which there is a risk of eye injury,
- (3) has 20/200 vision or is blind in either eye, or
- (4) is working or passing through an area which the manager or inspector has designated as requiring such protection.

Employees were found to be without hard hats and safety glasses.

The manager shall ensure that all employees are properly equipped for working on a mine site by October 11/13.

**Workplace to Be Hazard Free**

2.2.1 The manager shall develop and implement an effective housekeeping program to ensure that all workplaces and travel ways are maintained in a safe condition, that materials and equipment are stored in a manner so as not to endanger persons, and that appropriate action is taken whenever necessary to maintain a hazard-free environment.

During the inspection it was clear that no or very little clean up is done on site especially in the FIRST AID area. A lot of clutter throughout this COMBO trailer is not acceptable. A gas generator is in the First Aid area oils are stored in another area but all in the same trailer.

all employees shall wear protect  
Headgear High vis clothing, Eye  
protection upon leaving trailer for  
Work.

BA

on going house keeping, trailer  
Replacement Being taken care  
of, Removed items in question

Date of Inspection

10/10/2013

Initials

25

(Inspector)

Initials

(Manager)



## Report of Inspector of Mines Page 3 of 4

## INSPECTION ORDERS

## MANAGERS RESPONSE OF ACTION TAKEN

The manager shall cause this situation to be corrected by October 17/13

**4.3.8 Every fuel storage tank shall**

- (1) have a means of accurately determining the amount of fuel it contains,
- (2) be identified as to its contents and that it is a fire hazard area.

The manager shall have 3 more placards attached to the fuel dispensing tank.

**Welding and Burning Equipment 4.4.7**

- (1) Whenever torches or welding equipment are being transported or used, the manager shall require that safe procedures are developed and followed.

- (2) Every compressed gas cylinder containing fuel gas or other gas, when not in use, shall

(a) be stored in an upright position and kept in a well ventilated area free from flammable material and electrical apparatus, and

(b) have a securely fastened, approved valve protection cap, and be adequately secured by chains or other acceptable means to prevent it from being knocked over.

- (3) At any time that compressed gas cylinders are being transported, they shall be secured on a special carrier or container designed for the purpose, and unless the carrier or container is of a type intended for safely moving gas cylinders, the cylinders shall be fitted with securely fastened, approved valve protection caps.

At the time of the inspection a number of gas bottles were found to have no valve protection covers fitted and some were free standing.

The manager shall cause this situation to be corrected By October 17/13.

**Fire Extinguisher**

**4.9.3 Every vehicle shall carry at least one fire extinguisher of adequate size and of the proper type.**

Not all equipment had an adequate fire extinguisher on board. This deficiency will be corrected by October 17/13.

**Vehicle Requirements 4.9.4**

- (1) All rubber tired mobile equipment over 7000 kg gross vehicle weight shall have a minimum of two wheel chocks which shall be used whenever necessary.

During the inspection there were no wheel chocks found in or in use on the equipment.

The manager shall remedy this by October 17/13

all sides have placards.

valve protection in place extra tank secured.

upgraded extinguishers.

purchased and Being implement.

Date of Inspection

10/10/2013

Initials



(Inspector)

Initials

(Manager)

## Report of Inspector of Mines Page 4 of 4

## INSPECTION ORDERS

## MANAGERS RESPONSE OF ACTION TAKEN

**Logbook to be Maintained**

6.19.2 The manager shall provide and maintain an effective logbook system for each unit of mobile equipment over 7000 kg gross vehicle weight where

- (a) the vehicle operator notes the operating condition prior to operating of the vehicle
- (b) note any unsafe conditions, and
- (c) a qualified person making repairs, notes any repairs made and if the vehicle is safe to operate

Although one logbook was found the information is inadequate. The manager will take the necessary steps to correct the lack of information and supply proper logbooks by October 31/13

**Fuel & Lubricants 9.9.1**

(1) Liquid hydrocarbon products shall be stored within a containment that minimizes the possibility of accidental discharge to the environment.

(2) Unless authorized by an inspector, bulk liquid hydrocarbon products shall not be stored within 30 meters of a stream, lake or wetland

There were a number of areas found to be without containment and a lot of used and new oil containers present around the quonset shed area. There is evidence of hydrocarbon product on the ground. The manager shall have the whole area cleaned to an acceptable standard by November 1/13.

all equipment has log book completed.

all oils in containment areas ongoing clean up. Soil will be removed from area.

Date of Inspection

10/10/2013

Initials



(Inspector)

Initials

(Manager)



Province of British Columbia  
**Ministry of Energy and  
Mines**

Report of Inspector of Mines  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 27499  
File: 18070-02-08  
Mine No.: 1500021  
Permit No.: Q-11-001  
Emp/Cont: 2 / 0  
Orders H&S: 12 RECL: 0  
Stop Work: 0

**Inspection Report**

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, 120.817 Kamloops
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	724 East Sarcee Street Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	Shop; Combo Trailer , Pit and Yard

**Persons Contacted**

MANAGEMENT

OHS COMMITTEE

WORKERS Dave Bowers

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**INSPECTION ORDERS**

SECTION :1.8.1	Manager's Responsibility
SECTION :1.8.2	Worker's Responsibility
SECTION :1.8.3	Protective Hat
SECTION :1.8.4	Protective Footwear
SECTION :1.8.5	Eye Protection
SECTION :2.2.1	Workplace to Be Hazard Free
SECTION :4.3.8	Fire Protection and Control

**MANAGERS RESPONSE OF ACTION TAKEN**

***DO NOT MODIFY THIS TEXT***

Sandy Gillies

Inspector of Mines, Mechanical

2nd Floor, 441 Columbia Street Kamloops BC V2C 2T3

Address

Date of Inspection: 10/10/2013

Copies To Steve Rothman.

Signature Inspector of Mines

Signature Manager

Dated: \_\_\_\_\_, 20\_\_\_\_



INSPECTION ORDERS		MANAGERS RESPONSE OF ACTION TAKEN
SECTION :4.4.7	Welding and Burning Equipment	
SECTION :4.9.3	Fire Extinguisher	
SECTION :4.9.4	Vehicle Requirements	
SECTION :6.19.2	Logbook to be Maintained	
SECTION :9.9.1	Fuel & Lubricants	

Date of Inspection

10/10/2013

Initials



(Inspector)

Initials

\_\_\_\_\_

(Manager)



Province of British Columbia  
**Ministry of Energy and  
Mines**

Report of Inspector of Mines  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 27499  
File: 18070-02-08  
Mine No.: 1500021  
Permit No.: Q-11-001  
Emp/Cont: 2 / 0  
Orders H&S: 12 RECL: 0  
Stop Work: 0

**Inspection Report**

NAME OF MINE	Red Lake Quarry	LOCALITY	50.933, 120.817 Kamloops
OWNER/OPERATOR	Absorbent Products Ltd.	ADDRESS	724 East Sarcee Street Kamloops BC V2H 1E7
MANAGER	Peter Aylen	AREAS INSPECTED	Shop; Combo Trailer , Pit and Yard

**Persons Contacted**

MANAGEMENT

OHS COMMITTEE

WORKERS Dave Bowers

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**INSPECTION ORDERS**

This inspection was conducted on October 10/13 by Sandy Gillies Inspector of Mines Mechanical and Rick Adams Inspector of Mines. The following orders were issued as a result of the inspection.

**1.8.1 The manager shall**

- (1) except for protective footwear and prescription eyeglasses, supply properly fitted personal protective equipment as required by the code,
- (2) ensure that workers are instructed in the use and maintenance of the equipment, the reasons for it, and also on its location and limitations, and
- (3) ensure that the equipment is adequate for its purpose.

**Workers' Responsibility**

**1.8.2 All persons shall wear the personal protective equipment as required by the code.**

**Protective Hat 1.8.3**

**MANAGERS RESPONSE OF ACTION TAKEN**

**DO NOT MODIFY THIS TEXT**

Sandy Gillies

Inspector of Mines, Mechanical

2nd Floor, 441 Columbia Street Kamloops BC V2C 2T3

Address

Date of Inspection: 10/10/2013

Copies To Steve Rothman.

Signature Inspector of Mines

Signature Manager

Dated: \_\_\_\_\_, 20\_\_\_\_

## INSPECTION ORDERS

## MANAGERS RESPONSE OF ACTION TAKEN

A protective hat complying with the relevant requirements of CSA Standard Z94.1-M1977 "Industrial Protective Headgear," and suitable for the type of work or activity being performed, shall be worn by persons where there is a risk of head injury or where required by the manager or an inspector. Where conditions may cause the hat to be accidentally dislodged

- (1) a device shall be incorporated into the hat and worn in order to prevent the hat being dislodged during a fall, and
- (2) in the case of underground work, a chin strap and hearing protection muffs attached to the hat shall be worn.

**Protective Footwear**

**1.8.4** Protective footwear complying with the relevant requirements of CSA Standard Z195-M1984 "Protective Footwear", and suitable for the type of work or activity being performed, shall be worn by persons where there is a risk of foot injury or where required by the manager or an inspector.

**Eye Protection 1.8.5**

Properly fitting goggles, face shields, or other eye protective equipment complying with the relevant requirements of CAN/CSA Standard Z94.3-M88 "Industrial Eye and Face Protectors," and suitable for the type of work or activity being performed, shall be worn by a person who

- (1) is handling or is exposed to any material which is likely to injure or irritate the eyes,
- (2) is engaged in any work in which there is a risk of eye injury,
- (3) has 20/200 vision or is blind in either eye, or
- (4) is working or passing through an area which the manager or inspector has designated as requiring such protection.

Employees were found to be without hard hats and safety glasses.

The manager shall ensure that all employees are properly equipped for working on a mine site by October 11/13.

**Workplace to Be Hazard Free**

**2.2.1** The manager shall develop and implement an effective housekeeping program to ensure that all workplaces and travel ways are maintained in a safe condition, that materials and equipment are stored in a manner so as not to endanger persons, and that appropriate action is taken whenever necessary to maintain a hazard-free environment.

During the inspection it was clear that no or very little clean up is done on site especially in the FIRST AID area. A lot of clutter throughout this COMBO trailer is not acceptable. A gas generator is in the First Aid area oils are stored in another area but all in the same trailer.



Date of Inspection

10/10/2013

Initials

\_\_\_\_\_

(Inspector)

Initials

\_\_\_\_\_

(Manager)



INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>The manager shall cause this situation to be corrected by October 17/13</p> <p><b>4.3.8 Every fuel storage tank shall</b></p> <p>(1) have a means of accurately determining the amount of fuel it contains,</p> <p>(2) be identified as to its contents and that it is a fire hazard area.</p> <p>The manager shall have 3 more placards attached to the fuel dispensing tank.</p> <p><b>Welding and Burning Equipment 4.4.7</b></p> <p>(1) Whenever torches or welding equipment are being transported or used, the manager shall require that safe procedures are developed and followed.</p> <p>(2) Every compressed gas cylinder containing fuel gas or other gas, when not in use, shall</p> <p>(a) be stored in an upright position and kept in a well ventilated area free from flammable material and electrical apparatus, and</p> <p>(b) have a securely fastened, approved valve protection cap, and be adequately secured by chains or other acceptable means to prevent it from being knocked over.</p> <p>(3) At any time that compressed gas cylinders are being transported, they shall be secured on a special carrier or container designed for the purpose, and unless the carrier or container is of a type intended for safely moving gas cylinders, the cylinders shall be fitted with securely fastened, approved valve protection caps.</p> <p>At the time of the inspection a number of gas bottles were found to have no valve protection covers fitted and some were free standing.</p> <p>The manager shall cause this situation to be corrected By October 17/13.</p> <p><b>Fire Extinguisher</b></p> <p><b>4.9.3 Every vehicle shall carry at least one fire extinguisher of adequate size and of the proper type.</b></p> <p>Not all equipment had an adequate fire extinguisher on board. This deficiency will be corrected by October 17/13.</p> <p><b>Vehicle Requirements 4.9.4</b></p> <p>(1) All rubber tired mobile equipment over 7000 kg gross vehicle weight shall have a minimum of two wheel chocks which shall be used whenever necessary.</p> <p>During the inspection there were no wheel chocks found in or in use on the equipment.</p>	



Date of Inspection

10/10/2013

Initials

\_\_\_\_\_

(Inspector)

Initials

\_\_\_\_\_

(Manager)

INSPECTION ORDERS	MANAGERS RESPONSE OF ACTION TAKEN
<p>The manager shall remedy this by October 17/13</p> <p><b>Logbook to be Maintained</b>  <b>6.19.2 The manager shall provide and maintain an effective logbook system for each unit of mobile equipment over 7000 kg gross vehicle weight where</b>  <b>(a) the vehicle operator notes the operating condition prior to operating of the vehicle</b>  <b>(b) note any unsafe conditions, and</b>  <b>(c) a qualified person making repairs, notes any repairs made and if the vehicle is safe to operate</b></p> <p>Although one logbook was found the information is inadequate. The manager will take the necessary steps to correct the lack of information and supply proper logbooks by October 31/13</p> <p><b>Fuel &amp; Lubricants 9.9.1</b>  <b>(1) Liquid hydrocarbon products shall be stored within a containment that minimizes the possibility of accidental discharge to the environment.</b>  <b>(2) Unless authorized by an inspector, bulk liquid hydrocarbon products shall not be stored within 30 meters of a stream, lake or wetland</b></p> <p>There were a number of areas found to be without containment and a lot of used and new oil containers present around the quonset shed area. There is evidence of hydrocarbon product on the ground. The manager shall have the whole area cleaned to an acceptable standard by November 1/13.</p>	

Date of Inspection

10/10/2013

Initials



(Inspector)

Initials

\_\_\_\_\_

(Manager)



Ministry of  
Energy and Mines

Ministry of Energy and Mines  
Mining & Mineral Division  
Report of Inspector of Mines  
Reclamation and Permitting  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 27557  
File: 18070-02-09  
Mine No.: 1500021  
Emp/Cont: 0 / 0  
Orders H&S: 0 RECL 2  
Stop Work: 0

Name of Property Red Lake Quarry Permit No. Q-11-001  
Location Kamloops  
Owner, Manager Peter Aylen  
  
Company Absorbent Products Ltd.  
Address 724 E. Sarcee Street  
Kamloops BC V2H 1E7  
  
Persons Contacted Steve Gurney, Dave Bowers  
  
Type of Mining INDUSTRIAL MINERALS - SURFACE  
Date of Inspection 10/10/2013  
Copies To

Written response is required from the Mine Manager within 15 days of receiving the report. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

Inspection Report Text

INSPECTION ORDERS

This inspection was conducted on October 10/13 by Rick Adams, Inspector of Mines, and Sandy Gillies, Inspector of Mines, Mechanical. The following orders were issued as a result of the inspection, and apply to that portion of the mine property described as: the Bepple Pit; the Bepple property; parcel identifier 014-526-280; and/or, the south west ¼ of the south west ¼ of Section 12 Township 23 Range 21 west of the 6<sup>th</sup> Meridian Kamloops Division Yale District, and as shown outlined in yellow on the attached map.

SECTION :10.7.4 Land Use

The land surface shall be reclaimed to an end land use approved by the chief inspector, that considers previous and potential uses.

Pursuant to Section: 10.7.4 of the Code, and Special Conditions: 4. of the *Mines Act* permit, the land surface shall be reclaimed to an end land use of forested timber lands. This is required effective immediately, and ongoing, as land is progressively

MANAGERS RESPONSE OF ACTION TAKEN

Rick Adams, RPF  
Inspector of Mines

Dated: 10/16/2013

Page 1

EGM-2013-00259  
Page 17



reclaimed.

**SECTION :10.7.5 Capability**

**Excluding lands that are not to be reclaimed, the average land capability to be achieved on the remaining lands shall not be less than the average that existed prior to mining, unless the land capability is not consistent with the approved end land use.**

Pursuant to Section: 10.7.5 of the Code, and Special Conditions: 4. of the *Mines Act* permit, the manager shall engage a Qualified Forest Professional to develop, and implement, a silviculture prescription to: reclaim the site to forested timber lands with native species of the same type, diversity, and forest productivity as existed prior to mining; and with planted tree seedling density sufficient to expect to produce commercially viable timber volumes at stand maturity. This is required effective immediately, and ongoing, as land is progressively reclaimed.



Rick Adams, RPF  
Inspector of Mines

Dated: 10/16/2013

Page 2





Mineral Titles  
OnlineBC

## Mineral Titles Online



### Legend

- ☐ Indian Reserves
- ☐ National Parks
- ☐ Conservancy Areas
- ☐ Parks
- ☐ Federal Transfer Lands
- ☐ First Nations Treaty Related Lands
- ☐ First Nations Treaty Lands
- ☐ Integrated Cadastral Fabric
- ☐ Survey Parcels
- ☐ BCGS Grid
- ☐ Contours (TRIM)
- ☒ Contour - Index
- ☒ Contour - Index, Indefinite
- ☒ Contour - Index, Depression
- ☒ Contour - Index, Depression Indefinite
- ☒ Contour - Intermediate
- ☒ Contour - Intermediate, Indefinite
- ☒ Contour - Intermediate, Depression
- ☒ Contour - Intermediate, Depression Indefinite
- ☒ Area of Exclusion
- ☒ Area of Indefinite Contours
- ☒ Annotation (1:20K)
- ☒ Transportation - Points (TRIM)
- ☒ Helipad
- ☒ Transportation - Lines (TRIM)
- ☒ Airfield
- ☒ Airport
- ☒ Airstrip
- ☒ Airport, Abandoned
- ☒ Ferry Route



Scale: 1:7,482

This map is a user generated static output from an Internet mapping site and is for general reference only. Data layers that appear on this map may or may not be accurate, current, or otherwise reliable. THIS MAP IS NOT TO BE USED FOR NAVIGATION.





**Ministry of Energy and Mines**  
Mining & Mineral Division  
**Report of Inspector of Mines**  
**Reclamation and Permitting**  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 27557  
File: 18070-02-09  
Mine No.: 1500021  
Emp/Cont: 0 / 0  
Orders H&S: 0 RECL 2  
Stop Work: 0

**Name of Property** Red Lake Quarry **Permit No.** Q-11-001  
**Location** Kamloops  
**Owner, Manager** Peter Aylen  
  
**Company** Absorbent Products Ltd.  
**Address** 724 E. Sarcee Street  
Kamloops BC V2H 1E7  
  
**Persons Contacted** Steve Gurney, Dave Bowers  
  
**Type of Mining** INDUSTRIAL MINERALS - SURFACE  
**Date of Inspection** 10/10/2013  
**Copies To**

Written response is required from the Mine Manager within 15 days of receiving the report. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**Inspection Report Text**

**INSPECTION ORDERS**

This inspection was conducted on October 10/13 by Rick Adams, Inspector of Mines, and Sandy Gillies, Inspector of Mines, Mechanical. The following orders were issued as a result of the inspection, and apply to that portion of the mine property described as: the Beppe Pit; the Beppe property; parcel identifier 014-526-280; and/or, the south west ¼ of the south west ¼ of Section 12 Township 23 Range 21 west of the 6<sup>th</sup> Meridian Kamloops Division Yale District, and as shown outlined in yellow on the attached map.

**SECTION :10.7.4 Land Use**

The land surface shall be reclaimed to an end land use approved by the chief inspector, that considers previous and potential uses.

Pursuant to Section: 10.7.4 of the Code, and Special Conditions: 4. of the *Mines Act* permit, the land surface shall be reclaimed to an end land use of forested timber lands. This is required effective immediately, and ongoing, as land is progressively

**MANAGERS RESPONSE OF ACTION TAKEN**

Rick Adams, RPF  
Inspector of Mines

Dated: 10/16/2013

Page 1



reclaimed.

**SECTION :10.7.5      Capability**

**Excluding lands that are not to be reclaimed, the average land capability to be achieved on the remaining lands shall not be less than the average that existed prior to mining, unless the land capability is not consistent with the approved end land use.**

Pursuant to Section: 10.7.5 of the Code, and Special Conditions: 4. of the *Mines Act* permit, the manager shall engage a Qualified Forest Professional to develop, and implement, a silviculture prescription to: reclaim the site to forested timber lands with native species of the same type, diversity, and forest productivity as existed prior to mining; and with planted tree seedling density sufficient to expect to produce commercially viable timber volumes at stand maturity. This is required effective immediately, and ongoing, as land is progressively reclaimed.