



# DGIR Incident Report DGIR 112782



Category: Code 1

Incident Date Time: 2012-01-17 04:00

MCTS#:

**DGIR INLAND** Spiller:

DISPLAY FIXTURES

Location:

SUPERSTORE 2280 **BARON RD** 

Area:

**KELOWNA** 

PEP Region: CTL

Other:

MOE Region: Thompson

Region

Material(s): Amount(s): R 438 A 200 LBS

Received From:

Caller A: Org:

Phone:

Time:

s.22

Alternate:

Alternate: Time:

Other Spill Type;

Received at PEP by Duty Officer: RICK

When Received: 2012-01-17 14:12

Caller B:

Org:

Phone:

Affected Environment: Atmosphere

Type of Spilling:

Equipment Failure

Accidents:

ector:

Commercial

Cause :

Advised that during service check, a leak found in the dairy cases.

Response:

Unit was isolated, pumped out, repaired, pressure tested and refilled.

Jurisdiction: Federal, Provincial

Taak#:

Amount:\$

Issued To :

Notification:

1420 briefed MOE RO Dennis Redford code 1 Fed/ Prov

1425 faxed MOE Kamloops/ Penticton

This report printed on: 2012-01-17 at 14:23:24

**Emergency Coordination Center** Phone 1-800-663-3456 Fax (250) 952-4872

> Page 1 MOE-2012-00316





DGIR Incident Report **DGIR 112913** 



Category: Code 1

Incident Date Time: 2012-01-30 15:00

MCTS#:

DGIR INLAND Spiller:

SUPER STORE - #1552

Location:

3020 LOUIE DRIVE -

WEST KELOWNA

Area:

**WEST KELOWNA** 

PEP Region: CTL

MOE Region: Thompson

→ MUE KAMEUUPS

Region

Material(s): Amount(s):

R507

100 LBS

Received From:

Caller A: Org:

Phone:

Alternate:

s.21

Alternate: Time:

Other Spill Type:

Time: 2012-01-30 17:00 Received at PEP by Duty Officer: CHUCK

When Received: 2012-01-30 17:00

Phone:

Caller B:

Org:

Affected Environment: Atmosphere

Type of Spilling:

Equipment Failure

Accidents:

Sector:

Commercial PRIVATE

Cause :

Advised a leak was discovered from refrigeration rack at the Super Store in West Kelowna. There was a stress fracture in the piping and 100 lbs of R507 vented to the atmosphere. Non recoverable.

Other:

Response:

Caller repaired the damaged pipe (welded) and recharge unit with 100 lbs of R507.

Jurisdiction: Provincial

Task # :124803

Amount : \$50

issued To: ED STOCKERL

Notification:

17:04 briefed on cell MOE RO Ed Stockerl - Nelson, code 1 prov

17:20 faxed MOE - Kamloops/Nelson

This report printed on: 2012-01-30 at 17:19:37 Emergency Coordination Center

Phone 1-800-663-3456 Fax (250) 952-4872







**DGIR Incident Report DGIR 112936** 



Category: Code 1

Incident Date Time: 2012-01-21

MCTS#:

**DGIR INLAND** 

**GORMAN BROTHERS** 

GORMAN BROS

Location:

Spiller:

LUMBER, 3900

**DUNFIELD ROAD** 

Area:

**KELOWNA** 

PEP Region: CTL

MOE Region: Thompson

Region

Material(s):

134A

Amount(s):

150 POUNDS

Received

From:

Caller A:

Org:

Phone: Alternate:

Time:

s.21

Other:

Received at PEP by Duty Officer: SHANNON

Time: When Received: 2012-02-01 09:17

Caller B:

Org:

Phone:

Alternate:

Affected Environment: Atmosphere

Type of Spilling :

Other Spill Type:

Equipment Failure

Accidents:

Sector:

Industrial

Cause:

Reports ozone depletion substance from dehumidifying unit was lost when they had trouble with the blower which caused vibrations resulting in a leak. Machine failed on the Saturday and it was turned off at the time.

Response:

New blowers, bearings and shaft have been replaced. The original piping was replaced with stainless steel and copper.

Jurisdiction: Provincial

Task#:

Amount:\$

Issued To:

Notification:

09:25 briefed MOE RO Dennis Redford Code 1 Prov

09:30 faxed MOE Kamleops





DGIR Incident Report DGIR 113412



Category: Code 1 Incident Date Time: 2012-03-01

**DGIR INLAND** MCTS#:

Spiller:

**GORMAN BROS. LUMBER** 

Location:

3900 DUNFIELD ROAD

Area:

**WEST KELOWNA** 

PEP Region: CTL

**MOE Region: Thompson** 

→ MOE KAMLOOPS

Region

Material(s):

R134A

Amount(s):

**90 LBS** 

Received From:

Caller A:

Org: Phone:

Alternate:

s.21

Phone: Alternate: Time:

Time: Received at PEP by Duty Officer : ERIN

When Received: 2012-03-19 09:50

Caller B:

Org:

Affected Environment: Atmosphere

Type of Spilling:

Other: Other Spill Type:

Accidents:

Sector:

Cause:

Calling to advise of a leak on the supply line to a distributor on a dehumidifier D1 occurred on Mar 1. All of the supply lines were replaced and leak tested, and the distributor was put back into service this morning.

Response:

Jurisdiction: Federal, Provincial

Task#:

Amount : \$

Issued To :

Notification;

09:56 briefed MOR RO Rick Wagner - Code 1 Prov/Fed

09:58 faxed MOE Kamloops

This report printed on: 2012-03-19 at 09:68:05

**Emergency Coordination Center** Phone 1-800-663-3456 Fax (250) 952-4872

> Page 4 MOE-2012-00316

# FIE COPY



13:45 faxed MOE Kamloops

# DGIR Incident Report DGIR 120395



Category: Code 1

Incident Date Time :

MCTS#: DGIR INLAND SUPERSTORE Spiller: SUPERSTORE 1564 -Location: 2280 BARON ROAD **MOE Region: Thompson** PEP Region: CTL **KELOWNA** Area: Region R507 Material(9): Amount(s): 200LBS Received From: Caller B: Caller'A: Org: s.22 Org : Phone: Phone: Alternate: Alternate : Time: Time: When Received: 2012-05-14 13:40 Received at PEP by Duty Officer: JIM Other: Affected Environment: Atmosphere Other Spill Type: Type of Spilling: Equipment Failure Accidents: Industrial Sector: Cause: Advised that he responded to the above location to repair a rupture on an evaporator coil. Re-charged system Response: Jurisdiction: Federal, Provincial Issued To: Amount:\$ Task#: Notification: 13:43 MOE EERO Rick Wagner code 1 prov/fed

This report printed on: 2012-05-14 at 13:44:04

Emergency Coordination Center Phone 1-800-663-3456 Fax (250) 952-4872





Notification:

1401 faxed MOE Kamloops

1355 briefed MOE RO Rick Wagner Code 1 Fed/Prov


# DGIR Incident Report DGIR 121209



Category: Code 1

Incident Date Time: 2012-07-29 16:00

**DGIR INLAND** MCTS#: Spiller: GORMAN BROTHERS LUMBER 3400 BROWN RD Location: MOE Region: Thompson Area: WEST KELOWNA PEP Region: CTL Region 134A Material(s): Amount(s): 110 LBS Received From: Caller A: Caller B: Org: Org: s.22 Phone: Phone: Alternate: Alternate: Time: Time: Received at PEP by Duty Officer: MIKE When Received: 2012-07-30 13:45 Affected Environment: Atmosphere Other: Type of Spilling: Other Spill Type: Equipment Failure Accidents: Sector: Commercial Cause: High pressure pilot line let go and released the material Response: Repaired system and refilled system. Jurisdiction: Federal, Provincial Task #: Amount:\$ Issued To:







**DGIR 121439** 



Category: Code 1

Incident Date Time: 2012-08-19 1630

DGIR INLAND		MCTS#:	
Spiller :	GORMAN BROTHERS L	UMBER	
Location:	3900 DUNFIELD ROAD	•	
Area:	WEST KELOWNA	PEP Region : CTL	MOE Region: Thompson Region
Material(s): Amount(s):	REFRIGERANT 134A EST. 105 LB		
Received			
From: Caller A :		Caller B:	
Org	s.22	C	Org:
Phone Alternate Time	:	Alterna Tir	ne : ite : ne :
Received at PEP by Duty Officer: YVONNE When Received: 2012-08-20 13:55			
Affected Environment : Atmosphere Other :			
Type of Spilling : Other Spill Type : Equipment Failure			
Accidents:			
Sector:	Commercial		
Cause: Balancing line was brittle and broke. Has been replaced and repaired.			
Response:			
Jurisdiction ; Provincial			
Task#:	Amount : \$	Issued To :	
Notification:			
1401 Briefed MOE RO Dennis Redford. Code 1.			
1408 Faxed MOE Kamloops.			





1506 Briefed MOE RO Rick Wagner; Code 1.

1508 Faxed MOE Kamloops.

Sep. 17. 2012 3:09PM

## DGIR Incident Report DGIR 121685



Category: Code 1

Incident Date Time: 2012-09-17 A.M.

**DGIR INLAND** MCTS#: Spiller: REAL CANADIAN SUPERSTORE # 1552 Location: 3020 LOUIE DRIVE MOE Region: Thompson PEP Region: CTL Area: WEST KELOWNA Region Material(s): **R507 REFRIGERANT** Amount(s): 200 LBS Received From: Caller A: Caller B: Org: Org: s.22 Phone: Phone: Alternate: Alternate: Time: Time: Received at PEP by Duty Officer: YVONNE When Received: 2012-09-17 14:31 Affected Environment: Atmosphere Other: Type of Spilling: Other Spill Type: Equipment Failure Accidents: Sector: Commercial Cause: Weld broke due to vibration. Response: Has been repaired and re-charged. Jurisdiction: Federal, Provincial Task #: Amount:\$ Issued To: Notification: 1504 Phoned MOE RO Dennis Redford on Cell (left message).

This report printed on: 2012-09-17 at 15:08:22





1845 - briefed MOE RO Rick Wagner, Fed/Prov code 1

1850 - faxed MOE Kamloops

# DGIR Incident Report DGIR 121709



Category: Code 1

Incident Date Time: 2012-09-18 11:00

MCTS#: DGIR INLAND SUPERSTORE Spiller: 3020 LOUIE DR Location: MOE Region: Thompson PEP Region: CTL **KELOWNA** Area: Region Material(s): R 507 Amount(s): UNKNOWN Received From: Caller B: Caller A: Org: Org : s.22 Phone: Phone: Alternate: Alternate: Time: Time: When Received: 2012-09-18 18:28 Received at PEP by Duty Officer: KAREN Other: Affected Environment: Atmosphere Other Spill Type : Type of Spilling : Equipment Failure Accidents: Sector: Unknown Cause : Advising that 2 coffin cases had a leak. They have been repaired but not refilled. They will not be refilled as it is running fine. Response: Jurisdiction: Federal, Provincial Issued To: RICK WAGNER Amount: \$50 Task #:132771 Notification: 1834 - left message for MOE RO Rick Wagner





Notification:

1848 faxed MOE Kamloops

1844 briefed MOE RO Rick Wagner Code 1 Fed/Prov

#### DGIR Incident Report **DGIR 121717**



Category: Code 1

Incident Date Time: 2012-09-19 14:00

MCTS#:

DGIR INLAND SUPER STORE 1564 Spiller: Location: 2280 BARREN ROAD MOE Region: Thompson PEP Region: CTL Area: **KELOWNA** Region Material(s): R507 Amount(s): UNKNOWN Received From: Caller B: Caller A: Org: Org s.22 Phone: Phone Alternate: Alternate: Time: Time: When Received: 2012-09-19 18:32 Received at PEP by Duty Officer: MIKE Affected Environment: Atmosphere Other: Type of Spilling: Other Spill Type: Equipment Failure Accidents: Sector: Cause: Vibration caused a solder joint to come apart and release refrigerant Response: Emptied sys, Rewielded pipe and tested and refilled the sys Jurisdiction: Federal, Provincial Task #:132782 Amount: \$50 Issued To: RICK WAGNER

This report printed on: 2012-09-19 at 18:48:45

**Emergency Coordination Center** Phone 1-800-663-3456 Fax (250) 952-4872





### DGIR Incident Report DGIR 122013



Category: Code 1

Incident Date Time: MCTS#:

DGIR INLAND Spiller:

REAL CANADIAN SUPERSTORE

REAL CANADIAN

Location:

SUPERSTORE - 3020

LOUIE DRIVE

Area:

WEST KELOWNA

PEP Region: CTL

Other:

MOE Region: Thompson

Region

Material(s):

R507

Amount(s): 50LBS

Received

From:

Caller A: · Org:

s.22

Phone: Alternate:

Time:

Alternate: Time:

Other Spill Type:

Received at PEP by Duty Officer: JIM

When Received: 2012-10-21 08:53

Caller B: Org:

Phone:

Affected Environment: Atmosphere

Type of Spilling:

Industrial

Equipment Failure

Accidents:

Sector:

Cause:

Suction Header on a rack leaked resulting in a release of R507.

Response:

Repaired the system. Not recharged at this time.

Jurisdiction: Federal, Provincial

Task #:133203

Amount: \$50

Issued To: HAROLD RIEDLER

Notification:

08:57 paged Harold Riedler MOE EERO

09;00 briefed Harold RiedlerMOE EERO code 1 fed/prov

09:00 faxed MOE Surrey, MOE Kamloops





Oct. 21. 2012. 9:12AM

# DGIR Incident Update Report **DGIR 122013**



Update #: 1

Type: INLAND UPDATE

Subject: R507

Task#: 133203

Assigned To: HAROLD RIEDLER

Incident Area: WEST KELOWNA

Original Entry Logged: 2012-10-21 08:53

Amount: \$50

ASE Number:

PEP Region: CTL

MOE Region: Thompson Region

MCTS#:

Location: REAL CANADIAN SUPERSTORE - 3020 LOUIE DRIVE

Caller: HAROLD

Organization: MOE

Primary No:

Alt No:

This Update Logged: 2012-10-21 09:08

PEP Duty Officer: BETH

#### Details:

s.22 Advised he received an update from The leak was detected early due to a chemical leak detection device in the immediate area of the leak and will be repaired tomorrow (very small leak). There was no temperature loss in the rack refrigerant area that would lead to potential food spoil, therefore Health authority will not require notification.

### Notification:

09:10 faxed MOE Surrey, MOE Kamloops





Nov. 20. 2012 10:25AM

### DGIR Incident Report DGIR 122290



Category: Code 1

Incident Date Time: 2011-11-07 12:00

MCTS#:

**DGIR INLAND** 

Spiller: WALMART

2170 LOUIE DRIVE

Location:

STORE #1093

Area:

WEST KELOWNA

PEP Region: CTL

MOE Region: Thompson

Region

Material(s):

R407 REFRIGERANT

Amount(s):

125 LBS

Received

From:

Caller A:

Org:

Phone:

Alternate:

Other Spill Type:

Alternate:

Time:

Received at PEP by Duty Officer: BETH

Time: 2012-11-02 09:16 When Received: 2012-11-20 10:15

Other:

Affected Environment: Atmosphere Type of Spilling:

Equipment Failure

Accidents:

Sector:

Unknown

Cause:

Advised that there was a release of R407 to the atmosphere at the above location. This report is a year old as it occurred in 2011. The leak was a result of faulty piping on a refrigeration rack.

Response:

The piping has now been repaired. No longer leaking

Jurisdiction: Federal

Task #:

Amount:\$

Issued To:

Notification:

10:22 phoned Rick Wagner MOE on cell, briefed. Advised code 1 FED

10:25 faxed MOE Kamloops and MOE Penticton