



Province of
British Columbia

Ministry of
Energy, Mines and
Petroleum Resources

Office address:
403 Vernon Street
Nelson, B.C. V1L 4E6
Telephone: (604) 354-6125
Mailing address:
310 Ward Street
Nelson, B.C. V1L 5S4

Tel: 354-6131 Fax: 354-6120

File: 18050-02
JACKHAMMER

July 9, 1991

Mr. Leonard Ogilvie
s.22

Dear Mr. Ogilvie:

Enclosed are two copies of the Inspection Report resulting
from my July 4, 1991 inspection of the Jackhammer Property.

Yours very truly,

D. Roach
Inspector of Mines

DR/sb

Encls.



Province of British Columbia
Ministry of Energy, Mines and Petroleum Resources

REPORT OF INSPECTOR OF MINES

(Issued pursuant to sections 5 and 6 of the Mining Regulation Act)

PROSPECTS UNDER EXPLORATION AND DEVELOPMENT

Name of Prospect: JACKHAMMER

Co-ordinates: 82F/10W
Lat. 49 42' Long. 116 57'

Owner: Jordan Hunter

Locality: Nelson M.D.

Manager: Leonard Ogilvie

Address: s.22

Number employed, including all contractors:

Surface	Underground	Contractors	Total
---------	-------------	-------------	-------

Persons Contacted

Company Representatives

Worker Representatives2

- Three test pits excavated in 1990 and two proposed trench sites were inspected. Inspection conducted with S. Ogilvie, L. Ogilvie and Jordan Hunter.
- All test pits hand-dug in 1990 have been backfilled and recontoured satisfactorily. All sites are stabilized with vegetation.
- The two proposed sites for backhoe trenches are located in a logged area. No trees shall be disturbed during the trenching program. The operators/owners informed me on site that topsoil would be separated for later use during reclamation (pursuant to Mineral Exploration Guidelines, Section 4.2).
- It was also discussed that in the event of trenches becoming deeper than 4 feet, the proper precautions shall be employed. Either slope the sides of the excavation to a safe angle or have the sides supported by a system approved by the District Inspector (pursuant to the Health, Safety and Reclamation Code, Section 11.8.1).



Province of British Columbia
Ministry of Energy, Mines and Petroleum Resources
Land Management and Policy Branch
REPORT OF INSPECTOR OF MINES
(Issued pursuant to Section 15 of the Mines Act)

MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
CRANBROOK, B.C.

NOV - 7 1995

FILE _____

File No.: 0500402-18050-02

Name of Mine: Nor Claim

Owner of Property: R. Davidson

Date of Inspection: October 19, 1995

Location: Lendrum Creek, Ainsworth

Manager: Ron Davidson

Address: s.22

Owner or Operator Representative: R. Davidson

Worker Representative: None

The mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the inspector within 15 days of receiving the report.

INSPECTION REPORT

Manager's Response of Action Taken

Joint inspection with G. MacKay.

Small scale trenching activity has occurred on this site since 1970. The owner was unaware of the requirement for a Mines Act permit.

Total disturbance comprises of a rock cut trench about 8 feet below the road surface, waste rock pile and a series of small shallow trenches on an old skid trail. No forest values or stream values are impacted or are likely to be impacted.

ARD concerns will not exist as the gangue is a quartz /calcite material.

The rock cut trench shall be back filled by July 1, 1996, in order to reduce the property liabilities. The other trenches shall be backfilled and seeded as well, if no longer needed.

A "Notice of Work" shall be submitted for further work on the property.

Steven E. Wuschke

Date: 95/10/24

Inspector: Steven E. Wuschke, P.Eng.

Suite 201, 100 Cranbrook St. N., Cranbrook, B.C. V1C 3P9

Copies to: MHS - Fernie

R Davidson

Date: Nov 3/95

Manager:

Page 4

Withheld pursuant to/removed as

Copyright