

INSPECTION RESULT:

REASON FOR INSPECTION:

**COLLISION REPAIR FACILITY:** 

INSPECTION TYPE:

INSPECTION CLASS:

Ministry of Transportation and Infrastructure

Commercial Vehicle Inspection Report

# FINAL INSPECTION CONFIRMATION NUMBER 10271776

PLACE DECAL HERE

DECAL EXPIRY DATE

PL12078

30 SEP 2015

WORK ORDER # 0486705

INSPECTION START DATE

18 MAR 2015 14:30

18 MAR 2015 19:00

REASON NOTE:

TECHNICIAN NAME:

PHONE #:

INSPECTOR'S NUMBER: 112918

INSPECTOR'S NAME: Huang, Bowen LICENCE EXPIRY DATE: 31-AUG-2016

FACILITY NUMBER: P7156

FACILITY NAME: GREYHOUND CANADA

TRANSPOR

**Pass** 

Complete

Semi-Annual

4 - Bus

OWNER/ LESSEE: GI

CITY:

YEAR:

GREYHOUND CANADA TRANS ULC

ADDRESS: 877 GREYHOUND WAY SW

CALGARY

PROV: AB

POSTAL CODE: T3C 3V8

REGISTRATION #: VEH. JURISDICTION: AB

MAKE: MCI s.15

MODEL:

BODY STYLE: BUS

ODOMETER: 1758470 KM

2000

FUEL TYPE: Diesel

VIN:

UNIT/FLEET #: 1134 BRAKE TYPE: Air

"F" Failed "R" Repaired Same Day "P" Passed "PC" Passed With Caution "O" Out Of Service "NA" Not Applicable PC O NA Pressure Fuel R Р PC 0 Section 1 - Power Train Liquid Propane Gas Compressed Natural Gas Pressure Fuel Inspector's Section 2 - Suspension Name & Number Air Brake Chamber Type, Size and Push Rod Stroke Measurement (mm) Axle # 2 3 6 Section 3 - Hydraulic Brakes Clamp DD-3 Clamp Type: Size: 24 30 16 Section 3A - Air Brakes Slack: Auto Auto Auto Left: 32 38 32 Right: 32 38 32 Section 4 - Steering Comments: Section 5 - Instruments, Auxillary Equipment Air Brake Camshaft Rotation Measurement (degrees) Axle # 2 3 5 6 9 Left: 90 30 30 Section 6 - Lamps Right: 90 30 30 Comments Section 7 - Electrical System Brake Lining/Pad Measurement (mm) 9 Axle # 2 3 5 6 Section 8 - Body & Frame Type: Lining (S Lining (S Lining (S Left: 16 19 19 Right: 16 19 19 Section 9 - Tires & Wheels Comments: Section 10 - Couplers & Hitches Rotor/Drum Measurement (mm) Axle # 2 3 5 6 8 9 Section 11 - Other Vehicle Components Type: Drum Drum Drum 368.3 419.1 381 Left: Right: 419.1 368.3 381 Comments: **General Inspection Comments:** 

Inspector's Name Huang, Bowen

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

Page 1 of 100 TRA-2016-60281



Ministry of Transportation and Infrastructure

Commercial Vehicle Inspection Report

## FINAL INSPECTION CONFIRMATION NUMBER 10678339

PLACE DECAL | HERE

**DECAL EXPIRY DATE** 

PM02105

31 MAR 2016

INSPECTION RESULT: **Pass** Complete INSPECTION TYPE:

Semi-Annual

WORK ORDER # INSPECTION START DATE 24 SEP 2015 06:00 0498558

INSPECTION COMPLETE DATE 24 SEP 2015 10:30

REASON NOTE:

**TECHNICIAN NAME:** 

CALGARY

PHONE #:

INSPECTOR'S NUMBER: 113202

REASON FOR INSPECTION:

**COLLISION REPAIR FACILITY:** 

Tu, Qing Fang INSPECTOR'S NAME:

LICENCE EXPIRY DATE: 31-MAR-2016

P7156 FACILITY NUMBER:

INSPECTION CLASS:

GREYHOUND CANADA FACILITY NAME:

TRANSPOR

4 - Bus

OWNER/ LESSEE:

GREYHOUND CANADA TRANS ULC

877 GREYHOUND WAY SW ADDRESS:

1134

2000

ODOMETER: 1804774 Mile

PROV: AB

POSTAL CODE: T3C 3V8

REGISTRATION #:

CITY:

VEH. JURISDICTION: AB MAKE: MCI

PLATE: S.15

MODEL:

YEAR: BODY STYLE: BUS

s.15 VIN:

FUEL TYPE: Diesel

UNIT/FLEET #:

BRAKE TYPE: Air

"PC" Passed With Caution "O" Out Of Service "NA" Not Applicable

	F	R	P PC	O N	Pres	sure Fu	əl					F	R	PF	со	N/
Section 1 - Power Train		•	<u> </u>		Lic	quid Pro	oane Ga	s								V
					Co	mpress	ed Natur	al Gas								
Section 2 - Suspension		•	<u> </u>		Pr Na	essure ime & N	Fuel Ins <sub>l</sub> umber	pector's ,								
								hamber Ty							nt (m	
Section 3 - Hydraulic Brakes				<b>-</b>	Axle # Type:	# 1 Clamp	2 DD-3	3 Clamp	4	5	6		7	8		9
			_		Size:	24	30	16								
Section 3A - Air Brakes			<u> </u>		_	Auto	Auto									
					Left:	32	38	32								
Section 4 - Steering					Right:		38	32								
Section 4 - Steering			<b>V</b>		Comn	nents:										
Section 5 - Instruments, Auxillary Equipment			╌		Ai	r Brake Ca	mshaft	Rotation	Measure					—		
					Axle #		2	3	4	5	6		7	8		9
Section 6 - Lamps					Left:	25	25	45								
Section 6 - Lamps			<b>V</b>		Right:		25	45								
					-											
Section 7 - Electrical System			<b>V</b>		┺											
					1	1		Brak 3	e Lining	g/Pad Me 5	asureme		<b>n)</b> 7	8		•
Section 8 - Body & Frame		-	<b>/</b>		Axle #		2 S Lining	ع S Lining (S)		5	ь		/	8		9
K)					Left:	20	20	16	6.							
					Right:		20	16								
Section 9 - Tires & Wheels		ш			Comn											
					1											
Section 10 - Couplers & Hitches			$\checkmark$		₽—				-1(D	14		(				
					Axle i	# 1	2	3 3	otor/Dru 4	ım Meası 5	urement 6		7	8		9
Section 11 Other Vehicle Components						7 I Drum	Drum		4	5	ь		/	8		9
Section 11 - Other Vehicle Components					Left:	419.1	368.3									
						419.1	368.3									
					Comn		300.0	301								
General Inspection Comments:																
SECTION OF																

Inspector's Name Tu, Qing Fang

Signature

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations. NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

Page 2 of 100 TRA-2016-60281



## Ministry of Transportation and Infrastructure

## **FACILITY AUDIT**

## **COMMERCIAL VEHICLE SAFETY & ENFORCEMENT**

Facility Number: P	P7156	│ New   又 Renewal	Audit Date:	August 25 2015				
Facility Name: _G	Greyhound Canada		Time In:	Time Out:				
Facility Address: 1	465 Thornton Stree	et	Telephone:	604 661 0322				
City: V	ancouver		Fax:					
Province: B	3C F	Postal Code:	Email:	paul.bhumrah@greyhound.com	·			
Authorized Inspectors Currently Employed by Facility Include additional Authorized Inspectors in the comments section or the Facility Audit Attachment Form.  Name: Al Number: Aaron Nilesh Chand 114491  Qing Fang Tu 113202  KEN KUMARAN NAIR 102655  EDGAR NEIL RAWLINS MO8737  MARK ROBERT LOCHHEAD MO8809  Dan Caliman 112584  Vehicle Inspections/ History: Total Active Inspections - Last 12 Months: 131  Total Active Inspections - Last 24 Months: 293  Rebuilt from Salvage Vehicles:			Authorized Classes of Vehicles to Inspect Recommend to: Add Remove Al Authorized  1 - MV5500 kg & under 2 - MV5501 kg & over  X 3 - Trailers  X 4 - Buses  5 - School Buses  6 - Motorcycles  Facility Endorsements  7 - Rebuilt from Salvage  8 - New to BC  X A - Air Brake  P - Pressure Fuel  Licence Restrictions:  Trailers - Utility trailers only  Buses - 5500 GVW and under only  Heavy Vehicles - 8,201 kg LGVW and under only  Other  Operator Initial					
Structural Integrity F Vehicle Inspection F All original S.I. Repo	Reports:	Yes No	Licence Restrictions	·				
Authorized Inspector and Autobody Technician: Yes No			Facility Dimensions: (New Facility Locations) Facility must fully accommodate vehicles inspected					
Additional comments			Door width: Longest bay length:					
			Door height:	Number of Bays:				
VIP Administra	tion:		Tools:					
Large Station Deca	1:	Displayed	Hoist/Pit (req	uired for light vehicles);	Yes			
Facility Licence disg	played:	Yes	Automotive h	and tools for authorized vehicles:	Yes			
Al Certificates displa	ayed:	All Displayed	Headlight aim	ning device:	Yes - Optical			
Inspection reports s	signed:	Yes in bus files	]	pth / Tire pressure gauge:	Yes			
Reports are submitt	ted within 10 days:	Yes	1	pension free-play measuring tools:	Yes			
Reports are retained	d for 18 months:	yes	ı	ch (sizes applicable to vehicle types):	'			
Reports are comple	17			wheel king pin gauge:	N/A			
Decal log complete:				: / Pintle hitch gauge:	Yes			
	nused decals are secure: Yes			nbly removal device;	Yes			
	Decals are accounted for:  Yes  Yes		Digital decibe					
Copy of the current manual: Hard copy on hand		] -	rter (pressure fuel):	Yes				
Copy of the current Regulations: Hard copy on hand			1	•	N/A			
DIF Operator Cours				mber measuring device:	Yes			
Dir Operator Cours		Sec comments below	parake drum/ili	ning measuring tools:	Yes			



## Ministry of Transportation and Infrastructure

## FACILITY AUDIT COMMERCIAL VEHICLE SAFETY & ENFORCEMENT

Concerns and/or Findings - *Areas of Non-Compliance must be specifically note	-d:			
		<u> </u>		
4 inspections were conducted on august 8 2015 at the facility on vehicles inspected by t s.15  CVIP PL12116 - results VP (fail) - no stroke indicators p CVIP PL12085 - result VP (fail) - cracked windshield, n CVIP PL 12105 - result VP (fail) - stroke indicators, 9 of CVIP PL12104, result VP (fail) - stroke indicators, front s	oresent and loose entrar no stroke indicators 20 LED's out on a brak	e lamp		
100% failure rate on 4 inspections.				
This is a large corporate maintenance facility with 4 hoists, 5 service pits and according inspections in the past year. No US buses have been inspected at this facility since last which is required to submit NSC reports directly to CVSE HQ in Victoria. Note: No in information of the program management additional inspectors:  ZHI YONG ZHANG M14388, RYAN DAVID WALSH 114496, HAI AN WU 200292, HAI MANVIR SINGH PUREWAL 200405	audit. This company is ormation is available on	an Alberta based carrier CVSE internal systems for		
Roadside inspection(s) conducted: Yes No Results: UNKNOWN		Date:		
Violation ticket(s) issued: Yes No VT Number:		Date:		
To: For:				
Recommendations / Relevant history / Next actions or follow up:				
course offered by BCIT. I recommend that each facility consider taking this 1 day course renewal. Contact BCIT or other institution for course details.  Facility Assessment completed: Yes Included Nolx Reason: Pacility Audit Attachment document included  Facility recommended for licencing	n prior to it being a mans	Operator Initial		
Facility recommended for licencing deferral				
Facility operator agrees to remedy the noted area(s) of non-compliance on o	r before:			
*Failure to comply with terms and conditions may result in a delay of facil	lity licencing, suspens	Operator Initial  Sion or cancellation.		
Facility Operator Name: Paul Bhumrah , Area Maintenance Manager	Facility Numbe	r: p7156		
Facility Operator Signature:	Date: 25 August 2015			
CVSE Officer Name: Greg Neal greg.neal@gov.bc.ca	Phone No.:	604 813 5839		
CVSE Officer Signature:	Next scheduled Audit: 24 months + -			
Mailing Address: PO Box 9250	Telephone: 250	· · · · · · · · · · · · · · · · · · ·		

CVSE0006 (112014)

Visit our Website at www.cvse.ca

Page 2 of 2

## Parkes, Norm E TRAN:EX

From: Hubner, Todd B TRAN:EX

Sent: Thursday, January 14, 2016 3:01 PM

To: Lorimer, Mike TRAN:EX

Cc: Parkes, Norm E TRAN:EX; Moores, Brad A TRAN:EX

**Subject:** Cariboo Hwy #97 Bus Crash update

Mike:

Further to below.

We've received additional information this pm with regards to the incident, which is now indicating that the bus was in fact northbound on Hwy 97 coming down the hill prior to the crash (sorry about this). It appears that the northbound vehicle lost control, did a 180 degree turn on the Highway and went off road left, coming to rest facing southbound. s.15

Todd.

From: Hubner, Todd B TRAN:EX

Sent: Thursday, January 14, 2016 2:03 PM

To: Lorimer, Mike TRAN:EX

Cc: Parkes, Norm E TRAN:EX; Moores, Brad A TRAN:EX

Subject: RE: Incident 4439 - Cariboo Hwy #97 N by Ewing Road

Hi Mike: Surface temps in the area have been hovering around zero over the last 24 hours. Hwy 97 yesterday was bare and wet from Williams Lake to the north Boundary as of early afternoon yesterday. (I was in Quesnel yesterday).

The webcam "replay of the day" in Hixon shows that it was bare and wet yesterday pm. In early evening there was a light dusting of snow evident in the video. By 3:00 am the webcam still indicated a light dusting of snow with it being bare in the wheel tracks. There is video evidence of maintenance overnight based on the Highway surface conditions. By just after daybreak today, the Highway was again bare and wet. Hixon Web cam link below.

## http://images.drivebc.ca/bchighwaycam/pub/html/www/252.html

In talking with our local area RAM whom was on-scene at 9:14 am today, the surface temp and air temp were hovering at 0 C at the time of his arrival. Although the Highway was snowcovered at the time of his arrival due to it now being closed, there was just a light dusting of snow on it. (perhaps 1 cm). He scraped it off with his boot and observed the pavement surface being wet with abrasives on it.

Emcon provided us with their best photo of the roadsurface taken at the time that they arrived (just after the crash occured), (quality is not the best), however there is clear evidence of abrasive and the wheel paths also slushing up.

- Northbound
- Southbound

## 3. Incident Description

- MVI

Comments: Greyhound bus southbound went off road left coming out of a curve

## 4. Public Comments

Not applicable

## 5. ETO\*

At Jan 14 10:00\*

Next Update\*: Jan 14 12:00

## 6. Detailed Event Description\*

Greyhound bus was southbound coming out of a left curve and proceeding to enter an uphill grade when it went off the road and ended up on its side.

Estimated Time of Event: Jan 14 08:00

## 7. Injuries\Fatalities

Num. People Involved: 7 (Confirmed)

Injuries: 3 (Confirmed)
Fatalities: 0 (Confirmed)

## 8. MoTi Staff\*

- Area Manager or District Rep: On-Scene

- Operations Manager: Monitoring

- DMT: Monitoring
- Names: Len Sauchuk

## 9. Incident Responders\*

Maintenance Contractor: On-Scene
 Fire / Search and Rescue: On-Scene

- Ambulance: On-Scene

- RCMP General Duty: On-Scene

## 10. Site History

Not applicable

## 11. Weather/Road Conditions


**Plowing & Sanding-salting In Progress** 

Air Temp: Cold

Road Surface: Hot Mix 0 C

## 12. MC's Activities

Plowing and sanding through incident area



## Parkes, Norm E TRAN:EX

From: Parkes, Norm E TRAN:EX Sent: Thursday, January 14, 2016 1:48 PM To: Stone, Todd TRAN:EX Cc: Bell, Jordan TRAN:EX; Diacu, Raz TRAN:EX; Sauder, Kit TRAN:EX; Main, Grant TRAN:EX; Richter, Kevin J TRAN:EX; Kislock, Lindsay M TRAN:EX; Quealey, Pat TRAN:EX; Duffy, Chris D TRAN:EX; Lorimer, Mike TRAN:EX; Cousins, Paula TRAN:EX; Jabs, Ryan GCPE:EX; Rorison, Trish GCPE:EX Subject: RE: MVI - greyhound - Hwy 97 north of Hixon Attachments: IMG\_3842.JPG Photo attached Note, the photo was taken about 90 min after the crash and it has been snowing lightly in the area Norm ----Original Message----From: Parkes, Norm E TRAN:EX Sent: Thursday, January 14, 2016 1:18 PM To: Stone, Todd TRAN:EX Cc: Bell, Jordan TRAN:EX; Diacu, Raz TRAN:EX; Sauder, Kit TRAN:EX; Main, Grant TRAN:EX; Richter, Kevin J TRAN:EX; Kislock, Lindsay M TRAN:EX; Quealey, Pat TRAN:EX; Duffy, Chris D TRAN:EX; Lorimer, Mike TRAN:EX; Cousins, Paula TRAN:EX; Jabs, Ryan GCPE:EX; Rorison, Trish GCPE:EX Subject: Re: MVI - greyhound - Hwy 97 north of Hixon Minister Updated info: Indications are the bus actually spun and is off road on the southbound side of the highway. Staff are confirming. Sent from my iPhone > On Jan 14, 2016, at 10:19 AM, Parkes, Norm E TRAN:EX < Norm.Parkes@gov.bc.ca > wrote: > > Minister > Bus was driving northbound (up hill), appears to have spun out. > RCMP have closed the northbound lanes to conduct a full analysis. Given there were no injuries or fatalities, we suspect they are considering whether driver actions had any baring on the crash. > Highway is at single lane alternating. > > Norm > Sent from my iPhone

>> On Jan 14, 2016, at 8:48 AM, Parkes, Norm E TRAN:EX < Norm.Parkes@gov.bc.ca > wrote:

From:

Haywood, Steven TRAN:EX

Sent:

Thursday, January 14, 2016 1:11 PM

To:

Lowe, Sonia GCPE:EX; Dennis, Perry TRAN:EX

Cc:

Lorimer, Mike TRAN:EX; Knight, Jeff J TRAN:EX; Rorison, Trish GCPE:EX; Jabs, Ryan

GCPE:EX; Thomson, Elizabeth GCPE:EX

Subject:

RE: INPUT REQUIRED - Media Request - CBC Vancouver - Motorcoach review

Looks good Sonia, the only amendment is the highlighted area – can be changed out with "to be completed early Spring 2016".

Regards,

Steve

From: Lowe, Sonia GCPE:EX

Sent: Thursday, January 14, 2016 1:08 PM

To: Haywood, Steven TRAN:EX; Dennis, Perry TRAN:EX

Cc: Lorimer, Mike TRAN:EX; Knight, Jeff J TRAN:EX; Rorison, Trish GCPE:EX; Jabs, Ryan GCPE:EX; Thomson, Elizabeth

GCPE:EX

Subject: INPUT REQUIRED - Media Request - CBC Vancouver - Motorcoach review

Hi Steve,

CBC Vancouver has called –asking for more information on the motorcoach review. I've pulled some information – if you can review for accuracy. Do we know if we've firmed up a date for when the review might be complete?

Minister Request Y/N: No – background information only

**Topic:** Motorcoach review

Reporter/ Contact: Tom Popyk - 604-609-5800 / 416-875-5968

Outlet: CBC Vancouver TV/Radio

Date/ Time received: January 14 – 1:00 pm

Deadline: asap to know

KMS:

s.13

•

•

Sonia Lowe | Public Affairs Officer Ministry of Transportation and Infrastructure Government Communications and Public Engagement

Tel: 250.356.8241 | Mobile: 250.882.6696 | email: sonia.lowe@gov.bc.ca

From:

Orrbine, Brian <bri> <bri> drian.orrbine@tc.gc.ca>

Sent:

Thursday, January 14, 2016 1:07 PM

To: Subject: Haywood, Steven TRAN:EX Re: Bus accident on hwy97

Thanks

В

Sent from my BlackBerry 10 smartphone on the Rogers network.

From: Haywood, Steven TRAN:EX

Sent: Thursday, January 14, 2016 3:57 PM

To: Orrbine, Brian

Subject: RE: Bus accident on hwy97

Hi Brian,

Single vehicle crash, Greyhound bus from Alberta went into ditch and turned onto its side, 9 people taken to hospital (3 of which being reported as serious).

Under investigation.

Regards, Steve

P.s. longform is Steven

From: Orrbine, Brian [mailto:brian.orrbine@tc.gc.ca]

Sent: Thursday, January 14, 2016 12:44 PM

To: Haywood, Steven TRAN:EX Subject: Bus accident on hwy97

Stephen. Any details at this time?

Brian

From:

Jim Sawitsky <jim.sawitsky@gov.ab.ca>

Sent:

Thursday, January 14, 2016 12:40 PM

To: Subject: Haywood, Steven TRAN:EX Re: Greyhound crash

Thanks Steve.....I'll be in touch.

Jim

Sent from my iPhone

On Jan 14, 2016, at 1:21 PM, Haywood, Steven TRAN:EX <Steven.Haywood@gov.bc.ca> wrote:

Hi Jim, just a heads up – we had a Greyhound crash this morning near Hixon, BC. What we know:

- the bus lost control and went into the ditch, flipping onto the side
- 9 people on the bus, 3 have serious injuries
- No other vehicles appear to be involved
- Compact snow and slush in the area
- Alberta plates Buss.15 and Trailer s.15

Investigation ongoing, picture attached.


Regards,

Steve

Up-to-date road information, including traffic delays, is a click or a call away. Call 5-1-1 toll-free, visit 511.alberta.ca or follow us on Twitter @511Alberta to get on the road to safer travel.

http://511.alberta.ca/ab/en.html https://twitter.com/511Alberta

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail.



From:

Haywood, Steven TRAN:EX

Sent:

Thursday, January 14, 2016 10:36 AM

To:

Hunsaker, Val D TRAN:EX

Subject:

RE: Accident hwy #97 by ewing

### Ok thanks

From: Hunsaker, Val D TRAN:EX

Sent: Thursday, January 14, 2016 10:33 AM

To: Haywood, Steven TRAN:EX

Subject: RE: Accident hwy #97 by ewing

I don't have any measurements yet. Just verbal comment.

**From:** Haywood, Steven TRAN:EX **Sent:** January-14-16 10:30 AM **To:** Hunsaker, Val D TRAN:EX

Subject: RE: Accident hwy #97 by ewing

s.15

From: Hunsaker, Val D TRAN:EX

Sent: Thursday, January 14, 2016 10:30 AM

To: Haywood, Steven TRAN:EX

Subject: RE: Accident hwy #97 by ewing

s.15

**From:** Haywood, Steven TRAN:EX **Sent:** January-14-16 10:28 AM **To:** Hunsaker, Val D TRAN:EX

Subject: RE: Accident hwy #97 by ewing

10-4 thanks

Joe give any indication regarding s.15

Regards, Steve

From: Hunsaker, Val D TRAN:EX

Sent: Thursday, January 14, 2016 9:59 AM

To: Haywood, Steven TRAN:EX

Subject: FW: Accident hwy #97 by ewing

Hello Steve,

I have yet to confirm the correct direction of travel.

Val

From: Hubner, Todd B TRAN:EX Sent: January-14-16 9:49 AM To: Hunsaker, Val D TRAN:EX

Subject: FW: Accident hwy #97 by ewing

Hi Val: here are some photos from Len Sauchuk, (local RAM), that is now on-scene. Our intel. is indicating the bus was Sthbd. (yet to be confirmed).

Todd

From: Moores, Brad A TRAN:EX

Sent: Thursday, January 14, 2016 9:46 AM

To: Hubner, Todd B TRAN:EX; Haywood, Steven TRAN:EX

Subject: FW: Accident hwy #97 by ewing

Hi, attached are the Greyhound bus accident. The bus was South Bound.

Len Sauchuk is on RAM on scene.

### **Thanks**

## Brad



From: Rorison, Trish GCPE:EX

Sent: Thursday, January 14, 2016 10:35 AM

To: Lowe, Sonia GCPE:EX; Maxwell, Scott D TRAN:EX; Haywood, Steven TRAN:EX

Cc: Parkes, Norm E TRAN:EX; LeGroulx, Courtney TRAN:EX; Jabs, Ryan GCPE:EX; Hubner,

Todd B TRAN:EX; Lorimer, Mike TRAN:EX

Subject: RE: BULLETS FOR APPROVAL - Bus crash - Hwy 97

s.13

From: Rorison, Trish GCPE:EX

Sent: Thursday, January 14, 2016 10:27 AM

**To:** Lowe, Sonia GCPE:EX; Maxwell, Scott D TRAN:EX; Haywood, Steven TRAN:EX **Cc:** Parkes, Norm E TRAN:EX; LeGroulx, Courtney TRAN:EX; Jabs, Ryan GCPE:EX

Subject: RE: BULLETS FOR APPROVAL - Bus crash - Hwy 97

## Approved by Norm:

- I understand that earlier this morning, a Greyhound bus drove off-road along Highway 97 north of Hixon.
- Details are still being confirmed but RCMP is leading the crash investigation. Commercial Vehicle
  Safety Enforcement staff are on scene assisting the RCMP and will conduct an inspection of the bus as
  a routine part of the investigation.
- There is a lane closure while the RCMP conduct their investigation. The Highway is currently open to single-lane alternating, at this time and Highway 97 is open in both directions.
- Drivers should check Drive BC for the most up-to-date information.

From: Lowe, Sonia GCPE:EX

Sent: Thursday, January 14, 2016 10:19 AM

To: Maxwell, Scott D TRAN:EX; Haywood, Steven TRAN:EX

Cc: Rorison, Trish GCPE:EX; Parkes, Norm E TRAN:EX; LeGroulx, Courtney TRAN:EX; Jabs, Ryan GCPE:EX

Subject: BULLETS FOR APPROVAL - Bus crash - Hwy 97

Importance: High

Hi Scott and Steven,

Draft / preliminary holding lines on the Hwy 97 bus crash for approval, please. Let me know if you have any changes.

I understand that just after 8:00 am(?) this morning, a Greyhound bus was involved in a crash on Highway 97 north of Hixon.

Details are still being confirmed but RCMP is leading the crash investigation. Commercial Vehicle Safety Enforcement staff are on scene assisting the RCMP.

This crash has not resulted in lane closures at this time and Highway 97 is open in both directions. Drivers should check Drive BC for the most up-to-date information.

Thank you,

Sonia Lowe | Public Affairs Officer
Ministry of Transportation and Infrastructure
Government Communications and Public Engagement
Tel: 250.356.8241 | Mobile: 250.882.6696 | email: sonia.lowe@gov.bc.ca

**Brad** 

Hucal, Jackie TRAN:EX					
From: Sent: To: Subject:	Haywood, Steven TRAN:EX Thursday, January 14, 2016 10:28 AM Hunsaker, Val D TRAN:EX RE: Accident hwy #97 by ewing				
10-4 thanks s.15					
Regards, Steve					
From: Hunsaker, Val D TRAN:EX Sent: Thursday, January 14, 201 To: Haywood, Steven TRAN:EX Subject: FW: Accident hwy #97	6 9:59 AM				
Hello Steve,					
I have yet to confirm the correct	direction of travel.				
Val					
From: Hubner, Todd B TRAN:EX Sent: January-14-16 9:49 AM To: Hunsaker, Val D TRAN:EX Subject: FW: Accident hwy #97  Hi Val: here are some photos f bus was Sthbd. (yet to be conf Todd	rom Len Sauchuk, (local RAM), that is now on-scene. Our intel. is indicating the				
From: Moores, Brad A TRAN:EX Sent: Thursday, January 14, 201 To: Hubner, Todd B TRAN:EX; Ha Subject: FW: Accident hwy #97	aywood, Steven TRAN:EX				
Hi, attached are the Greyhound b	ous accident. The bus was South Bound.				
Len Sauchuk is on RAM on scene.					
Thanks					



From: Haywood, Steven TRAN:EX

Sent: Thursday, January 14, 2016 10:22 AM

To: Lowe, Sonia GCPE:EX; Maxwell, Scott D TRAN:EX

Cc: Rorison, Trish GCPE:EX; Parkes, Norm E TRAN:EX; LeGroulx, Courtney TRAN:EX; Jabs,

Ryan GCPE:EX

Subject: RE: BULLETS FOR APPROVAL - Bus crash - Hwy 97

Hi Sonia,

The messaging is good except that Drive BC is showing single lane alternating traffic as of 10:08am. .

Regards, Steve

From: Lowe, Sonia GCPE:EX

Sent: Thursday, January 14, 2016 10:19 AM

To: Maxwell, Scott D TRAN:EX; Haywood, Steven TRAN:EX

Cc: Rorison, Trish GCPE:EX; Parkes, Norm E TRAN:EX; LeGroulx, Courtney TRAN:EX; Jabs, Ryan GCPE:EX

Subject: BULLETS FOR APPROVAL - Bus crash - Hwy 97

Importance: High

Hi Scott and Steven,

Draft / preliminary holding lines on the Hwy 97 bus crash for approval, please. Let me know if you have any changes.

I understand that just after 8:00 am(?) this morning, a Greyhound bus was involved in a crash on Highway 97 north of Hixon.

Details are still being confirmed but RCMP is leading the crash investigation. Commercial Vehicle Safety Enforcement staff are on scene assisting the RCMP.

This crash has not resulted in lane closures at this time and Highway 97 is open in both directions. Drivers should check Drive BC for the most up-to-date information.

Thank you,

Sonia Lowe | Public Affairs Officer


Ministry of Transportation and Infrastructure

Government Communications and Public Engagement

Tel: 250.356.8241 | Mobile: 250.882.6696 | email: sonia.lowe@gov.bc.ca







From: Haywood, Steven TRAN:EX

Sent: Thursday, January 14, 2016 9:18 AM

To: Lowe, Sonia GCPE:EX
Cc: Rorison, Trish GCPE:EX

Subject: Re: MVI - greyhound - Hwy 97 north of Hixon

Yes of course, CVSE staff from Prince George on route. We are unsure if there will be cell service at the incident location.

Regards, Steve

----- Original message ------From: "Lowe, Sonia GCPE:EX"

Date: 2016-01-14 9:04 AM (GMT-08:00)

To: "Haywood, Steven TRAN:EX" Cc: "Rorison, Trish GCPE:EX"

Subject: FW: MVI - greyhound - Hwy 97 north of Hixon

Hi Steven,

In Elizabeth's absence - hoping you can loop myself and Trish in on any new developments on this Hwy 97 crash..

Thanks, Sonia s.17

----Original Message----From: Rorison, Trish GCPE:EX

Sent: Thursday, January 14, 2016 8:55 AM

To: Groot, Jeff GCPE:EX; McAndrews, Caroline GCPE:EX

Cc: Jabs, Ryan GCPE:EX; Thomson, Elizabeth GCPE:EX; Lowe, Sonia GCPE:EX

Subject: FW: MVI - greyhound - Hwy 97 north of Hixon

FYI - early details.

----Original Message----

From: Parkes, Norm E TRAN:EX

Sent: Thursday, January 14, 2016 8:48 AM

To: Stone, Todd TRAN:EX

Cc: Bell, Jordan TRAN:EX; Diacu, Raz TRAN:EX; Sauder, Kit TRAN:EX; Main, Grant TRAN:EX; Richter, Kevin J TRAN:EX; Kislock, Lindsay M TRAN:EX; Quealey, Pat TRAN:EX; Duffy, Chris D TRAN:EX; Lorimer, Mike TRAN:EX; Cousins, Paula

TRAN:EX; Jabs, Ryan GCPE:EX; Rorison, Trish GCPE:EX

Subject: MVI - greyhound - Hwy 97 north of Hixon

Minister

We have initial reports of a greyhound bus off road right just north of Hixon.

The bus is in its side. 8 passengers. No serious injuries.

No road closure required.

Roads were slushy. No indication of cause.

Ops staff and CVSE are on route.

Details when available.

Sent from my iPhone

Page 026 to/à Page 093

Withheld pursuant to/removed as

s.15

## Cerina, Carla TRAN:EX

From:

Hunsaker, Val D TRAN:EX

Sent:

Thursday, March 3, 2016 9:34 AM

To:

Nordquist, Laura TRAN:EX FW: Accident hwy #97 by ewing

Subject: Attachments:

IMG\_3842.JPG; IMG\_3844.JPG; IMG\_3845.JPG; IMG\_3847.JPG; IMG\_3848.JPG

From: Hubner, Todd B TRAN:EX Sent: January-14-16 9:49 AM To: Hunsaker, Val D TRAN:EX

Subject: FW: Accident hwy #97 by ewing

Hi Val: here are some photos from Len Sauchuk, (local RAM), that is now on-scene. Our intel. is indicating the bus

was Sthbd. (yet to be confirmed).

Todd

From: Moores, Brad A TRAN:EX

Sent: Thursday, January 14, 2016 9:46 AM

To: Hubner, Todd B TRAN:EX; Haywood, Steven TRAN:EX

Subject: FW: Accident hwy #97 by ewing

Hi, attached are the Greyhound bus accident. The bus was South Bound.

Len Sauchuk is on RAM on scene.

Thanks

Brad



