Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: NCT 2015 11 21 05 01

Location of Incident: 1700 HIGHWAY 3 E

**CHRISTINA LAKE BC V0H 1E0** 

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$.21

Related to Wildland Interface Fire: NO Property Value: \$.21 Content Value: \$0 Total Value at Risk: \$.21

Code Name: Code Description

PROPERTY COMPLEX: 1700 FOOD OR BEVERAGE ESTABLISHMENT

PROPERTY CLASSIFICATION: 1730 PUB/NEIGHBOURHOOD TAVERN - INCLUDES PLACES SPECIALIZING IN T

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 4000 1001 TO 2500M2 (10765 - 26910FT2)

YEAR OF CONSTRUCTION: 1974 1974

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY

SMOKE ALARM OPERATION: 9500 ALARM NOT ACTIVATED - UNKNOWN

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 1000 BASEMENT, SUB-BASEMENT

FIRE ORIGIN, AREA: 7300 CEILING & FLOOR ASSEMBLY - INCLUDES CONCEALED FLOOR/CEILING

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI MATERIAL FIRST IGNITED: 8000 BUILDING COMPONENT - FLOOR, CEILING, ROOF. (EXCLUDES FLOOR C

ACT OR OMISSION: 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge # Telephone ReportDate
GRESLEY-JONES, KEN 1101 250-666-0911 2015-11-23

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner  ${\tt FIRE\ REPORT\ \textbf{-}\ STRUCTURE\ (NARRATIVE)}$ 

INCIDENT NUMBER: NCT 2015 11 21 05 01

## Remarks:

DETAILED INVESTIGATION REVEALED BURNED WIRING FOR A 3 PHASE SYSTEM IN TWO LOCATIONS UNDER THE DANCE FLOOR THAT CAUSED SUFFICIENT EXPLOSION TO START A FIRE AND WERE DIRECTLY UNDER THE AREAS WHERE THE FIRE SELF VENTED THROUGH THE ROOF. THIS BUILDING WAS A TOTAL LOSS. ELECTRICAL OPINIONS WERE OBTAINED FROM AN ELECTRICIAN BUT WE CANNOT SAY ABSOLUTELY THAT THE SHORT CIRCUIT IN THESE TWO LOCATIONS WAS THE DEFINITE CAUSE.

Investigating Officer GRESLEY-JONES, KEN LAFC Badge #

1101

Telephone 250-666-0911 ReportDate 2015-11-23

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: NCT 2015 11 21 05 01

s.22

: OWNER

Name no. : 1

Name : OLDROYD, RUPERT

Address :s.22

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: \$.21 Content Loss: \$0 Total Loss: \$.21

REMARKS:

OWNER WAS NOT ON SCENE AT THE TIME OF THE FIRE, BUILDING WAS UNOCCUPIED

Investigating Officer LAFC Badge # Telephone ReportDate GRESLEY-JONES, KEN 1101 250-666-0911 2015-11-23

3 of 4

Incident Report Page 4 of 4