


## REPORT OF FATAL COLLISION

The information collected on this form is directly related to, is necessary for, and will be used to assess safety problems and evaluate the need for safety improvement action plans. If you have any questions about the collection, use and disclosure of this information, contact the Senior Highway Safety Engineer (250) 356-5292 BC Ministry of Transportation, PO Box 9850 Stn Prov Govt, Victoria BC V8W 9T5 From: District Manager, Transportation Regional Traffic Engineer To: Ron Marshall, Prince George , BC BC Norm Schien, Prince George 23 2015 02 01 Accident Case Number from Top R 2015-98 Valemt Accident Date/Time: Left Corner of Police MVA Form: Hour Minute Year Month Day 24 Hr Format Location of Collision: Highway 5, 750 metres north of Jackman Flat Road 5 140.44 8 9 N/A 9 5 1 **GPS Coordinates** LKI Longitude Latitude Km Seg. Hwy Railway Crossing Signalized Intersection ☐ Unsignalized Intersection Driveway ☐ Bridge Mighway Section Ramp Other 2 % Grade Radius of Curve ⊠ Tangent m Weather: ☐ Clear ☒ Cloudy ☐ Raining ☐ Snowing/Sleet ☐ Hail ☐ Fog ☐ Smog/Smoke ☐ Strong Wind Road Surface Conditions: ☐ Dry ☐ Wet ☐ Muddy ☒ Snow ☐ Slush ☒ Ice km/h Advisory Speed: 100 km/h Posted Speed: Vehicle Type Pickup Semi Transport Truck Vehicle Type □N⊠S□E□W  $\boxtimes$ N  $\square$ S  $\square$ E  $\square$ W Direction: Direction: ⊠ NO Any highway maintenance/construction activity in immediate collision vicinity? ☐ YES (If yes, please include record plan of work site showing all signs and other control(s)) □ NO Has location been inspected by MoT since the collision? Brief description of the vehicle(s) movement(s) just before and during the collision: NB Semi lost control and appeared to jack knife into SB lane. SB pickup moved to NB lane to avoid a head on collision. The passenger side of the pickup hit the semi's passenger side of the trailer and flipped upside down onto right of way next to NB shoulder. The semi ended in SB ditch facing south, ripped from the trailer still facing north over shoulder. Lucille Green, Area Manager Roads. Form completed by: (print name and position) Other Comments: Highway surface: Wheel paths were bare with well sanded light ice, with packed snow between. The driver of the pickup was killed upon impact. The driver of the semi was uninjured.



Optional attachments: Newspaper clips, maintenance report and photos

~ CONFIDENTIAL ~