Emcon Services Inc. **SIGN REFLECTORIZATION REVIEW**
(Signs with <80% reflectorization)

AREA 12 Revelstoke

ROAD NAME & #	ROAD CLASS	INSPECTION DATE	LOCATION	TYPE	DATE ORDERED	REPAIRED/ REPLACED	DAMAGE
TCH West #1	A	April 26/18	23 South	Intersection			
			3.5km west	Passing lane ahead			Bent
			Woods Overhead				
			0.2	3V alley Frontage rd			Lettering Damaged
			3.7	Logging Truck			Reflective
			Crazy Cr. Bdg Eastbound.				
			0.1KM East	NO Left turns			Bent
			19mile Overhead				
			1.3 KM	Camping lodging			Reflective
			Camp Cr. Bdg.				
			0.1 KM	For 1 KM			Reflective
			2.7 KM	Diminishing Lane			"
			4.0KM	Trucks Turning			upside down
			3V overhead				
			60 Km	Trucks Turning			Reflective
			1.0KM	Logging Truck			"
			1.5KM	Tippy Truck			"
			Wap lk. rd.				
			0.7 KM	Rockfall			"
			1.3 KM	Left Curve			Bent
			3 KM	3V Frontage Rd.			Lettering Reflective
			3V frontage Rd.				
			0.3KM	No Stopping Avalanche Left side			Reflective
			Woods Overhead				
			1.0KM	Mile Marker to Revy			Damaged lettering
			Summit Lk. Overhead				
			0.2KM	80KM (Yellow)			Damaged
			1.2KM	Passing lane			Reflective
			1.2 KM	For 3KM			"
			1.3 KM	Keep right let others pass			"
			Clanwilliam Rd.				
			6.0KM	Pole Rd Ahead			Damaged Lettering

Pothole 3V hill

NOTE:
The Maintenance Contractor pulled images below from Google Maps, showing signage in question in position. In between that time frame, they were only able to find one sign reflectivity inspection for west of Revelstoke from April 2018, this sign is not mentioned in their report which implies there was no observed issues with it.

Currently shown: Jun 2018
2007
2019
Eagle River Drive
Taft Rd
Google
Image capture: Jun 2018 © 2022 Google