PROVINCE OF BRITISH COLUMBIA Ministry of Justice	F	FIRE REPORT - STRUCTURE			
Emergency Management BC / Office of th	e Fire Commissioner		INCIDENT NUMBER: CKA 2014 02 06 01 01		
Location of Incident:	900 MCGIL KAMLOOP	LL ROAD PS BC V2C5N3			
# of Occupants (At time of fire): 1	# of Injured: 0	# of Deaths: 0	Total Do	llar Loss Estimate: \$39,920	
Related to Wildland Interface Fire: NO	Property Value: \$0	Content Value:	\$0	Total Value at Risk: \$0	
Code Name	: Code Descri	iption			
PROPERTY COMPLEX	: 1300 EDUCATIO	NAL INSTITUTION (NO	N-RESIDEN	TIAL)	
PROPERTY CLASSIFICATION	: 1380 COLLEGE,	UNIVERSITY			
GENERAL CONSTRUCTION	: 2000 PROTECTE	D COMBUSTIBLE CONS	STRUCTION	- WOOD PROTECTED BY PLAST	
BUILDING HEIGHT	: 0030 3 STORIES	ABOVE GRADE			
GROUND FLOOR AREA	: 4000 1001 TO 250	00M2 (10765 - 26910FT2)			
YEAR OF CONSTRUCTION	: 0000 CANNOT B	E DETERMINED			
MANUAL FIRE PROTECTION	: 4000 EXTINGUIS	SHER ONLY			
OUTSIDE FIRE PROTECTION	: 5000 PRIVATE H	IYDRANT PROTECTION	N & FIRE DE	PARTMENT	
SPRINKLER PROTECTION	: 7000 NO SPRINK	LER PROTECTION			
AUTOMATIC FIRE ALARM SYSTE	: 3000 FIRE ALAR	M SYSTEM - OFF-SITE	MONITORIN	NG AGENCY	

AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY	
SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED	
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S	
TRANSMISSION OF ALARM: 1000 911	
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY	
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED	
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT	
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE	
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)	
FIRE ORIGIN, AREA : 3100 KITCHEN, COOKING AREA	
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN	
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN	
IGNITING OBJECT : 3300 CLOTHES DRYER	
FUEL OR ENERGY : 6000 ELECTRICITY	
FORM OF HEAT : 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE	
MATERIAL FIRST IGNITED : 8100 FIBRES - INCLUDES ALL NATURAL AND SYNTHETIC FIBRES, EITHER R	
ACT OR OMISSION : 6300 LACK OF MAINTENANCE	

Investigating Officer GUERTIN, SHELDON LAFC Badge # 1368 Telephone ReportDate 250-571-2965 2014-02-14

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner

LOG # ITEM TYPE ITEM DESCRIPTION	: 169944 : DRYER, CLOTHES :
MAKE	: MAYTAG
MODEL YEAR	: ATLANTIS :
LICENSE NO.	:
SERIAL NO.	:
MAKE	: MAYTAG

CERT. AGENCY1 : CERT. AGENCY2 : CERT. AGENCY3 : CERT. AGENCY4 : CERT. AGENCY5 :

FIRE REPORT - STRUCTURE (PRODUCT/EQUIPMENT)

INCIDENT NUMBER: CKA 2014 02 06 01 01

COMMENTS :

THE ABILITY TO IDENTIFY THE MODEL

Investigating Officer GUERTIN, SHELDON LAFC Badge # 1368
 Telephone
 ReportDate

 250-571-2965
 2014-02-14

Page 3 of 5

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CKA 2014 02 06 01 01

Remarks:

FIRE CREW ARRIVED ON SCENE TO FIND THE CULINARY ARTS KITCHEN HEAVILY FILLED WITH SMOKE AND A SMALL FIRE ON THE CLOTHES DYER LOCATED IN THE BACK OF THE KITCHEN. THE FIRE WAS QUICKLY EXTINGUISHED WITH A 1'3/4' HAND-LINE. AS A PART OF THE FIRE INVESTIGATION THE DRYER WAS TAKEN APART. IT WAS NOTED THAT THE MOTOR WAS FREELY MOVING AND THE THERMAL PROTECTION VISUALLY LOOKED OKAY. THESE WAS A LARGE AMOUNT OF LINT BUILD-UP IN THE EXHAUST VENT APPROXIMATELY 2' IN DEPTH. BASED ON THE AMOUNT OF DAMAGE TO THE DRYER IT APPEARS THAT THE FIRE STARTED AS THE RESULT OF THE BUILD UP OF LINT. THE INSTALLATION OF THE DYER APPEARED TO MEET THE REQUIREMENT OF THE MANUFACTURER, WITH THE EXCEPTION OF THE EXHAUST BEING PIPED INTO WHAT LOOKED LIKE THE COLD AIR RETURN FOR THE HVAC SYSTEM.

Investigating Officer GUERTIN, SHELDON LAFC Badge # 1368

 Telephone
 ReportDate

 250-571-2965
 2014-02-14

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner		FIRE REPORT - STRUCTURE (NAMES) INCIDENT NUMBER: CKA 2014 02 06 01 01		
Name no. Name Address	: 1 s.22	Name Status Phone	: WITNESS :	
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: 1. HANSON , BRETT : 1. ASSOCIATED ADJUSTERS : 1 <mark>s.22</mark> : 1. UNIVERSITY & COLLEGE INSURANCE PRO : 1. NIL	VIDERS		
LOSS ESTIMATES: Property Loss : \$27,313	Content Loss: \$12,607	Total Loss: \$39,	920	
REMARKS:				
MANAGER OF HEALTH	I AND SAFETY. WAS ON SCENE FOR INVESTIGA	FION AND PROVIDED A	ASSISTANCE.	

Name no. Name Address	: 2 : s.22 :		Name Status Phone	: WITNESS : <mark>s.22</mark>
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number				
LOSS ESTIMATES: Property Loss : \$0		Content Loss : \$0	Total Loss: \$0	
REMARKS:				

WAS DOING SECURITY ROUNDS, ENTERED THE CULINARY ARTS SECTION FROM THE BACK DOOR TO THE KITCHEN. I COULD SEE SMOKE IN THE ROOM, AS I WENT AROUND THE CORNER, I COULD SEE FIRE ON TOP OF THE DRYER. I WENT INTO THE KITCHEN AND GRABBED THE SILVER EXTINGUISHER AND ATTEMPTED THE PUT OUT THE FIRE. I ALSO RADIOED MY PARTNER AND TOLD THEM TO CALL 911, THAT WE HAD A FIRE IN THE CULINARY ARTS KITCHEN.

Investigating Officer GUERTIN, SHELDON LAFC Badge # 1368

Telephone ReportDate 250-571-2965 2014-02-14

Incident Report