Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CSY 2014 07 29 21 05

Location of Incident:

107 - 8173 128 ST SURREY BC

of Occupants (At time of fire): 0

of Injured: 0

of Deaths: 0

Total Dollar Loss Estimate S.21

Related to Wildland Interface Fire: NO

Property Value: S.21

Content Value: s.21

Total XI

Total Value at Risk: S.21

Code Name :

Code Description

PROPERTY COMPLEX: 5700 COMMERCIAL CENTRE, SHOPPING CENTRE, STRIP MALL

PROPERTY CLASSIFICATION: 5910 PROFESSIONAL SUPPLY SALES - INCLUDES SALES OF STETHOSCOPES,

GENERAL CONSTRUCTION: 5000 PROTECTED NON-COMBUSTIBLE CONSTRUCTION - PROTECTED STEEL OR

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 3000 501 TO 1000M2 (5383 - 10764FT2)

YEAR OF CONSTRUCTION: 1998 1998

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 3000 ALARM ACTIVATED - OCCUPANT(S) UNABLE TO RESPOND

INITIAL DETECTION: 5000 AUTOMATIC SPRINKLER SYSTEM

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4400 65MM OR 77MM (2 1/2" OR 3") HOSE - I HAND LINE

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 3900 FUNCTION AREA - UNCLASSIFIED (DESCRIBE)

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 5900 ELECTRICAL DISTRIBUTION EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 7300 PLASTICS - (EXCLUDES CELLULOSE NITRATE CLASSIFIED UNDER 720.

ACT OR OMISSION: 5900 CONSTRUCTION, DESIGN OR INSTALLATION DEFICIENCY - UNCLASSIFI

Investigating Officer

LAFC Badge #

SHEEL, DANIEL

1810

Telephone 604-543-6700 ReportDate 2014-07-30

Page 1 JAG-2015-00054 2015-01-30 PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CSY 2014 07 29 21 05

Remarks:

WHOLE BURNT THRU MEZZANINE, HEAVY FIRE DAMAGE IN THAT AREA. POSSIBLE ELECTRICAL CORD IN AREA OF FIRE,

Investigating Officer SHEEL, DANIEL

LAFC Badge #

1810

Telephone ReportDate 604-543-6700 2014-07-30

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CSY 2014 07 29 21 05

Name no.

:0

Name Address : JASSAL, HARJINDER

Name Status

: OWNER

Phone

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: S.21

Content Loss: s.21

Total Loss: s.21

REMARKS:

Investigating Officer SHEEL, DANIEL

LAFC Badge #

1810

Telephone 604-543-6700

ReportDate 2014-07-30