

Location of Incident: **6670 KING GEORGE BLVD
SURREY BC**

of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate s.21

Related to Wildland Interface Fire: NO Property Value: s.21 Content Value: s.21 Total Value at Risk: s.21

Code Name : Code Description

PROPERTY COMPLEX : 3300 HOTEL, MOTEL, LODGE, HOSTEL, BOARDING HOUSE, DORMITORY
PROPERTY CLASSIFICATION : 8360 UNOCCUPIED PROPERTY - PROPERTY LEFT UNOCCUPIED OVER 30 DAYS
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9500 ALARM NOT ACTIVATED - UNKNOWN
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 1400 LOUNGE, LIVING ROOM - INCLUDES MUSIC ROOM, COMMON ROOM, TV R
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 7220 LIGHTER - NOT USED IN CONJUNCTION WITH SMOKING
FUEL OR ENERGY : 3000 GASOLINE
FORM OF HEAT : 4000 DIRECT FLAME
MATERIAL FIRST IGNITED : 4900 WOOD, PAPER PRODUCTS - UNCLASSIFIED (DESCRIBE)
ACT OR OMISSION : 1240 SUSPICIOUS - SUSPECT NOT IDENTIFIED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MAHIL, PAUL	1289	604-543-6700	2013-02-01

Remarks:

SUSPICIOUS FIRE STARTED IN UNIT 110 FIRST FLOOR, FLAMMABLE LIQUID FOUND BY NYA IN UNIT 110 AND TWO OTHER UNITS LEFT SAMPLE FOR RCMP

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MAHIL, PAUL	1289	604-543-6700	2013-02-01

Name no. : 1
Name : BOLLYWOOD, MOTEL LTD
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
MAHIL, PAUL

LAFB Badge #
1289

Telephone
604-543-6700

ReportDate
2013-02-01