

Location of Incident:

**920 FIFTH AVENUE P.O. Box 1267
LADYSMITH BC V9G 1A9**

# of Occupants (At time of fire): 0	# of Injured: 0	# of Deaths: 0	Total Dollar Loss Estimate: s.22
Related to Wildland Interface Fire: NO	Property Value: s.22	Content Value: s.22	Total Value at Risk: s.22

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR ROUND USE DWELLING 1 FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 1000 1 TO 100M2 (1 1076FT2)
YEAR OF CONSTRUCTION : 0021 1921 TO 1945
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 2000 VOLUNTEER/PAID ON CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE 1 HAND LINE
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 3100 KITCHEN, COOKING AREA
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 1020 STOVE, RANGE, TOP BURNER AREA INVOLVING FIRE IN PAN, WOK
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 6000 HOT OBJECT DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED : 8210 FOOD, STARCH (POTATO, RICE, PASTA)
ACT OR OMISSION : 7900 HUMAN FAILING UNCLASSIFIED (DESCRIBE)

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250 245 6436	2011 10 25

Remarks:

TENNENT WAS COOKING BEANS IN POT ON STOVE ELEMENT. TENNENT LEFT RESIDENCE FOR SHOPPING TRIP TO NANAIMO AND FORGOT TO TURN OFF ELEMENT ON STOVE. FIRE SPREAD FROM POT TO SURROUNDING COMBUSTIBLES. FIRE DAMAGE TO STOVE, KITCHEN CABINETS, AND WALLS AND CEILING ABOVE STOVE AND KITCHEN FLOOR. HEAVY SMOKE DAMAGE THROUGHOUT RESIDENCE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250 245 6436	2011 10 25

Name no. : 1
Name : s.22
Address : 1267 920 FIFTH AVENUE
LADYSMITH BRITISH COLUMBIA V9G 1A9

Name Status : OCCUPANT
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.22 Content Loss : \$0 Total Loss : s.22

REMARKS:

NO INSURANCE BY TENNENT ON CONTENTS.

Name no. : 2
Name : s.22
Address : 920 FIFTH AVENUE
LADYSMITH BRITISH COLUMBIA

Name Status : OWNER
Phone :

Claims Adjuster Name : 1. DAYTON , TODD
Claims Adjuster Firm :
Claim Number : s.22
Insurance Company : 1. INTAC
Policy Number : s.22

LOSS ESTIMATES:

Property Loss : s.22 Content Loss : \$0 Total Loss : s.22

REMARKS:

THERE IS NO CONTENTS INSURANCE POLICY BY RENTER.

Investigating Officer LAFC Badge #
DELCOURT, RAYMOND 1247

Telephone ReportDate
250 245 6436 2011 10 25