

Stage 1 Preliminary Site Investigation 508 Clarke Road Coquitlam, BC

Prepared For:

BC Ministry of Transportation & Infrastructure

4B 940 Blanshard Street
Victoria, BC
PO Box 9850 Stn. Prov. Govt

Prepared By:

Steve Boyce, B.A. Project Scientist

Reviewed By:

David Kneale, P.Geo. Senior Hydrogeologist

Project Number: 328P June 2011

EXECUTIVE SUMMARY

This report summarizes the results of a Stage 1 Preliminary Site Investigation (Stage 1) for the property located at 508 Clarke Road, in Coquitlam, BC, (herein referred to as the 'Site'). The Stage 1 was prepared for the BC Ministry of Transportation and Infrastructure (TRAN) by Active Earth Engineering Ltd. in order to identify Areas of Potential Environmental Concern (APECs) associated with current or past uses of the Site and surrounding properties. The Stage 1 assesses the likelihood of soil, soil vapour and/or groundwater contamination based upon a review of readily accessible historical information and completion of a site visit.

On May 25, 2011, the Property Agent, Stan Wong, indicated that the Project's interest in the Site was limited to a Statutory Right-of-Way (SRW) that varies from approximately 13m to 14m in width (southwest to northeast), situated along the western property line. As such, the investigation owed particular attention to the proposed SRW.

The Stage 1 identified the following APEC and associated Potential Contaminants of Concern (PCOCs):

Areas of Potential Environmental Concern - Summary

APEC	PCOC			
Off-Site				
APEC 1 – Historic and Current Automotive Repair to the north (Up- Gradient) at 518 Clarke Road.	Soil: LEPH, HEPH, PAH, VOC, VPH, Glycols, PCBs, Metals Groundwater: LEPHw, PAH, VOC, VPH, Glycols, Metals Soil Vapour: Naphthalene, VOC			
Note: LEPH – Light Extractable Petroleum Hydrocarbons HEPH – Heavy Extractable Petroleum Hydrocarbons				

PAH – Polycyclic Aromatic Hydrocarbons

VPH – Volatile Petroleum Hydrocarbons

VOC - Volatile Petroleum Hydrocarbons

PCBs - Polychlorinated Biphenyls

Off-Site APEC 1 is located to the north (up-gradient) of the Site. A single-bay service/repair garage was observed within the building. The operation was closed and service/repair equipment appeared to have been removed. The garage was not inspected, although the floor was observed to be concrete and indications of a former above-ground hoist were observed. A concrete patch was observed, which may be indicative of a former below ground hydraulic hoist. No ASTs or USTs were observed on the property. Given the history, proximity, and up-gradient orientation relative to the Site, this APEC presents a moderate risk of contamination to the Site, and specifically to the SRW.

No on-Site APECs were identified.

Further investigation in the form of a Stage 2 is recommended. This Stage 2 may be limited to a single borehole/monitoring-well located within the northwest extent of the SRW.

Hemmera completed a Screening Level Contaminated Sites Assessment along the proposed alignment of the Evergreen Line Rapid Transit Project (the "Project") to evaluate the potential of encountering soil and/or groundwater contamination along the proposed alignment.

Hemmera identified an historic boat sales/service operation at 509 Clarke Road and automotive service station at 687 North Road within NR11. However, the historic service station at 687 North Road would have been located at the south-east corner of the intersection of North Road and Cottonwood Ave (currently 504 Cottonwood Ave). A Hemmera Tier 1 risk-ranking is likely appropriate for this location.

An historic title search of 509 Clarke Road does not indicate any automotive service stations existing at this location. Given these findings, it is highly unlikely that a historic automotive service station existed within the bounds of Hemmera site NR11, and therefore a lowered risk ranking (Tier 2 or 3) is likely appropriate.

TABLE OF CONTENTS

EXECU	TIVE SUMMARY	. ii
TABLE	OF CONTENTS	
1.0	INTRODUCTION	. 1
1.1	General	1
1.2	Scope of Work	
1.3	Regulatory Framework	
2.0	SITE DETAILS	. 2
2.1	Location	
2.2	Legal Description	
2.3	Current Facilities	
2.4	Current Surrounding Properties	5
3.0	PREVIOUS INVESTIGATIONS	
3.1	Hemmera Screening Level Assessment (2009)	
3.	1.1 CR1 (500B, 506, and 515 Cottonwood Ave)	7
	1.2 NR11 (687 North Road and 509 Clarke Road)	
4.0	PHYSICAL SETTING	
4.1	Geology	8
4.2	Topography	
4.3	Hydrogeology	
4.4	Area Water Uses	
4.4.1	Surface Water	
4.4.2	Drinking Water	9
4.5	Climate Norms	
5.0	LAND USE HISTORY	10
5.1	Site	
• .	1.1 Historic Land Uses	
5.	1.2 Schedule 2 Activities	.11
5.2	Surrounding Properties	.11
5.3	BC Online Site Registry Records	
6.0	STAGE 1 DISCUSSION	15
6.1	Site	
6.2	Surrounding Properties	
7.0	CONCLUSIONS	18
8.0	LIMITATIONS	19

ATTACHMENTS

=1	IGI	JR	ES

Figure 1 Site Location Plan

Figure 2 Surrounding Land Use Plan Showing Off-Site APECs

Figure 3 Site Plan

PHOTOGRAPHS

Photographs 1 to 16

APPENDICES

Appendix A Current Legal Title, Lot Plan and Property Acquisition Plan

Appendix B Topographic Map

Appendix C BC Water Resource Atlas

Appendix D Air Photos

Appendix E BC Site Registry Search Results

Appendix F Historical City Directories
Appendix G Historical Title Search Results

1.0 INTRODUCTION

1.1 General

Active Earth Engineering Ltd. (Active Earth) was retained by the BC Ministry of Transportation and Infrastructure (TRAN) to complete a Stage 1 Preliminary Site Investigation (Stage 1) at 508 Clarke Road, in Coquitlam, BC (referred to as the "Site"). This work is being undertaken as part of the Evergreen Rapid Transit Project (the 'Project'). On May 25, 2011, the Property Agent, Stan Wong, indicated that the Project's interest in the Site was limited to a Statutory Right-of-Way (SRW) that varies from approximately 13m to 14m in width (southwest to northeast), situated along the western property line. As such, the investigation owed particular attention to the proposed SRW.

The purpose of the Stage 1 was to assess the likelihood of soil, soil vapour and/or groundwater contamination based upon a review of readily accessible historical information, and completion of a site visit.

Potential contaminant sources are classified as having a low, moderate or high potential risk of having caused contamination. Issues that are considered to present a low risk are not recommended for further investigation. Active Earth would recommend further investigation for any issues that are considered to present a moderate to high risk of contamination. These moderate to high risk issues are then termed Areas of Potential Environmental Concern (APECs). The regulated contaminants associated with the APECs are termed Potential Contaminants of Concern (PCOCs).

This Stage 1 report generally complies with CSA Standard Z768-01 – Phase I Environmental Site Assessment and BC Ministry of Environment Technical Guidance 10 – Checklist for Reviewing a Preliminary Site Investigation.

1.2 Scope of Work

The Stage 1 consisted of the following scope of work:

- Viewing of the Site and the surrounding areas to identify evidence and sources of possible contamination or environmental impairment;
- Reviewing available historical records, documenting Site use as listed in business directories, fire insurance plans and as shown in aerial photographs;
- Investigating and collecting relevant information pertaining to environmental concerns about the Site from the Ministry of Environment;
- Reviewing available published geotechnical, environmental and geological information;
- Interviewing suitable individuals to obtain background information on past and current Site use;

- Preparing a report summarizing our findings and identifying Areas of Potential Environmental Concern; and,
- Providing a recommendation on the need for further environmental investigation.

1.3 Regulatory Framework

The Contaminated Sites Regulation (CSR, BC. Reg. 375/96, including amendments) and the Hazardous Waste Regulation (HWR, BC Reg. 63/88 including amendments) under the Environmental Management Act regulate the assessment and remediation of contaminated sites in BC. The CSR provides guidance for completion of Stage 1 reports, as follows:

• BC MOE. 2005. Technical Guidance on Contaminated Sites 10: Checklist for Reviewing a Preliminary Site Investigation. BC Ministry of the Environment (BC MOE), Victoria, BC

In addition to the CSR, the Canadian Standards Association (CSA) also provides guidance on Phase I report, as follows:

CSA Standard Z768-01 – Phase I Environmental Site Assessment

The BC Contaminated Sites Regulation provides standards for soil, soil vapour, groundwater and sediment for various land uses.

2.0 SITE DETAILS

2.1 Location

The Site is located along the east side of Clarke Road, between Cottonwood Avenue and Smith Avenue, in Coquitlam, BC. The general area of the Site is shown on Figure 1. The Site is currently zoned C-2 (General Commercial) which allows for a variety of uses including offices, entertainment, shopping plazas and tourist accommodation, at medium densities¹. The cartographic co-ordinates for the centre of the Site are approximately 122° 53' 31.5" west and 49° 15' 34.3" north. Figures 2 and 3 show the surrounding land uses and Site respectively.

The Site is approximately 0.34 hectares in area with approximately 58.1m of frontage along Clarke Road.

٠

¹ City of Coquitlam Zoning Bylaw 1996, No. 3000

2.2 Legal Description

The Site consists of a single legal parcel described as follows:

Legal Description

PID	Legal Description
001-032-569	Lot 12, District Lot 7, Group 1, New Westminster District, Plan 3967

The Site is currently owned by UPN Holding Society (Incorporation #S20701). The current land title and legal lot plan are provided in Appendix A. A historic title search was conducted by West Coast Title Search and is summarised in the following table.

Historical Title Search Summary

Registered Owner	Title Registered	Title Cancelled
UPN Holding Society	Dec 23, 1986	Current
U.R.P.N.B.C Holding Society	Dec 21, 1984	Dec 23, 1986
U.R.P.N.B.C Holding Society (1/2 interest)	Aug 31, 1983	Dec 21, 1984
Registered Psychiatric Nurses Association of British Columbia	Jan 14, 1981	Dec 21, 1984
Sunnyvale Development Ltd.	Dec 12, 1978	Jan 14, 1981
Sunnyside Estates Ltd.	Feb 13, 1969	Dec 12, 1978
Farwest Investments Ltd.	June 15, 1966	Feb 13, 1969
Reginald Frank Cooper	Jan 26, 1960	June 15, 1966
Reginald Frank Cooper + Jesse Cooper	July 15, 1953	Jan 26, 1960
Reginald Frank Cooper	Aug 5, 1947	July 15, 1953
Anthony Breckner	June 19, 1942	Aug 5, 1947

A SRW (K7935) registered by BC Hydro and Power Authority (BCH) appears on historical titles from circa 1969 through to the current title. This BCH SRW is located along the western property line, as shown on Plan 42516 (Appendix A). The BCH SRW does not interfere with the planned Evergreen Rapid Transit Project SRW. Charge information contained on the historical titles indicated that a lease was registered in 1974 by Dial Financial Ltd.

The legal lot boundaries are approximated on Figures 2 and 3 as transcribed from base plans supplied by TRAN. Historical title search results are included as Appendix G.

2.3 Current Facilities

On May 26, 2011, a representative of Active Earth conducted a Site visit to review current conditions. All details regarding the current use of the property are based on the Site visit.

The Site was occupied by a two-story brick building with a concrete slab-on-grade, which covers approximately 30% of the Site, as shown on Figure 3. The upper exterior story is finished with wood shingle siding. Two gas meters were observed along the southern exterior wall; natural gas is inferred to be used for restaurant operations and heating throughout the building. Electric baseboard heaters were also observed within several building units.

The ground-level of the building was occupied by the following units:

- Unit 101 Korean and Japanese Restaurant
- Unit 102 CCB International School
- Unit 103 Vacant
- Unit 104 Beauty Salon
- Unit 105 Noodle House Restaurant
- Unit 107 Denture Clinit
- Un-numbered Unit Spa

The upper story was occupied by the following units:

- Unit 200 Union of Psychiatric Nurses Offices
- Unit 201 Design Studio Offices
- Unit 202 Coquitlam Firefighters Local 1782 Offices
- Unit 203 Accountant
- Unit 204 Un-marked Offices
- Unit 205 Un-marked Offices
- Unit 206 Tour Operator Offices
- Unit 207 Accountant
- Unit 208 Real Estate Offices

As directed by the Property Agent, Active Earth attempted to obtain a key for access to the electrical control and maintenance room. However, the key was not available at the time of the Site Visit. The interior of the building units were not inspected, and it is unknown whether any chemical storage areas are present on-Site. However, given the current Site uses, it is anticipated that no significant chemical handling or storage occurs on-Site.

The remainder of the Site was occupied by asphalt entrance and parking areas (approximately 50% of the Site), and vegetated landscaped areas (approximately 20%). Dumpsters and a cooking-oil disposal tank were observed on a concrete pad in the south-east corner of the lot; the soil in the vicinity of the cooking oil tank appeared slightly stained. No evidence of Aboveground Storage Tanks (ASTs), Underground Storage Tanks (USTs), or oil-water separators was observed on-Site. No evidence of previous intrusive environmental investigations (i.e. boreholes or groundwater monitoring wells) was observed. No significant staining was observed on the asphalt surfaces.

A representative of Keystone Environmental was on-site during the Site visit, conducting what appeared to be a Phase 2 investigation involving the advancement of three boreholes and installation of groundwater monitoring wells. An auger drill rig, operated by Beck Drilling and Environmental Services Ltd. was observed on-Site. It is understood that this Phase 2 investigation was being completed on behalf of the current property owner.

A discussion of the potential for the various facilities at the Site to present an environmental risk is provided in Section 6.1.

2.4 Current Surrounding Properties

During the site visit, Active Earth conducted a visual inspection of the surrounding properties from publicly accessible areas. The following table outlines our observations. Current and historic activities having significant potential contaminant sources are presented in bold and discussed in Section 6.2.

Current Surrounding Land Use

Direction	Address	Current Usage / Observations	
	500 Clarke Road	Mount Athos Pizza Beauty Salon	
South (down-gradient ²)	504 Clarke Road	Sun Gong Wonton House Vacant Unit (formerly bicycle sales)	
(acim gradient)	503 Cottonwood Ave	Refa Supermarket	
	511-515 Cottonwood Ave	Cottonwood Market Various Offices	

² The term down-gradient refers to the direction toward which groundwater would be expected to flow.

Direction	Address	Current Usage / Observations
		Tae Kwondo
		Spring New Restaurant
	2763-2781 North Road,	Residential
	9989 Lynderhurst St	Residential
	518 Clarke Road	CSC Tires (appears currently closed)
	520 Clarke Road	Speedy Signs
North (up-gradient ³)	522 Clarke Road	Vacant
(up gradient)	524 Clarke Road	Computer Repair and Internet Cafe
	522 Smith Avenue	Residential Apartments
West	513 Clarke Road	Trinity Auto Centres
(cross-gradient ⁴)	509 Clarke Road	Trinity Auto Centre
East	519-521 Cottonwood Ave	Apartment Building
(cross-gradient)	N/A	Whiting Way Cul-de-Sac

3.0 PREVIOUS INVESTIGATIONS

The following report was reviewed as part of the Stage 1:

Environmental Assessment Certificate Application for the Evergreen Line Rapid Transit Project, Section 11 – Screening Level Contaminated Site Assessment, prepared for the BC Ministry of Transportation and Infrastructure by Hemmera, 2009.

Active Earth completed a review of this report to obtain information relevant to this investigation (i.e. identification of APECs and PCOCs). A summary of relevant report findings is provided in the following subsections.

3.1 Hemmera Screening Level Assessment (2009)

Hemmera undertook a Screening Level Contaminated Sites Assessment along the proposed alignment of the Evergreen Line Rapid Transit Project (the "Project"). The purpose of their assessment was to evaluate the potential of encountering soil and/or groundwater contamination along the proposed alignment. The assessment focussed on areas where the Project would be required to acquire property and where potentially contaminated soil or groundwater may be encountered during construction.

³ The term up-gradient refers to the direction from which groundwater would be expected to flow.

⁴ The term cross-gradient refers to the expectation of groundwater flowing parallel with respect to the Site.

Hemmera assigned tier rankings (Low, Moderate and High) to sites in the vicinity of the proposed alignment. Sites were ranked considering such factors as site history (based on review of records from various sources), position according to the alignment, nature of possible contamination, geology and depth to the groundwater. The assessment of potential site contamination was described by identifying properties with a high, moderate and low potential for contamination (i.e. Tier 1, Tier 2, and Tier 3 sites).

Hemmera did not identify the Site as presenting a potential risk to the proposed alignment, and therefore did not assign a Site ID. As shown on Figure 11.2 and Table 11A-1, Hemmera assigned a Tier 2 risk ranking to site CR2 (518 Clarke Road), which is the current and former location of several tire sales and potential automotive repair operations directly north (upgradient) of the Site. Based on past and present use of this property, a Tier 2 risk rating is appropriate.

Hemmera also assigned Tier 1 risk rankings to sites CR1 (500B, 506, and 515 Cottonwood Ave) and NR11 (687 North Road and 509 Clarke Road). These sites are also shown on Figure 2, attached. Hemmera's interpretation of each site is discussed below.

3.1.1 CR1 (500B, 506, and 515 Cottonwood Ave)

Site CR1 included a former dry-cleaning operation (North Road One Hour Martinizing) and a current dry-cleaning operation (Norgetown Dry Cleaners). However, the addresses provided for both were incorrect. Norgetown Dry Cleaners was located at 500 Clarke street, Coquitlam and North Road Martinizing was historically located at 515B Cottonwood Ave, Coquitlam. These operations were correctly located within the bounds of site CR1, as shown on Hemmera figure 11.2. A tier 1 risk ranking is likely appropriate.

Hemmera incorrectly included the historic Chapple Enterprises Auto Transmission (506 Cottonwood Ave) within site CR1; the address is listed correctly, but as even numbered addresses are situated along the south side of Cottonwood Ave, the correct location is across the street (to south) from site CR1. Active Earth identified Chapple Enterprises in the 1971 street directories, as first the property to the east of North Road along the south side of Cottonwood Ave. 506 Cottonwood Ave is no longer a current civic address, but would have been situated on the current 504 Cottonwood Ave location (discussed further below).

3.1.2 NR11 (687 North Road and 509 Clarke Road)

Site NR11 identified a historic boat sales/service operation at 509 Clarke Road and an historic automotive service station at 687 North Road within NR11. However, according to historic street directories for North Road reviewed by Active Earth, 687 North Road is situated immediately south of Cottonwood Ave (i.e. not at Hemmera site NR11). As odd-numbered addresses are located along the east side of North Road, the historic service station at 687 North Road would have been located at the south-east corner of the intersection of North Road and Cottonwood Ave (currently 504 Cottonwood Ave). Active Earth conducted a historic title search of the lot at

504 Cottonwood Ave (PID 010-148-299, attached as Appendix G). The British American Oil Company Limited was identified as the title holder from 1955 to 1974.

Active Earth also conducted a historic title search of the lot at 509 Clarke Road (PID 017-413-818), results of which do not indicate any historic automotive service stations existing at this location. Given these findings, it is highly unlikely that a historic automotive service station existed within the bounds of Hemmera site NR11, and therefore a lowered risk ranking (Tier 2 or 3) is likely appropriate. Records reviewed by Active Earth indicate that instead, a service station was operated historically at 687 North Road (Currently 504 Cottonwood Ave). A Hemmera Tier 1 risk-ranking is likely appropriate for this location.

4.0 PHYSICAL SETTING

4.1 Geology

As part of the Stage 1 investigation, Active Earth assessed the surficial geology of the Site. Review of Surficial Geology Map 1484A indicates the geology in the area consists of Vashon Drift and Capilano Sediments (sand, gravel and silt to 8m thick, overlain by marine deposits to 3m thickness).

The log for nearby water well 16664 (attached as Appendix C) indicates that till extends to 15m depth, overlaying sand, gravel and silt to 25m, overlaying clay.

4.2 Topography

The Site has an average elevation of about 102m geodetic. The grade at the Site slopes gently to the southwest. Regionally, the topography also slopes to the southwest. A topographic map is included as Appendix B.

4.3 Hydrogeology

Regional groundwater flow is inferred to follow local topography to the southwest, towards the Brunette River. Locally, groundwater flow can be affected by building foundations, drainage and subsurface utilities. Depending on their depth, these underground structures may significantly influence shallow groundwater flow from the Site.

The log for water well 16664 identifies a water bearing aquifer from 18 to 25m depth. Depth to water within shallower soils or local fills is not known.

4.4 Area Water Uses

4.4.1 Surface Water

The BC Contaminated Sites Regulation (CSR) Technical Guidance 6 indicates that Aquatic Life Standards (AW) generally apply to all groundwater located within 500m of a surface water body containing aquatic life. Investigations must show that groundwater containing substances at concentrations greater than the applicable aquatic life water use standards does not have the potential to migrate to within 500m of a surface water body used by aquatic life, considering preferential flow corridors.

The closest surface water body is Stoney Creek, located approximately 550 m west of the Site. Port Moody (Burrard Inlet) is located approximately 3km north of the Site. Given proximity and steep topographic gradients between the Site and Stoney Creek (and the Brunette River), and underground services (potential preferential pathways), Aquatic Life Standards (freshwater) are assumed to apply.

4.4.2 Drinking Water

The CSR Technical Guidance Document 6 further indicates that Drinking Water Standards (DW) generally apply where current drinking water sources are within 500m of the outer extent of a groundwater contamination source. If the groundwater flow direction has been reliably determined, this distance is limited to 100m up-gradient (remaining at 500m down-gradient) of the outer extent of a contamination source.

Future drinking water use must also be considered in the evaluation of whether or not DW applies at a site. This includes evaluation of the underlying aquifer to assess hydraulic parameters including yield and hydraulic conductivity. If the aquifer underlying a site has a hydraulic conductivity greater than 1X10⁻⁶ m/s, and a yield greater than or equal to 1.3 L/min, then DW standards are considered to apply.

Exceptions to the application of DW include situations where the natural groundwater quality is considered unsuitable for drinking water use based on elevated Total Dissolved Solids (TDS \geq 4,000 mg/L); or where groundwater is contained within organic soils or muskeg. Also, in situations where there exists a confining geological unit that adequately protects the aquifer, DW does not apply.

Irrigation (IW) and Livestock Watering (LW) uses are considered to apply where these resources are present within 500m down-gradient and 100m in an up-gradient direction.

A search of water wells on the BC Water Resource Atlas revealed one water well within 500m of the Site. Well logs indicate this wells was installed in 1960 to a depth of 28m. Coquitlam is fully

serviced by a piped drinking water distribution system. It is therefore unlikely that this well is currently in use. It is likely that the underlying till soil has a hydraulic conductivity of les than 1x10⁻⁶ m/sec, and DW standards may be discounted, however further investigation will be required to confirm this, if it is deemed necessary to do so. Based on future drinking water considerations, DW standards are considered to apply to the Site for the time being.

BC Water Resource Atlas search results are included as Appendix C.

4.5 Climate Norms

Climate information was obtained for the Coquitlam Como Lake Avenue station, located approximately 1.8 km to the northeast of the Site. The Climate Normals were based on data collected between 1971 and 2000.

Total annual precipitation averaged 1,924mm of which 1,859mm falls as rain and 648mm as snow.

5.0 LAND USE HISTORY

5.1 Site

The following two subsections present a summary of the Site history and a listing of any historic activities that would be classified by the BC Contaminated Sites Regulation under Schedule 2.

5.1.1 Historic Land Uses

The history of the Site was interpreted based on a review of the following available historic information:

- Aerial photographs from 1949, 1954, 1963, 1974, 1979, 1984, 1991, 1997, and 2004 (see Appendix D);
- Historic city directories (every four to five years from 1956 to 2001, plus additional years from 1968 to 1974 see Appendix F); and,

Based on this review, Active Earth assessed the historic Site usage, as follows:

- Vacant/Treed until 1942
- Residential 1942-1970
- Vacant 1970-1974
- Commercial 1974 to present

Air photos up to 1963 show the Site as partially developed, likely with a private residence. The subsequent 1974 air photo shows the Site in its current configuration. The Site is first listed in the 1956/1957 street directory (the earliest directory reviewed) as a residential address. The

address does not appear in the 1970, 1971, or 1972 directories. The address first appears as a commercial building in the 1974 directory. Collectively, these lines of evidence point to redevelopment between 1970 and 1974, and commercial land use from circa 1974 to present.

The historic uses of the Site, based on all available historical information reviewed, are outlined in the following table. No historic activities with potential contaminant sources were identified.

Site History

Address	Dates	Historic Activities
508 Clarke Road	1956/1957/1961/1966/1968	Residential
	1970/1971/1973	Address not Listed
	1974/1976/1981/1986/1991/1996/2001	Various commercial, including various offices, plumbing and heating operation, electronics sales/service, hair salon, medical/dental clinic, dog grooming.

No fire insurance maps that covered the area of the Site were identified.

5.1.2 Schedule 2 Activities

Schedule 2 of the Contaminated Sites Regulation lists a number of activities that could result in contamination. No Schedule 2 activities were identified for current or historic uses at the Site.

In most BC municipalities a Site Profile must be provided when an application is made for a zoning, development, subdivision, soil removal or demolition permit. The Site Profile asks a number of questions about the history of a site, in particular Schedule 2 Activities. When such activities have occurred on a site, then it is likely that a Ministry instrument (e.g. Certificate of Compliance or Determination) will be required prior to re-zoning, development or permitting.

The City of Coquitlam is not currently part of the Site Profile system.

Since no Schedule 2 activities have occurred on this Site, no Ministry instruments would be required.

5.2 Surrounding Properties

The historic uses of the surrounding area, based on all available historical information reviewed, are outlined in the following table. Historic activities with potential contaminant sources are bolded and discussed in Section 6.2.

Surrounding Property History

Surrounding Property History					
Direction	Address	Dates	Historic Activity		
(Orientation)					
		1956-1966 1971-2001 1981	Address not Listed Norgetown Laundry & Dry Cleaning Donald Gordon's Taratown Ltd. Apollo Pizza & Spaghetti House		
	500 Clarke Road	1986	Donald Gordon's Tarantown Ltd. Pizza 222		
		1991	Can Pro Carpet Upholstery Pizza Two Two Two		
		1996 2001	Coquitlam Halal Meat & Deli Seung Hee Beauty Shop Mount Athos Pizza		
		1956/1957	Residential Clarke Road Mkt gro		
		1961 1966	Huddleston Radio and TV Del Rio Sporting Goods		
	504.01	1971-1976 1981	Del Rio Sporting Goods Bicycle Gallery One Arcade		
	504 Clarke Road	1986 1991	Wonder Meats Sommerfeld Goldsmithing Horizons Drop in Centre		
	503 Cottonwood Ave	1996	TEC European Connection Residential		
		2001	Coburn Physiotherapy Corp Advanced Electronic Repair Services		
South (down-gradient)		1971-2001 1981	Mac's Milk / Mac's Convenient Store Dowco Consultants Ltd. Ferrante Albert dentist		
			Karro Allan J dentist North Road Holdings Ltd		
	504 Cottonwood Ave	1981 1986	Ferra Management Corp. Professional Building		
	506 Cottonwood Ave	1956/1957 1961/1966	Address Not Listed Residential		
		1971 1976	Residential Chapple A Enterprises Auto Trans Residential		
		1981-2001	Address Not Listed		
		1956-1966 1971 1976-2001	Residential Address not Listed La Caprice Hairstyles		
		1976	Captain Scott's Fish & Chips		
		1981	The Sea-Shanty Tocam Pizza		
	511 Cottonwood Ave	1986	The Sea-Shanty Roman Eagle Pizza		
		1991	The Sea-Shanty Roman Eagle Pizza		
		1996	Sea Cove Fish & Chips Roma 2 for 1 Pizza		
		2001	Roman Eagle Pizza Golden Chilli Szechuan Restaurant Angel's Pizza		

North Rd One Hr Martinizia Cottonwood Barber Shop Khan A B Dentist Sibley J C phys Safeco Ins Coquittam Pic-a-Pop Mar-Gail Ceramilics Maple Leaf Realty Ltd., Khan Abu B Dentist North Road Holdings Ltd. Kim's Market Sherwins Ceramics Khan Abu B Dentist North Road Holdings Ltd. Kim's Market Sherwins Ceramics Khan Abu B Dentist St. Ives on Shuswap Resorts	rity		Historic Activity	Dates	Address	Direction
1971					Orientation)	
Cottonwood Barber Shop Khan A B Dentist Sibley J C phys Safeco Ins Coquittam Pic-a-Pop Mar-Gail Ceramiics Maple Leaf Realty Ltd. Khan Abu B Dentist North Road Holdings Ltd. Kim's Market Sherwins Ceramics Khan Abu B Dentist St. Ives on Shuswap Resorts Khan Abu B Dentist St. Ives on Shuswap Resorts Kim's Market Khan Abu B Dentist Artificial Eve Laboratory Golden Star Management Inc. F Storage Kim's Market Khan Abu B Dentist Four Corners Forwarding In Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Residential Cottonwood School Progral St. Leonards Youth & Family Se Resi	rocery es dry cln	cln	Mini Mart No 37 grocery Maxwell M Enterprises dry cln			
1976 Coquitlam Pic-a-Pop Mar-Gail Ceramiics Maple Leaf Realty Ltd. Khan Abu B Dentist North Road Holdings Ltd. Kim's Market Sherwins Ceramics Khan Abu B Dentist St. Ives on Shuswap Resorts Kim's Market Khan Abu B Dentist Artificial Eve Laboratory Golden Star Management Inc. F Storage Kim's Market Khan Abu B Dentist Artificial Eve Laboratory Golden Star Management Inc. F Storage Kim's Market Khan Abu B dentist Four Corners Forwarding In Residential Cottonwood School Progras St. Leonards Youth & Family Se Residential Cottonwood Supermarket Cottonwood Supermarket Cottonwood Supermarket St. Leonards Youth & Family Se St. Leonards Youth & Famil	er Shop tist	_	Cottonwood Barber Shop Khan A B Dentist			
1981	niics ty Ltd.		Coquitlam Pic-a-Pop Mar-Gail Ceramiics Maple Leaf Realty Ltd.	1976		
1986 St. Ives on Shuswap Resorts Kim's Market Khan Abu B Dentist Artificial Eve Laboratory Golden Star Management Inc. F Storage 1991 Kim's Market Khan Abu B dentist Four Corners Forwarding In Residential Cottonwood School Progral St. Leonards Youth & Family Se 2001 Residential Cottonwood School Progral St. Leonards Youth & Family Se St. Leonards Youth & F	ngs Ltd. et mics		North Road Holdings Ltd. Kim's Market Sherwins Ceramics	1981		
1991 Storage Kim's Market Khan Abu B dentist Four Corners Forwarding In Residential Cottonwood School Progral St. Leonards Youth & Family Se Cottonwood Supermarket Cottonwood Supermarket Cottonwood School Progral St. Leonards Youth & Family Se St. Leonards Youth & Family Se Cottonwood School Progral St. Leonards Youth & Family Se St. Leonards Youth & Family Se Cottonwood School Progral St. Leonards Youth & Family Se Co	Resorts Ltd. et entist		St. Ives on Shuswap Resorts Ltd Kim's Market Khan Abu B Dentist	1986	515 Cottonwood Ave	
1996 Residential Cottonwood School Program St. Leonards Youth & Family Set Residential Cottonwood Supermarket Cottonwood School Program St. Leonards Youth & Family Set Cottonwood School Program St. Leonards Youth & Family Set St. Leonards Youth & St. Leona	et ntist		Kim's Market Khan Abu B dentist	1991	687 North Road	
St. Leonards Youth & Family Set	-		Residential	1996		
St. Leonards Youth & Family Set	mily Service market	ervices t	St. Leonards Youth & Family Service Residential Cottonwood Supermarket	2001		
1961 Northway B A Serice Gar 1966 Cottonwood BA Serv 1971 Cottonwood Gulf Serv 1976 Vacant 1981-2001 Address not Listed 1961 Address not Listed 1966/1971 Braconnier's Tire 1976 Nalder Tire Ltd. Tire	mily Service		St. Leonards Youth & Family Servi			
1971 Cottonwood Gulf Serv 1976 Vacant 1981-2001 Address not Listed 1961 Address not Listed 1966/1971 Braconnier's Tire 1976 Nalder Tire Ltd. Tire	ice Gar	ır	Northway B A Serice Gar			
1981-2001 Address not Listed 1961 Address not Listed 1966/1971 Braconnier's Tire 518 Clarke Road 1976 Nalder Tire Ltd. Tire				1971		
1966/1971 Braconnier's Tire 1976 Nalder Tire Ltd. Tire	sted					
1 518 Clarke Road 1						North (up-gradient)
		Tire	Nalder Tire Ltd. Tire Overend Automotive Big O Tir		518 Clarke Road	
1991 Braconnier's Tires Ltd 1996/2001 Braconnier's CSC Tires		;				
1 10/1_1001 Browniae Racina Fried ("hick		ken	Address not Listed Brownies Recipe Fried Chicken			
1971 Trus Joist SIs roof & floor supp 1976-1991 Buschman Dental Lab	oor supports al Lab	ports	Trus Joist SIs roof & floor support	1976-1991	520 Clarke Road	
1981 Academy Driving School 1986 Young Drivers of Canada 1991/1996/2001 Coquitlam Pro Life Society	School Canada Society	a Y		1981 1986	520 Clarke Road	

Direction (Orientation)	Address	Dates	Historic Activity
	522 Clarke Road	1956/1957 1961 1966 1971 1976 1981 1986 1991	Address Not Listed Coquitlam Dive-Air diving equip. Address Not Listed Bennett Ins Agcies Bennett Insurance Agencies Coquitlam Suburban Estates Ltd. Anderson Gregg chiropractor Wasylynko David E chiropractor Shilo Counselling group therapy Card Shark Sports Cardsharks
	524 Clarke Road	1966 1971/1976 1981 1986-2001	Address Not Listed Town & Country Estates Ltd. Vacant Choices Consignment Inc.
	1956/1957 1961 Ca 1966 1971 Gilla 1976 1981/1986/1991 526 Clarko Road 1981/1986/1991 Br		Address Not Listed Campbell T Texaco Serv gar Ron's Texaco Serv Gillard & Assoc Distrs serv sta Burquitlam Texaco Sears Catalogue Store Brunette Insurance Agencies Coquitlam Public Library Alley Estates Sales Foto Quik Taverne Burquitlam Plaza Om's Bakers M&M Meat Shops
	518-522 Smith Avenue 509 Clarke Road	1966 1971-2001 1956/1957 1961-1991	Addresses not Listed Residential Address not Listed Sea Fun Marina
West (cross-gradient)	512 Clarke Road	1996/2001 1991 1996	Its My Party Shop Address not Listed Up-Date Accounting Services Inc.
Foot	513 Clarke Road 519 Clarke Road	1956-2001 1956-1971 1976-2001	Residential Residential Address not Listed
East (cross-gradient)	521 Clarke Road	1956-1971 1976 1981-2001	Grootendoat JG Landscaping Vacant Residential

A number of historic activities on surrounding properties were identified as having potential activities of environmental concern. The potential for contamination to have migrated to the Site is assessed further in Section 6.2.

5.3 BC Online Site Registry Records

BC Online maintains a Site Registry of contaminated sites on behalf of the Ministry of Environment (MOE). Any sites that have had MOE involvement after 1988 are listed on the Site

Registry. Not all sites listed in the Registry are considered to be contaminated; rather, some have only been investigated or have received MOE approvals for remediation. The Site Registry also includes sites for which a Site Profile has been submitted to the MOE regardless of whether or not environmental concerns were subsequently identified.

A Site Registry search was completed by Active Earth on May 15, 2011, for the Site. The database was searched on the basis of geographic location within 0.5km radius of the centre of the Site. Copies of the Site Registry search are provided in Appendix E.

A total of five records for neighbouring properties showed up on the Site Registry search as follows:

Site Registry Search Results

Address	Site ID No.	Location	Direction (Orientation)	Distance from Site Boundary
640 Aspen Avenue	11891	Intersection of Aspen and Foster Ave	Southeast (cross- gradient)	460m
556 Clarke Road	4592	Clarke Road between Smith and Como Lake Ave	North (up-gradient)	250m
525-575 Clarke Road	7383	Clarke Road between Smith and Como Lake Ave	North (up-gradient)	150m
604 and 606 Como Lake Ave	12648	Intersection of Como Lake Ave and Emerson St	North (up-gradient)	530m
590 Clarke Road	147	Intersection of Como Lake Ave and Clarke Road	North (up-gradient)	540m

A search based on the Site PID did not identify any historic records.

6.0 STAGE 1 DISCUSSION

This section discusses the findings of the Stage 1 and assesses the likelihood of soil, soil vapour and/or groundwater contamination at the Site. Activities with a moderate to high likelihood of having caused significant contamination are classified as Areas of Potential Environmental Concern (APECs). The regulated compounds for each APEC are termed Potential Contaminants of Concern (PCOCs).

Further investigation in the form of a Stage 2 would be recommended for any of the APECs assessed as moderate or high risk. No further investigation would be recommended for low risk issues.

The following two subsections discuss the potential risks associated with current and historic Site and surrounding property activities, respectively.

6.1 Site

Active Earth did not identify any issues of environmental concern related to the Site and therefore did not identify any on-Site APECs.

6.2 Surrounding Properties

Active Earth identified several issues related to the Site based on historical and current uses of surrounding properties. One of these (APEC 1) was identified as presenting a moderate risk while the remainder were considered to present low risk to the Site. The low-risk rationale for each identified issue is discussed further below.

Areas of Potential Environmental Concern - Off-Site

APEC	PCOC	
Off-Site		
APEC 1 – Historic and Current Automotive Repair to the north (Up-Gradient) at 518 Clarke Road.	Soil: LEPH, HEPH, PAH, VOC, VPH, PCBs, Glycols, Metals Groundwater: LEPHw, PAH, VOC, VPH, Glycols, Metals Soil Vapour: Naphthalene, VOC	

Note: LEPH – Light Extractable Petroleum Hydrocarbons

PAH – Polycyclic Aromatic Hydrocarbons

VPH – Volatile Petroleum Hydrocarbons

HEPH - Heavy Extractable Petroleum Hydrocarbons

VOC - Volatile Petroleum Hydrocarbons

PCBs – Polychlorinated Biphenyls

According to historic directories, the operations at 518 Clarke Road (APEC 1) have consisted of tire sales. However, during the Site visit, a small (1 bay) automotive repair garage was observed within the building. The operation was closed and repair equipment appeared to be no longer present. The garage was not inspected, although the floor was observed to be concrete and indications of a former above-ground hoist were observed. A concrete patch was observed, which may be indicative of a former below ground hydraulic hoist. No ASTs or USTs were observed on the property. However, given the extensive history of automotive operations, this property is considered and APEC.

Low Risk Rationale – Off-Site Properties

Issue	Distance / (Orientation)	Low Risk Rationale
Historic and Current Dry- Cleaning to the South (Down-Gradient) at 500 Clarke Road.	40m South/Southwest	Dry-cleaning operations were observed to occur in the southwest corner of the property, furthest from the Site. The property at 504 Clarke is located between the dry-cleaner and the Site. Based on local topography, groundwater is inferred to flow south/south-west, away from the Site. This facility is considered to present a minimal risk of contamination to the Site.

Issue	Distance / (Orientation)	Low Risk Rationale
Historic Dry-Cleaning to the South (Down- Gradient) at 515 Cottonwood Ave	25m South	Dry-cleaning operations were observed at the property in street directories from 1970 and 1971 only (not present in 1968 or 1972 directories). According to these directories, the dry-cleaner operated in the building at 515 Cottonwood Ave, currently Cottonwood Market. As such, the building at 511 Cottonwood Ave (currently Tae Kwondo studio) is situated between the former drycleaner and the Site. Based on local topography, groundwater is inferred to flow south/south-west, away from the Site. This historic operation is considered to present a minimal risk of contamination to the Site.
Historic Service Station and Auto Repair to the South (Down-Gradient) at 504 Cottonwood Ave	80m South	An automotive transmission operation historically operated at 506 Cottonwood Ave (circa 1968-1972). An automotive service station formerly operated at 687 North Road (circa 1960-1970). According to historic street directories, these operations were located at the south-east corner of the intersection of Cottonwood Ave and North Road (currently 504 Cottonwood Ave). Given the distance from the Site, anticipated down-gradient orientation, and limited length of historic operation, these are considered to present a minimal risk of contamination to the Site.
Historic Service Station to the North (Up-Gradient) at 526 Clarke Road	120m North (approximate)	An automotive service station historically operated at 526 Clarke Road (circa 1960-1976). According to historic street directories, the property was located north of the intersection of Clarke Road and Smith Ave. Given the extensive redevelopment of the area surrounding the Site, it is unclear exactly where the property was situated (between Smith and Como Lake Ave). Given the distance from the Site and limited length of historic operation, this property is considered to present a minimal risk of contamination to the Site.
Used Auto Sales to the west (Cross-Gradient) at 509 and 513 Clarke Road	30m West	Trinity Auto Centre is currently present at 509 and 513 Clarke Road. A boat sales (and possibly service) operation previously operated at this location. It is likely that any automotive repair work conducted on the property is limited in scale, and would be conducted in the building at the south of the property. The areas of the property used for auto storage were observed to be asphalt-covered. The property is located in an anticipated cross-gradient orientation. This property is considered to present a minimal risk of contamination to the Site.

Active Earth considers the risk of environmental contamination to the Site from off-Site properties, not discussed above, to be low.

7.0 CONCLUSIONS

The Stage 1 identified the following APECs and associated PCOCs:

Areas of Potential Environmental Concern - Summary

VPH – Volatile Petroleum Hydrocarbons

	APEC	PCOC
Off-Site		
	1 – Historic and Current Automotive r to the north (Up-Gradient) at 518 Clarke Road.	Soil: LEPH, HEPH, PAH, VOC, VPH, PCBs, Glycols, Metals Groundwater: LEPHw, PAH, VOC, VPH, Glycols, Metals Soil Vapour: Naphthalene, VOC
	PH – Light Extractable Petroleum Hydrocarbon	•
PA	AH – Polycyclic Aromatic Hydrocarbons	VOC – Volatile Petroleum Hydrocarbons

PCBs - Polychlorinated Biphenyls

Off-Site APEC 1 is located to the north (up-gradient) of the Site. A single-bay automotive repair garage was observed within the building. The operation was closed and repair equipment appeared to have been removed. The garage was not inspected, although the floor was observed to be concrete and indications of a former above-ground hoist were observed. A concrete patch was observed, which may be indicative of a former below ground hydraulic hoist. No ASTs or USTs were observed on the property. Given the history, proximity, and up-gradient orientation relative to the Site, this APEC presents a moderate risk of contamination to the Site, and specifically to the SRW.

No on-Site APECs were identified.

Further investigation in the form of a Stage 2 is recommended. This Stage 2 may be limited to a single borehole/monitoring-well located within the northwest extent of the SRW.


The historical street directories, air photos, and historical title searches reviewed by Active Earth indicate that a historic automotive service station did not exist within the bounds of Hemmera site NR11 (currently 509 Clarke Road), and therefore a lowered risk ranking (Tier 2 or 3) is likely appropriate for this property. Records reviewed by Active Earth indicate that instead, a service station historically operated at 687 North Road (Currently 504 Cottonwood Ave). A Hemmera Tier 1 risk-ranking is likely appropriate, and the completion of a Stage 1 may be warranted for 504 Cottonwood Ave.

8.0 LIMITATIONS

This report has been prepared by Active Earth Engineering Ltd. for the BC Ministry of Transportation (TRAN) and Infrastructure based on limited information obtained through historical records and other information sources.

This report is intended to provide an assessment of the potential for soil, soil vapour and/or groundwater contamination from on-Site and off-Site activities. The conclusions made in this report reflect Active Earth's best judgement in light of the information available at the time of reporting. Should additional information become available or Site conditions change, the conclusions and recommendations of this report may be subject to change.


Any use which the client or a third party makes of this report, or any reliance on or decisions to be made based on it, are the responsibility of such parties. Active Earth accepts no responsibility for damages, if any, suffered by TRAN, or third parties as a result of business decisions made or actions based on this report.






BC Ministry of Transportation & Infrastructure












Photo 1 -

On-Site Building with ground-level commercial tenants and second-floor offices. Looking northeast from southwest corner of Site.



Photo 2 -

On-Site building, landscaped areas and asphalt parking. Crew from Beck Drilling and Environmental Services and Keystone Environmental conducting Stage 2 investigation work. Looking southwest from northeast corner of Site.





Photo 3 -

Asphalt driveway showing storm drain catch-basin and gas meters along southern wall of on-Site building. Wall of neighbouring property to the south (504 Clarke Road) is shown on the left. Looking west from Site, toward Clarke Road.



Photo 4 –

Garbage dumpsters and waste cooking oil bin, located in southeast corner of Site. Looking east.





Photo 5 -

Off-Site property to the North at 518 Clarke Road (APEC 1). Looking northeast from Clarke Road.



Photo 6 -

Auto repair area at 518 Clarke Road, showing likely former aboveground hoist location.





Photo 7 –

Rear yard to 518 Clarke Road. Looking east from Lane.



Photo 8 -

Off-Site residential apartments tower to the northeast at 522 Smith Avenue. Looking east.





Photo 9 -

Off-Site residential apartments to the southeast at 533 Cottonwood Ave. Also shows Whiting Way cul-desac. Looking southeast from northeast corner of Site.



Photo 10 -

Off-Site residential apartments to the south at 521 Cottonwood Ave. Looking northwest from Cottonwood Ave.





Photo 11 -

Off-Site commercial building (Cottonwood Market and others) at 515 Cottonwood Ave. Looking northwest from Cottonwood Ave.



Photo 12 –
Off-Site
commercial
building at 511
Cottonwood Ave.
Building at 515
Cottonwood Ave
is visible on the
right. Looking
north from
Cottonwood Ave.





Photo 13 -

Off-Site building to the south, including Dry-Cleaners (500 Clarke Road) and Refa Supermarket (503 Cottonwood Ave). Looking north from Cottonwood Ave / Clarke Road intersection.



Photo 14 -

Off-Site building to the south at 504 Clarke Road. Looking northeast from Clarke Road.





Photo 15 -


Off-Site property to the west at 509 Clarke Road (Trinity Auto Centres). Looking west from Site.



Photo 16 -


Off-Site property to the west at 513 Clarke Road (Trinity Auto Centres). Looking west from Site.







Pages 38 through 40 redacted for the following reasons:

S3





on the 22 nd. day of November, 1926 Oeposited in the Land Registry Office at New Westminster, B.C. · Witness According to Sketois Plan 17º1946 in the Mew Westminster Land Registry Office Subdivision, of the M.12 of the M.12 of Bearings are astronomic assumed from bearing of North Road Road 5.1/2 of 11.1/2 of 10.1.7 D.L. 7, 61., M.W.D. 13 11.32 AC. Scale-200'=1" I, Chas.I. Hamilton, of the City of Vancouver, British Columbia Land Surveyor, make oath and say that I was present at and did personally superintend the survey represented by this plan and that the survey and plan are 0 Road





Map Print Page Page 1 of 1





Page 45 TRA-2012-00100

Page 46 TRA-2012-00100



Report 1 - Detailed Well Record


			Construction	Date: 1960-	-11-01 00:00:00.0
Well Tag Number:	16664		Driller: Albe	rt Aikens 8	& Forrester
Owner: VICTOR FU	JNG		Well Identifi Plate Attache		ce Number:
Address: 2849 NC	ORTH ROAD		Where Plate A	-	
Area: BURQUITLAM			1	0 (Drill	OF DRILLING: ler's Estimate)
Township: Secti	Plan: 48351 Lot:		Development M Pump Test Inf Artesian Flow Artesian Pres Static Level:	o Flag:	
Island:) 27): 092G026411	Well: 1	WATER QUALITY Character: Colour:	:	
Class of Well: Subclass of Well Orientation of W Status of Well: Well Use: Unknow Observation Well Construction Met Diameter: 12.0 i Casing drive sho Well Depth: 93 f Elevation: 0 Final Casing Sti Well Cap Type: Bedrock Depth: Lithology Info F File Info Flag: Sieve Info Flag: Screen Info Flag: Site Info Detail	Nell: New IN Well Use Number: Status: Chod: Drilled Inches De: Geet feet (ASL) Ick Up: inches Ifeet Ifag: Is: Is: Is: Inches Inc		Odour: Odour: Well Disinfec EMS ID: Water Chemist Field Chemist Site Info (SE Water Utility Water Supply Water Supply SURFACE SEAL: Flag: Material: Method: Depth (ft): 0 Thickness (in Liner from WELL CLOSURE Reason For Cl Method of Clo	ry Info Fla ry Info Fla AM): : System Name System Well feet): To: INFORMATION osure:	e: L Name:
Other Info Flag: Other Info Detai			Closure Seala Closure Backf Details of Cl	nt Material ill Materia	
Screen from	to feet	Туре	Slot	Size	
0	0	_ -	0		
0	0		0		
0	0		0		
0	0		0		
Casing from	to feet	Diameter	Mater	ial	Drive Shoe
0	0	0	null		null
ļī.					,


```
GENERAL REMARKS:
ANODE WELL, MAY NOW BE UNDER NORTH ROAD ALLOWANCE
LITHOLOGY INFORMATION:
From
       0 to
             49 Ft.
                        Till
From
       49 to
              83 Ft. Interbedded sand, gravel and silt
               0 Ft. W.B. 58 - 83'
From
       0 to
              93 Ft.
From
       83 to
                       Blue clay
```

- Return to Main
- Return to Search Options
- Return to Search Criteria


Information Disclaimer

The Province disclaims all responsibility for the accuracy of information provided. Information provided should not be used as a basis for making financial or any other commitments.

















































Page 59 TRA-2012-00100

Site Reg Search- Lat_ 49 Long_ 122

As Of: MAY 15, 2011	BC On	line: Site Regist	try	11/05/17
Folio: 328P		ACTIVE EARTH ENG		10:28:56 Page 1
			deg, 15 min, 34.3	sec
and Longitude 12	22 deg, 53 min	, 31.5 sec		
	stupd Address			
0000147 114	APR28 590 CLA	RKE ROAD		
	COQUITL	ΔM		
0004592 04	APR01 556 CLA	RKE ROAD		
	COQUITL	ΔM		
0007383 11/	APR04 525 TO	572 CLARKE ROAD		
	COQUITL			
0011891	•	EN STREET		
00==00=	COOUITL	_		
0012648		06 COMO LAKE AVEI	NUE	
0012010	COQUITL		102	
	COQUITE	-u·i		

Site Reg Search- PID_ Nil

As Of: MAY 15, 2011

Folio: 328P

11/05/17

BC Online: Site Registry For: PA54738 ACTIVE EARTH ENGINEERING LTD.


10:27:29 Page

PID Nil Search

As of MAY 15, 2011, no records from Site Registry match Land Titles PID 001032569


You have been charged for this information.

Sites may be revealed by searching with alternate search methods. For example, a site not revealed in an Area search may be revealed by searching with another piece of information such as PID, PIN, address or Crown Lands File Number



Stage 1 PSI - MOT Evergreen Line

	Ц						YEAR				
AREA		1956/1957	1961	1966	1971	1976	1981	1986	1991	1996	2001
Clarke Road (from North Road toward Como Lake Road)											
_	,				B Norgetown Coin Operated Dry	Norgetown Coin Operated Dry	Norgetown Coin Operated Dry	Norgetown Coin Operated	Norgetown Laundry & Dry	Norgetown Laundry & Dry	Norgetown Laundry & Dry
500 Clarke Road					100000000000000000000000000000000000000		Donald Gordon's Taratown Ltd.	Donald Gordon's Tarantown Ltd.	Can Pro Carpet Upholstery	Halal Meat & Deli	Seung Hee Beauty Shop
	gno						Apollo Pizza & Spaghetti House	Pizza 222	Pizza Two Two Two		Mount Athos Pizza
-uw	ž č	sidental Hutoro	Ť	Del Rio Sporting Goods	Del Rio Sporting Goods Dicycle	Del No Sporting Goods Dicycle	Variety One Arcade	Wonder Meats	Horizons Drop in Centre	Tec european connection	Advanced Electronic Repair Services Recidential
504 Clarke Road	<u> </u>						Vacant	Sommerfeld Goldsmithing			
	+									Coburn Physiotherapy Corp	
508 Clarke Road	Site	Residential Re	Residential	Residential	Address not Listed	Professional Building	Professional Building	Professional Building	Professionial Building	Professionial Building	Professionial Building
-s	1ne	- %	Sea Fun Marina	Sea Fun Marina Boats	Sea Fun Marina Ltd.	Sea Fun Marina Ltd.	Sea Fun Marina Ltd.	Sea Fun Marina Ltd.	Sea Fun Marina		Its My Party Shop
SOJ	ibs									Up-Date Accounting Services Inc.	
aq	10 ()	sidential Re	Residential	Residential	Residential	Residential	Residential	Residential	Residential		Residential
518 Clarke Road				Braconnier's Tire	Braconnier's Tire	Naider Tire Ltd. Tire	.6	Overend Automotive Big O Tire Stor	Braconnier's Tires Ltd	Braconnier's CSC Tires Ltd	Braconnier's CSC Tirecraft
					True loist Sle roof & floor supports	Brownies Recipe Fried Criticken Brownies Recipe Fried Criticken Brischman Dental Laboratory dental mach Brischman Dental Laboratory dental in Brischman Dental Laboratory	Brochman Dental Laborator dental in	Brownies redipe Fried Cricken	Brownies Recipe Fried Chicken Buschman Dental Lab	- C Dental Laboratory	Dental Laboratory
520 Clarke Road	(ча				Tree Solat de 1001 de 1001 august de	Doscillian Delica Laboratory Verical mode	Descrine Dense Laboratory Voltra	Puscillian Demai Laborardi	Cognition Pro Life Society		Pro-Life Society
	JON					Coquittam Driving School	Academy Driving School	Young Drivers of Canada	Young Drivers of Canada	Young Drivers of Canada	Young Drivers of Canada
n to) tn					Vacant		Vacant	Young Drivers of Canada addl space		
522 Clarke Road	ıəib	٠	Coquitlam Dive-Air diving equ	,	Bennett Ins Agcies	Bennett Insurance Agencies Coquillam Lil Anderson Gregg chiropractor	Anderson Gregg chiropractor	Wasylynko David E chiropractor	Shilo Counselling group therapy	Card Shark Sports Cardsharks	Card Shark Sport Cardsharks
524 Clarke Boad	en£				Town & Country Estates 11d	Town & Country Estates 11d	Vacant	Choices Consignment Inc	Choices Consignment used dothing	Choices Consignment	Choices Consignment
	o-dr		ampbell T Texaco Serv galF	Ron's Texaco Serv	Gillard & Assoc Distrs serv sta		Sears Catalogue Store	Sears Catalogue Store	Sears Catalogue Store	Om's Bakers	M&M Meat Shops
526 Clarke Road	 -						Alley Estates Sales	Foto Quik	Foto Quik		Brunette Insurance Agencies
0.000 0.000							Brunette Insurance Agencies	Brunette Insurance Agencies	Brunette Insurance Agencies	Burquitlam Plaza	Burquitlam Plaza
							Coquitiam Public Library	Coquitam Public Library	Laverne		averne
Cottonwood Avenue (from North Road toward Fairview Street)									П		
					Mac's Milk	Mac's Milk Ltd. Groceries	Mac's Convenient Store Ltd.	Mac's Convenient Stores Ltd.	Mac's Convenient Store	Mac's Convenient Store	Super Mac's
			. .				Dowco Consultants Ltd. Ferrants Albert dentiet				
503 Cottonwood Avenue							Karro Allan J dentist				
							North Road Holdings Ltd				
							Vacant				
504 Cottonwood Avenue	1						Ferra Management Corp.	Professional Building			
506 Cottonwood Ave	(ц	ž	Kesidential		Residential Changle A Enterprises Auto Trans	Mesidential -					
inoé	å	sidential	Sesidential	Residential	- Interior	La Caprice Hair Stylist	La Caprice Hairstvlist	La Caprice Hairstviist			La Caprice Hairstyles
_			,			Captain Scott's Fish & Chips					Golden Chilli Szechuan Restaurant
511 Cottonwood Avenue	tnei						Tocam Pizza	zza	Roman Eagle Pizza		
ben										Roman Eagle Pizza	Angel's Pizza
9-1	완	Redental	esidential	Residential							Residential
w/O	MO				Mini Mart No 37 grocery	Coquittam Pic-a-Pop	Kim's Market	Kim's Market	Kim's Market		
									Vacant		
A de service de la constant de la co					Maxwell M Enterprises dry cln	Mar-Gall Ceramlics					
aniaya noowiioii oo ci c					Cottonwood Barbar Shop						
					Khan A B Dentist	Khan Abu B Dentist	Khan Abu B Dentist	Khan Abu B Dentist	Khan Abu B dentist	Cottonwood School Program	Cottonwood School Program
					Vacant			Artificial Eve Laboratory	No Return		
					Sibley J C phys	North Road Holdings I M and develorm	St. Ives on Shuswap Resorts Ltd.	Storage Room Colden Star Management Inc. Rental a	Four Corners Forwarding Inc.	St. Leonards Youth & Family Services	St. Leonards Youth & Family Services
519 Cottonwood Avenue	ne (1s	Residential Re	Residential	Residential	Residential	,			,		
SOI	ibe e3										
521 Cottonwood Avenue G &	10) j	ootendoat JG Landsca Gr	roolendoat JG Landscaping	Grootendoat JG Landscaping	Grootendoat JG Landsca Grootendoat JG Landscaping Grootendoat JG Landscaping Grootendoat JG Landscaping	Vacant	Residential	Residential	Residential	Residential	Residential
Smith Avenue (from North Road toward Fairview Street)											
tne	isse				Residential	Vacant	Residential	Residential	Residential	Residential	
-qU sibe	the (1				0		
Gr	oN)	+			Residential	No Keturn Residential	Residential	Residential	Residential	Residential	Residential
North Road (South of Cottonwood Ave)											
L	1										
687 North Road Down-	neiber© (dtuo2)	- -	Northweay B A Serice Gar	Cottonwood BA Serv	Cottonwood Gulf Serv	Vacant	,		,		
	,										



ENVIRONMENTAL SEARCH FORM

PID: 001-039-569

Plan 3967

GK.I NWD

٠ ٣ DL

> 16 5

CURRENT LEGAL:

Page 1 of ALTINE EARTH Invoice #: Client:

328p - 508 Clarke Rd. File Ref.:

Coquition.

Title No.	Registered Owner	Title Registered	Title Cancelled	Prior Legal(s)	Charge Information
Z 236201E	UPN Holding Society	23.12.1986 Current	current		Title attacked
XILZ896E	U.R.P. N. B.C. Holding Soviety	4361.61.16	33.12.1986		- Computer title notvieuxed
FEE/DEED XIBJ8966	FEE (DEED W.R.P. A. B.C. Holding Society (1) interest)	12.1984	Converted to online title		- no manual ct
	"				
W121814E	BOTH X 122 SOLG. HOLDING SOLGETY (1210)	Sint 31.8.1982	4861:KI 16		SKW: K7935 4546:2236201
74517	iatric Nurses	14.1.1981	H861.K1.16		SRW: K1935 as above
	Association of British Columbia				
PIZIBITE	Sunnyvale Developments Ltd.	8761.61.61	14.1.1981		SRW: K7935 as above
					(Lease: K93024 (9.8.74)
IMPORTANT: As all co	IMPORTANT: As all computer titles may not have been checked characs announced as the state of th	in the state of th			Dial Financial Ctd.

As all computer titles may not have been checked, charges appearing on them that could affect the property, such as leases, are not noted. Information must be checked against LTO records to verify.

Please request document copies or titles if required. If you have any questions concerning how to read this form, please contact West Coast Title Search Ltd. in New Westminstelementary 1.800.553.1936 and in Victoria at 405.6000 or 1.800.667.7767.

ENVIRONMENTAL SEARCH FORM

010-148-299

Active Garth 47-1950S Invoice #: Client:

328p

File Ref.: Plan 15907 dor"A" (M8S9coe) District dory Co I NWD CURRENT LEGAL:

Title No.	Registered Owner	Title Registered	Title Cancelled	Prior Legal(s)	Charge Information
8B 4166.36	P&WI Holding Xtd.	<i>C</i> .	current		Didnotview
BA 338339	Her Majesty the Queen in Right of Canada	2006	۷٠		Did not view
Br147986	Br147986 635334 B.C Ltd.	Z 80 2	9008		Did not view
BE239156	BG239156 B.P.Y.A. 1039 Holdings Ltd.	1993	2002		Did not view
AC134490	AC134490 Jeeng Kock Ko	1989	1993		Did not view
M859∞€	Hesco Holdings Atd.	1976	1989		Did not view
Manual Title 1785900 E	Hesco Holdings attd.	15 Sept 1976	Converted	15 Sept 1976 Converted 200 "A" (785900) Of "SRW N 24002 11/2/77 15 Sept 1976 Converted 200 4+5 of Parcel "A" DISTRICT OF COGNITION DL 7 GP 1 Plan 15907 (Plan 52061-Ancillary AUD)	* SRW N 24003 11/3/77 DISTRICT OF CEGUITIAM (Plan 52061-Ancillay

Please request document copies or titles if required. If you have any questions concerning how to read this form, please contact West Coast Title Search Ltd. in New Westminster at 604,659,8600 or IMPORTANT: As all computer titles may not have been checked, charges appearing on them that could affect the property, such as leases, are not noted. Information must be checked against LTO records to verify. 1.800.553.1936 and in Victoria at 405.6000 or 1.800.667.7767,

Page 66 TRA-2012-00100

ENVIRONMENTAL SEARCH FORM (Continued)

Page 2 of 4

					2000
Title No.	Registered Owner	Title Registered	Title Cancelled	Prior Legal(s)	Charge Information
Manual Title ((Charge intermation continual)		1		Lease N 66295 30/6/77
					M.J.K. Vanagement Inc.
					Corpora Hion
	M85900 E comes from O	2	56644E and @ 1756643E	6643€	
E	_				
26644E	Hesco Holdings Atd.	25 June 1976	15 Sept 1976	15 Sept 1976 LOT 18 OF BACKS 4+5	NIC
				plan 15907 NWD	
666/65€	C.A. DE FEHR JR LTO.	16 June 1964 25 June 1976	25 June 1978	\C	NIC
	TILLICUM INVESTMENTS ATO.				
	ECHO ESTATES ATO.				
42/33CE	Leslie Edwin Eddy a	21 OCT 1958	16 June 1969		NIC
	Christine Eddy				
2756643E	Hesco Holdings Atd	2554ne 1976 15:50 2+ 1976		407 16 A Barks 4+5	77.7.6
				of par. A" DL 7 CO1	
			7	Plan 15907 NWO	
Westerminal Public Land form: envite frui doc					

Page 67 TRA-2012-00100

ENVIRONMENTAL SEARCH FORM (Continued)

Page 3 of 4

Title No.	Danistoned Owner	Title Desistand	Teda Consulta	V. V	
	Tolling to the state of the sta	Tille Megistered	The Cancelled	rnor Legal(s)	Charge Information
K 118099E	C. A. DE FEHR JR. LTO.	12 NOU 1974	25 June 1976		NIC
	FILLICUM INVESTMENTS LTD.				
	1++H INVESTMENTS CTD				
358150€	The British American	22 NOU 1955	12 NOU 1974		NIC
	Oil Company Limited				
358026€	Clifford John Towers	18 NOU 1955	22 NOV 1955	22 NOV 1955 DETS 16, 1-7+18 OF	MIC (as to Cors
	& Kathleen Main Towers			Blocks 4+5 OF Pel"A"	(8/+9/
)			DL7 Cp 1 Plan 15907	
				NWD,	
Websterminal Public Land forms covere firm doc					

Page 68 TRA-2012-00100

ENVIRONMENTAL SEARCH FORM

017-413-818

Pagetof 4 Betive Earth, Invoice #: Client:

47-1950S

3380

File Ref.:

92 47 Plan 1220 Group 1 District Lor 7 0 LOT CURRENT LEGAL:

6y J 126608 Holdings CH. 26/338C Did noturey Did not view notview Charge Information Clark Whiting renewood 15/11/73 19/5/59 Lors "A"+"B" of NIL Sease D10 NUN 11WD Plan 19762 LOT 7 Bulaw Except: 19762 40 Prior Legal(s) Plan 42365, 0F + 40 N1/5 Plan Parcel"3 dor"B" 100 GD 1 CURRENT Concerted Title Cancelled 2003 1991 24 Dec 1958 Title Registered ci ci 2003 166 0 Edgar Bryant Mc Donald Clark Clark Edgar BrygatMc Donald Clark J DOUGLE K MARKET LH Florence Clark Edar Bryant Mc Donald Registered Owner & Sulvia BE 136815 35191 360076 Manual Title Title No. 80 7

Please request document copies or titles if required. If you have any questions concerning how to read this form, please contact West Coast Title Search Ltd. in New Westminster at 604,659.8600 or 1.800.657.7767. IMPORTANT: As all computer titles may not have been checked, charges appearing on them that could affect the property, such as leases, are not noted. Information must be checked against LTO records to verify.

Page 69 TRA-2012-00100

ENVIRONMENTAL SEARCH FORM (Continued)

			-		File Ref.: 545 - 508 Clarke Rd
Title No.	Registered Owner	Title Registered	Title Cancelled	Prior Legal(s)	Charge Information
655228E	Sunnyside Estates Ltd.	13.2.1969	8191. EI . EI		SRW: K1936
				,	Lease: K93024 5 asour.
581091E	Farwest Investments Ltd.	15.6.1966	13.2.1969	70 21 N Jo 21 N Jo 21 701	lio
				lot 7 Plan 3967	
453804E	Reginald Frank Coper	26. 1. 1960	15.6.1966		23.
314 320E	Reginald Frank Cooper.	15-7-1953	26.1.1960		4
	Jessie Cooper				
22C781E	Reginal Frank Goper	5.8.1947	15.7.1963		lic
151497E	Anthony Breckner	19.6.1942	5.8,1947		(RP: 96766c (33.7.45)
			-		
					No.
					Page 70
Westerminal Public Landorm tense circuloc					I KA-2012-00100