**Incident Report** Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CSY 2011 11 09 02 04 •

Location of Incident: 16241 84 AVE **SURREY BC** 

# of Injured: 0 # of Deaths: 0 # of Occupants (At time of fire): 0 Total Dollar Loss Estimate: \$

Related to Wildland Interface Fire: NO Property Value: \$ s.22 Content Value: \$ s.22 Total Value at Risk: \$ s.22

> Code Name: **Code Description**

PROPERTY COMPLEX: 7900 INDUSTRIAL STORAGE FACILITY, BULK STORAGE TANKS

PROPERTY CLASSIFICATION: 7520 WOOD PRODUCTS STORAGE

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 4000 1001 TO 2500M2 (10765 - 26910FT2)

YEAR OF CONSTRUCTION: 1980, 1980.

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 2000 PUBLIC HYDRANT PROTECTION & NO FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA: 7300 CEILING & FLOOR ASSEMBLY - INCLUDES CONCEALED FLOOR/CEILING

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 0000 CANNOT BE DETERMINED FUEL OR ENERGY: 0000 CANNOT BE DETERMINED

FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #

Telephone ReportDate BERG, FRED 2061 604-543-6700 2011-12-01 Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner  $\label{eq:fire_report_structure} \textbf{FIRE REPORT - STRUCTURE} \ (\textbf{NARRATIVE})$ 

INCIDENT NUMBER: CSY 2011 11 09 02 04

## Remarks:

TOTAL FIRE DAMAGE TO WOOD STORAGE STRUCTURE. FIRE EXTENDING FROM ROOF & WALLS UPON FIRE CREW ARRIVAL. BUILDING WAS FILLED WITH STACKED LUMBER & STACKS OF LUMBER WERE BEING STORED AROUND EXTERIOR. BUILDING WAS UNSTABLE & IN ORDER TO EXTINGUISH THE FIRE, A LARGE BACK HOE WAS NEEDED TO PULL DOWN THE WALLS & REMOVE BURNING WOOD STORAGE. BECAUSE OF REQUIRED OVERHALL AREA OF ORIGIN COULD NOT BE PROPERLY INVESTIGATED. REPORT FORM TENANT STATED THEY HAD PROBLEM WITH AN OVERHEAD GAS FIRED HEATER THE PRIOR YEAR & HAS JUST STARTED IT UP FOR THE WINTER APPROX. THREE DAYS BEFORE THE FIRE. IT APPEARS THE FIRE ORIGIN AREA WAS IN THE AREA OF THIS GAS FIRED HEATER.

Investigating Officer BERG, FRED LAFC Badge #

2061

Telephone 604-543-6700

ReportDate 2011-12-01

Page 3 of 4 **Incident Report** 

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CSY 2011 11 09 02 04

Name Status : OCCUPANT Name no. : 1 Name s.22 Phone

: 0 Address

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: \$ s.22 Content Loss: \$ s.22 Total Loss: \$ s.22

REMARKS:

LAFC Badge # Investigating Officer Telephone ReportDate BERG, FRED 604-543-6700 2061 2011-12-01

> Page 3 JAG-2014-00394

Incident Report Page 4 of 4