PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CSY 2012 02 01 17

01

Location of Incident:

18173 8 AVE **SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0**

of Deaths: **0** Total Dollar Loss Estimate:

s.22

Related to Wildland Interface Fire:

ue:

e:

at Risk:

NO

s.22

s.22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3190 ONE & TWO-FAMILY DWELLING - UNCLASSIFIED (DESCRIBE)

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 4000 1001 TO 2500M2 (10765 - 26910FT2)

YEAR OF CONSTRUCTION: 1980 1980

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 2000 PUBLIC HYDRANT PROTECTION & NO FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9500 ALARM NOT ACTIVATED - UNKNOWN

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA: 1090 MEANS OF EGRESS - UNCLASSIFIED (DESCRIBE)

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 9810 SPONTANEOUS COMBUSTION

FUEL OR ENERGY: 0009 FUEL OR ENERGY - UNCLASSIFIED (DESCRIBE)

FORM OF HEAT: 7000 SPONTANEOUS OR CHEMICAL CAUSATION

MATERIAL FIRST IGNITED: 4900 WOOD, PAPER PRODUCTS - UNCLASSIFIED (DESCRIBE)

ACT OR OMISSION: 7900 HUMAN FAILING - UNCLASSIFIED (DESCRIBE)

Investigating Officer

LAFC Badge #

Telephone

ReportDate

SHEEL, DANIEL

968

604-543-6700 2012-02-03

PROVINCE OF BRITISH COLUMBIA

Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: CSY 2012 02 01 17

01

Remarks:

FIRE STARTED ON OUTSIDE SIDE WALL NEAR FRONT DOOR. ALSO DEEP BURN TO INSIDE OF CLOSET. SUSPECT SLOW FIRE, DAMAGE TO FRONT OFFICE AREA AND OUTSIDE WALL, SHOE REPAIR HOUSE. SUSPECT FIRE MAY HAVE STARTED IN CARDBOARD BOXES, POSSIBLE SPONTANEOUS COMBUSTION.

Investigating Officer SHEEL, DANIEL

LAFC Badge #

968

Telephone ReportDate 604-543-6700 2012-02-03

PROVINCE OF BRITISH COLUMBIA

Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: **CSY 2012 02 01 17**

01

Name no. :1

Name : s.22

Address :

Name Status : OCCUPANT

Phone :

Claims Adjuster Firm : Claim Number :

Insurance Company :

Policy Number

Claims Adjuster Name

LOSS ESTIMATES:

Property Loss: s.22 Content Loss: s.22 Total Loss: s.22

REMARKS:

Incident Report

Investigating Officer SHEEL, DANIEL

LAFC Badge # 968

Telephone ReportDate 604-543-6700 2012-02-03