

STRUCTURE FIRE REPORT

OFFICE OF THE FIRE COMMISSIONER PO Box 9491 Stn. Prov. Govt. VICTORIA BC V8W 9N7 TEL. (250) 356-9000 FAX (250) 356-9019

> Incident Number/ 0 / CKE10073121/02

> > POSTAL CODE

Location of Fire Incident (Suite, Number, Street, City)

KIRSCHNER 1851

RD

KELOWNA

THE FOLLOWING SECTION REFERS TO SELECTED STATUS:

Property Complex: 5700 Commercial centre, shopping centre, strip mall

Property Classification: 7990 Miscellaneous storage properties - unclassified (descr

General Construction: 2000 Protected combustible construction - wood protected by

Building Height: 0010 1 Storey above grade

Ground Floor Area: 5000 2501 to 5000 m^2 (26911 - 53820 ft^2)

Year of Construction: 0000 Cannot be determined Manual Fire Protection: 4000 Extinguisher only

Outside Fire Protection: 1000 Public hydrant protection & fire department

Sprinkler Protection: 7000 No sprinkler protection Automatic Fire Detection: 1000 No fire alarm system 0000 Cannot be determined Smoke Alarm Operation:

> Initial Detection: 7000 Visual sighting or other means of personal detection (

Transmission of Alarm: 1000 911

> 3000 Composite - career & volunteer/paid-on-call fire depar Fire Service:

1000 Fire - fire department attended Incident: Action Taken: 3000 Extinguished by fire department

Method of Fire Control: 4700 Combinations of 38/42mm (1 1/2"/1 3/4"), 65mm (2 1/2")

Fire Origin (Level): 0000 Cannot be determined Fire Origin (Area): 0000 Cannot be determined

Extent of Fire: 6000 Extended beyond property of origin Extent of Damage: 6000 Extended beyond building of origin

Igniting Object: 0000 Cannot be determined Fuel or Energy: 0000 Cannot be determined Form of Heat: 0000 Cannot be determined 0000 Cannot be determined Material First Ignited:

Act or Omission: Number of Occupants: 0

Property Value:

s.21

Contact Number: 0 Contact Type Owner Status

Contact Name: Bisaro Donna

0000 Cannot be determined

Business Name: Whitworth Holdings

Address:

City: Adjustor Name:

Adjustor Company: Jac Jas Claim Number:

Insurance Company: Policy Number:

Reporting Officer: JASON L BROLUND

Date Pfi h 程8: 11/08/2010 Contents Value:

BuildingVehicle Loss:

Building/Vehicle Value:

s.21 s.21

Telephone:

Postal Code:

Signature

Total Claim Paid

Rank: ASST.CHIEF

LAFC #: 1844 JAG 2012-00584

Page 1

s.22

Last Name, First Name



STRUCTURE FIRE REPORT

OFFICE OF THE FIRE COMMISSIONER PO Box 9491 Stn. Prov. Govt. VICTORIA BC V8W 9N7 TEL. (250) 356-9000 FAX (250) 356-9019

REMARKS: EXPLAIN CIRCUMSTANCES UNDER WHICH FIRE ORIGINATED:

At 21:37 the Kelowna Fire Department responded to a major commercial building fire at Stewart Centre 1855 Kirschner Rd. On arrival crews found the building fully involved. 4 Engines, 2 Ladder Trucks, 1 Rescue Truck, 1 Hazmat Truck, Command Unit, Safety Officer, RCMP and BCAS are on scene. A tactical evacuation has been done in the area temporarily which has closed Harvey Ave from Burtch to Cooper and Springfield Rd from Burtch to Cooper. Any residents affected by the tactical evacuation are asked to attend the 1st United Church at 721 Bernard Ave(corner of Richter and Bernard) further updates will be provided on when affected residents may return to the area. No injuries reported at this time, damage assessment not available at this time, the cause of the fire is under investigation.

Thomas Doherty Assistant Fire Chief Kelowna Fire Department

REMARKS: EXPLAIN CIRCUMSTANCES UNDER WHICH FIRE ORIGINATED:

An update as of 0500hrs:

Kelowna Fire Department crews remain onscene. The fire has been suppressed, however many hotspots remain within the building and crews are focusing their efforts on knocking these down to limit the amount of smoke that continues to be given off. Hard work and determination by fire crews this evening resulted in containment of the fire to one building, saving the structure located next door from what appeared to be almost certain destruction. One firefighter was injured after experiencing smoke inhalation and was treated at the hospital and has since been released.

Springfield Rd and Highway 97 have both been re-opened to traffic and any evacuees can now return. The ESS centre has been closed after caring for residents that were displaced in the evacuation.

Access to the area immediately surrounding the fire remains restricted. This includes Kirschner Rd, Dickson Ave and Dolphin Ave. We ask that the public stay away at this time, if at all possible.

A major point of concern exists around the types of materials being stored in the building, including a welding supply, irrigation supply and agricultural supply warehouse. A volatile mix of explosive materials combined with fertilizers and pesticides have burnt, hence the need for the evacuation and ongoing concern regarding water contamination due to firefighting water than has runoff from the scene. The fire department and the city are taking all steps required to mitigate this emergency, including a number of city crews that are removing contaminated water from catch basins and sampling water courses that run through the area.

The provincial Environment Ministry has been advised and we are working with Interior Health to address air and water quality monitoring issues as required.

An emergency response team has been dispatched, representing the tenants in the building and we will be working with this team to mitigate the remaining product and any environmental damage caused by the fire and fire suppression activities.

Tenants of the building that have not been notified are asked to meet at the building at 9am Sunday morning for further information. The fire investigation has begun, however no cause has been determined and no dollar loss is available at this time.

Jason Brolund Assistant Chief Kelowna Fire Department

REMARKS: EXPLAIN CIRCUMSTANCES UNDER WHICH FIRE ORIGINATED:

From: Jason Brolund Sent: August 2, 2010 15:19 Subject: RE: Commercial Fire on Kirschner

A fire investigation was conducted and, the cause was not determined. The investigation has been turned over to the RCMP. The dollar loss is estimated to be s.21 dollars, based upon the building value.

Information regarding the Mill Creek Spill will be provided via the Emergency Operations Centre.

Investigation Remarks

LAFC Badge 2495

Investigator: PAUL JOHNSON

Date Investigation Began: 31/07/2010

Incident date: July 31, 2010 Location: 1851 Kirschner Road Paten Printe o 13/08/2010

Incident Number CKE1007312102 LAFC Performing Investigation: Johnson Completion Date: 03/08/2010

Signature



STRUCTURE FIRE REPORT

OFFICE OF THE FIRE COMMISSIONER
PO Box 9491 Stn. Prov. Govt.
VICTORIA BC V8W 9N7
TEL. (250) 356-9000 FAX (250) 356-9019
RCMP File Number 2010-37678

INVESTIGATORS ANALYSIS:

Date Printed 11/08/2010

Investigation July 31, 2010 22:30

For location reference the front of the structure (facing west) shall be considered the Alpha side, the north wall shall be considered the Bravo side, the east wall shall be considered the Charlie side and the south side shall be considered the Delta side.

A structure fire was reported at commercial building located at 1851 Kirschner Road. The structure is a wood frame structure with containing a fire wall and fire separations. The roof was combustible construction with a large glue laminate beam running down the centre of the building from east to west.

The businesses occupying the building (from East to West) were Univar Chemicals, Pro Source Irrigation, Reliable Welding Supplies, Stay Tuned Sports, Tile and Stone Factory Outlet and Interior Health.

I attended the scene at approximately 22:30 during the fire event. I proceeded to photograph all sides of the fire as the structure burned. Additionally, I spoke with several firefighters who were on the first line trucks and witnesses who were near the fire ground.

The firefighters I spoke with stated that the fire had already gone through the roof and was fully involved by the time they arrived. Platoon Captain Kelly Stephens stated that it appeared the fire may have originated at the rear of the building, possibly at Pro Source Irrigation. It appeared to more intense during initial stages of the fire attack. Analysis of photos posted on Castanet.net showed the Stone business was more or less intact during earlier photos.

Witnesses and spectators were questioned during the fire event. s.22 stated that s.22 had been watching TV when they heard an explosion. s.22 saw the fire s.22 and called 911. While calling, they noted an individual riding to the top of the adjacent parkade on a low trick mountain bike. The individual had s.22 . Apparently he was riding his bike extremely fast. After the second explosion he left the parkade. RCMP were immediately notified of the witness that evening and the witnesses phone number was provided.

s.22 was another witness to the fire. s.22 filmed the fire with his I-Phone prior to the explosions. He was filming the fire prior to the first

Signature



STRUCTURE FIRE REPORT

OFFICE OF THE FIRE COMMISSIONER PO Box 9491 Stn. Prov. Govt. VICTORIA BC V8W 9N7 TEL. (250) 356-9000 FAX (250) 356-9019

fire crews arriving. At the time of submitting the report, I had not recieved a copy of the video.

Another set of witnesses were

s.22

. All s.22 stated that they had gone to

s.22

located at the s.22 approximately 1 hour earlier. Upon leaving s.22 they stated that they did smell smoke.

I left the scene at approximately midnight and returned the following day with Inspector Pacholzuk.

The fire scene was considered unsafe and a complete and thorough investigation could not be conducted. The fire scene was photographed. Photos were taken from the roof as well as from all sides of the fire scene. There were no visible burn patterns which could aid in the investigation. Nor were there any indicators which could assist in determining the area of origin.

The large glue laminated beam which ran down the centre of the building from east to west was no longer intact. The beam was still standing in the Tile and Stone Business as well as the welding business. The beam had come down in Univar and in Pro Source Irrigation. A quick analysis was done on the fallen beam within the two businesses. Although the beam had separated, it appeared as if there was even charring throughout the length of the beam. This may indicate an even burn throughout the interior of the building.

No further investigation could be conducted at this time due to safety reasons. Fire investigators from several insurance companies are organizing to begin their respective investigations forthwith. The RCMP have been advised of the results of the investigation and Constable Burna Barkman is the assigned officer for the investigation.

Fire Cause

The fire cause is considered undetermined. The area of origin as well as the point of origin could be determined at this time due to safety reasons for the investigators.

Date Printed 11/08/2010

Signature

Page 4

NAMES REPORT

Incident Date and Time: 31/07/2010 21:37:06

Incident Address: 1851 KIRSCHNER

City: KELOWNA Incident Number: CKE1007312102

Postal Code:

Reporting Officer: JASON L BROLUND Rank: ASST.CHIEF LAFC#: 1844

Total Loss:

s.21

Contact Number: Contact Name:

0

Contact Type

Owner

Status:

Bisaro

Donna

Last Name, First Name

Business Name:

Whitworth Holdings

Address:

City:

Telephone:

Postal Code:

MAC R 1 998

Adjustor Name: Adjustor Company:

Claim Number: Insurance Company: Policy Number:

Contents Loss: 0

Contents Value:

BuildingVehicle Loss:

{} s.21

Building/Vehicle Value:

s.21

Total Claim Paid:

0

Reporting Officer: JASON L BROLUND

Rank: ASST.CHIEF

LAFC #: 1844

Date Printed 11/08/2010

Signature

JAG 2012-00584

Page 5

PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CKE 2010 07 31 21

01

Location of Incident:

NO

1851 KIRSCHNER ROAD

KELOWNA BC

of Occupants (At time of fire): **0** # of Injured: **0**

of Deaths: 0

s.21

Related to Wildland Interface Fire:

Property Value: s.21

Content Value: \$0

Total Value at Risk:

oss Estimate:

s.21

Code Name: Code Description

PROPERTY COMPLEX: 5700 COMMERCIAL CENTRE, SHOPPING CENTRE, STRIP MALL

PROPERTY CLASSIFICATION: 7990 MISCELLANEOUS STORAGE PROPERTIES - UNCLASSIFIED (DESCRIBE)

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 5000 2501 TO 5000M2 (26911 - 53820FT2)

YEAR OF CONSTRUCTION: 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7

FIRE ORIGIN, LEVEL: 0000 CANNOT BE DETERMINED

FIRE ORIGIN, AREA: 0000 CANNOT BE DETERMINED

EXTENT OF FIRE: 6000 EXTENDED BEYOND PROPERTY OF ORIGIN

EXTENT OF DAMAGE: 6000 EXTENDED BEYOND BUILDING OF ORIGIN

JAG 2012-00584 Page 6

IGNITING OBJECT: 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 0000 CANNOT BE DETERMINED

FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer BROLUND, JASON

LAFC Badge #

1844

Telephone

ReportDate

250-860-6419 2010-08-03

PROVINCE OF BRITISH COLUMBIA

Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: **CKE 2010 07 31 21**

01

Remarks:

SEE ELECTRONIC REFERENCE NOTES.

Investigating Officer

LAFC Badge #

BROLUND, JASON 1

1844

250-860-6419 2010-08-03

ReportDate

PROVINCE OF BRITISH COLUMBIA

Ministry of Public Safety and Solicitor General

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

Telephone

INCIDENT NUMBER: **CKE 2010 07 31 21**

s.21

01

Name no. :1

Name : BISARO, DONNA

Address :

Name Status : OWNER

Phone :

Claims Adjuster Firm : Claim Number :

Claims Adjuster Name

Insurance Company :

Policy Number :

LOSS ESTIMATES:

Property Content Loss: \$0 Total Loss:

Loss: s.21

REMARKS:

Incident Report

Investigating Officer BROLUND, JASON

LAFC Badge # 1844

Telephone ReportDate 250-860-6419 2010-08-03