Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DSQ 2012 06 08 17 01

Location of Incident: 1011 TOBERMORY WAY SOUAMISH BC VON 1T0

of Occupants (At time of fire): 2 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$ s.22

Related to Wildland Interface Fire: NO Property Value: \$ 5.22 Content Value: \$ 5.22 Total Value at Risk: \$ 5.22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 1997 1997

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL : $4000\,$ 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA : 7400 CEILING & ROOF/CEILING SPACE (ATTIC)

EXTENT OF FIRE: 4000 CONFINED TO FLOOR LEVEL OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

 $IGNITING\ OBJECT\ :\ 5900\ ELECTRICAL\ DISTRIBUTION\ EQUIPMENT\ -\ UNCLASSIFIED\ (DESCRIBE)$

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

 ${\tt MATERIAL\ FIRST\ IGNITED\ :\ 8000\ \ BUILDING\ COMPONENT\ -\ FLOOR,\ CEILING,\ ROOF.\ (EXCLUDES\ FLOOR\ CEILING,\ ROOF)\ (EXCLUDES\ FLOOR\ CEILING)\ (E$

ACT OR OMISSION: 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge # Telephone ReportDate FULTON, BOB 1138 604-898-9666 2012-06-20

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DSQ 2012 06 08 17 01

Remarks:

ELECTRICIAN WAS CHECKING A PROBLEM WITH POWER SURGES, WHEN HE POWERED UP THE MAIN BREAKER THE FIRE STARTED.

Investigating Officer FULTON, BOB

LAFC Badge #

1138

Telephone 604-898-9666

ReportDate 2012-06-20

Page 3 of 4 **Incident Report**

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DSQ 2012 06 08 17 01

Name no. : 1 Name Status : OWNER Phone

Name s.22

Address

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: \$ s.22 Content Loss: \$ s.22 Total Loss: \$ s.22

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate FULTON, BOB 604-898-9666 2012-06-20 1138

> Page 3 JAG-2014-00490

Incident Report Page 4 of 4