

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CNE 2014 07 16 01 01

Location of Incident: 1808 GRANITE RD
NELSON BC V1L6T8

of Occupants (At time of fire): 1 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: S.22

Related to Wildland Interface Fire: NO Property Value: S.22 Content Value: S.22 Total Value at Risk: S.22

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 7000 FIRE DEPARTMENT ONLY
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 5000 ALARM ACTIVATED - OCCUPANT ACTION UNKNOWN
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7600 EXTERIOR WALL
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 5900 ELECTRICAL DISTRIBUTION EQUIPMENT - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 3000 SPARK, STATIC ELECTRICAL
MATERIAL FIRST IGNITED : 9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #
MAIDA, RICK 2118

Telephone ReportDate
250-352-3103 2014-07-16

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CNE 2014 07 16 01 01

Remarks:

REPORTED AS AHOUSE BURNING ON THE OUTSIDE NEAR THE POWER SERVICE. UPON OUR ARRIVAL WE FOUND THE FIRE TO BE OUT WITH THE EXCEPTION OF SOME SMOLDERING. THE POWERLINE BURNED OFF THE MAST AND WAS ON THE GROUND. ALSO THERE WAS EXTENSION UP THE SIDE OF THE HOUSE AND UNDER THE EVE AREA. APPLIED APPROX. FIFTY GALLONS OF WATER TO ENSURE EXTINGUISHMENT CHECKED THE HOUSE BOTH INSIDE AND OUT FOR EXTENSION. NONE FOUND. THERE WERE MULTIPLE BREAKERS THAT HAD TRIPPED. PHOTOS ARE AVAILABLE UPON REQUEST. NELSON HYDRO ATTENDED THE SCENE TO DISCONNECT THE POWER AT THE POLE. THERE WAS A WORKING SMOKE ALARM IN THE HOUSE AT THE TIME OF THE INCIDENT.

Investigating Officer
MAIDA, RICK

LAFC Badge #
2118

Telephone
250-352-3103

ReportDate
2014-07-16

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CNE 2014 07 16 01 01

Name no. : 1
Name : s.22
Address : 1808 GRANITE RD
NELSON BRITISH COLUMBIA V1L6T8

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : \$0

Total Loss : s.22

REMARKS:

I WAS SLEEPING AND WAS AWAKEN BY A LOUD NOISE. I THOUGHT IT WAS A BEAR BUT THE NOISES(AND POPPING GREW LOUDER AND THEN A BRIGHT LIGHT FLASHED.(LIKE FIREWORKS). I IMMEDIATELY LEFT THE HOUSE AND SAW THAT OUTSIDE PLANTS WERE ON FIRE. AT 1.58 AM I CALLED 911.

Investigating Officer

MAIDA, RICK

LAFC Badge #

2118

Telephone

250-352-3103

ReportDate

2014-07-16

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DNC 2013 11 01 02 01

Location of Incident: 20 - 3101 HERON'S WAY
NORTH COWICHAN BC V9L 6Z4

of Occupants (At time of fire): 3 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: s.21

Related to Wildland Interface Fire: NO Property Value: s.21 Content Value: s.21 Total Value at Risk: s.21

Code Name : Code Description

PROPERTY COMPLEX : 3100 RESIDENTIAL - ROW, GARDEN, TOWN HOUSING, CONDOMINIUM
PROPERTY CLASSIFICATION : 3230 APARTMENT, TOWNHOUSE - 5 TO 20 UNITS WITH BUSINESS
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 2011 2011
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION : 1000 SMOKE ALARM DEVICE
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7600 EXTERIOR WALL
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 0000 CANNOT BE DETERMINED
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #
CLARK, ROB 999

Telephone ReportDate
250-746-3100 2013-11-19

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DNC 2013 11 01 02 01

Remarks:

THE FIRE ORIGINATED AT UNIT 21 (CENTRE UNIT) AT THE REAR CORNER WHERE UNIT 22 JOINED ON THE OUTSIDE WALL AT THE CONCRETE PATIO. THE FIRE STARTED AT GROUND LEVEL IN THE CORNER AND QUICKLY SPREAD UP THE RAIN SCREENING (BETWEEN THE SIDING AND WALL SHEETING). ONCE THE FIRE MOVED TO SOFIT, BRANCHED INTO THE ROOF STRUCTURE OF THE UNIT 22 AND 21. NO IGINTION SOURCE WAS FOUND AT THE AREA OF ORIGIN.

Investigating Officer
CLARK, ROB

LAFC Badge #
999

Telephone
250-746-3100

ReportDate
2013-11-19

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DNC 2013 11 01 02 01

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address : s.21

Name Status : BUSINESS OWNER
Phone : 250-748-3200

Claims Adjuster Name : I. DORGY, DUNCAN
Claims Adjuster Firm : I. AVIVA
Claim Number : s.21
Insurance Company : I. AVIVA
Policy Number : s.21

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : \$0

Total Loss : s.21

REMARKS:

Investigating Officer : LAFC Badge #
CLARK, ROB : 999

Telephone : Report Date
250-746-3100 : 2013-11-19

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DNV 2013 12 28 03 01

Location of Incident: **1370 REDWOOD ST
NORTH VANCOUVER DISTRICT BC**

of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: s.21

Related to Wildland Interface Fire: NO Property Value: s.21 Content Value: s.21 Total Value at Risk: s.21

Code Name : Code Description

PROPERTY COMPLEX : 1300 EDUCATIONAL INSTITUTION (NON-RESIDENTIAL)
PROPERTY CLASSIFICATION : 1310 NURSERY SCHOOL, KINDERGARTEN, PRE-SCHOOL
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 1300 SMALL ASSEMBLY AREA - 60 PEOPLE OR LESS - INCLUDES CLASSROOM
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 0000 CANNOT BE DETERMINED
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer LAFB Badge #
WILSON, BENJAMIN 2549

Telephone ReportDate
604-980-7575 2014-10-28

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DNV 2013 12 28 03 01

Remarks:

UPON REVIEW OF THIS INCIDENT BY CHIEF DE ROY AND LIEUTENANT SUTHERLAND, WE REVIEWED THE TIMESTAMPS AND DISPATCHERS NOTES. CHIEF DE ROY WAS AWARE DEI RETURNED TO THE SCENE AS PER REQUEST FROM THE DC TO PICK UP EQUIPMENT AND RETURN TO THE HALL. THIS IS WHY WE ADDED AN EXTRA REPORT. WE ALSO ADDED THE DAY SHIFT CREW ATTENDING ON DEI. IN CONVERSATION WITH CAPT WILSON, WE NOTICED THE TIMESTAMPS FOR FPO1 WERE NOT ACCURATE. REFERRING TO THE DISPATCH NOTES, THE DISPATCHER DISPATCHED FPO1 ALMOST A FULL HOUR EARLIER. AN ESTIMATE WAS GIVEN FOR FPO1'S RESPONDING TIME. FPO1'S OTHER TIMESTAMPS APPEARED ACCURATE. DUE TO THE URGENCY OF A FOI REQUEST FROM ADMINISTRATION, CHIEF DE ROY AND LT. SUTHERLAND REVIEWED THE INCIDENT BEFORE LOCKING IT.

Investigating Officer LAFC Badge #
WILSON, BENJAMIN 2549

Telephone ReportDate
604-980-7575 2014-10-28

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DNV 2013 12 28 03 01

Name no. : 1
Name : HUBBARD, LISA
Address : 0

Name Status : BUSINESS OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer : LAFB Badge #
WILSON, BENJAMIN : 2549

Telephone : 604-980-7575
ReportDate : 2014-10-28

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CPG 2012 01 21 07 01

Location of Incident: **1489 MCCULLAGH AVENUE
PRINCE GEORGE BC**

of Occupants (At time of fire): **2** # of Injured: **1** # of Deaths: **0** Total Dollar Loss Estimate: **\$22**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : Code Description

PROPERTY COMPLEX : 3500 RESIDENTIAL - DUPLEX, 3-PLEX, 4-PLEX
PROPERTY CLASSIFICATION : 3990 RESIDENTIAL MISCELLANEOUS - UNCLASSIFIED (DESCRIBE)
GENERAL CONSTRUCTION : 0000 CANNOT BE DETERMINED
BUILDING HEIGHT : 0000 CANNOT BE DETERMINED
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 0000 CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 4700 VEHICLE STORAGE - INCLUDES GARAGE, CARPORT. (EXCLUDES OUTSID
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION : 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge #
IVERSON, JOHN 2356

Telephone ReportDate
250-561-7667 2012-01-24

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CPG 2012 01 21 07 01

Remarks:

STRUCTURE FIRE IN A FOUR-PLEX. FIRE APPEARS TO HAVE STARTED IN THE ELECTRICAL PANEL IN THE GARAGE. CREWS WERE ABLE TO RESCUE A WOMAN WHO WAS TRAPPED IN THE BASEMENT SUITE WHO WAS THEN TAKEN TO HOSPITAL BY BCAS. RULED ACCIDENTAL.

Investigating Officer
IVERSON, JOHN

LAFC Badge #
2356

Telephone
250-561-7667

ReportDate
2012-01-24

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CPG 2012 01 21 07 01

Name no. : 1
Name : s.22
Address :
PRINCE GEORGE BRITISH COLUMBIA

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Name no. : 2
Name : s.22
Address :

Name Status : OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : \$0

Total Loss : s.22

REMARKS:

Investigating Officer
IVERSON, JOHN

LAFC Badge #
2356

Telephone
250-561-7667

ReportDate
2012-01-24

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: CPG 2012 01 21 07 01

Name no. : 3
Name : UNKNOWN, UNKNOWN
Address :

Name Status : OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Name no. : 4
Name : UNKNOWN, s.22
Address :

Name Status : OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Investigating Officer : LAFB Badge #
IVERSON, JOHN : 2356

Telephone : ReportDate
250-561-7667 2012-01-24

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (CASUALTY)

INCIDENT NUMBER: CPG 2012 01 21 07 01

CASUALTY NO : 1
NAME : UNKNOWN, UNKNOWN
ADDRESS :

AGE : s.22
GENDER : F
STATUS : CIVILIAN
DATE OF DEATH :

Code Name : Code Description

NATURE OF CASUALTY : 003 - MINOR INJURY (LESS THAN ONE DAY HOSPITAL OR OFF WORK)
CONDITION OF CASUALTY : 010 - CONDITION OF CASUALTY UNKNOWN
ACTION OF CASUALTY : 020 - ACTION OF CASUALTY UNKNOWN
IGNITION OF CLOTHING : 030 - NOT APPLICABLE
TYPE OF FABRIC IGNITED : 040 - NOT APPLICABLE
CAUSE OF FAILURE TO ESCAPE : 050 - UNKNOWN
CAUSE OF INJURY/DEATH : 100 - SMOKE INHALATION

Investigating Officer
IVERSON, JOHN

LAFC Badge #
2356

Telephone
250-561-7667

ReportDate
2012-01-24

