

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: **DNC 2011 11 17 18 01** ▪

Location of Incident:

**6496 DIANA DRIVE
NORTH COWICHAN BC V9L 5V3**# of Occupants (At time of fire): **4** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate **s.22**Related to Wildland Interface Fire: **NO** Property Value: **s.22** Content Value: **s.22** Total Value at Risk: **s.22****Code Name : Code Description**

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 1972 1972
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9500 ALARM NOT ACTIVATED - UNKNOWN
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 4300 SUPPLIES, EQUIPMENT AREA - INCLUDES TOOL ROOM, MAINTENANCE S
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 6000 EXTENDED BEYOND BUILDING OF ORIGIN
IGNITING OBJECT : 4990 APPLIANCES & EQUIPMENT - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer
CLARK , ROBLAFC Badge #
999Telephone
250-746-3100 ReportDate
2011-11-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **DNC 2011 11 17 18 01**

Remarks:

THE PROPERTY OWNER ARRIVED HOME AT 1700 HRS AND WENT INTO A SIDE ROOM OFF THE WORKSHOP AND TURNED ON THE PARAFFIN BATH SPA WHICH WAS LOCATED ON TOP OF A TEAK DESK. AT 1849 HRS THE PROPERTY OWNER'S WIFE NOTICED A SMELL OF BURNING PLASTIC. THE OWNER OPENED THE DOOR BETWEEN THE KITCHEN AND THE WORKSHOP AND FOUND THE ROOM TO BE FULL OF SMOKE. UPON EXITING THE HOUSE AND INVESTIGATING FURTHER, A NUMBER OF DOORS WERE LEFT OPEN. THE FIRE QUICKLY SPREAD THROUGHOUT THE WORKSHOP AND THE GARAGE. THE SUSPECTED CAUSE OF THE FIRE WAS THE PARAFFIN BATH SPA

Investigating Officer
CLARK , ROB

LAFC Badge #
999

Telephone
250-746-3100 

ReportDate
2011-11-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)INCIDENT NUMBER: **DNC 2011 11 17 18 01**

Name no. : 1
Name : s.22
Address : 6496 DIANA DRIVE
DUNCAN BRITISH COLUMBIA V9L 5V3

Name Status : OWNER
Phone : s.22

Claims Adjuster Name : 1. VOGSTAD , GLENN
Claims Adjuster Firm : 1. ASSOCIATED INDEPENDENT ADJUSTERS
Claim Number : s.22
Insurance Company : 1. CANADIAN NORTHERN SHIELD
Policy Number : s.22

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : s.22

Total Loss : s.22

REMARKS:

THE PROPERTY OWNER ARRIVED HOME AT 1700 HRS AND WENT INTO A SIDE ROOM OFF THE WORKSHOP AND TURNED ON THE PARAFFIN BATH SPA WHICH WAS LOCATED ON TOP OF A TEAK DESK. AT 1849 HRS THE PROPERTY OWNER'S WIFE NOTICED A SMELL OF BURNING PLASTIC. THE OWNER OPENED THE DOOR BETWEEN THE KITCHEN AND THE WORKSHOP AND FOUND THE ROOM TO BE FULL OF SMOKE. UPON EXITING THE HOUSE AND INVESTIGATING FURTHER, A NUMBER OF DOORS WERE LEFT OPEN. THE FIRE QUICKLY SPREAD THROUGHOUT THE WORKSHOP AND THE GARAGE. THE SUSPECTED CAUSE OF THE FIRE WAS THE PARAFFIN BATH SPA.

Name no. : 2
Name : s.22
Address : 6496 DIANA DRIVE
DUNCAN BRITISH COLUMBIA V9L 5V3

Name Status : OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

CO-OWNER, FIRST TO NOTICE BURNING PLASTIC SMELL. LOSS ESTIMATE IS UNDER OTHER OWNER.

Investigating Officer : LAFC Badge #
CLARK , ROB : 999

Telephone : 250-746-3100
ReportDate : 2011-11-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)INCIDENT NUMBER: **DNC 2011 11 17 18 01**

Name no. : 3
Name **s.22**
Address : 6496 DIANA DRIVE
DUNCAN BRITISH COLUMBIA V9L 5V3

Name Status : OCCUPANT
Phone **s.22**

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

YEAR OLD SON - IN UPSTAIRS BEDROOM AT THE TIME.

Name no. : 4
Name **s.22**
Address : 6496 DIANA DRIVE
DUNCAN BRITISH COLUMBIA V9L 5V3

Name Status : OCCUPANT
Phone **s.22**

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

YEAR OLD SON - IN UPSTAIRS BEDROOM AT THE TIME.

Investigating Officer :
CLARK , ROB

LAFC Badge # :
999

Telephone :
250-746-3100

ReportDate :
2011-11-30

