Emergency Management BC / Office of t	INCIDENT	INCIDENT NUMBER: CRI 2014 04 15 03 07	
Location of Incident:	4351 WOODHEA RICHMOND BC	D RD	
# of Occupants (At time of fire): 0	# of Injured: 0 # of	Deaths: 0 Total I	Dollar Loss Estimate: \$ s.22
Related to Wildland Interface Fire: NO	Property Value: \$ s.22	Content Value: \$ s.22	Total Value at Risk: \$ s.22

Code Name :	Code Description
PROPERTY COMPLEX : 3400	RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110	YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000	PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0020	2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 1000	1 TO 100M2 (1 - 1076FT2)
YEAR OF CONSTRUCTION : 1985	1985
MANUAL FIRE PROTECTION : 7000	NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000	PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000	NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000	NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 0000	ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 7000	VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000	911
FIRE SERVICE : 1000	CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000	FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000	EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300	38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 2000	CRAWL SPACE, UNDER STRUCTURE
FIRE ORIGIN, AREA : 7100	CRAWL SPACE - INCLUDES SUB-STRUCTURE SPACE
EXTENT OF FIRE : 2000	CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 5000	CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 0000	CANNOT BE DETERMINED
FUEL OR ENERGY : 0000	CANNOT BE DETERMINED
FORM OF HEAT : 0000	CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000	CANNOT BE DETERMINED
ACT OR OMISSION : 1240	SUSPICIOUS - SUSPECT NOT IDENTIFIED

Investigating Officer TIMMONS, MARK

LAFC Badge #

Telephone ReportDate 604-278-5131 2014-05-07

Remarks:

THIS HOUSE IS A SPLIT LEVEL HOME APPROXIMATELY 50' X 30' CONSISTING OF WOOD FRAME CONSTRUCTION THE ROOFING MATERIAL WAS ASPHALT SHINGLES AND THE EXTERIOR WAS WOOD SIDING AND STUCCO. THE FIRE STARTED IN THE CRAWL SPACE THEN PROCEEDED TO BURN ON THE UNDERSIDE OF THE LIVING ROOM FLOOR. FIRE DAMAGE WAS CONTAINED TO THE CRAWL SPACE AND 90% OF THE LIVING ROOM FLOOR WAS DISTROYED. THE REST OF THE HOUSE HAD HEAVY SMOKE AND WATER DAMAGE. PROBABLE CAUSE: INCENDIARY CIRCUMSTANCES: SOMEONE ENTERED THE PROPERTY AND REMOVED A GRATE FROM THE FRONT OF THE HOUSE WHICH GAVE THEM ACCESS TO THE CRAWL SPACE. THEY THEN IGNITED COMBUSTIBLE MATERIAL IN THE CRAWL SPACE.

Investigating Officer TIMMONS, MARK LAFC Badge #

 Telephone
 ReportDate

 604-278-5131
 2014-05-07

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CRI 2014 04 15 03 07

PROVINCE OF BRITISH	I COLUMBIA	FIRE REPORT - STRUCTURE (NAMES)		
Ministry of Justice Emergency Management BC / Office of the Fire Commissioner		INCIDENT NUMBER: CRI 2014 04 15 03 07		
Name no. Name Address	: 1 : <u>s.22</u> : 0 4351 WOODHEAD RD V6X1J1	Name Status: OWNERPhone: s.22		
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number				
LOSS ESTIMATES: Property Loss : \$ s.22	Content Loss : \$ s.22	Total Loss : s.22		
REMARKS:				
Name no. Name Address	: 2 : : s.22	Name Status : WITNESS Phone : s.22		
Name	:			
Name Address Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company	s.22			

Investigating Officer		
TIMMONS, MARK		

LAFC Badge #

 Telephone
 ReportDate

 604-278-5131
 2014-05-07

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Ministry of Justice Emergency Management BC / Office of the Fire Commissioner		e of the Fire Commissioner	INCIDENT NUMBER: CRI 2014 04 15 03 07
Name no. Name Address	: 3 : :	s.22	Name Status : WITNESS Phone : s.22
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: : : :		
LOSS ESTIMATES: Property Loss : \$0		Content Loss : S	D Total Loss : \$0
REMARKS:			

Investigating Officer TIMMONS, MARK LAFC Badge #

 Telephone
 ReportDate

 604-278-5131
 2014-05-07

Incident Report