



Ministry of  
Energy and Mines

Province of British Columbia  
**Ministry of Energy and  
Mines**

Report of Inspector of Mines  
(Issued pursuant to Section 15 of the *Mines Act*)

Inspection No.: 23131  
File: 18080-02-XX  
Mine No.: 0400805  
Permit No.: G-4-115  
Emp/Cont: 0 / 0  
Orders H&S: 0 RECL: 0  
Stop Work: 0

**Inspection Report**

NAME OF MINE	McIntyre Pit	LOCALITY	49.247, -119.520 Oliver
OWNER/OPERATOR	W. Barisoff & Sons Limited	ADDRESS	Site #41, Comp #7, RR 2 Oliver BC V0H 1T0
MANAGER	Barry Barisoff	AREAS INSPECTED	access road, working faces, stock piles and buffer zone

**Persons Contacted**

MANAGEMENT Barry Barisoff

OHS COMMITTEE

WORKERS

A copy has been forwarded to the Joint Occupational and Safety Committee and the union as applicable. The Mine manager shall complete the right hand column noting specific corrective actions taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

**INSPECTION ORDERS**

Weather was warm, sunny with a light wind from the north.

Access road was watered during the timing of inspection. Watering was done via a time sprinkler system which is programmed to activate 3 times per day.

Crushing was completed prior to the third week in May. No production equipment was operating in the pit. Loading out of product is the only operation occurring.

No issues were noted at time of inspection.

**MANAGERS RESPONSE OF ACTION TAKEN**

Bruce Hupman, P. Ag.

Senior Inspector of Mines

441 Columbia Street Kamloops BC V2C 4T3

Address

Date of Inspection: 5/30/2012

Copies To

Signature – Inspector of Mines

Signature – Manager

Dated: \_\_\_\_\_, 20\_\_\_\_