PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DMA 2013 04 17 15 01

Location of Incident: 1020 FRONTAGE ROAD
MACKENZIE BC V0J2C0

of Occupants (At time of fire): 3 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: s.22

Related to Wildland Interface Fire: NO Property Value: s.22 Content Value: s.22 Total Value at Risk: s.22

Code Name: Code Description

PROPERTY COMPLEX: 4100 OFFICE BUILDING

PROPERTY CLASSIFICATION: 5730 VEHICLE REPAIR GARAGE, VEHICLE PAINT/POWDER COATING SHOP. (E

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 0066 1966 TO 1968

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 3550 MAINTENANCE SHOP - INCLUDES REPAIR SHOP, WELDING SHOP, WORKS

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

 ${\tt IGNITING\ OBJECT\ :\ 9700\ COMMERCIAL\ \&\ INDUSTRIAL\ MACHINERY, EQUIPMENT\ -\ INCLUDES\ SAWI}$

FUEL OR ENERGY: 3000 GASOLINE

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 5100 GASOLINE

ACT OR OMISSION: 7900 HUMAN FAILING - UNCLASSIFIED (DESCRIBE)

Investigating Officer LAFC Badge # Telephone ReportDate
GUISE, JAMIE 2329 250-997-4221 2013-04-24

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DMA 2013 04 17 15 01

Remarks:

THE OWNER WAS DRAINING THE FLUIDS ON A CAR IN HIS SHOP IN PREPARATION FOR CRUSHING THE CAR, DECIDED TO DRILL A HOLE IN THE FUEL TANK TO DRAIN THE FUEL. OWNER DECIDED TO DRILL A SECOND HOLE IN THE TANK TO SPEED UP THE DRAINING AND IGNITED THE FUMES. OWNER ATTEMPTED TO USE A FIRE EXTINGUISHER TO PUT THE FIRE OUT, AFTER BEING UNSUCCESSFUL CALLED THE FIRE DEPARTMENT.

Investigating Officer
GUISE, JAMIE

LAFC Badge # 2329

Telephone 250-997-4221

ReportDate 2013-04-24

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

INCIDENT NUMBER: DMA 2013 04 17 15 01

: BUSINESS OWNER

Name no. : 1

Name : s.22

Address : 1020 FRONTAGE ROAD

MACKENZIE BRITISH COLUMBIA V0J 2C0

Claims Adjuster Name
Claims Adjuster Firm
Claim Number
Insurance Company
Policy Number
:

LOSS ESTIMATES:

Property Loss: s.22 Content Loss: s.22 Total Loss: s.22

REMARKS:

Investigating OfficerLAFC Badge #TelephoneReportDateGUISE, JAMIE2329250-997-42212013-04-24