

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CNA 2014 03 05 19 02

Location of Incident: **2127 LANG CRES
NANAIMO BC**

of Occupants (At time of fire): **4** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: \$ **s.22**

Related to Wildland Interface Fire: **NO** Property Value: \$ **s.22** Content Value: \$ **s.22** Total Value at Risk: **s.22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 1990 1990
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9500 ALARM NOT ACTIVATED - UNKNOWN
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W
METHOD OF FIRE CONTROL : 1800 MULTI-PURPOSE DRY CHEMICAL
FIRE ORIGIN, LEVEL : 1000 BASEMENT, SUB-BASEMENT
FIRE ORIGIN, AREA : 3200 LAUNDRY AREA - INCLUDES WASH HOUSE
EXTENT OF FIRE : 3000 CONFINED TO ROOM OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 3300 CLOTHES DRYER
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED : 3900 CLOTHING, TEXTILES - UNCLASSIFIED (DESCRIBE) (EXCLUDES PAPER
ACT OR OMISSION : 6300 LACK OF MAINTENANCE

Investigating Officer LAFC Badge #
MOND, ENNIS 1030

Telephone ReportDate
250-753-7311  2014-03-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**
(PRODUCT/EQUIPMENT)
INCIDENT NUMBER: CNA 2014 03 05 19 02

LOG # : 170180
ITEM TYPE : DRYER, CLOTHES
ITEM DESCRIPTION :
MAKE : LG
MODEL : DLEX2550S
YEAR : 2012
LICENSE NO. :
SERIAL NO. : 205KWDJAQ226
MAKE : LG

CERT. AGENCY1 :
CERT. AGENCY2 :
CERT. AGENCY3 :
CERT. AGENCY4 :
CERT. AGENCY5 :

COMMENTS :

Investigating Officer : LAFB Badge #
MOND, ENNIS : 1030

Telephone : ReportDate
250-753-7311  2014-03-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CNA 2014 03 05 19 02**

Remarks:

THE OWNER OF THE HOUSE WAS ON HER FOURTH LOAD OF CLOTHS IN THE DRYER. SHE WAS UPSTAIRS PUTTING HER DAUGHTERS TO BED WHEN SHE SMELLED SMOKE. SHE WENT DOWN TO THE LAUNDRY ROOM IN THE BASEMENT TO INVESTIGATE. SHE COULD SEE SMOKE IN THE LAUNDRY ROOM AND NOTED THAT SMALL WOODEN PLANTER WITH ARTIFICIAL FLOWERS ON THE TOP OF THE DRYER WAS BURNING WITH FLAMES SHOWING. SHE IMMEDIATELY CALLED HER FATHER NEXT DOOR AND HE CAME OVER AND EXTINGUISHED IT WITH A FIRE EXTINGUISHER. AFTER CALLING HER FATHER SHE HAD CALLED THE FIRE DEPARTMENT. UPON ARRIVAL AND INVESTIGATION BY THE FIRE DEPARTMENT IT WAS ALSO FOUND THAT THE SCREEN OF THE LINT TRAP HAD HOLES BURNED THROUGH IT. DURING THE INVESTIGATION IT WAS LEARNED THAT THE MALE OWNER HAD JUST RECENTLY CLEANED THE DRYER DUCTS. IT APPEARS THAT BURNING LINT MATERIAL BURNED THROUGH THE PLASTIC FLEX DRYER VENT PIPE AND IGNITED THE ARTIFICIAL PLANT WHICH WAS ON THE TOP OF THE DRYER ADJACENT TO THE PLASTIC DRYER VENT PIPE. NOTHING WAS FOUND BURNING PRIOR TO THE CREWS DEPARTING THE SCENE.

Investigating Officer	LAFC Badge #
MOND, ENNIS	1030

Telephone	Report Date
250-753-7311 	2014-03-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)INCIDENT NUMBER: **CNA 2014 03 05 19 02**

Name no. : 1
Name :
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$ **s.22**Total Loss : **s.22**

REMARKS:

Name no. : 2
Name :
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Investigating Officer :
MOND, ENNIS

L AFC Badge # :
1030

Telephone :
250-753-7311

ReportDate :
2014-03-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)INCIDENT NUMBER: **CNA 2014 03 05 19 02**

Name no. : 3
Name :
Address : 0

Name Status : OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Name no. : 4
Name :
Address : 0

Name Status : OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Investigating Officer : L AFC Badge #
MOND, ENNIS : 1030

Telephone : ReportDate
250-753-7311 2014-03-30

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: VCU 2013 08 08 13 01

Location of Incident: **2868 BRUCE STREET
CUMBERLAND BC V0R1S0**

of Occupants (At time of fire): **3** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **s.22**

Related to Wildland Interface Fire: **NO** Property Value: **s.22** Content Value: \$ **s.22** Total Value at Risk: **s.22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 2010 2010
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 6000 ALARM NOT ACTIVATED - UNSUITABLE LOCATION
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 1200 WATER PRESSURIZED
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 1020 STAIRWAY, EXTERIOR - INCLUDES FIRE ESCAPE, RAMP
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 1010 NO IGNITING OBJECT (I.E. LIGHTNING, SUN'S RAYS)
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 3000 EXTERIOR WALL COVERING, SURFACE, FINISH - INCLUDES EAVE
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge #
WILLIAMSON, MICHAEL

Telephone ReportDate
250-336-2291  2014-06-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **VCU 2013 08 08 13 01**

Remarks:

FIRE STARTED OUTSIDE HOME VERY NEAR OR IN TELUS BOX. VINYL SIDING BURNT UP AND GOT INTO ATTIC SPACE.
FULLY INVIVLED ATTIC SPACE, GABLE AND SOFFIT

Investigating Officer LAFC Badge #
WILLIAMSON, MICHAEL

Telephone ReportDate
250-336-2291  2014-06-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **VCU 2013 08 08 13 01**

Name no. : 1
Name : **s.22**
Address : 2868 BRICE STREET
CUMBERLAND BRITISH COLUMBIA V0R1S0

Name Status : OWNER
Phone :

Claims Adjuster Name : 1. SCOTT , BOB
Claims Adjuster Firm :
Claim Number : 1. **s.22**
Insurance Company : 1. HUB
Policy Number :

LOSS ESTIMATES:

Property Loss : \$ **s.22**

Content Loss : \$ **s.22**

Total Loss : \$ **s.22**

REMARKS:

Investigating Officer : LAFC Badge #
WILLIAMSON, MICHAEL

Telephone : 250-336-2291  ReportDate : 2014-06-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CCQ 2014 04 21 05 02

Location of Incident:

**463 BYNG ST
COQUITLAM BC**# of Occupants (At time of fire): **4** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **s.22**Related to Wildland Interface Fire: **NO** Property Value: **s.22** Content Value: \$ **s.22** Total Value at Risk: \$ **s.22****Code Name : Code Description**

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 7810 GARAGE: INDIVIDUAL, DETACHED RESIDENTIAL PARKING IN ONE-STOR
GENERAL CONSTRUCTION : 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 0061 1961 TO 1965
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 4700 VEHICLE STORAGE - INCLUDES GARAGE, CARPORT. (EXCLUDES OUTSID
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 0000 CANNOT BE DETERMINED
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer
EBERLE, BRYAN

LAFC Badge #
2368

Telephone
604-927-6400 

ReportDate
2014-06-11

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CCQ 2014 04 21 05 02**

Remarks:

THIS FIRE OCCURRED IN THE EARLY MORNING AT A RESIDENTIAL PROPERTY CONTAINING A WOOD FRAMED DETACHED CARPORT ADJACENT TO SINGLE FAMILY DWELLING. WRITER WAS REQUESTED TO INVESTIGATE THE FIRE CAUSE AND ORIGIN THE DAY AFTER THE FIRE. SCENE SECURITY HAD BEEN MAINTAINED BY PRIVATE CONTRACTOR ARRANGED THROUGH THE PROPERTY OWNERS INSURANCE ADJUSTER. ACCORDING TO BURN PATTERNS AND WITNESS STATEMENTS THE FIRE STARTED IN THE CARPORT AND SPREAD TO THE DWELLING. IN THE CARPORT WAS PARKED A BMW X6; RECYCLING & GARBAGE BINS; CARDBOARD; PLASTIC BOTTLES AND SHELVING WITH A SMALL AMOUNT OF MISCELLANEOUS HOUSEHOLD ITEMS. POINT OF ORIGIN COULD NOT BE DETERMINED DUE TO THE EXTENT OF DAMAGE TO THE CARPORT. THE AREA OF ORIGIN APPEARED TO BE IN THE SOUTH-EAST CORNER OF THE CARPORT. NO EVIDENCE OF ACCELERANTS WAS NOTED. THE OCCUPANTS DID NOT REPORT HAVING PROBLEMS WITH ANYONE. CST. GUERVARA (RCMP) WAS REQUESTED TO CHECK BACKGROUND OF OCCUPANTS AND ASSOCIATES - VERBALLY ADVISED THAT NOTHING OF INTEREST CAME BACK. THE OCCUPANTS ARE NON-SMOKERS. GARBAGE BIN HAD BEEN DUMPED ON THURSDAY AND SAT EMPTY UNTIL HOUSEHOLD GARBAGE WAS PLACED IN IT ON SATURDAY, IT DIDN'T CONTAIN ANYTHING OUT OF THE ORDINARY (NOTHING THAT WOULD POTENTIALLY SELF-HEAT AND IGNITE). IN THE AREA OF ORIGIN THERE WERE ELECTRICAL SOURCES FROM THE VEHICLE ENGINE COMPARTMENT; ELECTRICAL CONDUIT RUNNING UNDERGROUND AND ATTACHING TO A JUNCTION BOX ON THE EXTERIOR OF THE CARPORT; AN OUTLET AND AN OVERHEAD FLUORESCENT LIGHT FIXTURE. BURN PATTERNS INDICATING THE DIRECTION OF TRAVEL IN TOWARDS THE ENGINE BAY SUGGEST ELIMINATING THE VEHICLE AS A SOURCE OF IGNITION. WHAT WAS LEFT OF THE ELECTRICAL JUNCTION BOX, NEARBY OUTLET AND FLUORESCENT LIGHT WERE REVIEWED AND DID NOT PROVIDE ANY EVIDENCE AS TO CAUSE AND ORIGIN. THE HOMEOWNER HAD REPORTED THAT THE FLUORESCENT LIGHT WOULD WORK INTERMITTENTLY AND ALWAYS HAD A HUM COMING FROM THE BALLASTS. CURRENTLY THE FIRE CAUSE AND ORIGIN IS LISTED AS UNDETERMINED. GAS AND POWER TO THE HOME HAD BEEN DISCONNECTED. BUILDING DEPARTMENT NOTIFIED AND DWELLING TAGGED AS UNOCCUPIABLE. THE PROPERTY WAS LEFT IN THE CARE OF THE SECURITY COMPANY HIRED BY THE INSURANCE ADJUSTER.

Investigating Officer	LAFC Badge #
EBERLE, BRYAN	2368


Telephone	ReportDate
604-927-6400 	2014-06-11

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CCQ 2014 04 21 05 02**

Name no. : 1
Name : **s.22**
Address : 0 463 BYNG ST.
V3K5N8

Name Status : OWNER
Phone : **s.22** 

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.22**

Content Loss : \$ **s.22**

Total Loss : **s.22**

REMARKS:

Investigating Officer : LAFC Badge #
EBERLE, BRYAN : 2368

Telephone : ReportDate
604-927-6400  2014-06-11

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CSY 2012 08 24 15 02

Location of Incident: **12547 68 AVE
SURREY BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: \$ **s.22**

Related to Wildland Interface Fire: **NO** Property Value: **s.22** Content Value: \$ **s.22** Total Value at Risk: \$ **s.22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION : 0066 1966 TO 1968
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7600 EXTERIOR WALL
EXTENT OF FIRE : 3000 CONFINED TO ROOM OF ORIGIN
EXTENT OF DAMAGE : 3000 CONFINED TO ROOM OF ORIGIN
IGNITING OBJECT : 5310 ELECTRICAL BYPASS (ILLEGAL OPERATIONS)
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED : 7300 PLASTICS - (EXCLUDES CELLULOSE NITRATE CLASSIFIED UNDER 720.
ACT OR OMISSION : 9950 ILLEGAL OPERATIONS/ACTIVITIES (E.G. GROW OPS, METH LABS)

Investigating Officer LAFC Badge #
BERUBE, MARC 632

Telephone ReportDate
604-543-6700 2012-09-04

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CSY 2012 08 24 15 02**


Remarks:

s.22

BYPASS IN GROUND BELOW METER. FIRE DAMAGED WALL.

Investigating Officer
BERUBE, MARC

LAFC Badge #
632

Telephone
604-543-6700 

ReportDate
2012-09-04

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CSY 2012 08 24 15 02**

Name no. : 1
Name : U/K, U/K
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.22**

Content Loss : \$0

Total Loss : \$ **s.22**

REMARKS:

Investigating Officer : LAFC Badge #
BERUBE, MARC : 632

Telephone : ReportDate
604-543-6700  2012-09-04

