PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CSY 2010 03 28 16 01

Location of Incident: 68 - 15355 26 AVENUE

**SURREY BC** 

# of Occupants (At time of fire): 3 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: S22

Related to Wildland Interface Fire: NO Property Value: S22 Content Value: S22 Total Value at Risk: S22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA: 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION: 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9500 ALARM NOT ACTIVATED - UNKNOWN

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 0000 CANNOT BE DETERMINED

METHOD OF FIRE CONTROL: 0000 CANNOT BE DETERMINED

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 1400 LOUNGE, LIVING ROOM - INCLUDES MUSIC ROOM, COMMON ROOM, TV R

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 0000 CANNOT BE DETERMINED

FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer LAFC Badge # Telephone ReportDate
MAHIL, PAUL 1289 604-543-6764 2010-05-12

Page1 PSS-2012-00156 PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CSY 2010 03 28 16 01

Remarks:

Investigating Officer MAHIL, PAUL

LAFC Badge # 1289

Telephone 604-543-6764 ReportDate 2010-05-12

## PROVINCE OF BRITISH COLUMBIA Ministry of Public Safety and Solicitor General Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

INCIDENT NUMBER: CSY 2010 03 28 16 01

S22

Name no. : 1

Name : S22

Address :

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: S22 Content Loss: S22 Total Loss: S22

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate MAHIL, PAUL 1289 604-543-6764 2010-05-12