

Location of Incident: **10191 MORTFIELD RD
RICHMOND BC**

of Occupants (At time of fire): **2** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)
YEAR OF CONSTRUCTION : 0061 1961 TO 1965
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 7000 FIRE DEPARTMENT ONLY
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION : 2000 SMOKE DETECTOR DEVICE
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA : 2100 SLEEPING - UNDER 5 OCCUPANTS - INCLUDES PATIENTS' ROOM, BEDR
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED : 3600 FABRIC - SYNTHETIC FIBRE - INCLUDES FINISHED GOODS. (EXCLUDE
ACT OR OMISSION : 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	LAFC Badge #	Telephone	ReportDate
WELLSTED, DARRYL	1854	604-278-5131	2017-07-23

Remarks:

SIZE UP: -TWO STOREY HOUSE. FIRE ON THE GROUND FLOOR NORTH/WEST CORNER OF THE HOUSE. CAUSE: -
OVERHEATING OF A TELUS TV BOX. CIRCUMSTANCE: -NO VENTILATION TO THE BOX AS IT WAS SITTING ON CARPET.
CONCLUSION: -ACCIDENTAL.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WELLSTED, DARRYL	1854	604-278-5131	2017-07-23

Name no. : 1
Name : s.22
Address :

Name Status : OCCUPANT
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Name no. : 2
Name : s.22
Address :

Name Status : OCCUPANT
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Investigating Officer : LAFC Badge #
WELLSTED, DARRYL : 1854

Telephone :
604-278-5131
ReportDate :
2017-07-23

Name no. : 3
Name : s.22
Address :

Name Status : OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

Investigating Officer LAFC Badge #
WELLSTED, DARRYL 1854

Telephone ReportDate
604-278-5131 2017-07-23