

Location of Incident: **36461 ENG ROAD  
NORTH FRASER BC**

# of Occupants (At time of fire): **1**      # of Injured: **0**      # of Deaths: **0**      Total Dollar Loss Estimate: **\$4,000**

Related to Wildland Interface Fire: **NO**      Property Value: **\$50,000**      Content Value: **\$4,000**      Total Value at Risk: **\$54,000**

**Code Name :      Code Description**

PROPERTY COMPLEX : 3800 RESIDENTIAL - MOBILE HOME/TRAILER PARK  
PROPERTY CLASSIFICATION : 3185 MANUFACTURED ("MOBILE HOME")  
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST  
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE  
GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)  
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED  
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY  
OUTSIDE FIRE PROTECTION : 7000 FIRE DEPARTMENT ONLY  
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION  
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM  
SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED  
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S  
TRANSMISSION OF ALARM : 1000 911  
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY  
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED  
ACTION TAKEN : 1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W  
METHOD OF FIRE CONTROL : 1800 MULTI-PURPOSE DRY CHEMICAL  
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)  
FIRE ORIGIN, AREA : 6200 HEATING EQUIPMENT ROOM - INCLUDES FURNACE ROOM, WATER HEATER  
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN  
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN  
IGNITING OBJECT : 0000 CANNOT BE DETERMINED  
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED  
FORM OF HEAT : 0000 CANNOT BE DETERMINED  
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED  
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	LAFC Badge #	Telephone	ReportDate
HOWELL, STEVE	3028	604-615-6766	2021-02-05

**Remarks:**

THE FIRE STARTED IN THE FURNACE AREA CANNOT DETERMINE CAUSE OF THE FIRE , WE WERE TOLD THE FURNACE WAS NEW .

---

Investigating Officer	L AFC Badge #	Telephone	ReportDate
HOWELL, STEVE	3028	604-615-6766	2021-02-05

Name no. : 1  
Name s.22  
Address

Name Status : OWNER  
Phone s.22

Claims Adjuster Name :  
Claims Adjuster Firm :  
Claim Number :  
Insurance Company :  
Policy Number :

LOSS ESTIMATES:

Property Loss : \$1,000

Content Loss : \$3,000

Total Loss : \$4,000

REMARKS:

FURNACE WAS ON FIRE

Investigating Officer LAFC Badge #  
HOWELL, STEVE 3028

Telephone ReportDate  
604-615-6766 2021-02-05