PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Location of Incident:

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DSQ 2022 02 21 16 01

40340 TANTALUS ROAD SOUAMISH BC VON 1T0

of Occupants (At time of fire): 10 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$2,259,200

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

Code Name: Code Description

PROPERTY COMPLEX: 3900 RESIDENTIAL - WITH BUSINESS/MERCANTILE, UP TO 3 STORIES

PROPERTY CLASSIFICATION: 3220 APARTMENT, TOWNHOUSE - 3 TO 4 UNITS WITHOUT BUSINESS

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 3000 501 TO 1000M2 (5383 - 10764FT2)

YEAR OF CONSTRUCTION: 1974 1974

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 6000 ALARM NOT ACTIVATED - UNSUITABLE LOCATION

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4800 PORTABLE/FIXED WATER DELUGE/MASTER STREAM SET

FIRE ORIGIN, LEVEL: 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA: 7200 EXTERIOR BALCONY - INCLUDES OPEN PORCH, DECK

EXTENT OF FIRE: 4000 CONFINED TO FLOOR LEVEL OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 7170 SMOKER'S MATERIAL - CANNOT BE DETERMINED

FUEL OR ENERGY: 5000 SMOKER'S MATERIAL - INCLUDES CIGARETTE, CIGAR, PIPE, MATCH O

FORM OF HEAT: 8000 HEAT FROM SMOKER'S MATERIAL - (EXCLUDES MATCH, LIGHTER, CLAS

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 2100 SMOKERS' MATERIAL (INCLUDES CARELESSLY DISCARDED SMOKING MAT

Investigating Officer LAFC Badge # Telephone ReportDate
DERKSEN, KYLE 1761 604-898-9666 2022-04-01

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DSQ 2022 02 21 16 01

Remarks:

THE FIRE DEPARTMENT WAS DISPATCHED AT 16:23:39 ON FEBRUARY 21, 2022 TO 40430 TANTALUS ROAD FOR A REPORT OF A STRUCTURE FIRE. AN ADDITIONAL 911 CALLER CONFIRMED THAT ?FLAMES WERE SEEN? AT 16:24:12. INCIDENT COMMAND WAS ESTABLISHED AT 16:27:56. AT THIS TIME THE INCIDENT PRIORITIES WERE TO PROVIDE RESCUE OF OCCUPANT VIA GROUND LADDERS AND APPLY WATER COOLING FROM THE APPARATUS MOUNTED DECK GUN. WIND SPEEDS AND GUSTING HAD A LARGE EFFECT ON THIS FIRE AND WERE REPORTED UPWARDS OF 80KM/HOUR AT TIMES. FIRE SUPPRESSION ACTIVITIES INSUED AND ?FIRE STRUCK/OVERHAULED? WAS CALLED AT 21:55:24. THE ADDITIONAL AGENCIES THAT ATTENDED THE SCENE WERE RCMP, BCAS, UTILITIES (HYDRO/GAS), EMERGENCY SOCIAL SERVICES, ETC. A FIRE GUARD/WATCH WAS ESTABLISHED FROM THE TIME SUPPRESSION ACTIVITIES ENDED UNTIL THE INSURANCE INVESTIGATION HAD BEEN COMPLETED. THE SPECIFIC POINT OF ORIGIN CANNOT BE DETERMINED DUE TO THE AMOUNT OF DAMAGE BUT DESCRIPTIONS, PICTURES, VIDEOS, AND INTERVIEW STATEMENTS ALL SEEM TO INDICATE THAT THE EARLY STAGES OF THE FIRE WERE SEEN ON THE SECOND FLOOR APARTMENT CLOSEST TO THE ALPHA SIDE OF THE BUILDING. THIS SUBSTANTIATED BY HAVING THE LARGEST AMOUNT OF DAMAGE IN THIS AREA. \$.22 \$.22 \$.22

Investigating Officer LAFC Badge # Telephone ReportDate DERKSEN, KYLE 1761 604-898-9666 2022-04-01

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

s.22

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: **DSQ 2022 02 21 16 01**

: BUSINESS OWNER

Name no. : 1

Name :s.22

Address :s.22 - 40340 TANTALUS ROAD

SQUAMISH BRITISH COLUMBIA V8B0A9

Claims Adjuster Name s.22

Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: \$0 Content Loss: \$200,000 Total Loss: \$200,000

REMARKS:

Name no. : 2 Name Status : BUSINESS OWNER

Name s.22 Phone s.22

Address s.22 - 40340 TANTALUS ROAD

SQUAMISH BRITISH COLUMBIA V8B0M1

Claims Adjuster Name \$.22

Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Property Loss: \$0 Content Loss: \$111,000 Total Loss: \$111,000

REMARKS:

Investigating OfficerLAFC Badge #TelephoneReportDateDERKSEN, KYLE1761604-898-96662022-04-01

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE (NAMES)

INCIDENT NUMBER: DSQ 2022 02 21 16 01

Name no. : 3 Name Status : OWNER

Name :s.22 Phone :

Address : 40340 TANTALUS ROAD

SQUAMISH BRITISH COLUMBIA

Claims Adjuster Name : s.22

Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: \$1,938,000 Content Loss: \$10,200 Total Loss: \$1,948,200

REMARKS:

THE TANTALUS MALL IS A RESIDENTIAL OVER COMMERCIAL BUILDING THAT HOUSED SEVERAL APARTMENTS ON THE SECOND AND GROUND FLOORS AND FOUR COMMERCIAL UNITS ALSO ON THE GROUND FLOOR. THE BUILDING DID NOT HAVE A SPRINKLER OR FIRE ALARM SYSTEM DUE TO THE AGE OF CONSTRUCTION.

Investigating Officer LAFC Badge # Telephone ReportDate
DERKSEN, KYLE 1761 604-898-9666 2022-04-01