Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CLA 2014 06 26 12 01

Location of Incident: 108 - 20551 LANGLEY BYPASS LANGLEY CITY BC V3A 5DE

of Injured: 0 # of Deaths: 0 # of Occupants (At time of fire): 3 Total Dollar Loss Estimate: s 21

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

> Code Name: **Code Description**

PROPERTY COMPLEX: 0000 CANNOT BE DETERMINED

PROPERTY CLASSIFICATION: 7330 LOOSE OR BAGGED PROCESSED FOODS STORAGE - INCLUDES PROCESSED

GENERAL CONSTRUCTION: 4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 3000 501 TO 1000M2 (5383 - 10764FT2)

YEAR OF CONSTRUCTION: 1988 1988

MANUAL FIRE PROTECTION: 4000 EXTINGUISHER ONLY

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 4100 PRODUCT STORAGE AREA - INCLUDES ALL AREAS WHERE PRODUCTS ARE

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 5110 PERMANENT ELECTRIC WIRING, CABLE (ALUMINUM)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

ACT OR OMISSION: 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge # GUNN, ROB

2705

Telephone

ReportDate

604-514-2880

2014-07-24

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CLA 2014 06 26 12 01

Remarks:

LARGE ELECTRICAL JUNCTION BOX CONTAINING 3 PHASE WIRING FROM O/S POWER POLE FAILED AFTER YEARS OF INSTALLATION. FAULTY INSTALLATION AND YEARS OF BUILDING MOVEMENT CAUSED ARC FOLLOWED BY FIRE.

Investigating Officer GUNN, ROB LAFC Badge #

2705

Telephone 604-514-2880 ReportDate 2014-07-24

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: CLA 2014 06 26 12 01

: BUSINESS OWNER

Name no. : 1

Name : EALEY, CARL

Address : 108 - 20551 LANGLEY BYPASS

LANGLEY BRITISH COLUMBIA V3A 5E8

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number : :

LOSS ESTIMATES:

Property Loss S 21 Content Loss: S.21 Total Loss: S 21

REMARKS:

LARGE ELECTRICAL JUNCTION BOX CONTAINING 3 PHASE WIRING FROM O/S POWER POLE FAILED AFTER YEARS OF INSTALLATION. FAULTY INSTALLATION AND YEARS OF BUIDING MOVEMENT CAUSED ARC FOLLOWED BY FIRE.

Investigating Officer LAFC Badge # Telephone ReportDate GUNN, ROB 2705 604-514-2880 2014-07-24

GUNN, ROB 2705 604-514-2880 2014-07-24

Incident Report Page 4 of 4