

ENTERED

Emergency
Management BCDangerous Goods
Incident Report

DGIR 142382 - INLAND

Category : Code 1

Incident Date Time : 2014-10-31 11:21

MCTS # :

Spiller : COAST MOUNTAIN BUS CO
 Location : UBC DIESEL BUS LOOP
 Area : VANCOUVER EMBC Region : SWE MOE Region : Lower Mainland Region
 Material(s): ENGINE COOLANT
 Amount(s): UNKNOWN AMOUNT

Received

From:

Caller A : HARINDER HUNDAL

Org : COAST MOUNTAIN BUS CO

Phone : Business 778-593-5525

Alternate :

Time :

Caller B :

Org :

Phone :

Alternate :

Time :

Received by EMBC Operations Officer : MIKE

When Received : 2014-10-31 12:18

Affected Environment : Ground

Other :

Type of Spilling :

Other Spill Type :

Equipment Failure

Accidents:

Sector: Commercial

Cause :

A broken clamp caused an unknown amount of coolant to spill to the roadway and then into a drain in their facility at the loop. BCIR number 2014517799. No idea if any water ways affected.

Response :

Tervita has been called to clean up the spill.

Jurisdiction : Federal, Provincial, Municipal

Task # : Amount : \$ Issued To :

Notification :

1224 paged LML

1234 paged LML

1241 briefed MOE RO Harold Riedler code 1 Fed/Prov/Mun

1242 faxed MOE Surrey

Haz: 13	Sec: TRAP.
Cause: EQUIP FAIL	
Env: Inland Wat	EA: NONE
PR: FA CONT.	
SR:	
Lat: 49.268573	
Long: -123.247925	

Risk Calculation	
[PT 1 + ES 3 + IS 2]	
(10) (1) (7)	
- [RT 3 + RC 3] = 0	
(1) (5)	
Attended _____	Responded _____
Received <input checked="" type="checkbox"/>	Sign: H. Riedler
LOW RISK	