

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**

INCIDENT NUMBER: **TLA 2015 10 24 18 02**

Location of Incident: **728 ESPLANADE
LADYSMITH BC**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **s.21**

Related to Wildland Interface Fire: **NO** Property Value: **s.21** Content Value: **s.21** Total Value at Risk: **s.21**

Code Name : Code Description

PROPERTY COMPLEX : 5500 SERVICE STATION WITH STORAGE IN BACK LOT - INCLUDES FUEL DIS
 PROPERTY CLASSIFICATION : 9440 GAS DISTRIBUTION SYSTEM, PIPELINE - INCLUDES TRANSMISSION LI
 GENERAL CONSTRUCTION : 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
 BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
 GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)
 YEAR OF CONSTRUCTION : 1980 1980
 MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
 OUTSIDE FIRE PROTECTION : 7000 FIRE DEPARTMENT ONLY
 SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
 AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
 SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED
 INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
 TRANSMISSION OF ALARM : 1000 911
 FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
 INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
 ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
 METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
 FIRE ORIGIN, LEVEL : 9000 EXPOSURE FIRE
 FIRE ORIGIN, AREA : 8300 VEHICLE - FUEL AREA - INCLUDES FUEL LINE
 EXTENT OF FIRE : 6000 EXTENDED BEYOND PROPERTY OF ORIGIN
 EXTENT OF DAMAGE : 6000 EXTENDED BEYOND BUILDING OF ORIGIN
 IGNITING OBJECT : 0000 CANNOT BE DETERMINED
 FUEL OR ENERGY : 3000 GASOLINE
 FORM OF HEAT : 4000 DIRECT FLAME
 MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
 ACT OR OMISSION : 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer LAFC Badge #
 DELCOURT, RAYMOND 1247

Telephone ReportDate
 250-245-6436 2015-10-26

Remarks:

VEHICLE FIRE AT GAS PUMPS WHICH WAS A 1981 VOLKSWAGON WESTFALIA. FIRE EXTENDED FROM VEHICLE TO GAS PUMPS AND UP INTO STATION CANOPY OVER PUMPS. EXPOSURE FIRE.

Investigating Officer LAFC Badge #
DELCOURT, RAYMOND 1247

Telephone ReportDate
250-245-6436 2015-10-26

Name no.	: 1	Name Status	: BUSINESS OCCUPANT
Name	: s.22	Phone	: s.22
Address	: 728 ESPLANADE		
	LADYSMITH BRITISH COLUMBIA		

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : \$0

Total Loss : s.21

REMARKS:

DAMAGE TO PUMPS AND OVERHEAD CANOPY

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250-245-6436	2015-10-26

PROVINCE OF BRITISH COLUMBIA
 Ministry of Justice
 Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE**

INCIDENT NUMBER: **TLA 2015 10 24 18 01**

Location of Incident: **728 ESPLANADE
LADYSMITH BC**

of Occupants (At time of fire): **2** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **s.21**

Related to Wildland Interface Fire: **NO** Property Value: **s.21** Content Value: **\$0** Total Value at Risk: **s.21**

Code Name : Code Description

PROPERTY CLASSIFICATION : 8610 AUTOMOBILE - INCLUDES CARS, LIGHT TRUCKS AND VANS, SINGLE BO

MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, AREA : 8200 VEHICLE - ENGINE AREA - INCLUDES RUNNING GEAR, WHEELS

EXTENT OF FIRE : 6000 EXTENDED BEYOND PROPERTY OF ORIGIN

IGNITING OBJECT : 0000 CANNOT BE DETERMINED

FUEL OR ENERGY : 3000 GASOLINE

FORM OF HEAT : 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED : 5100 GASOLINE

ACT OR OMISSION : 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250-245-6436	2015-10-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE**
(PRODUCT/EQUIPMENT)
INCIDENT NUMBER: **TLA 2015 10 24 18 01**

LOG #
ITEM TYPE
ITEM DESCRIPTION
MAKE
MODEL
YEAR
LICENSE NO.
SERIAL NO.
MAKE

: 172664
: AUTOMOBILE
:
: VOLKSWAGON
: WESTFALIA
: 1981
: s.22
:
: VOLKSWAGON

CERT. AGENCY1
CERT. AGENCY2
CERT. AGENCY3
CERT. AGENCY4
CERT. AGENCY5

:
:
:
:
:

COMMENTS :

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250-245-6436	2015-10-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE** (NARRATIVE)
INCIDENT NUMBER: **TLA 2015 10 24 18 01**

Remarks:

VEHICLE CAUGHT FIRE AFTER REFUELING AT SERVICE NEXT TO GAS PUMPS. VEHICLE OWNER HAD JUST REFUELED VEHICLE AND WAS RESTARTING VEHICLE WHEN ENGINE BACKFIRED AND FIRE STARTED NEAR REAR OF VEHICLE. VEHICLE WAS TOTALLY DISTROYED BY FIRE. POSSIBLE BROKEN FUEL LINE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250-245-6436	2015-10-26

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **VEHICLE** (NAMES)

INCIDENT NUMBER: **TLA 2015 10 24 18 01**

Name no. : 1
Name : s.22
Address :

Name Status : OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company : 1. ICBC
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : \$0

Total Loss : s.21

REMARKS:

VEHICLE TOATALY DISTROYED BY FIRE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
DELCOURT, RAYMOND	1247	250-245-6436	2015-10-26

