Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: TSM 2016 09 13 09 01

Location of Incident: 4187 7TH AVE

SMITHERS BC V02N0

of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: s.22

Related to Wildland Interface Fire: NO Property Value: s.22 Content Value: s.22 Total Value at Risk: s.22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION: 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 8000 ROOF LEVEL - INCLUDES CONCEALED ROOF SPACE, ATTIC

FIRE ORIGIN, AREA: 7400 CEILING & ROOF/CEILING SPACE (ATTIC)

EXTENT OF FIRE: 7000 CONFINED TO ROOF/ATTIC SPACE

EXTENT OF DAMAGE: 7000 CONFINED TO ROOF/ATTIC SPACE

IGNITING OBJECT : 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 0000 CANNOT BE DETERMINED

FORM OF HEAT: 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED: 0000 CANNOT BE DETERMINED

Investigating Officer

STECKO, KEITH

LAFC Badge #

1620

Telephone

ReportDate

250-847-2015

2016-09-20

1 of 4

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: TSM 2016 09 13 09 01

Remarks:

FIRE DEPARTMENT ARRIVED AT APPROXIMATELY 09:30HRS. UPON ARRIVAL THE FIRE HAD SELF VENTED THROUGH THE ROOF NEXT TO THE CHIMNEY STACK. THE FIRE DEPARTMENT WAS ABLE TO CONTROL THE FIRE TO THE ROOF SECTION USING TWO 1/34' LINES, AN UNMANNED MONITOR AND LADDER TRUCK. THE AREA OF ORIGIN WAS IN THE ROOF SPACE, ABOVE THE ATTIC. THE POINT OF ORIGIN, SOURCE OF IGNITION, AND MATERIAL FIRST IGNITED WERE UNABLE TO BE DETERMINED.

Investigating Officer STECKO, KEITH LAFC Badge # 1620

Telephone 250-847-2015 ReportDate 2016-09-20

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: TSM 2016 09 13 09 01

: OWNER

Name no. :1

Name : s.22

Address : 4187 7THAVE

SMITHERS BRITISH COLUMBIA V0J2N0

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: s.22 Content Loss: s.22 Total Loss: s.22

REMARKS:

Investigating OfficerLAFC Badge #TelephoneReportDateSTECKO, KEITH1620250-847-20152016-09-20

3 of 4

Incident Report Page 4 of 4