Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: NGN 2017 07 31 02 01

Location of Incident: 1723 JENSEN ROAD
GIBSONS BC V0N1V6

# of Occupants (At time of fire): 7 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: c 22

Related to Wildland Interface Fire: NO Property Value: \$.22 Content Value: \$.22 Total Value at Risk: \$.22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 1000 1 TO 100M2 (1 - 1076FT2)

YEAR OF CONSTRUCTION: 1992 1992

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 9200 COURT, PATIO, TERRACE

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 7110 SMOKER'S MATERIAL - CIGARETTE

FUEL OR ENERGY: 5000 SMOKER'S MATERIAL - INCLUDES CIGARETTE, CIGAR, PIPE, MATCH O

FORM OF HEAT: 8000 HEAT FROM SMOKER'S MATERIAL - (EXCLUDES MATCH, LIGHTER, CLAS

MATERIAL FIRST IGNITED: 8900 AGRICULTURAL, FORESTRY PRODUCTS - UNCLASSIFIED (DESCRIBE)

ACT OR OMISSION: 2100 SMOKERS' MATERIAL (INCLUDES CARELESSLY DISCARDED SMOKING MAT

Investigating Officer LAFC Badge # Telephone ReportDate

BOGHEAN, DALE 586 604-885-6870 2017-08-02

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: NGN 2017 07 31 02 01

## Remarks:

IGNITED, SPENT, SMOKING MATERIAL WAS BUTTED OUT IN AN OUTDOOR PLASTIC PLANT POT NEAR THE REAR SLIDING DOOR OF THE HOUSE LEADING TO A CONCRETE DECK. A BURN PATTERN ALONG THE EXTERIOR WALL WAS CONSISTENT WITH A FIRE STARTING IN THIS PLANT POT

Investigating Officer BOGHEAN, DALE LAFC Badge #

586

Telephone 604-885-6870 ReportDate 2017-08-02

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: NGN 2017 07 31 02 01

: OWNER

: 1 Name no.

Name Phone s.22 s.22

Address

Claims Adjuster Name : 1. BJORNSON, SEAN

Claims Adjuster Firm : 1. BJORNSON & CO. CLAIMS ADJUSTORS LTD.

Claim Number : 1. 912556

Insurance Company : 1. WAWANESA INSURANCE COMPANY

Policy Number : 1. HPC1910674

LOSS ESTIMATES:

Content Loss: s.22Total Loss: S.22 Property Loss: \$.22

REMARKS:

LANDLADY OF PROPERTY RENTED TO FIVE \$.22 . INSURED WITH TALBOT INSURANCE SERVICES LTD. TENANTS WERE THERE FOR OVER A YEAR.

Name no. Name Status : OCCUPANT : 2

Name c 22 Phone

: 1723 JENSEN ROAD Address

LANGDALE BRITISH COLUMBIA V0N1V6

Claims Adjuster Name : 1. GOJEVIC, MIKE

Claims Adjuster Firm : 1. PENINSULA ADJUSTORS (2007) LTD.

Claim Number : 1. 233216-1

: 1. SQUAREONE INSURANCE SERVICES INC. Insurance Company

Policy Number : 1. 233216

LOSS ESTIMATES:

Total Loss : \$.22 Content Loss: \$.22 Property Loss: s.2

REMARKS:

'VISITORS AT THE TIME OF THE FIRE. RECREATIONAL USE OF THE REAR PATIO AREA AROUND 2100 HRS THE NIGHT BEFORE INCLUDING THE SMOKING OF A CIGARETTE. 27 REPORTED ODOUR OF SMOKE NEAR 2300 HRS BUT TOOK NO ACTION TO DISCOVER SOURCE. SMOKE SMELL INSIDE THE BUILDING NEAR MIDNIGHT -0100 HRS WITH NO DISCOVERY OF FIRE INVOLVEMENT BY 6 22 WHO CHECK GARAGE AND LAUNDRY AREA BEFORE TURNING IN FOR THE NIGHT. VISUAL SIGHTING OF ORANGE FLICKERING LIGHT AT THE BATHROOM WINDOW ALERTED 272 TO INVESTIGATE. WHEN WINDOW OPENED SMOKE CAME INTO HOUSE -ACTIVATING THE SMOKE ALARMS AND ALL PERSONS IN THE HOUSE WOKE AND EVACUATED 272 ATTEMPTED FIRE CONTROL OF SIDING ON FIRE AT THE REAR PATIO AREA WITH A GARDEN HOSE UNTIL FIRE DEPARTMENT ARRIVAL. FIRE ENTERED INTO THE ATTIC SPACE AND TOTALLY CONSUMED THE ROOF OF THE STRUCTURE.

Investigating Officer LAFC Badge # Telephone ReportDate BOGHEAN, DALE 586 604-885-6870 2017-08-02 Incident Report Page 4 of 4