

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**INCIDENT NUMBER: **CSY 2014 12 02 05 03**

Location of Incident: **8976 146 ST
SURREY BC**

of Occupants (At time of fire): **6** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$22**

Related to Wildland Interface Fire: **NO** Property Value: **\$22** Content Value: **\$22** Total Value at Risk: **\$22**

Code Name : Code Description

PROPERTY COMPLEX : 3400 RESIDENTIAL - SINGLE DETACHED
PROPERTY CLASSIFICATION : 3110 YEAR-ROUND USE DWELLING - 1-FAMILY
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA : 3000 501 TO 1000M2 (5383 - 10764FT2)
YEAR OF CONSTRUCTION : 2007 2007
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 6000 ALARM NOT ACTIVATED - UNSUITABLE LOCATION
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7500 WALL ASSEMBLY - INCLUDES CONCEALED WALL SPACE
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED : 9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION : 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFB Badge #	Telephone	ReportDate
BERG, FRED	2061	604-543-6700	2014-12-04

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **CSY 2014 12 02 05 03**

Remarks:

FIRE IN WALL AREA, CLOSE TO METER APPEARS A WIRING FAILURE WAS THE CAUSE DAMAGE FROM GROUND LEVEL, TO ROOF

Investigating Officer	L AFC Badge #	Telephone	ReportDate
BERG, FRED	2061	604-543-6700	2014-12-04

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **CSY 2014 12 02 05 03**

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address : 0

Name Status : OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.22**

Content Loss : **s.22**

Total Loss : **s.22**

REMARKS:

Investigating Officer
BERG, FRED

LAFC Badge #
2061

Telephone
604-543-6700

ReportDate
2014-12-04

