Incident Report Page 1 of 5

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CRI 2017 07 11 03 05

10191 MORTFIELD RD Location of Incident: RICHMOND BC

# of Occupants (At time of fire): 2 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$0

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

> Code Name: **Code Description**

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 1000 1 TO 100M2 (1 - 1076FT2)

YEAR OF CONSTRUCTION: 0061 1961 TO 1965

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 7000 FIRE DEPARTMENT ONLY

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 0000 CANNOT BE DETERMINED

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 2000 SMOKE DETECTOR DEVICE

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE

FIRE ORIGIN, LEVEL: 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA: 2100 SLEEPING - UNDER 5 OCCUPANTS - INCLUDES PATIENTS' ROOM, BEDR

EXTENT OF FIRE: 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN

EXTENT OF DAMAGE: 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN

IGNITING OBJECT: 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE

MATERIAL FIRST IGNITED: 3600 FABRIC - SYNTHETIC FIBRE - INCLUDES FINISHED GOODS. (EXCLUDE

ACT OR OMISSION: 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer LAFC Badge # Telephone ReportDate

WELLSTED, DARRYL 604-278-5131 2017-07-23 1854

Incident Report Page 2 of 5

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CRI 2017 07 11 03 05

## Remarks:

SIZE UP: -TWO STOREY HOUSE. FIRE ON THE GROUND FLOOR NORTH/WEST CORNER OF THE HOUSE. CAUSE: -OVERHEATING OF A TELUS TV BOX. CIRCUMSTANCE: -NO VENTILATION TO THE BOX AS IT WAS SITTING ON CARPET. CONCLUSION: -ACCIDENTAL.

Investigating Officer
WELLSTED, DARRYL

LAFC Badge #

1854

Telephone 604-278-5131 ReportDate 2017-07-23

Page 3 of 5 Incident Report

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner INCIDENT NUMBER: CRI 2017 07 11 03 05

: 1 Name no.

Name : s.22

Address : 0 10191 MORTFIELD RD. Name Status : OCCUPANT Phone :s.22

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Content Loss: \$0 Total Loss: \$0 Property Loss: \$0

REMARKS:

Name no. : 2 : OCCUPANT Name Status

: s.22 Phone Name : s.22

Address : 0 10191 MORTFIELD RD

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Content Loss: \$0 Total Loss: \$0 Property Loss: \$0

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate

WELLSTED, DARRYL 1854 604-278-5131 2017-07-23 Incident Report Page 4 of 5

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner INCIDENT NUMBER: CRI 2017 07 11 03 05

Name no.: 3Name Status: OWNERName: \$.22Phone\$.22

Address :

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: \$0 Content Loss: \$0 Total Loss: \$0

REMARKS:

Investigating OfficerLAFC Badge #TelephoneReportDateWELLSTED, DARRYL1854604-278-51312017-07-23

Page 4 of 5

Incident Report Page 5 of 5