Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: CPA 2015 04 16 23 01

Location of Incident: 5019 MONTROSE ST PORT ALBERNI BC

# of Occupants (At time of fire): 12 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$0

Related to Wildland Interface Fire: NO Property Value: \$.22 Content Value: \$0 Total Value at Risk: \$.22

Code Name: Code Description

PROPERTY COMPLEX: 3100 RESIDENTIAL - ROW, GARDEN, TOWN HOUSING, CONDOMINIUM

PROPERTY CLASSIFICATION: 3240 APARTMENT, TOWNHOUSE - 5 TO 20 UNITS WITHOUT BUSINESS

GENERAL CONSTRUCTION: 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST

BUILDING HEIGHT: 0020 2 STORIES ABOVE GRADE

GROUND FLOOR AREA: 3000 501 TO 1000M2 (5383 - 10764FT2)

YEAR OF CONSTRUCTION: 0021 1921 TO 1945

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7

FIRE ORIGIN, LEVEL: 9000 EXPOSURE FIRE

FIRE ORIGIN, AREA: 9980 EXPOSURE - INCLUDING SMOKE DAMAGE

EXTENT OF FIRE: 6000 EXTENDED BEYOND PROPERTY OF ORIGIN

EXTENT OF DAMAGE: 6000 EXTENDED BEYOND BUILDING OF ORIGIN

IGNITING OBJECT: 5610 EXTENSION CORD

FUEL OR ENERGY: 6000 ELECTRICITY

 ${\tt FORM\ OF\ HEAT\ :\ 2000\ SPARK,\ ELECTRICAL\ -\ INCLUDES\ ARC,\ DISCHARGE.\ (EXCLUDES\ STATION CONTROL OF CONTROL OF$ 

MATERIAL FIRST IGNITED: 9500 INSULATION, ELECTRIC - CONFINED TO ELECTRICAL EQUIPMENT - IN

ACT OR OMISSION: 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer LAFC Badge # Telephone ReportDate

THOEN, RANDOLPH L. 1957 250-724-1351 2015-06-04

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CPA 2015 04 16 23 01

## Remarks:

PORT ALBERNI FIRE DEPARTMENT RESPONDED TO A REPORT OF A STRUCTURE FIRE OCCURRING AT 5019 MONTROSE STREET AT 23:18 HOURS ON APRIL 16, 2015. UPON ARRIVAL, FIRE CREWS FOUND HEAVY SMOKE AND FIRE SHOWIING THROUGH THE ROOF OF THE STRUCTURE ON THE REAR SIDE. FIRE WAS ACTIONED USING A COMBINATION OF MASTER STREAMS ON THE EXTERIOR AND THEN HANDLINES INTERIOR. FIRE WAS INVESTIGATED AND CAUSE FOUND TO BE AN ELECTRICAL FAILURE OF AN EXTENSION CORD BEING USED TO CHARGE A MOBILITY VEHICLE ON THE EXTERIOR OF THE BUILDING.

Investigating Officer
THOEN, RANDOLPH L.

LAFC Badge #

1957

Telephone 250-724-1351

ReportDate 2015-06-04

Page 3 of 4 Incident Report

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: CPA 2015 04 16 23 01

s.22

: OWNER

Name no. s.22 Name

s.22 Address

Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Content Loss: \$0 Total Loss: \$0 Property Loss: \$0

REMARKS:

Name Status : OCCUPANT Name no. : 2 Phone

s.22 Name

: 0 s.2 · 5019 MONTORSE STREET Address

PORT ALBERNI BRITISH COLUMBIA V9Y1M1

Claims Adjuster Name Claims Adjuster Firm : Claim Number Insurance Company Policy Number

LOSS ESTIMATES:

Content Loss: \$0 Total Loss: \$0 Property Loss: \$0

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate

THOEN, RANDOLPH L. 1957 250-724-1351 2015-06-04 Incident Report Page 4 of 4