Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: VGL 2016 09 07 08 01

Location of Incident: 585 SHAW ROAD GIBSONS BC

of Occupants (At time of fire): 1 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$.21

Related to Wildland Interface Fire: NO Property Value: \$0 Content Value: \$0 Total Value at Risk: \$0

Code Name: Code Description

PROPERTY COMPLEX: 2300 LICENSED CARE FACILITY (REGISTERED ASSISTED LIVING ARE CONSI

PROPERTY CLASSIFICATION: 2350 CARE FACILITY - 7 ORE MORE PERSONS IN CARE

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA: 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION: 2006 2006

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S

AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 1000 SMOKE ALARM DEVICE

TRANSMISSION OF ALARM: 3000 PRIVATE FIRE ALARM SYSTEM - INCLUDES SIGNAL/ALARM RECEIVED I

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 4000 EXTINGUISHED BY AUTOMATIC SYSTEM

METHOD OF FIRE CONTROL: 6100 WET PIPE SYSTEM - INCLUDES CENTRAL STATION SUPERVISED OR WAT

FIRE ORIGIN, LEVEL: 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA: 3100 KITCHEN, COOKING AREA

EXTENT OF FIRE: 3000 CONFINED TO ROOM OF ORIGIN

EXTENT OF DAMAGE: 4000 CONFINED TO FLOOR LEVEL OF ORIGIN

IGNITING OBJECT: 1040 STOVE, RANGE, TOP BURNER AREA - INVOLVING OTHER CIRCUMSTANCE

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE

Telephone

MATERIAL FIRST IGNITED: 7300 PLASTICS - (EXCLUDES CELLULOSE NITRATE CLASSIFIED UNDER 720.

ACT OR OMISSION: 7800 DISTRACTED, PREOCCUPIED

Investigating Officer LAFC Badge #

ROBINSON, CODY 2499 604-885-6870 2016-11-15

ReportDate

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: VGL 2016 09 07 08 01

Remarks:

GIBSONS AND DISTRICT VOLUNTEER FIRE DEPARTMENT RESPONDED TO AN AUTOMATIC ALARM. UPON ARRIVAL A SPRINKLER ACTIVATION WAS SHOWING ON THE ALARM PANEL IN UNIT 108. IT WAS FOUND THAT THE OCCUPANT HAD ACCIDENTALLY TURNED AN ELEMENT OF THE KITCHEN STOVE ON WITH A TOASTER SITTING ON THE ELEMENT. THE ELEMENT MELTED AND IGNITED THE PLASTIC CASING OF THE TOASTER WHICH THEN IGNITED SOME OF THE CABINETS ADJACENT TO THE STOVE. THE SMOKE ALARM WAS ACTIVATED NOTIFYING THE RESIDENT WHO WAS IN THE OTHER ROOM TO EVACUATE THE UNIT. THE FLAMES FROM THE FIRE THEN ACTIVATED ONE OF THE FIRE SPRINKLER HEADS IN THE UNIT WHICH EXTINGUISHED THE FIRE. THE BUILDING SUSTAINED A LARGE AMOUNT OF WATER DAMAGE FROM THE SPRINKLER ACTIVATION. SMOKE AND FIRE DAMAGE APPEARED TO BE LIMITED TO THE ROOM AND UNIT OF ORIGIN.

Investigating Officer ROBINSON, CODY LAFC Badge #

2499

Telephone 604-885-6870 ReportDate 2016-11-15

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA

FIRE REPORT - STRUCTURE (NAMES)

Name Status

Phone

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

INCIDENT NUMBER: VGL 2016 09 07 08 01

: BUSINESS OWNER

: 604-886-8747

Name no. : 1

Name : BROWN, LESLIE

Address : 585 SHAW ROAD

GIBSONS BRITISH COLUMBIA V0N1V8

Claims Adjuster Name : Claims Adjuster Firm : Claim Number : Insurance Company : Policy Number :

LOSS ESTIMATES:

Property Loss: \$.21 Content Loss: \$.21 Total Loss: \$.21

REMARKS:

Investigating Officer LAFC Badge # Telephone ReportDate ROBINSON, CODY 2499 604-885-6870 2016-11-15

Page 3 of 4 TRA-2016-65163 2016-12-23 Incident Report Page 4 of 4