Incident Report Page 1 of 4

PROVINCE OF BRITISH COLUMBIA

Ministry of Justice

Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: DWK 2016 06 24 11 03

Location of Incident: 3273 MCGINNIS ROAD WEST KELOWNA BC

of Occupants (At time of fire): 4 # of Injured: 0 # of Deaths: 0

Total Dollar Loss Estimate \$.22

Related to Wildland Interface Fire: NO

Property Value: s.22

Content Value: s.22

Total Value at Risk: \$.22

Code Name: **Code Description**

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3990 RESIDENTIAL MISCELLANEOUS - UNCLASSIFIED (DESCRIBE)

GENERAL CONSTRUCTION: 0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)

BUILDING HEIGHT: 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION: 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT: 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 1600 CARBON DIOXIDE

FIRE ORIGIN, LEVEL: 1000 BASEMENT, SUB-BASEMENT

FIRE ORIGIN, AREA: 3000 ELECTRONIC EQUIPMENT COMMUNICATION ROOM - INCLUDES RADAR, TE

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT: 0000 CANNOT BE DETERMINED

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 1700 INSULATION - PLASTIC - EXCLUDES ELECTRIC INSULATION

ACT OR OMISSION: 0000 CANNOT BE DETERMINED

Investigating Officer BREDIN, TREVOR

LAFC Badge #

Telephone

ReportDate

778-797-3200

2016-06-24

Incident Report Page 2 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: **DWK 2016 06 24 11 03**

Remarks:

DISPATCHED TO A FIRE AROUND AN ELECTRICAL PANEL. UPON ARRIVAL TENANT INDICATED THERE WAS FLAMES COMING FROM AROUND THE ELECTRICAL PANEL IN THE BASEMENT OF THE RESIDENCE. FIRE CREW MADE ENTRY AND EXTINGUISHED THE FIRE WITH A CO2 EXTINGUISHER. EXTENSIVE CHARRING WAS EVIDENT AROUND THE ELECTRICAL PANEL AND UPWARDS TOWARDS THE ELECTRICAL METER ON THE EXTERIOR OF THE RESIDENCE. OVERHAUL WAS DELAYED UNTIL HYDRO COULD DISCONNECT POWER TO THE RESIDENCE AT THE STREET. FIRE CREW OPENED CEILING IN THE BASEMENT, INTERIOR WALLS ON THE SECOND FLOOR, AND REMOVED SIDING AND STUCCO ON THE EXTERIOR, IN THE 'ALPHA' / 'DELTA' CORNER OF THE BUILDING AROUND THE ELECTRICAL METER AND DOWN TO THE BASEMENT ELECTRICAL PANEL. EXTENSIVE CHARRING WAS DISCOVERED AROUND ELECTRICAL WIRING, AND SURROUNDING WOOD FRAMING. ATTIC WAS CHECKED FOR EXTENSION, ALL OK. RESIDENCE WAS VENTILATED WITH PPV. FIRE WATCH WAS INITIATED FOR TWO HOURS UNTIL SCENE COULD BE TURNED OVER TO HOMEOWNERS INSURANCE COMPANY AND RESTORATION COMPANY. LIABILITY SIGNED. OWNER 5.22

INSURANCE COMPANY- CLAIMSPRO- BRETT MCAVENA 250-575-6606.

Investigating Officer LAFC Badge # Telephone ReportDate

BREDIN, TREVOR 778-797-3200 2016-06-24

Incident Report Page 3 of 4

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner		INCIDENT NUMBER: DWK 2016 06 24 11 03
Name no. Name Address	s.22 :	Name Status : OWNER Phone \$.22
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: 1. MCAVENA , BRETT : : : 1. CLAIMSPRO :	
LOSS ESTIMATES: Property Loss: \$.22 REMARKS:	Content Loss: \$0	Total Loss : S.22

Investigating OfficerLAFC Badge #TelephoneReportDateBREDIN, TREVOR778-797-32002016-06-24

Incident Report Page 4 of 4