From:
 TRAN SIR FOI Requests TRAN:EX

 To:
 TRAN SIR FOI Requests TRAN:EX

 Subject:
 Response: TRA-2021-11108

 Date:
 April 21, 2021 8:25:26 AM

Attachments: Culvert Location Report - Princeton Summerland Road.pdf

From: Keir, Chris TRAN:EX
Sent: April 20, 2021 1:51 PM
To: TRAN Sir Ok Admin TRAN:EX

Cc: Wiseman, Jeff TRAN:EX; Lachmuth, Erik TRAN:EX **Subject:** FW: Proposed Response: TRA-2021-11108

Leah,

I have pared down submission to the bare response based on request:

MoTI Response:

Formal request for the following details to a specific portion of the Princeton Summerland Road, which is 10km radius from Latitude 49-36-59-69N and Latitude 119-48-43-16W:

- Location of the nearest culvert (and other drainage provisions) prior to the failure on April 16, 2018 and subsequent repairs;
- Attached printout from CHRIS
 - the road standards that were in place around the time period for when the road was constructed, and the standards that would cover the time of repairs; details on the repairs and modifications to the roadway (changes in base material, etc.);
 - Princeton Summerland Road has been maintained as a public road, most likely an old wagon road at one time. No official dates in our records. Road has been upgraded many times and at different times, different road standards would have been in effect. Design Standards at time of repairs in response to the washout would be: BC Supplement to TAC 2007 (Design Standard) and Standard Specifications for Highway Construction 2016 (Construction Specifications). As repairs only involved a single site, Design Specifications would not apply.
 - engineering reports/inspection documentation by the province or their representatives during the road repairs;
 - Attached information submitted by Argo Road Maintenance (South Okanagan) Inc. No engineering reports/inspections were completed during the road repairs. Culvert installation and road repair was managed and supervised by Argo Road Maintenance (South Okanagan) Inc.
 - o and drainage modifications during repairs including information on additional culverts installed.
 - Two culverts installed by Argo Road Maintenance (South Okanagan) Inc. and road reconstructed. Two 600mm culverts were installed in the location of the washout.

(Date Range for Record Search: From **1/1/2008 To 3/11/2021**)

Argo Road Maintenance (South Okanagan) Inc. response (Bernie Corbach, Assistant General Manager, Argo Road Maintenance (South Peace) Inc. :

Location of the nearest culvert (and other drainage provisions) prior to the failure on April 16, 2018 and subsequent repairs;

Using the Ministry of Transportation & Infrastructure IMAP&RFI data the following are the drainage appliances located in the field on April 16, 2018 (Km stations are as per the RFI)

Existing culvert at 16.935 KM CULV X ROADWAY | GALVANIZED | 600 (315 metres to the west)

Incident 17.250 km

Existing culvert at 17.41 KM CULV X ROADWAY | GALVANIZED | 600 (160 metres to the east)

• the road standards that were in place around the time period for when the road was constructed, and the standards that would cover the time of repairs; details on the repairs and modifications to the roadway (changes in base material, etc.);

SCHEDULE "21" Maintenance Specifications 2003-2004 HIGHWAY MAINTENANCE CONTRACTS Maintenance Standards engineering

https://www2.gov.bc.ca/assets/gov/driving-and-transportation/transportation-infrastructure/highway-bridge-maintenance/highway-

maintenance/maintenance-

agreements/schedule_21_maintenance_specifications.pdf

- engineering reports/inspection documentation by the province or their representatives during the road repairs; No engineering reports/inspections were completed during the road repairs.
- and drainage modifications during repairs including information on additional culverts installed 2 - 600mm Diameter culverts were added at Km station 17.250km during the 2018 Summer season under the flood repairs.

chris

Inventory Item Location Report

Sorted by Highway Number

Page 1 of 5 2021-04-14 10:25 AM

Service Area: South Okanagan SA

AMA: 08-A - Pentiction

Sub Area: 08-A-@

RFI Highway: 08-A-@-00040 Princeton-Summerland Road

RFI Length: 23.582
RFI Direction: E

Inventory				Chain	age	Modification	
Item	Primary Key	XSP	Attributes	Start	End Length	Date	
HRP	2001212		Intersection 10960 TURNAROUND	0.000		2021-04-14	
CULV	2001349	х	Roadway 500 Galvanized No Unknown Unknown No No 	0.075	0.075	2021-04-14	
CULV	2001348	Х	Roadway 500 Galvanized No Unknown Unknown No No 	0.207	0.207	2021-04-14	
CULV	2001346	Х	Roadway 500 Galvanized No Unknown Unknown No No	0.285	0.285	2021-04-14	
CULV	2001345	Х	Roadway 500 Galvanized No Unknown Unknown No No	0.763	0.763	2021-04-14	
CULV	2001352	Х	Roadway 500 Galvanized No Unknown Unknown No No	1.577	1.577	2021-04-14	
CULV	2001351	Х	Roadway 500 Galvanized No Unknown Unknown No No	2.611	2.611	2021-04-14	
CULV	2001347	х	Roadway 500 Galvanized No Unknown Unknown No No	3.211	3.211	2021-04-14	
CULV	2001350	Х	Roadway 300 Galvanized No Unknown Unknown No No	3.966	3.966	2021-04-14	
HRP	2001211		Bridge Abutment 10979 W.END 2ND BRIDGE	4.711	4.711	2021-04-14	
HRP	2001210		Bridge Abutment 10980 W. END TROUT CRK BRG	6.821	6.821	2021-04-14	
CULV	3787534	Х	Roadway 600 Galvanized No	8.507	8.507	2021-04-14	
CULV	3787535	X	Roadway 600 Galvanized No	8.978	8.978	2021-04-14	

Inventory Item Location Report

Sorted by Highway Number

Page 2 of 5 2021-04-14 10:25 AM

Service Area: South Okanagan SA

AMA: 08-A - Pentiction

Sub Area: 08-A-@

RFI Highway: 08-A-@-00040 Princeton-Summerland Road

RFI Length: 23.582

RFI Direction: E

RFI Direction: E						
Inventory				Chainage		Modification
Item	Primary Key	XSP	<u>Attributes</u>	Start	End	Length
CULV	2001339	Х	Roadway 600 Galvanized No Unknown Unknown No No 	9.770	9.770	2021-04-14
CULV	3787536	х	Roadway 600 Galvanized No	9.952	9.952	2021-04-14
CULV	3787537	X	Roadway 500 Galvanized No	10.563	10.563	2021-04-14
CULV	2001340	Х	Roadway 500 Galvanized No Unknown Unknown No No 	11.077	11.077	2021-04-14
CULV	2001341	LRW	Roadway 500 Galvanized No No Unknown No No	11.371	11.371	2021-04-14
CULV	2001342	Х	Roadway 500 Galvanized No Unknown Unknown No No 	11.550	11.550	2021-04-14
CULV	3787539	Х	Roadway 600 Galvanized No	11.729	11.729	2021-04-14
CULV	2001338	Х	Roadway 600 Galvanized No Unknown Unknown No No	11.731	11.731	2021-04-14
CULV	2001328	Х	Roadway 600 Galvanized No Unknown Unknown No No 	11.733	11.733	2021-04-14
CULV	2001327	RRW	Flume 0 Galvanized No No Unknown No No	12.356	12.356	2021-04-14
CULV	2001329	х	Roadway 500 Galvanized No Unknown Unknown No No 	12.356	12.356	2021-04-14
CULV	2001326	х	Roadway 500 Galvanized No Unknown Unknown No No 	12.410	12.410	2021-04-14
CULV	3787542	RS	Down Drain 150 Plastic No	12.473	12.473	2021-04-14

Inventory Item Location Report

Sorted by Highway Number

Page 3 of 5 2021-04-14 10:25 AM

Service Area: South Okanagan SA

AMA: 08-A - Pentiction

Sub Area: 08-A-@

RFI Highway: 08-A-@-00040 Princeton-Summerland Road

RFI Length: 23.582
RFI Direction: E

Inventory Item	Primary Key	XSP	<u>Attributes</u>	<u>Chai</u> <u>Start</u>	nage End	Modification Length
CULV	2001330	Х	Roadway 600 Galvanized No Unknown Unknown No No OUTLET CULVERT EXTENTSION	12.483	12.483	2021-04-14
CULV	3787543	RS	Down Drain 150 Plastic No	12.498	12.498	2021-04-14
CULV	3787544	RS	Down Drain 150 Plastic No	12.514	12.514	2021-04-14
CULV	2001343	Х	Roadway 600 Galvanized No Unknown Unknown No No OUTLET EXTENTSION 600MM	13.094	13.094	2021-04-14
CULV	3787556	х	Roadway 600 Galvanized No	13.754	13.754	2021-04-14
CULV	2001325	х	Roadway 600 Galvanized No Unknown Unknown No No	14.098	14.098	2021-04-14
CULV	2001324	Х	Roadway 500 Galvanized No Unknown Unknown No No	14.900	14.900	2021-04-14
CULV	2001332	Х	Roadway 600 Galvanized No Unknown Unknown No No	15.167	15.167	2021-04-14
CULV	2001331	Х	Roadway 400 Galvanized No Unknown Unknown No No 	15.538	15.538	2021-04-14
CULV	2001333	Х	Roadway 500 Galvanized No Unknown Unknown No No 	15.777	15.777	2021-04-14
CULV	2001323	Х	Roadway 500 Galvanized No Unknown Unknown No No 	15.968	15.968	2021-04-14
CULV	2001334	Х	Roadway 600 Galvanized No Unknown Unknown No No	16.142	16.142	2021-04-14
CULV	2001335	Х	Roadway 600 Galvanized No Unknown Unknown No No	16.393	16.393	2021-04-14

Inventory Item Location Report

Sorted by Highway Number

Page 4 of 5 2021-04-14 10:25 AM

Service Area: South Okanagan SA

AMA: 08-A - Pentiction

Sub Area: 08-A-@

RFI Highway: 08-A-@-00040 Princeton-Summerland Road

RFI Length: 23.582
RFI Direction: E

Inventory					inage	Modification
Item	Primary Key	XSP	Attributes	Start	End	<u>Length</u>
			I			
CULV	2001336	Х	Roadway 600 Galvanized No Unknown Unknown No No	16.935	16.935	2021-04-14
CULV	2001320	Х	Roadway 600 Galvanized No Unknown Unknown No No	17.410	17.410	2021-04-14
CULV	2001319	х	Roadway 450 Galvanized No Unknown Unknown No No	17.411	17.411	2021-04-14
CULV	2001318	Х	Roadway 600 Galvanized No Unknown Unknown No No	17.790	17.790	2021-04-14
CULV	2001344	х	Roadway 600 Galvanized No Unknown Unknown No No	17.957	17.957	2021-04-14
CULV	2001322	Х	Roadway 300 Galvanized No Unknown Unknown No No	18.535	18.535	2021-04-14
CULV	2001321	LRW	Entrance 500 Galvanized No No Unknown No No	18.756	18.756	2021-04-14
HRP	2762649		Intersection 10985 MOUNTAIN VIEW ROAD	18.886	18.886	2021-04-14
CULV	2001337	Х	Other 0 Galvanized No Unknown Unknown No No BOTTOMLESS ARCH 2740MM X 1440MM	20.438	20.438	2021-04-14
HRP	2001213		Intersection 10990 FISH LK RD	20.450	20.450	2021-04-14
HRP	2013400		Intersection 16460 DEANS ROAD	22.539	22.539	2021-04-14
HRP	3782871		Jurisdictional Boundary 16465 SUMMERLAND MUNICIPAL BDRY	23.582	23.582	2021-04-14

Page 5 of 5 Inventory Item Location Report

Sorted by Highway Number

2021-04-14 10:25 AM

