
Location of Incident: **6253 HWY 97A
ENDERBY BC V0E1V0**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$20,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$1,000,000** Content Value: **\$1,000,000** Total Value at Risk: **\$2,000,000**

Code Name : **Code Description**

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN

GENERAL CONSTRUCTION : 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE

GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)

YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION : 6000 STANDPIPE SYSTEM ONLY

OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA : 7600 EXTERIOR WALL

EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT : 7800 HOT ASHES, EMBERS - NOT ASSOCIATED WITH SMOKER'S MATERIAL

FUEL OR ENERGY : 8000 EXPOSURE FIRE

FORM OF HEAT : 7000 SPONTANEOUS OR CHEMICAL CAUSATION

MATERIAL FIRST IGNITED : 4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD

ACT OR OMISSION : 2300 INADEQUATE CONTROL OF "OPEN" FIRE

Investigating Officer	LAFB Badge #	Telephone	ReportDate
CRICK, ALASTAIR	1952	250-550-3700	2007-01-10

Remarks:

SAWDUST PILE FIRE PREVIOUSLY "THOUGHT TO HAVE BEEN EXTINGUISHE', BURN DOWN INTO SAWDUST PILE AND CAUSED WOOD FRAME STRUCTURE TO CATCH FIRE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
CRICK, ALASTAIR	1952	250-550-3700	2007-01-10

Name no. : 1
Name : s.22
Address : 6253 HWY 97A ,
ENDERBY SKIDEGATE V0E1V0

Name Status : BUSINESS OWNER
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
CRICK, ALASTAIR

L AFC Badge #
1952

Telephone
250-550-3700

ReportDate
2007-01-10

Location of Incident: **RR#3 SITE #10
KAMLOOPS BC V2C5K1**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$30,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : **Code Description**

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN

GENERAL CONSTRUCTION : 3000 HEAVY TIMBER CONSTRUCTION

BUILDING HEIGHT : 0050 5 STORIES ABOVE GRADE

GROUND FLOOR AREA : 7000 10,001M2 AND OVER (10764IFT2 AND OVER)

YEAR OF CONSTRUCTION : 0046 1946 TO 1950

MANUAL FIRE PROTECTION : 2000 EXTINGUISHERS & STANDPIPE SYSTEM

OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION : 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S

AUTOMATIC FIRE ALARM SYSTE : 2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)

SMOKE ALARM OPERATION : 2000 ALARM ACTIVATED - INAUDIBLE

INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL : 8000 ROOF LEVEL - INCLUDES CONCEALED ROOF SPACE, ATTIC

FIRE ORIGIN, AREA : 7300 CEILING & FLOOR ASSEMBLY - INCLUDES CONCEALED FLOOR/CEILING

EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT : 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY : 6000 ELECTRICITY

FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED : 8000 BUILDING COMPONENT - FLOOR, CEILING, ROOF. (EXCLUDES FLOOR C

ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	LAFB Badge #	Telephone	ReportDate
FUNK, DANIEL	2271	250-571-2966	2010-01-20

Remarks:

FIRE STARTED AT A JUNCTION BOX NEAR THE CEILING ABOVE THE HYDROLIC PRESS. TOLKO ELECTRICIANS WERE DEALING WITH IT.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
FUNK, DANIEL	2271	250-571-2966	2010-01-20

Name no. : 1
Name : s.22
Address : RR3 SITE 10 6275 OLD HWY 5
KAMLOOPS BRITISH COLUMBIA V2C5K1

Name Status : OCCUPANT
Phone : s.22

Claims Adjuster Name : s.22
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21 Content Loss : s.21 Total Loss : s.21

REMARKS:

FIRE STARTED BETWEEN 23:30-24:00 HRS, IN A JUNCTION BOX UP ABOVE THE PRESS HYDROLIC UNIT.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
FUNK, DANIEL	2271	250-571-2966	2010-01-20

Location of Incident: **6275 OLD HIGHWAY 5
KAMLOOPS BC V2H1T8**

of Occupants (At time of fire): **5** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$500,000** Total Value at Risk: **\$500,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	7000 10,001M2 AND OVER (107641FT2 AND OVER)
YEAR OF CONSTRUCTION :	1971 1971
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	7000 FIRE DEPARTMENT ONLY
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4900 FIRE DEPARTMENT - WATER APPLICATION - UNCLASSIFIED (DESCRIBE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	3800 PROCESS, MANUFACTURING AREA
EXTENT OF FIRE :	3000 CONFINED TO ROOM OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	4990 APPLIANCES & EQUIPMENT - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	8200 DUSTS, GRAIN, FLOUR, STARCH
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFC Badge #	Telephone	ReportDate
TOMM/GUERTIN, COLIN/SHELDON	1368	250-571-2964	2011-02-03

Remarks:

SUSPECTED SHORT IN THE LATHE MOTOR THAT PRODUCED SPARKS INTO PILE OF SAWDUST AND WOOD CHIPS PRODUCED BY THE LATHE ABOVE THE MOTOR. FIRE DID NOT RESULT IN DAMAGE TO THE BUILDING OR CONTENTS TO ANY SUBSTANCIAL DEGREE. LOSSES ARE PROJECTED TO BE APPROXIMATELY \$500,000 IN PRODUCTION s.22
s.22

Investigating Officer	LAFC Badge #	Telephone	ReportDate
TOMM/GUERTIN, COLIN/SHELDON	1368	250-571-2964	2011-02-03

Name no. : 1
Name : s.22
Address :

Name Status : BUSINESS OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
TOMM/GUERTIN,
COLIN/SHELDON

L AFC Badge #
1368

Telephone
250-571-2964

ReportDate
2011-02-03

Location of Incident: **6275 OLD HIGHWAY 5
KAMLOOPS BC 2H1T8**

of Occupants (At time of fire): **40** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$3,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	5000 2501 TO 5000M2 (26911 - 53820FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7500 WALL ASSEMBLY - INCLUDES CONCEALED WALL SPACE
EXTENT OF FIRE :	3000 CONFINED TO ROOM OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	9200 INDUSTRIAL OVEN - INCLUDES KILN. (EXCLUDES OVEN USED FOR FOO
FUEL OR ENERGY :	4100 FUEL GAS - NATURAL GAS
FORM OF HEAT :	1000 SPARK, EMBER - INCLUDES FLYING BRAND OR SPARK SHOWER
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	6300 LACK OF MAINTENANCE

Investigating Officer	LAFB Badge #	Telephone	ReportDate
GUERTIN, SHELDON	1368	250-571-2965	2011-07-12

Remarks:

FIRE CREW ARRIVED TO FIND TOLKO EMPLOYEES ATTEMPTING TO EXTINGUISH A FIRE THAT WAS LOCATED IN A WALL IN THE AREA OF THE VENEER KILN. APPROXIMATELY A 200 SQUARE FOOT AREA OF EXTERIOR METAL CLADDING WAS REMOVED FROM THE WALL TO CHECK FOR EXTENSION. THE INTERIOR OF THE WALL IS NOT COVER WITH AND THING AND ARE BARE STUDS SUBJECT TO CREOSOTE BUILD UP FROM THE KILN. THE FIRE STARTED AS A RESULT OF A DAMAGE DOOR GASKET ON THE DRYING KILN. FIRES ARE NORMAL INSIDE THE KILN AND THE KILN IS EQUIPPED WITH A DELUGE SUPPRESSION SYSTEM IN THE DRY KILN. A SPARK PASSED THROUGH A DAMAGED GASKET ON DOOR #15. LANDING ON THE SILL PLATE OF THE ADJACENT WALL. THERE WAS A 2 X4 RUNNING PARALLEL TO THE SILL PLATE ALLOWING THE BUILD UP OF SAWDUST IN THAT AREA. THE SPARK THEN LANDED IN THE BUILD UP OF SAWDUST. THE FIRE WAS FIRST NOTICED BY AN EMPLOYEE WALKING BY THE OUTSIDE OF THE BUILDING. ATTEMPTS WERE MADE BY THE EMPLOYEES TO EXTINGUISH THE FIRE. AFTER APPROXIMATELY 45 TO 60 MINUTE THE FIRE DEPARTMENT WAS CALLED.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GUERTIN, SHELDON	1368	250-571-2965	2011-07-12

Name no. : 1
Name : s.22
Address : 6275 OLD HIGHWAY 5
KAMLOOPS BRITISH COLUMBIA V2H 1T8

Name Status : BUSINESS OCCUPANT
Phone : 250-578-7212

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

s.22

Investigating Officer
GUERTIN, SHELDON

L AFC Badge #
1368

Telephone
250-571-2965

ReportDate
2011-07-12

Remarks:

SPARKS FROM SIDTEGRINDER IGNITED SPRAY WAX.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ROWLAND, J.	1309	250-561-7667	2002-01-30

Name no. : 1
Name : LE PAS LUMBER COMPANY
Address :

Name Status : BUSINESS OCCUPANT
Phone :

Claims Adjuster Name : 1. NO CLAIM
Claims Adjuster Firm : 1. NO CLAIM
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

GRINDER IGNITED WAX BUILDUP IN SPRAY BOOTH.

Investigating Officer
ROWLAND, J.

L AFC Badge #
1309

Telephone
250-561-7667

ReportDate
2002-01-30

Location of Incident: **1385 RIVER ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **10** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$500**

Related to Wildland Interface Fire: **NO** Property Value: **\$19,400** Content Value: **\$0** Total Value at Risk: **\$19,400**

Code Name : **Code Description**

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN

GENERAL CONSTRUCTION : 5000 PROTECTED NON-COMBUSTIBLE CONSTRUCTION - PROTECTED STEEL OR

BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION : 1974 1974

MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED

OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION : 0009 SPRINKLER PROTECTION - UNCLASSIFIED (DESCRIBE)

AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED

SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION : 0000 CANNOT BE DETERMINED

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W

METHOD OF FIRE CONTROL : 5900 FIRE DEPARTMENT - OTHER THAN WATER - UNCLASSIFIED (DESCRIBE)

FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)

FIRE ORIGIN, AREA : 7600 EXTERIOR WALL

EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN

EXTENT OF DAMAGE : 1000 CONFINED TO OBJECT OF ORIGIN

IGNITING OBJECT : 9700 COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI

FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO

FORM OF HEAT : 1000 SPARK, EMBER - INCLUDES FLYING BRAND OR SPARK SHOWER

MATERIAL FIRST IGNITED : 4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD

ACT OR OMISSION : 4100 PART FAILURE, LEAK, BREAK

Investigating Officer	LAFB Badge #	Telephone	ReportDate
MOSTROM, R	1616	250-561-7667	2004-09-17

Remarks:

HOT BEARING THREW SPARKS INTO NEARBY SAWDUST AND IGNITED WOOD PILED UP AGAINST THE WALL.
EMPLOYEES PUT WATER ON THE FIRE TO EXTINGUISH.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MOSTROM, R	1616	250-561-7667	2004-09-17

Name no. : 1
Name : LAKELAND SAWMILLS
Address : 1385 RIVER ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OWNER
Phone : 250-564-6810

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer
MOSTROM, R

L AFC Badge #
1616

Telephone
250-561-7667

ReportDate
2004-09-17

Location of Incident: **1850 RIVER ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **20** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : **Code Description**

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN

GENERAL CONSTRUCTION : 5000 PROTECTED NON-COMBUSTIBLE CONSTRUCTION - PROTECTED STEEL OR

BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED

YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED

OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION : 0009 SPRINKLER PROTECTION - UNCLASSIFIED (DESCRIBE)

SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED

INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 1200 WATER PRESSURIZED

FIRE ORIGIN, LEVEL : 0000 CANNOT BE DETERMINED

FIRE ORIGIN, AREA : 4100 PRODUCT STORAGE AREA - INCLUDES ALL AREAS WHERE PRODUCTS ARE

EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN

EXTENT OF DAMAGE : 1000 CONFINED TO OBJECT OF ORIGIN

IGNITING OBJECT : 0000 CANNOT BE DETERMINED

FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO

FORM OF HEAT : 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED : 9160 HOG FUEL (GROUND WOOD WASTE)

ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	LAFB Badge #	Telephone	ReportDate
MOSTROM, R	1632	250-561-7667	2005-04-04

Remarks:

HOG FUEL CAUGHT ON FIRE OUTSIDE THE HOG FUEL BURNER. WINTON GLOBAL CREWS WERE ON THE SCENE ATTACKING THE FIRE WHEN FIRE CREWS ARRIVED.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MOSTROM, R	1632	250-561-7667	2005-04-04

Name no. : 1
Name : WINTON GLOBAL
Address : 1850 RIVER ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OCCUPANT
Phone : 250-562-2231

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer
MOSTROM, R

L AFC Badge #
1632

Telephone
250-561-7667

ReportDate
2005-04-04

Location of Incident: **6988 LANDOOZ ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **20** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$50,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$8,000,000** Content Value: **\$10,000,000** Total Value at Risk: **\$18,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION :	1986 1986
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W
METHOD OF FIRE CONTROL :	4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	3800 PROCESS, MANUFACTURING AREA
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	5400 PANEL BOARD, SWITCHBOARD - INCLUDES FUSE, CIRCUIT BREAKER
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	3000 SPARK, STATIC ELECTRICAL
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFB Badge #	Telephone	ReportDate
KRONEBUSH, DALE	1863	250-561-7667	2006-10-11

Remarks:

ELETRICAL SHORT ON BREAKERS CAUSED SPARKS THAT IGNITED FINE SAWDUST IN THE EDGER PART OF THE MILL.
DAMAGE WAS CONTATED TO ELECTRICAL CONTROLS AND CATWALK.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
KRONEBUSH, DALE	1863	250-561-7667	2006-10-11

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address : 5162 NORTHWOOD PULMILL ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OWNER
Phone : 250-962-3500

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

NO DAMAGE TO STRUCTURE. CONTENTS LOSS ONLY.

Name no. : 2
Name : UNKNOWN, UNKNOWN
Address : 6988 LANDOOZ ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OCCUPANT
Phone : 250-962-4701

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

DAMAGE TO ELECTRICAL CONTROLS & CATWALK IN EDGER PART OF MILL

Investigating Officer
KRONEBUSH, DALE

L AFC Badge #
1863

Telephone
250-561-7667

ReportDate
2006-10-11

Location of Incident: **1385 RIVER ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **20** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$30,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$145,000** Content Value: **\$100,000** Total Value at Risk: **\$245,000**

Code Name : Code Description

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION : 0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT : 0040 4 STORIES ABOVE GRADE
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 0009 SPRINKLER PROTECTION - UNCLASSIFIED (DESCRIBE)
AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA : 7500 WALL ASSEMBLY - INCLUDES CONCEALED WALL SPACE
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 7600 WELDING EQUIPMENT
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
LANE, JOHN	1309	250-561-7667	2006-11-14

Remarks:

ACCIDENTAL FIRE STARTED BY WELDING ABOVE AREA OF IGNITION.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
LANE, JOHN	1309	250-561-7667	2006-11-14

Name no. : 1
Name :
Address :

s.22

Name Status : WITNESS
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Name no. : 2
Name :
Address :

s.22

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
LANE, JOHN

L AFC Badge #
1309

Telephone
250-561-7667

ReportDate
2006-11-14

Location of Incident: **1850 RIVER ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$500,000** Content Value: **\$0** Total Value at Risk: **\$500,000**

Code Name : Code Description

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION : 4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 1976 1976
MANUAL FIRE PROTECTION : 2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION : 7000 FIRE DEPARTMENT ONLY
SPRINKLER PROTECTION : 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA : 4100 PRODUCT STORAGE AREA - INCLUDES ALL AREAS WHERE PRODUCTS ARE
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 8900 EXPOSURE - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO
FORM OF HEAT : 4000 DIRECT FLAME
MATERIAL FIRST IGNITED : 4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION : 7900 HUMAN FAILING - UNCLASSIFIED (DESCRIBE)

Investigating Officer	L AFC Badge #	Telephone	ReportDate
KRONEBUSCH, DALE	1863	250-561-7667	2007-03-21

Remarks:

SAWDUST WHICH HAD PREVIOUSLY BEEN EXPOSED TO UNREPORTED PLANNER MILL FIRE WAS TRANSFERRED TO CYCLONE IGNITING CHIPS AND STARTING FIRE IN CHIP PIT (CYCLONE). NO DAMAGE, EXTINGUISHED BY FD.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
KRONEBUSCH, DALE	1863	250-561-7667	2007-03-21

Name no. : 1
Name : WINTON, GLOBAL
Address : 1850 RIVER ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OWNER
Phone : 250-562-3361

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer : LAFB Badge #
KRONEBUSCH, DALE : 1863

Telephone :
250-561-7667
ReportDate :
2007-03-21

Location of Incident: **6988 LANDOOZ RD
 PRINCE GEORGE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name :	Code Description
PROPERTY COMPLEX :	0009 BUILDING/STRUCTURE UNCLASSIFIED (DESCRIBE)
PROPERTY CLASSIFICATION :	6990 INDUSTRIAL MANUFACTURING PROPERTIES - UNCLASSIFIED (DESCRIBE)
GENERAL CONSTRUCTION :	0000 CANNOT BE DETERMINED
BUILDING HEIGHT :	0000 CANNOT BE DETERMINED
GROUND FLOOR AREA :	0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	0000 CANNOT BE DETERMINED
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	0000 CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE :	0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W
METHOD OF FIRE CONTROL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, LEVEL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA :	0000 CANNOT BE DETERMINED
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ROWLAND, JEFF	1309	250-561-7670	2010-05-19

Remarks:

FIRE DEPARTMENT WAS DIRECTED TO THE BACK SIDE OF THE LOG SAW BUILDING. INFORMED BY THE ON SCENE PERSONNEL THAT THE FIRE WAS OUT AND THEY WERE LOOKING FOR FIRE EXTENSION IN THE OUTSIDE WALL. SCENE PASSED OFF TO E-12 CAPT B. GARDINER. CAPT B. GARDINER CONSULTED WITH ON SCENE MILL STAFF AS TO ORIGIN SITE AND DEGREE OF EXTENSION. THEY HAD OPENED UP ALL APPROPRIATE WALLS AND AREAS ADJACENT TO FIRE ORIGIN, AND HAD EXTINGUISHED ALL SIGNS OF FIRE. FIRE DEPARTMENT'S THERMAL CAM SHOWED NO SIGN OF RESIDUAL HOT SPOTS. NO WIRE RUNNING THROUGH THE WALL WHERE THE FIRE STARTED. THERE WAS A VENT FROM RADIANT HEATER THAT EXITED HORIZONTALLY THROUGH THE WALL, BUT THE SURROUNDING AREA WASN'T FIRE DAMAGED. QUESTIONING OF ON DUTY COMPANY STAFF, INCLUDING GENERAL MANAGER s.22
s.22 PRODUCED NO THEORY AS TO THE SOURCE OF IGNITION.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
ROWLAND, JEFF	1309	250-561-7670	2010-05-19

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address :

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
ROWLAND, JEFF

L AFC Badge #
1309

Telephone
250-561-7670

ReportDate
2010-05-19

Location of Incident: **6988 LANDOOZ ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **3** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : Code Description

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION : 0000 CANNOT BE DETERMINED
BUILDING HEIGHT : 0000 CANNOT BE DETERMINED
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED
OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 0000 CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 0000 CANNOT BE DETERMINED
FIRE ORIGIN, LEVEL : 0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA : 0000 CANNOT BE DETERMINED
EXTENT OF FIRE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 0000 CANNOT BE DETERMINED
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
FORM OF HEAT : 0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	LAFB Badge #	Telephone	ReportDate
GILDAY, KELLY	1612	250-561-7667	2011-05-27

Remarks:

PLANER ON SITE EXPLAINED THAT THE FIRE WAS CAUSED BY CHIPS IGNITING ON THE PLANER BED PLATE WHICH WAS EXCESSIVELY HOT DUE TO THE FAILURE OF A COOLING SYSTEM DESIGNED TO KEEP IT WITHIN SAFE OPERATING TEMPERATURES

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GILDAY, KELLY	1612	250-561-7667	2011-05-27

Name no. : 1
Name : s.22
Address : 6988 LANDOOZ ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

CALLER

Name no. : 2
Name : s.22
Address : 6988 LANDOOZ ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

MILLWRIGHT

Investigating Officer
GILDAY, KELLY

L AFC Badge #
1612

Telephone
250-561-7667

ReportDate
2011-05-27

Name no. : 3
Name : N/A, N/A
Address : 5162 NORTHWOOD PULPMILL ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : OWNER
Phone : 250-962-3500

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer
GILDAY, KELLY

L AFC Badge #
1612

Telephone
250-561-7667

ReportDate
2011-05-27

Location of Incident: **6988 LANDOOZ RD
 PRINCE GEORGE BC**

of Occupants (At time of fire): **10** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$25,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6990 INDUSTRIAL MANUFACTURING PROPERTIES - UNCLASSIFIED (DESCRIBE
GENERAL CONSTRUCTION :	0000 CANNOT BE DETERMINED
BUILDING HEIGHT :	0000 CANNOT BE DETERMINED
GROUND FLOOR AREA :	0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	0000 CANNOT BE DETERMINED
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	0000 CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE :	0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	1000 CAREER FIRE DEPARTMENT ONLY
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA :	0000 CANNOT BE DETERMINED
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	0000 CANNOT BE DETERMINED
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	LAFB Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-08-12

Remarks:

RESPONDED TO FIRE. LOCATED IN PLANNER ROOM. EXTINGUISHED QUICKLY. ENSURED THAT FIRE WAS OUT.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-08-12

Location of Incident: **9359 NORTHERN CRESCENT
 PRINCE GEORGE BC**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$100,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : Code Description

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING
 PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
 GENERAL CONSTRUCTION : 0000 CANNOT BE DETERMINED
 BUILDING HEIGHT : 0000 CANNOT BE DETERMINED
 GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
 YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
 MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED
 OUTSIDE FIRE PROTECTION : 0009 OUTSIDE FIRE PROTECTION - UNCLASSIFIED (DESCRIBE)
 SPRINKLER PROTECTION : 0000 CANNOT BE DETERMINED
 AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
 SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED
 INITIAL DETECTION : 0000 CANNOT BE DETERMINED
 TRANSMISSION OF ALARM : 1000 911
 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
 INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
 ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
 METHOD OF FIRE CONTROL : 4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
 FIRE ORIGIN, LEVEL : 0000 CANNOT BE DETERMINED
 FIRE ORIGIN, AREA : 0000 CANNOT BE DETERMINED
 EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
 EXTENT OF DAMAGE : 0000 CANNOT BE DETERMINED
 IGNITING OBJECT : 9700 COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI
 FUEL OR ENERGY : 0000 CANNOT BE DETERMINED
 FORM OF HEAT : 0000 CANNOT BE DETERMINED
 MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED
 ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	LAFB Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-10-12

Remarks:

SPARKS FROM ELECTRICAL MOTOR OVERHEATING IGNITED SAWDUST AND HYDRAULIC FLUID. CHARRED INTERIOR WALLS OF COMPRESSOR ROOM BUT WAS CONTAINED.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-10-12

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address :
PRINCE GEORGE BRITISH COLUMBIA

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Name no. : 2
Name : UNKNOWN, UNKNOWN
Address : 9395 NORTHERN CRESCENT
PRINCE GEORGE BRITISH COLUMBIA

Name Status : OCCUPANT
Phone : 250-561-2169

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

MILL CREWS ONSITE HELPING FIGHT THE FIRE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-10-12

Name no. : 3
Name : TAYLOR, GREG
Address :

Name Status : OWNER
Phone : 250-561-2169

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
IVERSON, JOHN

L AFC Badge #
2356

Telephone
250-561-7667

ReportDate
2011-10-12

Location of Incident: **6988 LANDOOZ ROAD
PRINCE GEORGE BC**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$3,000,000** Content Value: **\$5,000,000** Total Value at Risk: **\$8,000,000**

Code Name :	Code Description
PROPERTY COMPLEX : 0009	BUILDING/STRUCTURE UNCLASSIFIED (DESCRIBE)
PROPERTY CLASSIFICATION : 6210	SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION : 0000	CANNOT BE DETERMINED
BUILDING HEIGHT : 0000	CANNOT BE DETERMINED
GROUND FLOOR AREA : 0000	CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000	CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 4000	EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION : 7000	FIRE DEPARTMENT ONLY
SPRINKLER PROTECTION : 0000	CANNOT BE DETERMINED
AUTOMATIC FIRE ALARM SYSTE : 0000	CANNOT BE DETERMINED
SMOKE ALARM OPERATION : 0000	ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION : 0000	CANNOT BE DETERMINED
TRANSMISSION OF ALARM : 1000	911
FIRE SERVICE : 1000	CAREER FIRE DEPARTMENT ONLY
INCIDENT : 1000	FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 1000	EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W
METHOD OF FIRE CONTROL : 0000	CANNOT BE DETERMINED
FIRE ORIGIN, LEVEL : 0000	CANNOT BE DETERMINED
FIRE ORIGIN, AREA : 6100	MACHINERY ROOM - INCLUDES ELEVATOR MACHINERY ROOM, ENGINE RO
EXTENT OF FIRE : 1000	CONFINED TO OBJECT OF ORIGIN
EXTENT OF DAMAGE : 1000	CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT : 9700	COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI
FUEL OR ENERGY : 0000	CANNOT BE DETERMINED
FORM OF HEAT : 0000	CANNOT BE DETERMINED
MATERIAL FIRST IGNITED : 0000	CANNOT BE DETERMINED
ACT OR OMISSION : 0000	CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-12-07

Remarks:

ENGINE 41 AND TENDER 41 WERE DISPATCHED TO A REPORTED STRUCTURE FIRE AT PG SAWMILL. UPON ARRIVAL AT THE MAIN GATE, WERE TOLD BY A MILL STAFF-MEMBER THAT THE FIRE APPEARED TO BE OUT AND HE GAVE THE DIRECTIONS TO FIND THE POWER PLANT. STAFF HAD COMPLETELY EXTINGUISHED THE FIRE PRIOR TO ARRIVAL AND THAT THERE HAD BEEN NO EXTENSION BEYOND THE OBJECT OF ORIGIN. A WALK THOUGH OF THE BUILDING WAS PERFORMED WITH THERMAL IMAGING TECHNOLOGY. THE FIRE HAD ORIGINATED IN A WET CONVEYER BELT LOCATED BELOW ONE OF THE FURNACES. NORMALLY HOT ASH DROPS ONTO THE WET CONVEYOR OUT OF THE BOTTOM FURNANCE AND THEN IS REMOVED FROM THE BUILDING. IN THIS CASE THERE WAS NO WATER IN THE CONVEYOR AND THE ASH CONTINUED TO BURN AFTER IT FELL.

Investigating Officer	LAFD Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-12-07

Name no. : 1
Name : UNKNOWN, UNKNOWN
Address :
PRINCE GEORGE BRITISH COLUMBIA

Name Status : WITNESS
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Name no. : 2
Name : UNKNOWN, UNKNOWN
Address : 6988 LANDOOZ ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : BUSINESS OWNER
Phone : 250-962-4700

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
IVERSON, JOHN	2356	250-561-7667	2011-12-07

Name no. : 3
Name : s.22
Address : 6988 LANDOOZ ROAD
PRINCE GEORGE BRITISH COLUMBIA

Name Status : OCCUPANT
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
IVERSON, JOHN

L AFC Badge #
2356

Telephone
250-561-7667

ReportDate
2011-12-07

Location of Incident: **1879 BROWN MILLER RD
QUESNEL BC**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,000,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$5,000,000** Content Value: **\$35,000,000** Total Value at Risk: **\$40,000,000**

Code Name : **Code Description**

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING

PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN

GENERAL CONSTRUCTION : 0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)

BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA : 4000 1001 TO 2500M2 (10765 - 26910FT2)

YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED

MANUAL FIRE PROTECTION : 2000 EXTINGUISHERS & STANDPIPE SYSTEM

OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION : 5000 PARTIAL SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON

AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM

SMOKE ALARM OPERATION : 9900 NO SMOKE ALARM INSTALLED

INITIAL DETECTION : 5000 AUTOMATIC SPRINKLER SYSTEM

TRANSMISSION OF ALARM : 1000 911

FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL : 4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE

FIRE ORIGIN, AREA : 0000 CANNOT BE DETERMINED

EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN

IGNITING OBJECT : 6900 ELECTRICAL EQUIPMENT - UNCLASSIFIED (DESCRIBE)

FUEL OR ENERGY : 6000 ELECTRICITY

FORM OF HEAT : 0000 CANNOT BE DETERMINED

MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED

ACT OR OMISSION : 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
RAWLING, MARK	1478	250-992-5121	2008-01-21

Remarks:

FIRE STARTED IN A TRANSFORMER ON THE FLOOR AND BURNED UP THE WALL ABOVE THE SPRINKLER SYSTEM AND INTO THE ROOM ABOVE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
RAWLING, MARK	1478	250-992-5121	2008-01-21

Location of Incident: **1879 BROWN MILLER RD
QUESNEL BC V2J 6R9**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$150,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$50,000,000** Content Value: **\$35,000,000** Total Value at Risk: **\$85,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	4000 1001 TO 2500M2 (10765 - 26910FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	6900 SPRINKLER PROTECTION - UNCLASSIFIED (DESCRIBE)
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	3800 PROCESS, MANUFACTURING AREA
EXTENT OF FIRE :	4000 CONFINED TO FLOOR LEVEL OF ORIGIN
EXTENT OF DAMAGE :	4000 CONFINED TO FLOOR LEVEL OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GAUTHIER, SYLVAIN	2324	250-992-5121	2009-08-10

Remarks:

MILLS WAS IN A SHUT DOWN MODE FOR THE WEEK END WHEN THE FIRE HAPPENED. THE SECURITY GUARD NOTICED SMOKE INSIDE THE BUILDING WHILE CONDUCTING HIS ROUND. HE PROCEEDED TO INVESTIGATE THE CAUSE OF THE SMOKE. AS HE MOVED FURTHER INTO THE MILLS, HE HEARD WATER RUNNING AND THEN SEW THAT THE SPRINKLER SYSTEM HAD ACTIVATED. IN THE MEANTIME HE HAD ALREADY CALLED 911 TO REQUEST RESPONSE FROM FIRE DEPARTMENT. DUTY OFFICER WAS FIRST ON SCENE AND PROCEEDE INSIDE THE MILLS WITH THE SECURITY GUARD TO CONDUCT A SIZE UP OF THE SITUATION. FLAMES WERE SEEN BY THE BOARD EDGER. UPON ARRIVAL OF THE FIRST ENGINE, DUTY OFFICER TOOK THE ENGINE OFFICER INSIDE TO SHOW HIM WHAT WE HAD. TWO 1 3/4 INCH HOSE WERE LAID OUT FROM THE ENGINE TO THE LOCATION OF THE FIRE. ONCE BOTH LINE WERE CHARGED AND ATTACK CREW IN POSITIONED, INSTRUCTIONED WERE GIVEN TO SHUT DOWN THE SPRINKLER SYSTEM SO THAT THE ATTACK TEAM COULD HAVE BETTER VISIBILITY. ONCE SPRINKLER WERE SHUT DOWN, ATTACK TEAM ADVANCED ON THE FIRE LOCATION AND EXTINGUISHED THE FIRE. FIRE WAS PUT OUT AND SALVAGE AND OVERALL WERE CONDUCTED. EXTENSIVE DAMAGE WAS DONE TO WIRE TRAYS ABOVE THE BOARD EDGER AND HEAVY CHARRING ON THE CEILING TIMBER MEMBRANE. DAMAGE TO THE BOARD EDGER WAS MAINLY ON THE OUTSIDE. A TOTAL OF 25 SPRINKLER HEAD ACTIVATED. CAUSE OF THE FIRE COULD NOT BE DETERMINED.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GAUTHIER, SYLVAIN	2324	250-992-5121	2009-08-10

Name no. : 1
Name : INDUSTRIES, TOLKO
Address : 1879 BROWN MILLER
 QUESNEL BRITISH COLUMBIA

Name Status : BUSINESS OWNER
Phone : 250-992-1700

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GAUTHIER, SYLVAIN	2324	250-992-5121	2009-08-10

Location of Incident: **1631 MILL STREET
 REVELSTOKE BC V0E2S0**

of Occupants (At time of fire): **2** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$500**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
BUILDING HEIGHT :	0010 1 STORY ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	4000 EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE :	3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	2200 STANDPIPE/HOSE SYSTEM SMALL HOSE - 38MM (1 1/2") NOMINAL SI
FIRE ORIGIN, LEVEL :	2000 CRAWL SPACE, UNDER STRUCTURE
FIRE ORIGIN, AREA :	5900 SERVICE FACILITIES - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	9600 BEARING, BELTING, CONVEYOR, BRAKE
FUEL OR ENERGY :	1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4100 PART FAILURE, LEAK, BREAK

Investigating Officer	L AFC Badge #	Telephone	ReportDate
GIRARD, ROB	2425	250-837-2884	2012-03-01

Remarks:

CAUSE OF THE FIRE WAS OVERHEATING BEARING ON CONVEYOR BELT. DATA COLLECTED BY FC ROB GIRARD DATA ENTERED BY ROGER ECHLIN LAFC 1964

Investigating Officer	LAFC Badge #	Telephone	ReportDate
GIRARD, ROB	2425	250-837-2884	2012-03-01

Name no. : 1
Name : s.22
Address : 1631 MILL STREET
REVELSTOKE BRITISH COLUMBIA V0E 2S2

Name Status : OWNER
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

s.22

Investigating Officer
GIRARD, ROB

L AFC Badge #
2425

Telephone
250-837-2884

ReportDate
2012-03-01

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC V2G3P6**

of Occupants (At time of fire): **30** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$5,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$34,000,000** Content Value: **\$0** Total Value at Risk: **\$34,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	4000 1001 TO 2500M2 (10765 - 26910FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	7000 TELEPHONE DIRECT TO FIRE DEPARTMENT OTHER THAN 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7600 EXTERIOR WALL
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	3000 EXTERIOR WALL COVERING, SURFACE, FINISH - INCLUDES EAVE
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2005-04-05

Remarks:

DAMAGED ELECTRICAL CABLE AGAINST THE EXTERIOR WALL. THE ACCIDENTAL ENERGIZING OF THE CABLE SHORTED IT OUT ON SOME METAL ON THE INSIDE OF THE EXTERIOR WALL, IGNITING THE WALL. THE WALL HAD SOME OIL SOAKED WOOD IN THE AREA AND THE FIRE SPREAD TO BELOW A HYDRAULIC OIL RESERVOIR.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2005-04-05

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC V2G3P6**

of Occupants (At time of fire): **50** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$500**

Related to Wildland Interface Fire: **NO** Property Value: **\$35,000,000** Content Value: **\$0** Total Value at Risk: **\$35,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	4000 1001 TO 2500M2 (10765 - 26910FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	4000 EXTINGUISHED BY AUTOMATIC SYSTEM
METHOD OF FIRE CONTROL :	6200 WET PIPE SYSTEM - LOCAL ALARM ONLY
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFB Badge #	Telephone	ReportDate
WEBSTER, DES	1510	250-392-1794	2005-06-16

Remarks:

WIRING TO AN ELECTRICAL MOTOR HAD LOOSENEED AND ARCED, IGNITING THE DUST AND SAWDUST IN THE ROOM. THERE WAS A MINOR DUST EXPLOSION. DAMAGE WAS MINOR, MELTING SOME PLASTIC SKIRTING, AND THE END OF THE ELECTRICAL CABLE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WEBSTER, DES	1510	250-392-1794	2005-06-16

Name no. : 1
Name : **s.22**
Address : 110 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : OWNER
Phone : 250-392-4121

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

THE VALUE OF THE MILL, (BUIDING AND CONTENTS), IS \$35,000,000

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WEBSTER, DES	1510	250-392-1794	2005-06-16

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC V2G3P6**

of Occupants (At time of fire): **26** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$14,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$20,000,000** Content Value: **\$40,000,000** Total Value at Risk: **\$60,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT :	0040 4 STORIES ABOVE GRADE
GROUND FLOOR AREA :	5000 2501 TO 5000M2 (26911 - 53820FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	6100 MOTOR, 1HP & OVER - INCLUDES MOTOR FORMING AN INTEGRAL PART
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4600 PART WORN OUT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2006-01-30

Remarks:

THE INCIDENT TOOK PLACE IN THE SAWMILL, A 250 HP ELECTRIC MOTOR, SEIZED, IGNITING THE SAWDUST AROUND IT. THE RESULTING FIRE SPREAD TO THE FLOOR AND WALL ABOVE.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2006-01-30

Name no. : 1
Name : s.22
Address : 110 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : OWNER
Phone : 250-392-4121

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

s.22

Investigating Officer
ISFELD, RANDY

L AFC Badge #
157

Telephone
250-392-1779

ReportDate
2006-01-30

Location of Incident: **4225 FRIZZI ROAD
WILLIAMS LAKE BC V2G5E4**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$600,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$1,000,000** Content Value: **\$2,500,000** Total Value at Risk: **\$3,500,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	3000 501 TO 1000M2 (5383 - 10764FT2)
YEAR OF CONSTRUCTION :	2001 2001
MANUAL FIRE PROTECTION :	4000 EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7
FIRE ORIGIN, LEVEL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA :	0000 CANNOT BE DETERMINED
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2007-03-13

Remarks:

THE MAIN BUILDING OF THE PLANT WAS FULLY INVOLVED UPON OUR ARRIVAL. WE ARE UNABLE TO DETERMINE THE EXACT CIRCUMSTANCES UNDER WHICH THE FIRE STARTED.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2007-03-13

Name no. : 1
Name :
Address : s.22

Name Status : BUSINESS OCCUPANT
Phone : s.22

Claims Adjuster Name : s.22
Claims Adjuster Firm :
Claim Number :
Insurance Company : s.22
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21 Content Loss : s.21 Total Loss : s.21

REMARKS:

s.22

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2007-03-13

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC V2G3P6**

of Occupants (At time of fire): **6** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$6,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$150,000** Content Value: **\$1,000,000** Total Value at Risk: **\$1,150,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	3000 501 TO 1000M2 (5383 - 10764FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE
FIRE ORIGIN, AREA :	6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	9700 COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	5310 HYDRAULIC FLUIDS - INCLUDES BRAKE, TRANSMISSION OR POWER
ACT OR OMISSION :	4600 PART WORN OUT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2007-04-14

Remarks:

A BEARING BURNED OUT IN LARGE GEAR DRIVING MACHINE THAT MOVED THE LOGS INTO THE DE-BARKER, IT IS POWERED BY ELECTRICITY. THE BEARING OVERHEATED AND IGNITED HYDRAULIC OIL AND LINES.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2007-04-14

Name no. : 1
Name : s.22
Address : 110 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OCCUPANT
Phone : 250-392-4121

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

DAMAGE TO BEARING AND HYRAULICS

Investigating Officer
ISFELD, RANDY

L AFC Badge #
157

Telephone
250-392-1779

ReportDate
2007-04-14

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **2** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$2,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$100,000** Content Value: **\$1,500,000** Total Value at Risk: **\$1,600,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	4000 EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4200 38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6100 MACHINERY ROOM - INCLUDES ELEVATOR MACHINERY ROOM, ENGINE RO
EXTENT OF FIRE :	1000 CONFINED TO OBJECT OF ORIGIN
EXTENT OF DAMAGE :	1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT :	9700 COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI
FUEL OR ENERGY :	0009 FUEL OR ENERGY - UNCLASSIFIED (DESCRIBE)
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	5310 HYDRAULIC FLUIDS - INCLUDES BRAKE, TRANSMISSION OR POWER
ACT OR OMISSION :	4200 AUTOMATIC CONTROL FAILURE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2008-01-21

Remarks:

THE COMPRESSOR OVER HEATED AND AN OIL LINE BROKE AND THE OIL AND THE COMPRESSOR CAUGHT FIRE. THE FIRE DAMAGE WAS CONTAINED TO THE COMPRESSOR.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2008-01-21

Name no. : 1
Name : s.22
Address : 0 110 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OCCUPANT
Phone : 250-392-3371

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2008-01-21

Location of Incident: **4255 ROTTACKER ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$250,000** Content Value: **\$0** Total Value at Risk: **\$250,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	1000 1 TO 100M2 (1 - 1076FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7900 STRUCTURAL AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	9600 BEARING, BELTING, CONVEYOR, BRAKE
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	5100 DESIGN DEFICIENCY

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-04-20

Remarks:

THE FIRE WAS LOCATED AT THE TOP OF THE WOOD CHIP HOPPER, FIRE DAMAGE WAS CONTAINED TO THIS AREA. THE FIRE WAS A RESULT OF WOOD JAMMING THE TOP ROLLER ON THE CONVEYOR BELT, RESULTING FRICTION HEAT IGNITED SOME SAWDUST/WOOD CHIPS AND THE FIRE DAMAGED THE ROLLER AND ADJACENT CONTROL BOX.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-04-20

Name no. : 1
Name : s.22
Address : 0 4255 ROTTACKER ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G2V4

Name Status : BUSINESS OCCUPANT
Phone : 250-392-7784

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
ISFELD, A. RANDY

L AFC Badge #
157

Telephone
250-392-2311

ReportDate
2009-04-20

Location of Incident: **110 HODGSON ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,500**

Related to Wildland Interface Fire: **NO** Property Value: **\$20,000** Content Value: **\$40,000** Total Value at Risk: **\$60,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0040 4 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	6000 PARTIAL SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS ON
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7900 STRUCTURAL AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT :	9600 BEARING, BELTING, CONVEYOR, BRAKE
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4600 PART WORN OUT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WEBSTER, DES M.	1510	250-392-2311	2009-06-08

Remarks:

A BEARING ON A CONVEYER MOTOR, IT HEATED UP AND IGNITED WOOD DEBRIS AROUND THE BEARING. FIRE DAMAGE WAS CONTAINED TO THIS AREA.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WEBSTER, DES M.	1510	250-392-2311	2009-06-08

Name no. : 1
Name : s.22
Address : 0 110 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OCCUPANT
Phone :

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
WEBSTER, DES M.	1510	250-392-2311	2009-06-08

Location of Incident: **180 HODGSON ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$5,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$40,000** Content Value: **\$0** Total Value at Risk: **\$40,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	3000 501 TO 1000M2 (5383 - 10764FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4700 COMBINATIONS OF 38/42MM (1 1/2"/1 3/4"), 65MM (2 1/2"), 7
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7500 WALL ASSEMBLY - INCLUDES CONCEALED WALL SPACE
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	5500 SWITCH, OUTLET - INCLUDES RECEPTACLE, SOCKET
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-06-08

Remarks:

THE FIRE WAS DETERMINED TO HAVE STARTED AS A RESULT OF AN ELECTRICAL SHORT IN A JUNCTION BOX LOCATED INSIDE ON THE CATWALK AREA OF THE BUILDING.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-06-08

Name no. : 1
Name : s.22
Address : 0 180 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OCCUPANT
Phone : 250-392-3371

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-06-08

Location of Incident: **4255 ROTTACKER ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$4,500**

Related to Wildland Interface Fire: **NO** Property Value: **\$15,000,000** Content Value: **\$30,000,000** Total Value at Risk: **\$45,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	4000 1001 TO 2500M2 (10765 - 26910FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4100 25MM (1"), OR LESS HOSE
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	1000 CONFINED TO OBJECT OF ORIGIN
EXTENT OF DAMAGE :	1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT :	5900 ELECTRICAL DISTRIBUTION EQUIPMENT - UNCLASSIFIED (DESCRIBE)
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-07-24

Remarks:

LARGE FUSES BLEW OUT THROUGH THEIR TOPS IGNITING DUST ABOVE THE PANELS AND IN THE DISTRIBUTION TRAY. FIRE DAMAGE WAS MINIMAL IN A FEW WALL AREAS AND IN SOME SAWDUST IN SEVERAL LOCATIONS ALONG THE DISTRIBUTION TRAYS.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-07-24

Name no. : 1
Name : s.22
Address : 0 4255 ROTTACKER ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G2V4

Name Status : BUSINESS OCCUPANT
Phone : s.22

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2009-07-24

Location of Incident: **180 HODGSON ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$500,000** Content Value: **\$0** Total Value at Risk: **\$500,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	1000 1 TO 100M2 (1 - 1076FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	6000 STANDPIPE SYSTEM ONLY
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	7000 NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE :	1000 NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE
FIRE ORIGIN, AREA :	7600 EXTERIOR WALL
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	7600 WELDING EQUIPMENT
FUEL OR ENERGY :	4300 FUEL GAS - OTHER (DESCRIBE)
FORM OF HEAT :	1000 SPARK, EMBER - INCLUDES FLYING BRAND OR SPARK SHOWER
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	2500 WELDING OR CUTTING TOO CLOSE

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2010-03-29

Remarks:

THE FIRE WAS LOCATED IN A CHIP PILES ON AND AROUND A 3 STORY HOPPER BIN AND WAS THE RESULT OF WELDING/CUTTING OPERATIONS TO THE HOPPER. THE FIRE FORE WAS CONTAINED TO FEW SMALL AREAS. NO FIRE DAMAGE TO THE STRUCTURE NO DOLLAR LOSS.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2010-03-29

Name no. : 1
Name : **s.22**
Address : 0 180 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OWNER
Phone : 250-392-3371

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer
ISFELD, A. RANDY

L AFC Badge #
157

Telephone
250-392-2311

ReportDate
2010-03-29

Location of Incident: **180 HODGSON ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$5,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$35,000,000** Content Value: **\$95,000,000** Total Value at Risk: **\$130,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	4000 NON-COMBUSTIBLE CONSTRUCTION - EXPOSED STEEL
BUILDING HEIGHT :	0040 4 STORIES ABOVE GRADE
GROUND FLOOR AREA :	6000 5001 TO 10,000M2 (53821 - 107640FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
SMOKE ALARM OPERATION :	0000 ALARM OPERATION CANNOT BE DETERMINED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6900 UTILITY & EQUIPMENT AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT :	5100 PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2010-04-19

Remarks:

THE FIRE WAS LOCATED AT THE END OF CHIP CONVEYOR IN AN ELECTRICAL CONTROL DEVICE. IT APPEARS TO HAVE SHORTED OUT AND EITHER A SPARK OR MELTING PLASTIC INSULATION IGNITED SAWDUST IN THE AREA. THE DAMAGE WAS CONTAINED TO THE DISTRIBUTION BOX AND THE ELECTRICAL WIRING IN THE AREA. DOLLAR LOSS IS ESTIMATED AT \$5000.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2010-04-19

Name no. : 1
Name : s.22
Address : 0 180 HODGSON ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G3P6

Name Status : BUSINESS OCCUPANT
Phone : 250-392-3371

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2010-04-19

Location of Incident: **5000 SODA CREEK ROAD
WILLIAMS LAKE BC**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$1,500**

Related to Wildland Interface Fire: **NO** Property Value: **\$2,600,000** Content Value: **\$5,000,000** Total Value at Risk: **\$7,600,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	0009 GENERAL CONSTRUCTION - UNCLASSIFIED (DESCRIBE)
BUILDING HEIGHT :	0040 4 STORIES ABOVE GRADE
GROUND FLOOR AREA :	4000 1001 TO 2500M2 (10765 - 26910FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	0000 CANNOT BE DETERMINED
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	5300 PUMPER - FOAM HAND LINES ONLY, VIA EDUCATOR/INJECTOR
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	6300 TRANSFORMER VAULT - INCLUDES ANCILLARY SWITCHGEAR
EXTENT OF FIRE :	4000 CONFINED TO FLOOR LEVEL OF ORIGIN
EXTENT OF DAMAGE :	4000 CONFINED TO FLOOR LEVEL OF ORIGIN
IGNITING OBJECT :	5300 SWITCHGEAR - INCLUDES POWER SWITCHGEAR ONLY
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4100 PART FAILURE, LEAK, BREAK

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2011-01-31

Remarks:

THE FIRE RESULTED FROM A FUSE NOT SECURELY BOLTED TO THE PANEL, (THE BOLT USED WAS TOO LONG) RESULTING IN AN EXPLOSION IN THE MC UNIT. THE EXPLOSION WAS STRONG ENOUGH TO DISLODGE THE 2X4 WALLS OF THE ROOM. FIRES STARTED IN THE EXTERIOR WALL. THESE WALLS CONSISTED OF 1/2 IN PLYWOOD ON THE INTERIOR AND EXTERIOR. THE FIRES APPROXIMATED THE SECOND FLOOR AREA. WE HAD TO REMOVE LARGE SECTIONS OF THE PLYWOOD BOTH ON THE EXTERIOR AND THE INTERIOR OF THE BUILDING, WHICH TOOK A CONSIDERABLE AMOUNT OF TIME TO TRACK DOWN, EXTINGUISH AND CHECK FOR EXTENSION. FIRE DAMAGE WAS VERY LIGHT AND CONTAINED TO THE WALLS.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2011-01-31

Name no. : 1
Name : s.22
Address : 0 5000 SODA CREEK ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G5H5

Name Status : BUSINESS OCCUPANT
Phone : 250-305-6800

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, A. RANDY	157	250-392-2311	2011-01-31

Location of Incident: **4255 ROTTACKER ROAD
WILLIAMS LAKE BC V2G2V4**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$80,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$200,000** Content Value: **\$150,000** Total Value at Risk: **\$350,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	5000 PROTECTED NON-COMBUSTIBLE CONSTRUCTION - PROTECTED STEEL OR
BUILDING HEIGHT :	0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA :	2000 101 TO 500M2 (1077 - 5382FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	7000 TELEPHONE DIRECT TO FIRE DEPARTMENT OTHER THAN 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL :	2200 STANDPIPE/HOSE SYSTEM SMALL HOSE - 38MM (1 1/2") NOMINAL SI
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6100 MACHINERY ROOM - INCLUDES ELEVATOR MACHINERY ROOM, ENGINE RO
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	3000 CONFINED TO ROOM OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2004-09-13

Remarks:

THE CAUSE OF THE FIRE CANNOT BE DETERMINED. WE SUSPECT (THIS IS A BEST GUESS BY s.22
s.22 THAT A SIGHT GLASS ON THE OIL LINE BROKE AND SPRAYED HOT OIL AROUND , WHICH WAS SUCKED
INTO THE COMPRESSOR AND IGNITED INSIDE AND OUTSIDE THE COMPRESSOR, DESTROYING IT AND BURNING THE
INTERIOR WALLS OF THE BUILDING.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2004-09-13

Name no. : 1
Name : s.22
Address : 4360 4255 ROTTACKER ROAD
WILLIAMS LAKE BRITISH COLUMBIA V2G2V4

Name Status : BUSINESS OCCUPANT
Phone : 250-392-7784

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21 Content Loss : s.21 Total Loss : s.21

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
ISFELD, RANDY	157	250-392-1779	2004-09-13

Location of Incident: **1397 MORICE RIVER ROAD P.O. Box 5000
HOUSTON BC V0J 1Z0**

of Occupants (At time of fire): **2** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$7,500**

Related to Wildland Interface Fire: **NO** Property Value: **\$11,250,000** Content Value: **\$0** Total Value at Risk: **\$11,250,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6230 WOOD, CORK PRODUCTS MANUFACTURE - INCLUDES THE MANUFACTURE O
GENERAL CONSTRUCTION :	1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	6000 5001 TO 10,000M2 (53821 - 107640FT2)
YEAR OF CONSTRUCTION :	1970 1970
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	2000 COMPLETE SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM :	7000 TELEPHONE DIRECT TO FIRE DEPARTMENT OTHER THAN 911
FIRE SERVICE :	2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	4000 EXTINGUISHED BY AUTOMATIC SYSTEM
METHOD OF FIRE CONTROL :	6200 WET PIPE SYSTEM - LOCAL ALARM ONLY
FIRE ORIGIN, LEVEL :	4000 2ND STOREY OR OVER 3M TO 6M (10FT TO 20FT) ABOVE GRADE
FIRE ORIGIN, AREA :	6100 MACHINERY ROOM - INCLUDES ELEVATOR MACHINERY ROOM, ENGINE RO
EXTENT OF FIRE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE :	2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT :	7800 HOT ASHES, EMBERS - NOT ASSOCIATED WITH SMOKER'S MATERIAL
FUEL OR ENERGY :	1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO
FORM OF HEAT :	1000 SPARK, EMBER - INCLUDES FLYING BRAND OR SPARK SHOWER
MATERIAL FIRST IGNITED :	9000 BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE
ACT OR OMISSION :	6250 FLYING EMBERS

Investigating Officer	L AFC Badge #	Telephone	ReportDate
THOMSON, KEN	263	250-845-2250	2007-02-14

Remarks:

SAWMILL COMPLEX - FLYING BRAND FROM BEE-HIVE BURNER LODGED UNDER EXTERIOR WALL COVERING, IGNITING PLYWOOD WALL. FIRE EXTENDED UP WALL TO EAVE/CEILING BREAKING THROUGH TO INTERIOR AND ACTIVATING WET SPRINKLER SYSTEM. DAMAGE CONTAINED TO WALL/CEILING AND INTERIOR ELECTRICAL GEAR (WET/GROUNDED).

Investigating Officer	LAFD Badge #	Telephone	ReportDate
THOMSON, KEN	263	250-845-2250	2007-02-14

Name no. : 1
Name : s.22
Address : 5000 1397 MORICE RIVER ROAD
HOUSTON BRITISH COLUMBIA V0J1Z0

Name Status : BUSINESS OWNER
Phone : 250-845-5200

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
THOMSON, KEN

L AFC Badge #
263

Telephone
250-845-2250

ReportDate
2007-02-14

Location of Incident: **1397 MORICE RIVER RD
HOUSTON BC V0J 1Z0**

of Occupants (At time of fire): **0** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$150,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$22,000,000** Content Value: **\$0** Total Value at Risk: **\$22,000,000**

Code Name : Code Description

PROPERTY CLASSIFICATION : 8190 OUTDOOR PROPERTY - UNCLASSIFIED (DESCRIBE)
TRANSMISSION OF ALARM : 7000 TELEPHONE DIRECT TO FIRE DEPARTMENT OTHER THAN 911
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES
FIRE ORIGIN, AREA : 9900 OUTSIDE AREA - UNCLASSIFIED (DESCRIBE)
EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT : 9200 INDUSTRIAL OVEN - INCLUDES KILN. (EXCLUDES OVEN USED FOR FOOD)
FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FOR)
FORM OF HEAT : 1000 SPARK, EMBER - INCLUDES FLYING BRAND OR SPARK SHOWER
MATERIAL FIRST IGNITED : 4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION : 5100 DESIGN DEFICIENCY

Investigating Officer	L AFC Badge #	Telephone	ReportDate
THOMSON, KEN	263	250-845-2250	2010-01-20

Remarks:

PELLET PLANT DRYER, WAS TEMPORARLIY SHUT DOWN DUE TO PRODUCT FEED PLUG UP, HOWEVER, FINE HAMMERMILL DUST CONTINUED TO FEED INTO DRYER UNKNOWN TO OPERATOR. NATURAL GAS BURNER ON LOW FIRE WITH INDUCED DRAFT TO MINIMUM, ALLOWED FINE DUST TO BUILD UP IN DRYER THUS IGNITION BY HOT EMBER/FLAME FROM GAS BURNER CAUSED A SEVERE EXPLOSION WHICH DISLODEGED DRYER (90 TON CYLINDER) FROM BASE. FIRE WAS SELF EXTINGUISHED, EXTENSIONS TO DUCTING AND SURROUNDINGS EXTINGUISHED BY FIRE DEPT.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
THOMSON, KEN	263	250-845-2250	2010-01-20

Name no. : 1
Name : CANFOR, CANFOR
Address : 158 1397 MORICE RIVER RD
HOUSTON BRITISH COLUMBIA V0J 1Z0

Name Status : OWNER
Phone : 250-845-5200

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : s.21

Content Loss : s.21

Total Loss : s.21

REMARKS:

Investigating Officer
THOMSON, KEN

L AFC Badge #
263

Telephone
250-845-2250

ReportDate
2010-01-20

Location of Incident:

**DECKER LAKE FORESTY PRODUCTS P.O. Box 250
REGIONAL DISTRICT OF BULKLEY-NECHAKO BC V0J 1E0**

of Occupants (At time of fire): **55** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$400,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$15,807,000** Content Value: **\$6,875,000** Total Value at Risk: **\$22,682,000**

Code Name : Code Description

PROPERTY COMPLEX : 6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION : 6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION : 3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA : 3000 501 TO 1000M2 (5383 - 10764FT2)
YEAR OF CONSTRUCTION : 1972 1972
MANUAL FIRE PROTECTION : 2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION : 6000 PRIVATE HYDRANT PROTECTION & NO FIRE DEPARTMENT
SPRINKLER PROTECTION : 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE : 2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION : 5000 AUTOMATIC SPRINKLER SYSTEM
TRANSMISSION OF ALARM : 5000 DIRECT VERBAL REPORT TO A FIRE STATION
FIRE SERVICE : 2000 VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT ONLY
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 5700 COMPRESSED AIR FOAM SYSTEMS
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 3550 MAINTENANCE SHOP - INCLUDES REPAIR SHOP, WELDING SHOP, WORKS
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 2000 CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 9700 COMMERCIAL & INDUSTRIAL MACHINERY, EQUIPMENT - INCLUDES SAWI
FUEL OR ENERGY : 6000 ELECTRICITY
FORM OF HEAT : 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED : 8000 BUILDING COMPONENT - FLOOR, CEILING, ROOF. (EXCLUDES FLOOR C
ACT OR OMISSION : 4900 MECHANICAL/ELECTRICAL FAILURE/MALFUNCTION - UNCLASSIFIED (DE

Investigating Officer
MCBRIDE, JIM

LAFC Badge #
827

Telephone
250-692-7587

ReportDate
2005-02-21

Remarks:

THIS FIRE IS THE RESULT OF AN ELECTRICAL ARC IN THE PRIMARIES OF A THREE HUNDRED HORSE ELECTRIC MOTOR. THE RESULT OF THIS ARCING SET FIRE TO THIS MOTOR WHICH IN TURN IGNITED ALL THE COMBUSTIBLES AROUND IT. THE FIRE IGNITED A SECOND COMPRESSOR AND EXTENDED INTO THE CEILING SPACE ABOVE WHICH WAS THE FLOOR AREA OF THE PRODUCTION FLOOR. THE FLAMES CRAWLED UP INSIDE THE WALLS AND DESTROYED THE COMPUTER ROOM, FIRST AID ROOM, LUNCH ROOM AND WASHROOM. THE FIRE WAS CONTAINED TO THESE TWO LOCATIONS..

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MCBRIDE, JIM	827	250-692-7587	2005-02-21

Location of Incident: **19479 HIGHWAY 16 E P.O. Box 4000
REGIONAL DISTRICT OF BULKLEY-NECHAKO BC V0J1E-**

of Occupants (At time of fire): **28** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$50,000,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$100,000,000** Content Value: **\$0** Total Value at Risk: **\$100,000,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	6000 5001 TO 10,000M2 (53821 - 107640FT2)
YEAR OF CONSTRUCTION :	1972 1972
MANUAL FIRE PROTECTION :	0009 MANUAL FIRE PROTECTION FACILITIES - UNCLASSIFIED (DESCRIBE)
OUTSIDE FIRE PROTECTION :	6000 PRIVATE HYDRANT PROTECTION & NO FIRE DEPARTMENT
SPRINKLER PROTECTION :	3000 COMPLETE SPRINKLER PROTECTION - UNSUPERVISED, LOCAL ALARMS O
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	0000 CANNOT BE DETERMINED
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	2000 BURNED OUT - NO EXTINGUISHMENT ATTEMPTED/NEEDED
METHOD OF FIRE CONTROL :	8200 UNABLE TO CONTROL BY FIRE DEPARTMENT ON ARRIVAL
FIRE ORIGIN, LEVEL :	0000 CANNOT BE DETERMINED
FIRE ORIGIN, AREA :	0000 CANNOT BE DETERMINED
EXTENT OF FIRE :	5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE :	5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT :	0000 CANNOT BE DETERMINED
FUEL OR ENERGY :	0000 CANNOT BE DETERMINED
FORM OF HEAT :	0000 CANNOT BE DETERMINED
MATERIAL FIRST IGNITED :	0000 CANNOT BE DETERMINED
ACT OR OMISSION :	0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MCBRIDE, JIM	827	250-692-7587	2012-02-21

Remarks:

AN EXPLOSION OF UNKNOWN ORIGIN CAUSED EXTENSIVE DAMAGE AND TOTALLY DESTROYED THE SAWMILL.

Investigating Officer	L AFC Badge #	Telephone	ReportDate
MCBRIDE, JIM	827	250-692-7587	2012-02-21

Location of Incident: **991 EXETER MCKINLEY ROAD
100 MILE HOUSE BC V0K 2E0**

of Occupants (At time of fire): **22** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$10,000**

Related to Wildland Interface Fire: **NO** Property Value: **\$6,381,000** Content Value: **\$25,000,000** Total Value at Risk: **\$31,381,000**

Code Name :	Code Description
PROPERTY COMPLEX :	6900 INDUSTRIAL MANUFACTURING
PROPERTY CLASSIFICATION :	6210 SAWMILL, PLANING MILL, WOOD PRODUCTS MILL - INCLUDES THE MAN
GENERAL CONSTRUCTION :	3000 HEAVY TIMBER CONSTRUCTION
BUILDING HEIGHT :	0020 2 STORIES ABOVE GRADE
GROUND FLOOR AREA :	6000 5001 TO 10,000M2 (53821 - 107640FT2)
YEAR OF CONSTRUCTION :	0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION :	2000 EXTINGUISHERS & STANDPIPE SYSTEM
OUTSIDE FIRE PROTECTION :	5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION :	5000 PARTIAL SPRINKLER PROTECTION - LOCAL ALARM, WATCHPERSON
AUTOMATIC FIRE ALARM SYSTE :	2000 FIRE ALARM SYSTEM - LOCAL (BUILDING ONLY)
SMOKE ALARM OPERATION :	9900 NO SMOKE ALARM INSTALLED
INITIAL DETECTION :	7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM :	1000 911
FIRE SERVICE :	3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT :	1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN :	1000 EXTINGUISHED BY OTHER THAN FIRE DEPARTMENT (I.E.. OCCUPANT/W
METHOD OF FIRE CONTROL :	1800 MULTI-PURPOSE DRY CHEMICAL
FIRE ORIGIN, LEVEL :	3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA :	6100 MACHINERY ROOM - INCLUDES ELEVATOR MACHINERY ROOM, ENGINE RO
EXTENT OF FIRE :	3000 CONFINED TO ROOM OF ORIGIN
EXTENT OF DAMAGE :	1000 CONFINED TO OBJECT OF ORIGIN
IGNITING OBJECT :	6100 MOTOR, 1HP & OVER - INCLUDES MOTOR FORMING AN INTEGRAL PART
FUEL OR ENERGY :	6000 ELECTRICITY
FORM OF HEAT :	5000 FRICTION HEAT
MATERIAL FIRST IGNITED :	4200 WOOD SHAVINGS - INCLUDES CHIPPINGS, SAWDUST, EXCELSIOR, WOOD
ACT OR OMISSION :	4100 PART FAILURE, LEAK, BREAK

Investigating Officer	L AFC Badge #	Telephone	ReportDate
BLADES, DARRELL	1211	250-395-2152	2012-04-19

Remarks:

DAMGE WAS LIMITED TO MECHANICAL EQUIPMENT WITHIN THE PLANER.

Investigating Officer	LAFC Badge #	Telephone	ReportDate
BLADES, DARRELL	1211	250-395-2152	2012-04-19

Name no. : 1
Name : NOT , APPLICABLE
Address : 926 EXETER STATION ROAD
100 MILE HOUSE BRITISH COLUMBIA V0K 2E0

Name Status : BUSINESS OWNER
Phone : 250-395-8200

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : **s.21**

Content Loss : **s.21**

Total Loss : **s.21**

REMARKS:

Investigating Officer	L AFC Badge #	Telephone	ReportDate
BLADES, DARRELL	1211	250-395-2152	2012-04-19