Ministry of Justice Emergency Management BC / Office of the Fire Commissioner INC Location of Incident: 2810 33RD - ST. VERNON BC # of Occupants (At time of fire): 3 # of Injured: 0 # of Deaths: 0 Related to Wildland Interface Fire: NO Property Value: s.21 Content Value: \$	
# of Occupants (At time of fire): 3 # of Injured: 0 # of Deaths: 0	CIDENT NUMBER: CVE 2013 01 13 12 01
Related to Wildland Interface Fire: NO Property Value: \$.21 Content Value: \$	Total Dollar Loss Estimate: s.21
	s.21 Total Value at Risk: s.21
Code Name : Code Description	
PROPERTY COMPLEX : 1700 FOOD OR BEVERAGE ESTABLISHM	ENT
PROPERTY CLASSIFICATION : 1710 RESTAURANT - INCLUDES EATING	PLACES SPECIALIZING IN FOOD PRI
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONST	RUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE	
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2)	
YEAR OF CONSTRUCTION : 0066 1966 TO 1968	
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY	
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & 1	

SPRINKLER PROTECTION : 7000	NO SPRINKLER PROTECTION
AUTOMATIC FIRE ALARM SYSTE : 1000	NO FIRE ALARM SYSTEM
SMOKE ALARM OPERATION : 9900	NO SMOKE ALARM INSTALLED

INITIAL DETECTION : 7000	VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000	911
FIRE SERVICE : 3000	COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000	FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000	EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4200	38MM OR 42MM (1 1/2" OR 1 3/4") HOSE - 1 HAND LINE
FIRE ORIGIN, LEVEL : 3000	GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 2300	DINING AREA - INCLUDES MESS ROOM, CANTEEN, LUNCHROOM, CAFETE
EXTENT OF FIRE : 2000	CONFINED TO PART OF ROOM/AREA OF ORIGIN
EXTENT OF DAMAGE : 2000	CONFINED TO PART OF ROOM/AREA OF ORIGIN
IGNITING OBJECT : 5100	PERMANENT ELECTRIC WIRING, CABLE (NON-ALUMINUM) - INCLUDES P
FUEL OR ENERGY : 6000	ELECTRICITY
FORM OF HEAT : 2000	SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI
MATERIAL FIRST IGNITED : 9000	BUILDING COMPONENT - WALL. (EXCLUDES EXTERIOR WALL CLASSIFIE

ACT OR OMISSION : 4400 ELECTRICAL SHORT CIRCUIT

Investigating Officer	LAFC Badge #	Telephone	ReportDate
SKOLROOD, LAWRIE	735	250-550-3563	2013-04-09

Page 1 JAG-2014-00234 2014-03-13

Remarks:

SHORT IN METER BASE IGNITED WOOD COMPONENTS OF INTERIOR WALL NEXT TO IT.

Investigating Officer SKOLROOD, LAWRIE LAFC Badge # 735
 Telephone
 ReportDate

 250-550-3563
 2013-04-09

http://www.ofc.gov.bc.ca/OFC/IncidentReport.jsp?incidentId=243496

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: CVE 2013 01 13 12 01

PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of the Fire Commissioner		FIRE REPORT - STRUCTURE (NAMES) INCIDENT NUMBER: CVE 2013 01 13 12 01		
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: 1. TAYLOR / 2. SHALOVELO , DA : 1. CRAWFORD AND COMPANY A : s.21 : 1. OPTIMUM WEST INSURANCE : s.21	ADJUSTERS / 2. SHALOVELO INSU		
LOSS ESTIMATES: Property Loss : s.21	Content Loss :	\$0 Total Loss : S	\$ s.21	
REMARKS:				
MRS. LOW IS THE OWN	NER OF THE RESTAURANT BUT REN	TED IT TO s.22		

Name no. Name Address	: 2 : :	s.22	Name Status Phone	: OCCUPANT : s.22
Claims Adjuster Name Claims Adjuster Firm Claim Number Insurance Company Policy Number	: : : :			
LOSS ESTIMATES: Property Loss : \$0		Content Loss : \$ s.22	Total Loss :	s.22
REMARKS:				

Investigating Officer SKOLROOD, LAWRIE	LAFC Badge # 735	Telephone 250-550-3563	ReportDate 2013-04-09

Incident Report