## PROVINCE OF BRITISH COLUMBIA Ministry of Community, Aboriginal and Women's Services Office of the Fire Commissioner

FIRE REPORT - STRUCTURE

INCIDENT NUMBER: **DWH 2008 02 01 10 01** 

Location of Incident: 6444 ST. ANDREWS WAY
WHISTLER BC VON 1B6

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: s.22

Related to Wildland Interface Fire: NO Property Value: s.22 Content Value: s.22 Total Value at Risk: s.22

Code Name: Code Description

PROPERTY COMPLEX: 3400 RESIDENTIAL - SINGLE DETACHED

PROPERTY CLASSIFICATION: 3110 YEAR-ROUND USE DWELLING - 1-FAMILY

GENERAL CONSTRUCTION: 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST

BUILDING HEIGHT: 0030 3 STORIES ABOVE GRADE

GROUND FLOOR AREA: 2000 101 TO 500M2 (1077 - 5382FT2)

YEAR OF CONSTRUCTION: 1985 1985

MANUAL FIRE PROTECTION: 7000 NO MANUAL FIRE PROTECTION

OUTSIDE FIRE PROTECTION: 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT

SPRINKLER PROTECTION: 7000 NO SPRINKLER PROTECTION

AUTOMATIC FIRE ALARM SYSTE: 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY

SMOKE ALARM OPERATION: 9500 ALARM NOT ACTIVATED - UNKNOWN

INITIAL DETECTION: 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S

TRANSMISSION OF ALARM: 1000 911

FIRE SERVICE: 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT

INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED

ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT

METHOD OF FIRE CONTROL: 4300 38MM/42MM (1 1/2"/1 3/4") HOSE - 2 OR MORE HAND LINES

FIRE ORIGIN, LEVEL: 2000 CRAWL SPACE, UNDER STRUCTURE

FIRE ORIGIN, AREA: 7100 CRAWL SPACE - INCLUDES SUB-STRUCTURE SPACE

EXTENT OF FIRE: 5000 CONFINED TO BUILDING OF ORIGIN

EXTENT OF DAMAGE: 5000 CONFINED TO BUILDING OF ORIGIN

 ${\tt IGNITING\ OBJECT\ :\ 2900\ HEATING\ EQUIPMENT\ -\ UNCLASSIFIED\ (DESCRIBE)}$ 

FUEL OR ENERGY: 6000 ELECTRICITY

FORM OF HEAT: 2000 SPARK, ELECTRICAL - INCLUDES ARC, DISCHARGE. (EXCLUDES STATI

MATERIAL FIRST IGNITED: 6300 PROPANE - INCLUDES BUTANE, LIQUEFIED PETROLEUM GASES

ACT OR OMISSION: 4100 PART FAILURE, LEAK, BREAK

Investigating Officer HUNTER, MITCH LAFC Badge #

Telephone 604-935-8260

ReportDate 2008-02-06