

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE**INCIDENT NUMBER: **DWH 2013 11 22 16 01**

Location of Incident: **4338 MAIN STREET
WHISTLER BC V0N 1B4**

of Occupants (At time of fire): **1** # of Injured: **0** # of Deaths: **0** Total Dollar Loss Estimate: **\$0**

Related to Wildland Interface Fire: **NO** Property Value: **\$0** Content Value: **\$0** Total Value at Risk: **\$0**

Code Name : Code Description

PROPERTY COMPLEX : 3900 RESIDENTIAL - WITH BUSINESS/MERCANTILE, UP TO 3 STORIES
PROPERTY CLASSIFICATION : 3250 APARTMENT, TOWNHOUSE - OVER 20 UNITS WITH OR W/O BUSINESS
GENERAL CONSTRUCTION : 2000 PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLAST
BUILDING HEIGHT : 0030 3 STORIES ABOVE GRADE
GROUND FLOOR AREA : 0000 CANNOT BE DETERMINED
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT
SPRINKLER PROTECTION : 1000 COMPLETE SPRINKLER PROTECTION - SUPERVISED (ON-SITE OR OFF-S
AUTOMATIC FIRE ALARM SYSTE : 3000 FIRE ALARM SYSTEM - OFF-SITE MONITORING AGENCY
SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S
TRANSMISSION OF ALARM : 1000 911
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 5000 3RD STOREY OR OVER 6M TO 9M (20FT TO 30FT) ABOVE GRADE
FIRE ORIGIN, AREA : 7200 EXTERIOR BALCONY - INCLUDES OPEN PORCH, DECK
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 7700 TORCH - OTHER THAN CUTTING, WELDING - INCLUDES PLUMBER'S FUR
FUEL OR ENERGY : 4200 FUEL GAS - PROPANE
FORM OF HEAT : 4000 DIRECT FLAME
MATERIAL FIRST IGNITED : 1900 BUILDING COMPONENTS - UNCLASSIFIED (DESCRIBE)
ACT OR OMISSION : 2600 TORCH TOO CLOSE

Investigating Officer LAFC Badge #
KIRKWOOD, SHEILA 1512

Telephone ReportDate
604-935-8264 2013-12-06

PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NARRATIVE)

INCIDENT NUMBER: **DWH 2013 11 22 16 01**

Remarks:

TORCH-ON ROOFING ON EXTERIOR BALCONY OF UNIT 322 TOOK PLACE AT APPROXIMATELY 1300 ON NOV 22, 2013. FIRE ON EXTERIOR BALCONY OF UNIT 322 CALLED IN BY VISUAL SIGHTING AT 1632. FIRE ARRIVING ENGINE REPORTED BALCONY FULLY INVOLVED WITH FLAME TRAVELLING UP THE OUTSIDE OF THE BUILDING ONTO THE ROOF AND INTO THE SOFFITS.

Investigating Officer	LAFC Badge #
KIRKWOOD, SHEILA	1512

Telephone	ReportDate
604-935-8264 	2013-12-06


PROVINCE OF BRITISH COLUMBIA
Ministry of Justice
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **DWH 2013 11 22 16 01**

Name no. : 1
Name :
Address :

s.22

Name Status : OWNER
Phone : s.22 

Claims Adjuster Name :
Claims Adjuster Firm :
Claim Number :
Insurance Company :
Policy Number :

LOSS ESTIMATES:

Property Loss : \$0

Content Loss : \$0

Total Loss : \$0

REMARKS:

STRATA MANAGER FOR BUILDING

Investigating Officer : LAFC Badge #
KIRKWOOD, SHEILA : 1512

Telephone : ReportDate
604-935-8264  2013-12-06

