

Location of Incident: **3318 HIGHWAY 16  
SMITHERS BC V0J2N0**

# of Occupants (At time of fire): **5**      # of Injured: **0**      # of Deaths: **0**      Total Dollar Loss Estimate: **s.22**

Related to Wildland Interface Fire: **NO**      Property Value: **s.22**      Content Value: **s.22**      Total Value at Risk: **s.22**

**Code Name :      Code Description**

PROPERTY COMPLEX : 5600 COMMERCIAL CENTRE INCLUDING FUEL DISPENSING (MAY INCLUDE RES  
PROPERTY CLASSIFICATION : 5670 GENERAL MAINTENANCE SHOP  
GENERAL CONSTRUCTION : 5000 PROTECTED NON-COMBUSTIBLE CONSTRUCTION - PROTECTED STEEL OR  
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE  
GROUND FLOOR AREA : 3000 501 TO 1000M2 (5383 - 10764FT2)  
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED  
MANUAL FIRE PROTECTION : 0000 CANNOT BE DETERMINED  
OUTSIDE FIRE PROTECTION : 1000 PUBLIC HYDRANT PROTECTION & FIRE DEPARTMENT  
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION  
AUTOMATIC FIRE ALARM SYSTE : 0000 CANNOT BE DETERMINED  
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED  
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S  
TRANSMISSION OF ALARM : 1000 911  
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT  
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED  
ACTION TAKEN : 3000 EXTINGUISHED BY FIRE DEPARTMENT  
METHOD OF FIRE CONTROL : 4900 FIRE DEPARTMENT - WATER APPLICATION - UNCLASSIFIED (DESCRIBE  
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)  
FIRE ORIGIN, AREA : 3550 MAINTENANCE SHOP - INCLUDES REPAIR SHOP, WELDING SHOP, WORKS  
EXTENT OF FIRE : 5000 CONFINED TO BUILDING OF ORIGIN  
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN  
IGNITING OBJECT : 0000 CANNOT BE DETERMINED  
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED  
FORM OF HEAT : 0000 CANNOT BE DETERMINED  
MATERIAL FIRST IGNITED : 0000 CANNOT BE DETERMINED  
ACT OR OMISSION : 0000 CANNOT BE DETERMINED

Investigating Officer	L AFC Badge #	Telephone	ReportDate
STECKO, KEITH	1620	250-847-2015	2012-03-26

**Remarks:**

FIRE DEPARTMENT ARRIVED ON SCENE AND NOTED THAT THE FIRE HAD VENTED THROUGH THE ROOF AND ENGULFED THE ENTIRE ROOF SECTION, SHORTLY THERE AFTER THE ROOF COLLAPSED INTO THE BUILDING.

---

Investigating Officer	L AFC Badge #	Telephone	ReportDate
STECKO, KEITH	1620	250-847-2015	2012-03-26

PROVINCE OF BRITISH COLUMBIA  
Ministry of Justice  
Emergency Management BC / Office of the Fire Commissioner

FIRE REPORT - **STRUCTURE** (NAMES)

INCIDENT NUMBER: **TSM 2012 03 23 12 01**

Name no. : 1  
Name :  
Address :

s.22

Name Status : BUSINESS OWNER  
Phone :

Claims Adjuster Name :  
Claims Adjuster Firm :  
Claim Number :  
Insurance Company :  
Policy Number :

LOSS ESTIMATES:

Property Loss : s.22

Content Loss : s.22

Total Loss : s.22

REMARKS:

Investigating Officer  
STECKO, KEITH

L AFC Badge #  
1620

Telephone  
250-847-2015

ReportDate  
2012-03-26