PROVINCE OF BRITISH COLUMBIA Ministry of Justice Emergency Management BC / Office of t		FIRE REPORT - STRUCTURE INCIDENT NUMBER: DWH 2013 10 22 04 01 -				
Location of Incident:	4661 BLAC WHISTLE					
# of Occupants (At time of fire): 4	# of Injured: 0	# of Deaths: 0		Total Dollar Loss Estimate: \$0		
Related to Wildland Interface Fire: NO	Property Value: \$	s.22	Content Value: \$	s.22	Total Value at Risk: \$	s.22

PROPERTY COMPLEX:3100RESIDENTIAL - ROW, GARDEN, TOWN HOUSING, CONDOMINIUMPROPERTY CLASSIFICATION:3240APARTMENT, TOWNHOUSE - 5 TO 20 UNITS WITHOUT BUSINESSGENERAL CONSTRUCTION:2000PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLASTBUILDING HEIGHT:00202 STORIES ABOVE GRADEGROUND FLOOR AREA:2000101 TO 500M2 (1077 - 5382FT2)YEAR OF CONSTRUCTION:0000CANNOT BE DETERMINEDMANUAL FIRE PROTECTION:4000EXTINGUISHER ONLYOUTSIDE FIRE PROTECTION:5000PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENTSPRINKLER PROTECTION:5000NO SPRINKLER PROTECTIONAUTOMATIC FIRE ALARM SYSTE:1000NO FIRE ALARM SYSTEMSMOKE ALARM OPERATION:1000SMOKE ALARM DEVICEINITIAL DETECTION:1000911FIRE SERVICE:3000COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENTDUCIDENT:1000COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
GENERAL CONSTRUCTION : 2000PROTECTED COMBUSTIBLE CONSTRUCTION - WOOD PROTECTED BY PLASTBUILDING HEIGHT : 00202 STORIES ABOVE GRADEGROUND FLOOR AREA : 2000101 TO 500M2 (1077 - 5382FT2)YEAR OF CONSTRUCTION : 0000CANNOT BE DETERMINEDMANUAL FIRE PROTECTION : 4000EXTINGUISHER ONLYOUTSIDE FIRE PROTECTION : 5000PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENTSPRINKLER PROTECTION : 5000NO SPRINKLER PROTECTIONAUTOMATIC FIRE ALARM SYSTE : 1000NO FIRE ALARM SYSTEMSMOKE ALARM OPERATION : 1000SMOKE ALARM DEVICEINITIAL DETECTION : 1000911FIRE SERVICE : 1000COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
BUILDING HEIGHT:00202 STORIES ABOVE GRADEGROUND FLOOR AREA:2000101 TO 500M2 (1077 - 5382FT2)YEAR OF CONSTRUCTION:0000CANNOT BE DETERMINEDMANUAL FIRE PROTECTION:4000EXTINGUISHER ONLYOUTSIDE FIRE PROTECTION:5000PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENTSPRINKLER PROTECTION:5000NO SPRINKLER PROTECTIONAUTOMATIC FIRE ALARM SYSTE:1000NO FIRE ALARM SYSTEMSMOKE ALARM OPERATION:1000ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATINGINITIAL DETECTION:1000SMOKE ALARM DEVICETRANSMISSION OF ALARM:1000911FIRE SERVICE:3000COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
GROUND FLOOR AREA : 2000 101 TO 500M2 (1077 - 5382FT2) YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT SPRINKLER PROTECTION : 5000 NO SPRINKLER PROTECTION AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
YEAR OF CONSTRUCTION : 0000 CANNOT BE DETERMINED MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
MANUAL FIRE PROTECTION : 4000 EXTINGUISHER ONLY OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENT SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
OUTSIDE FIRE PROTECTION : 5000 PRIVATE HYDRANT PROTECTION & FIRE DEPARTMENTSPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTIONAUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEMSMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATINGINITIAL DETECTION : 1000 SMOKE ALARM DEVICETRANSMISSION OF ALARM : 1000 911FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTIONAUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEMSMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATINGINITIAL DETECTION : 1000 SMOKE ALARM DEVICETRANSMISSION OF ALARM : 1000 911FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
SMOKE ALARM OPERATION : 1000 ALARM ACTIVATED - ASSISTED OCCUPANT(S) IN EVACUATING INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INITIAL DETECTION : 1000 SMOKE ALARM DEVICE TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
TRANSMISSION OF ALARM : 1000 911 FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
FIRE SERVICE : 3000 COMPOSITE - CAREER & VOLUNTEER/PAID-ON-CALL FIRE DEPARTMENT
INCIDENT : 1000 FIRE - FIRE DEPARTMENT ATTENDED
ACTION TAKEN: 3000 EXTINGUISHED BY FIRE DEPARTMENT
METHOD OF FIRE CONTROL : 4500 65MM/77MM (2 1/2"/3") HOSE -2 OR MORE HAND LINES
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)
FIRE ORIGIN, AREA : 7200 EXTERIOR BALCONY - INCLUDES OPEN PORCH, DECK
EXTENT OF FIRE : 6000 EXTENDED BEYOND PROPERTY OF ORIGIN
EXTENT OF DAMAGE : 5000 CONFINED TO BUILDING OF ORIGIN
IGNITING OBJECT : 7220 LIGHTER - NOT USED IN CONJUNCTION WITH SMOKING
FUEL OR ENERGY : 1000 SOLID FUEL (E.G. COAL, WOOD, PELLETS, PAPER OR WASTE USED FO
FORM OF HEAT : 6000 HOT OBJECT - DIRECT HEAT BY CONDUCTION OR RADIATION, NO DIRE
MATERIAL FIRST IGNITED : 4400 PAPER, PACKING MATERIAL - INCLUDES SHREDDED PAPER
ACT OR OMISSION : 2430 ADULT - 18 YEARS OF AGE AND OLDER

Investigating OfficerLAFCKIRKWOOD, SHEILA1512

LAFC Badge # 1512 Telephone ReportDate 604-935-8264 2013-12-18

Remarks:

THE FIRE STARTED ON THE REAR DECK. POINT OF ORIGIN WAS AT DECK LEVEL. BURNED RECYLING MATERIALS FOUND IN AREA OF ORIGIN BESIDE SMALL BBQ AND 2 PROPANE BOTTLES. OCCUPANTS REPORTED 2 LOUD BANGS AND WOOSHING SOUNDS. BOTH PROPANE TANKS WERE SOOT STAINED FROM THE BOTTOM UPWARD, 1 TANK HAD THE RELIEF VALVE BLOWN OUT AND THE OTHER TANK HAD MELTED THROUGH THE HOSE, THIS TANK WAS IN THE OPEN POSITION. OCCUPANTS REPORTED SMOKING ON THE DECK. AS THERE WERE NO OTHER IGNITION SOURCES PRESENT IT IS BELIEVED TO BE SMOKERS MATERIALS IGNITED THE RECYCLING, THEN EXPOSING THE BBQ TANKS, WHICH FURTHER FUELED THE FIRE, WHICH TRAVELED UP THE EXTERIOR OF THE BUILDING AND ENTERED TO SOFFITS AND COMMON ATTIC SPACE.

Investigating Officer KIRKWOOD, SHEILA LAFC Badge # 1512

 Telephone
 ReportDate

 604-935-8264 (2013-12-18)
 2013-12-18)

FIRE REPORT - STRUCTURE (NARRATIVE)

INCIDENT NUMBER: DWH 2013 10 22 04 01

Page 2 JAG-2014-01401 2014-10-28

PROVINCE OF BRITISH Ministry of Justice	/ IBIA	FIRE REPORT - STRUCTURE (NAMES)					
Emergency Management BC / Office of the Fire Commissioner			INCIDENT NUMBER: DWH 2013 10 22 04 01				
Name no.	:1	- 00		Name Status	: OWNER	2	
Name Address	:	s.22		Phone	s.22	8	
	WHI	STLER BRI	TISH COLUMBIA VON 1B8				
Claims Adjuster Name	:						
Claims Adjuster Firm	:						
Claim Number	:						
Insurance Company	:						
Policy Number	:						
LOSS ESTIMATES:							
Property Loss: \$0			Content Loss: \$0	Total Loss: \$0			
REMARKS:							

Investigating Officer KIRKWOOD, SHEILA LAFC Badge # 1512
 Telephone
 ReportDate

 604-935-8264 (2013-12-18)
 2013-12-18

Incident Report