

Location of Incident: SUITE 135B 10TH AVE. CHOPAKA RD  
LOWER SIMILKAMEEN BAND BC V0E 2Y0

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$400,000

Related to Wildland Interface Fire: NO Property Value: \$250,000 Content Value: \$150,000 Total Value at Risk: \$400,000

**Code Name : Code Description**

PROPERTY COMPLEX : 1400 CHURCH, FUNERAL HOME  
PROPERTY CLASSIFICATION : 1410 CHURCH, CHAPEL  
GENERAL CONSTRUCTION : 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST  
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE  
GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)  
YEAR OF CONSTRUCTION : 0020 1920 OR BEFORE  
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION  
OUTSIDE FIRE PROTECTION : 8000 NO OUTSIDE FIRE PROTECTION  
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION  
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM  
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED  
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S  
TRANSMISSION OF ALARM : 1000 911  
FIRE SERVICE : 8000 NO FIRE SERVICE  
INCIDENT : 1100 NO ALARM FIRE - NOT RESPONDED TO BY FIRE DEPARTMENT  
ACTION TAKEN : 2000 BURNED OUT - NO EXTINGUISHMENT ATTEMPTED/NEEDED  
METHOD OF FIRE CONTROL : 8300 BURNED OUT, NO EXTINGUISHMENT - OUTSIDE FIRE PROTECTION AREA  
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)  
FIRE ORIGIN, AREA : 1010 HALLWAY, CORRIDOR  
EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN  
EXTENT OF DAMAGE : 1000 CONFINED TO OBJECT OF ORIGIN  
IGNITING OBJECT : 0000 CANNOT BE DETERMINED  
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED  
FORM OF HEAT : 4000 DIRECT FLAME  
MATERIAL FIRST IGNITED : 5000 FLOOR COVERING - WOOD  
ACT OR OMISSION : 1230 SUSPICIOUS -s.15

Investigating Officer  
BLAIR, JACK

LAFC Badge #  
1262

Telephone  
236-597-7515

ReportDate  
2021-06-30

**Remarks:**

EXTENSIVE FIRE DAMAGE TO ENTIRE STRUCTURE AND CONTENTS. FIRE APPEARS TO HAVE BEEN SET FROM INTERIOR OF BUILDING. CHURCH IS OWNED BY LOWER SIMILKAMMEN INDIAN BAND. s.15; s.22  
s.15; s.22 FIRE SERVICES ADVISOR BLAIR WAS NOTIFIED BY RCMP CST. REBECCA FRASER AT 083 HRS JUNE 26 /202 AND ATTENDED SCENE ALONG WITH RCMP CRPL. LAURIE ROCK ON SUNDAY JUNE 27/2021 0900HRS. BAND CHIEF KEITH CROW ALSO PRESENT AT SCENE.

---

Investigating Officer	L AFC Badge #	Telephone	ReportDate
BLAIR, JACK	1262	236-597-7515	2021-06-30

Name no. : 1  
Name : UNK, UNK  
Address :

Name Status : BUSINESS OWNER  
Phone :

Claims Adjuster Name :  
Claims Adjuster Firm :  
Claim Number :  
Insurance Company :  
Policy Number :

LOSS ESTIMATES:

Property Loss : \$250,000

Content Loss : \$150,000

Total Loss : \$400,000

REMARKS:

---

---

Investigating Officer      LAFC Badge #  
BLAIR, JACK                1262

Telephone      ReportDate  
236-597-7515      2021-06-30



Location of Incident: SUITE 135B 10TH AVE. HIGHWAY 3  
UPPER SIMILKAMEEN BAND BC V0E 2Y0

# of Occupants (At time of fire): 0 # of Injured: 0 # of Deaths: 0 Total Dollar Loss Estimate: \$300,000

Related to Wildland Interface Fire: NO Property Value: \$200,000 Content Value: \$100,000 Total Value at Risk: \$300,000

**Code Name : Code Description**

PROPERTY COMPLEX : 1400 CHURCH, FUNERAL HOME  
PROPERTY CLASSIFICATION : 1410 CHURCH, CHAPEL  
GENERAL CONSTRUCTION : 1000 COMBUSTIBLE CONSTRUCTION - OPEN WOOD JOIST  
BUILDING HEIGHT : 0010 1 STORY ABOVE GRADE  
GROUND FLOOR AREA : 1000 1 TO 100M2 (1 - 1076FT2)  
YEAR OF CONSTRUCTION : 0020 1920 OR BEFORE  
MANUAL FIRE PROTECTION : 7000 NO MANUAL FIRE PROTECTION  
OUTSIDE FIRE PROTECTION : 8000 NO OUTSIDE FIRE PROTECTION  
SPRINKLER PROTECTION : 7000 NO SPRINKLER PROTECTION  
AUTOMATIC FIRE ALARM SYSTE : 1000 NO FIRE ALARM SYSTEM  
SMOKE ALARM OPERATION : 0000 ALARM OPERATION CANNOT BE DETERMINED  
INITIAL DETECTION : 7000 VISUAL SIGHTING OR OTHER MEANS OF PERSONAL DETECTION (E.G. S  
TRANSMISSION OF ALARM : 1000 911  
FIRE SERVICE : 8000 NO FIRE SERVICE  
INCIDENT : 1100 NO ALARM FIRE - NOT RESPONDED TO BY FIRE DEPARTMENT  
ACTION TAKEN : 2000 BURNED OUT - NO EXTINGUISHMENT ATTEMPTED/NEEDED  
METHOD OF FIRE CONTROL : 8300 BURNED OUT, NO EXTINGUISHMENT - OUTSIDE FIRE PROTECTION AREA  
FIRE ORIGIN, LEVEL : 3000 GROUND FLOOR, GRADE LEVEL OR GRADE TO 3M (10FT)  
FIRE ORIGIN, AREA : 7600 EXTERIOR WALL  
EXTENT OF FIRE : 1000 CONFINED TO OBJECT OF ORIGIN  
EXTENT OF DAMAGE : 1000 CONFINED TO OBJECT OF ORIGIN  
IGNITING OBJECT : 0000 CANNOT BE DETERMINED  
FUEL OR ENERGY : 0000 CANNOT BE DETERMINED  
FORM OF HEAT : 4000 DIRECT FLAME  
MATERIAL FIRST IGNITED : 3000 EXTERIOR WALL COVERING, SURFACE, FINISH - INCLUDES EAVE  
ACT OR OMISSION : 1230 SUSPICIOUS -s.15

Investigating Officer	LAFC Badge #	Telephone	ReportDate
BLAIR, JACK	1262	250-597-7515	2021-06-30

**Remarks:**

EXTENSIVE FIRE DAMAGE TO ENTIRE STRUCTURE. CHURCH WAS ON THE UPPER SIMILKAMEEN BAND LANDS. **s.15**  
**s.15** FIRE SERVICE ADVISOR JACK BLAIR ATTENDED SCENE WITH CRPL.  
LAURIE ROCK OF PENTICTON DETACHMENT AT 1040 HRS SUNDAY JUNE 27TH 2021. FSA BLAIR WAS NOTIFIED OF  
INCIDENT BY RCMP CST. REBECCA FRASER 0830 HRS SAT JUNE 26 2021

---

Investigating Officer	L AFC Badge #	Telephone	ReportDate
BLAIR, JACK	1262	250-597-7515	2021-06-30

Name no. : 1  
Name : UNK, UNK  
Address :

Name Status : BUSINESS OWNER  
Phone :

Claims Adjuster Name :  
Claims Adjuster Firm :  
Claim Number :  
Insurance Company :  
Policy Number :

LOSS ESTIMATES:

Property Loss : \$200,000

Content Loss : \$100,000

Total Loss : \$300,000

REMARKS:

Investigating Officer :  
BLAIR, JACK

L AFC Badge #  
1262

Telephone :  
250-597-7515

ReportDate  
2021-06-30

