	COLUMBIA COLUMBIA	INCIDENT	T REPORT ID: 236266 X-Ref: IDIR\VMETCALF 2010/02/05 00:00:00
	7077 DUNCAN STR POWELL RIVER BC	FOREST DISTRICT REET C V8A1W1 mperial Oil Ltd	Tenure (type/no): / RMCP-WATER MANAGEMENT-SCSR-DSC 2010/02/05 0:00 Regional Inspection: □ Location 4419 Marine Ave., Powell River, BC, V8A 2J9
		Hooper 	Area Inspected
В	Inspection Method ⊠ □	Area Inspected: Complete Location Inspected:	Area Inspected e
С	Site or Activity Status: Petroleum Storage F	- -acility Inspections of Imperial Oil in	n Powell River.
D			
		om the Seperator is below the provi	rincial standard of 15 mg/L. Seperator System is inspected ution Facility Regulation as are all records.
Е	Inspector: (I certify that this inspection of	Vince Metcalf conforms to Ministry of Forests' compliance	Joe Hooper
	Checklist: Checklist: Other:		
	File # 23040-13/Ministry of Environment - Environmental Protection File #		